

ASS. REC. BY:

REF: CS3 / MS9 19011823 / TICD302 Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Jusmina Lot Chong Khai of MS19

Date/Time: 3.7.19 16.06 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: VN 499IT

Insured: XE 3384 L

at Workshop m/s Miracle Works

Tel: 96477568

of 48 Toh Guan Road East #04-126

Policy No: 29004165 MEC

Claim No: 598456

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.7.19 10.01 a.m

Person Contacted: Nicole

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	VN 499IT - X
	XE 3384L - X
	Resurvey: 8/7/2019

Tanpin

REF MS19

## ASSIGNMENT

From Date: 4.7.2019

Veh No: YN 4991T Yr Regn: 2014, March

Estimated Cost:

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: YN 4991T

Make: Mitsubishi Canter c.c. 2998

at Workshop n/s: Miracle Works

Colour: white A/C: Insured / Std / NI / NA

of 48 Toh Guan Road East #04-126

Sp. Reading: 426121 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/85R15

R: (17)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO (YOKO) or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal. 6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 6 mm

Est. Repairs:

6

days

Res.: Yes or No

D.O.A.

D.O.L.

Lump Sum:

%

3 Val: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

up

Des. of Damages: Frl / Rstr / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range Only  
 - Estimated repair range \$4,500 - \$5,300  
 Range will repair at Hwi Song Kee Cargo Box @ 39 Sg Kedat St 4

9/7/2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 6

1)

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format:

PRE

Lump Sum / I.B.E. (\$)

Survey Fee:

120

Transportation:

S + RS, 30

Photos

Others

11

TOTAL

131

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019		03 Jul 2019 16:06 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>				
Insured:	Progress Galvanizing Pte Ltd, Co. Reg. No.: 199101791K			
Main Claimant:	MCI Corp Pte Ltd			
Vehicle Reg. No.:	YN4991T	Date of Loss:	28/06/2019 10:00 - :59 [25 Months From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 598456	Policy/Cover Note No.:	29004165MKC (Comprehensive) Coverage: 11/08/2018 - 10/08/2019	
Vehicle Reg. No. (Insured):	XE3384L	Policy No. (Claimant):		
		Excess:		
Repairer:	Miracle Works Pte Ltd (HQ) 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB, 608586 Jurong West - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2019]			
Adj Asg. Remarks:	on WP. Liab: dispute (OI NR) TP lawyer disagree on SJE - assign LKK Auto. Contact: Nicole @ 8204 5858 / 9647 2568/ 6468 3096.			
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>				
There are no mail for this case.				
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div>				
No results.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6231W
<b>Vehicle Details</b>	
Vehicle No.:	YN4991T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4P10B02840
Chassis No.:	FEB21EA00220
Maximum Power Output:	-
Open Market Value:	\$29,658.00
Original Registration Date:	25 Mar 2014
First Registration Date:	25 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$1,483.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,302.00
COE Rebate Amount:	\$26,546.00
<b>Total Rebate Amount:</b>	<b>\$26,546.00</b>

The information contained herein is correct as at 06 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/06/2019 13:37
Date Of Accident	28/06/2019 10:30
Exact Location Of Accident	ADMIRALTY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN4991T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MCI CORP PTE LTD
Co Reg No	199506231W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84230053
Alternative Phone No	OFFICE-98318554

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108392048
Cover Note Number	

### Driver

Name of Driver	RAJA SATHISH
NRIC No	G2199671N
Date Of Birth	14/02/1991
Occupation	OUTDOOR
Date Of Driving Pass	24/01/2015
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98318554
Fax Number	
Contact Number	OFFICE-98318554
EMail Address	NOEMAIL

Address	30 BUKIT BATOK CRESCENT
Postcode	S658070
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY VEHICLE WAS STOPPED AT THE JUNCTION ADMIRALTY ROAD DUE TO "RED" LIGHT INFRONT, ALL OF A SUDDEN, A TRUCK CAME FROM BEHIND AND HIT ONTO THE REAR PORTION OF MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3384L
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANG POH ENG
NRIC/Passport Number	S1565244F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**IDAC BUKIT BATOK (P)O**  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg




Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



XE 3384L

YN 4991 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

511 Bukit Timah Road

### DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Date &amp; Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

(If driver is not the policyholder)

Date &amp; Time:

**IDAC BUKIT BATU (PAC)**  
511 Bukit Batok Street 25  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: [vacbb@singnet.com.sg](mailto:vacbb@singnet.com.sg)

511 Fifth Avenue, New York, N.Y. 10017

Singapore 655545

Tel: 6560 3312 Fax: 6569 0722

Email: [vacbb@singnet.com.sg](mailto:vacbb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019		03 Jul 2019 16:06 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>Progress Galvanizing Pte Ltd</b> , Co. Reg. No.: 199101791K									
Main Claimant: <b>MCI Corp Pte Ltd</b>									
Vehicle Reg. No.: <b>YN4991T</b>		Date of Loss: 28/06/2019 10:00 - :59 [63 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 598456</b>		Policy/Cover Note No.: 29004165MKC (Comprehensive) Coverage: 11/08/2018 - 10/08/2019							
Vehicle Reg. No. (Insured): <b>XE3384L</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Miracle Works Pte Ltd (HQ)</b> 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB, 608586 Jurong West - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 04/07/2019]									
Adj Asg. Remarks: on WP. Liab: dispute (OI NR) TP lawyer disagree on SJE - assign LKK Auto. Contact: Nicole @ 8204 5858 / 9647 2568/ 6468 3096.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*YN4991T (598456)**  
**[XE3384L]**  
**TP**  
**MCI Corp Pte Ltd**  
**Jun 28 2019 10:00AM**  
**[Progress Galvanizing Pte Ltd]**  
**Miracle Works Pte Ltd**



































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

<b>Assessment Reports</b>				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	08/07/19 08:24	<b>Accident Statement</b> <small>From: SC - Reg. No: XE3384L, Claimant: PROGRESS GALVANIZING PTE LTD</small>		Load HTM	

<b>Photos/Images</b>				3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	06/07/19 15:08	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/07/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/19 19:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/19 19:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/19 19:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/07/19 17:13	PRI from C Yogarajah LLC	 Load PDF	
2	03/07/19 11:42	Disagree on SJE	 Load PDF	
3	08/07/19 08:41	TP YN4991T E-FILE REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19011823/T1CD3E2

Date: 29/07/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29004165MKC

Claimant Vehicle No : YN4991T

Insured Vehicle No : XE3384L

Date of Loss: 28/06/2019

Nature of Claim: TP

Claim No: 598456

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YN4991T

Make &amp; Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)

Engine No: 4P10B02840

Reg. Date: 25/03/2014 (Man. Year: 2013)

Chassis No: FEB21EA00220

Colour: White

Odometer: 426121 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/85 R15

Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 03/07/2019

Date Inspected: 04/07/2019 Inspected At:

Miracle Works Pte Ltd (HQ)  
48 TOH GUAN ROAD EAST #04-126  
ENTERPRISE HUB  
Singapore 608586

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,300.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 29 Jul 2019)

**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for YN4991T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >