

ASS. REC. BY: _____ REF: CS/CT19011863/Kvd302 Special Instructions: _____

Surveyor: Kenneth **ASSIGNMENT (Office)**

From (Person): Chung Boon Sen of CTI Date/Time: 3/7/2019 5:42pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGG 5419Z Insured: ABG 8499G

at Workshop m/s Supreme Auto Tel: 64528211

of No. 176 R/m #03-01

Policy No: DMCVSN17671318011 Claim No: SNM19D203093

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 4/7 Person Contacted: Yubi Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGG 5419Z-X</u>
	<u>ABG 8499G-X</u>
	<u>18/7 11 Pm 8900d email & confirmed (Red 5284, 561)</u>

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ *new work*

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *05* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to
GIA not ready

RECEIVED 15 JUL 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/7 - typist

Report Format:

Lump Sum / I.B.I. (\$) *merimen 4000/-*Days Of Repair: *5*Resurvey No. of Trip: *1*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation: *5 - RS. \$*

Fuel

Others

TOTAL

220

Veh No: *SGG 54192* Yr Regn: *19/10, 09*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *Wagon*
Make: *Toy Alphard* cc *2362*Colour: *W.D. Grey* A/C: Insured / Std / NI / NASp. Reading: *136024* T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: *AN1410* *0145085*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModl: *NI / S/Rim* / STD A/Rim orTyre Size: F: *245/40ZR19*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Falken*

Front

R/Bal. *6* mmL/Bal. *6* mmD.O.A. *3/7/19*Survey held at *✓*Des. of Damages: *Front* / Rear / O/S / N/S / U/C / Rooftop or*N/S 1st body*

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019		05 Jul 2019 11:45 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	CHAN KWOK HOONG PHILIP, ID: S1797635D			
Vehicle Reg. No.:	SGG5419Z	Date of Loss:	03/07/2019 08:00 - :59	
Claim Type:	TP / SNM19D203093C02	Policy/Cover Note No.:	DMCVSN17671318011	
Vehicle Reg. No. (Insured):	GBG8499G	Policy No. (Claimant):	5104966757	
		Excess:	S\$0.00	
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0715			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/07/2019]			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 3 July 2019 5:42 PM
To: assignments
Subject: FW: OUR REF : SNM19D203093/CHONGBS - FW: PRI ACC INVOLVING SGG 5419 Z TP CNTP GBG8499G

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Wednesday, 3 July, 2019 5:42 PM

To: admin@supreme.sg

Subject: RE: OUR REF : SNM19D203093/CHONGBS - FW: PRI ACC INVOLVING SGG 5419 Z TP CNTP GBG8499G

Without Prejudice

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 3 July, 2019 5:18 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So

* CFW <sochow.chee@sg.cntaiping.com>; admin@supreme.sg

Subject: OUR REF : SNM19D203093/CHONGBS - FW: PRI ACC INVOLVING SGG 5419 Z TP CNTP GBG8499G

Dear Boon Sen,

Please conduct PRS for SGG5419Z.

***** Officer-In-Charge – Chong Boon Sen – 63896171 (file with OIC).**

Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: admin@supreme.sg [<mailto:admin@supreme.sg>]

Sent: Wednesday, 3 July, 2019 3:17 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: PRI ACC INVOLVING SGG 5419 Z TP CNTP GBG8499G

Dear Sir/Mdm,

Attached is the PRI for your assignation of surveyor.

Thank you.

Best regards,

Yuki Ho

Supreme Auto Service Pte Ltd

No.176 Sin Ming Drive

#02-01 Singapore 575721

Tel: 64528211

Fax: 64517423

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7635D
Vehicle Details	
Vehicle No.:	SGG5419Z
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2AZB194484
Chassis No.:	ANH100145045
Maximum Power Output:	117.0 kW (156 bhp)
Open Market Value:	\$33,761.00
Original Registration Date:	16 May 2006
First Registration Date:	16 May 2006
Transfer Count:	5
Actual ARF Paid:	\$37,138.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$31,589.00
Total Rebate Amount:	\$31,589.00

The information contained herein is correct as at 05 Jul 2019

OK

MSI319087057 / STA INSPECTION PTE LTD - Boon Lay
 ENTRY DATE & TIME: 04/07/2019 13:11
 SUBMITTED BY: Woodford Richard Vincent

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/07/2019 13:11
 Date Of Accident 03/07/2019 08:30
 Exact Location Of Accident 464 UPPER SERANGOON ROAD CARPARK LOT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGG5419Z
 Insured/Policyholder
 Name Of Registered Owner CHAN KWOK HOONG PHILIP
 NRIC No S1797635D
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97310254
 Alternative Phone No Others-97310254
 Vehicle Particulars
 Manufacturer TOYOTA
 Model ALPHARD
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5104966757
 Cover Note Number
 Driver
 Name of Driver CHAN KWOK HOONG PHILIP
 NRIC No S1797635D
 Date Of Birth 09/07/1967
 Occupation INDOOR
 Date Of Driving Pass 16/08/1995
 Driving Experience 23 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97310254
 Fax Number
 Contact Number OTHERS-97310254
 Email Address NOEMAIL

7/5/2019

E-FILE

Address 38 LORONG 30 GEYLANG
#07-22

Postcode 398371

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED - TYPE OF ACCIDENT HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG8499G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the parking lot of 464 Upper Serangoon Road when suddenly, vehicle B, which was driving out of one of the lot hit the front left portion of my vehicle with a hard impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIABAC SketchPlanForm_V3

2

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



From Owner:

R032459

VIN:

SGG5419Z

Year:

10

Date

4.7.19 18:20



SGG5419Z

Before

Toyota : Alphard / Vellfire

Front : Left

Actual	Before	Specified Range
-2°34'	-2°30'	-1°25' 0°05'
3°18'	3°18'	1°40' 3°10'
-0°01'	0°00'	-0°05' 0°05'
13°15'	13°11'	10°05' 11°35'
10°41'	10°41'	8°40' 11°40'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°34'	-1°34'	-1°25' 0°05'
2°29'	2°29'	1°40' 3°10'
-0°09'	-0°09'	-0°05' 0°05'
12°09'	12°09'	10°05' 11°35'
10°34'	10°34'	8°40' 11°40'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-1°00'	-0°56'	-0°45' 0°45'
0°49'	0°49'	-0°45' 0°45'
1°07'	1°03'	
-0°10'	-0°09'	-0°10' 0°10'

Rear : Left

Actual	Before	Specified Range
-1°10'	-1°10'	-2°00' -1°00'
0°09'	0°09'	-0°08' 0°08'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°15'	-1°16'	-2°00' -1°00'
0°05'	0°04'	-0°08' 0°08'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°05'	0°06'	-0°30' 0°30'
0°14'	0°13'	-0°15' 0°15'
0°02'	0°02'	
0mm	0mm	

Work Order: K054803
 License: SLF2280X
 Year: 15
 Date: 5.7.19 18:22

Toyota Harrier

After

Front : Left

Actual	Before	Specified Range
-0°36'	-0°39'	-0°55' 0°35'
6°03'	6°03'	5°10' 6°40'
0°00'	0°03'	-0°02' 0°07'
12°03'	12°07'	10°45' 12°15'
11°28'	11°28'	9°50' 12°50'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°09'	-0°06'	-0°55' 0°35'
5°54'	5°54'	5°10' 6°40'
-0°02'	0°01'	-0°02' 0°07'
11°24'	11°20'	10°45' 12°15'
11°15'	11°15'	9°50' 12°50'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°27'	-0°33'	-0°45' 0°45'
0°09'	0°09'	-0°45' 0°45'
0°40'	0°46'	
-0°01'	0°04'	-0°05' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°03'	-1°07'	-2°00' -0°30'
0°04'	0°03'	0°00' 0°09'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°16'	-1°13'	-2°00' -0°30'
0°05'	0°05'	0°00' 0°09'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
0°13'	0°06'	-0°45' 0°45'
0°09'	0°08'	0°00' 0°19'
-0°01'	-0°01'	
0mm	0mm	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not Authorized
L1 Reg 84000L
Running After Paint
5 days*

CHAN KWOK HOONG PHILIP

c/o 46 Lenton Plain

Singapore 786548

Date: 3/7/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA ALPHARD / SGG5419Z		
1 pc	front door LH <i>1496.10</i>	<i>Ref/less</i> 2,614.20
1 pc	front door chrome moulding LH	<i>Ref</i> 359.60
1 pc	front fender LH <i>716.60</i>	<i>Ref</i> 795.40
1 pc	front fender dust cover LH	<i>Ref</i> 278.60
1 pc	front knuckle LH	<i>Ref</i> 567.10
1 pc	front lower arm LH	<i>Ref</i> 434.10
1 pc	front wheel bearing LH <i>310.60</i>	<i>Ref</i> 365.70
1 pc	front wheel hub LH	<i>Ref</i> 321.60
1 pc	front steering tie rod LH	<i>Ref</i> 246.40
1 pc	front steering tie rod joint LH	<i>Ref</i> 195.60
1 pc	front side mirror assy	<i>Ref</i> 876.40
	front door protector LH	<i>Ref</i> 461.70
	front fender protector LH	<i>Ref/less</i> 195.60
	sub-total	7,712.00
	less 25%	1,928.00
	sub-total	5,784.00
1 set	door visor	<i>Ref</i> 120.00
1 pc	alloy rim	<i>Ref</i> 400.00
1 litre	transmission fluid ATF	<i>Ref</i> 950.00
	front fender arch rubber guard	<i>Ref</i> 45.00
		<i>Ref</i> 90.00
	sub-total	7,269.00

USE Auto Consultants hence notify the Receiver of the following:

- To recover before/after spray painting
- To insure damaged part(s) during recovery
- Participations are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (single modification) is allowed
- Supplementary items must be recovered and
- It is subject to final approval from Insurance Company

Authorised by Receiver
Signature

balance brought forward

7,269.00

To remove and replace the parts mentioned above, panel beat and
realign the necessary affected areas.

500
800.00

To check wiring system.

200 40.00

To remove and install front undercarriage parts to enable repair.

1400 260.00

To machine press wheel bearing.

200 40.00

To perform 4 wheels computerised alignment.

600 85.00

To apply putty and spray painting on affected areas.

600 750.00

To replace alloy rims and perform wheel balancing.

200 40.00

Total

9,284.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011863/KVD3N2

Date: 23/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17671318011	
Claimant Vehicle No :	SGG5419Z	Insured Vehicle No :	GBG8499G	
Date of Loss:	03/07/2019	Nature of Claim:	TP	Claim No: SNM19D203093C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG5419Z	Engine No:	2AZB194484
Make & Model:	TOYOTA ALPHARD, 2.4 (A)	Chassis No:	ANH100145045
Reg. Date:	16/05/2006 (Man, Year: 2006)	Odometer:	136024 km
Colour:	Metallic Dark Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR19	Rear Tyre Size:	245/40ZR19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,269.00	3,651.67	3,617.33	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,015.00	1,360.00	655.00	32.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,284.00	5,011.67	4,272.33	46.02
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	9,284.00	4,000.00	5,284.00	56.92

INSPECTION

Date of Assignment:	05/07/2019	Inspected At:	Autoworx House
Date Inspected:	04/07/2019		176 Sin Ming Drive #02-01
			Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2019)
Parts:	M1-MPV	TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG5419Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent/Warped	2,614.20 FL	*1,496.10 FL
2	1		*FRONT DOOR CHROME MOULDING LH	Necessary	359.60 FL	*359.60 FL
3	1		*FRONT FENDER LH	Bent	795.40 FL	*716.60 FL
4	1		*FRONT FENDER DUST COVER LH	Serviceable	278.60 FL	*- FL
5	1		*FRONT KNUCKLE LH	Bent	567.10 FL	*567.10 FL
6	1		*FRONT LOWER ARM LH	Serviceable	434.10 FL	*- FL
7	1		*FRONT WHEEL BEARING LH	Necessary	365.70 FL	*310.60 FL
8	1		*FRONT WHEEL HUB LH	Bent	321.60 FL	*321.60 FL
9	1		*FRONT STEERING TIE ROD LH	Serviceable	246.40 FL	*- FL
10	1		*FRONT STEERING TIE ROD JOINT LH	Serviceable	195.60 FL	*- FL
11	1		*FRONT SIDE MIRROR ASSY	Serviceable	876.40 FL	*- FL
12	1		*FRONT DOOR PROTECTOR LH	Dented	461.70 FL	*461.70 FL
13	1		*FRONT FENDER PROTECTOR LH	Dented/Cut	195.60 FL	*195.60 FL
14	1		*SET DOOR VISOR	Necessary	400.00 FS	*120.00 FS
15	1		*ALLOY RIM (LOCAL REPAIR)	Dented	950.00 FS	*120.00 FS
16	1		*LITRE TRANSMISSION FLUID ATF	Not Necessary	45.00 FS	*- FS
17	1		*FRONT FENDER ARCH RUBBER GUARD	Necessary	90.00 FS	*90.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	9,197.00	4,758.90
- List Item Discount on L Items 25.00/25.00% (S\$)	1,928.00	1,107.23
Total Parts (S\$)	7,269.00	3,651.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	800.00	500.00
2	TO CHECK WIRING SYSTEM	New	40.00	20.00
3	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	260.00	140.00
4	TO MACHINE PRESS WHEEL BEARING	New	40.00	20.00
5	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
6	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	750.00	600.00
7	TO REPLACE ALLOY RIMS AND PERFORM WHEEL BALANCING	New	40.00	20.00
Gross Labour Cost (S\$)			2,015.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >