

ASS. REC. BY:

REF:

C83/CTI19011867/Gcd3er

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

4/7/2019

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SML7197C

Insured:

PA 3524R

at Workshop m/s King's Auto

Tel:

6457 8629

of BIK 176 S/m #02-10

Policy No: DMBLSN1545281R033

Claim No:

SNM19D203003CC2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SML7197C-X
	PA3524R-NBA/CTI19011265/Y DOA: 26/6/2019.
	Dismantle: 15/7/2019

PRS
CR.

REF

CTI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OT / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SML 7197C
at Workshop n/s: King's Auto.
of BLK 176 S/m Drive #02-10
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR / Soon: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SML 7197C Regn: 31 May 2019
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai Avante c.c. 1591
Colour: silver A/C: Insured / Std / NI / NA
Sp. Reading: 2184 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMHD841 CMKU905302
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Air / or
Tyre Size: F: 195 / 65 R 15
R: "
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or NEXEN
Front: _____ Rear: _____
R/Bal: 9 mm R/Bal: 9 mm
L/Bal: 9 mm L/Bal: 9 mm
D.O.A. _____ D.O.L. 04-08-19
Survey held at: W/S 1 pm
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
o/s Rear.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: \$1000 - \$2000

[Signature]
5/7/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: PRG

Lump Sum / L.B.I: (\$)

Survey Fee:

Transportation:

) 3 + 125 = 128

) Photos

) Others

)

TOTAL

190

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2019		01 Aug 2019 18:36 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	RENT & DRIVE PTE LTD, Co. Reg. No.: 201535359D
Vehicle Reg. No.:	SML7197C
Claim Type:	TP / SNM19D203003C02
Vehicle Reg. No. (Insured):	PA3524R
Date of Loss:	27/06/2019 08:00 - :59
Policy/Cover Note No.:	DMB1SN15452818033
Policy No. (Claimant):	5107900484 (DRIVO CLASSIC)
Excess:	S\$0.00
Repairer:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/08/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Thursday, 4 July 2019 9:04 AM
To: Chong Boon Sen
Cc: assignments
Subject: Re: OUR REF: SNM19D203003/CHONGBS - Our Ref: L.19.0853.AT//Your Ref: PA 3524R//PRS

Hi Boon Sen

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

KING'S AUTO AIR-CONDITIONING SERVICE
Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721
Contact: 6457 8629

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Best regards
Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Thursday, 4 July 2019, 8:48:39 am SGT, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

SAVE AS TO COSTS

Veh In - XGQ

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Wednesday, 3 July, 2019 5:40 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D203003/CHONGBS - Our Ref: L.19.0853.AT//Your Ref: PA 3524R//PRS

Hi Boon Sen

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Best regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 3 July 2019, 4:52:02 pm SGT, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Wednesday, 3 July, 2019 4:49 PM

To: KURULEGAL@YAHOO.COM.SG; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D203003/CHONGBS - Our Ref: L.19.0853.AT//Your Ref: PA 3524R//PRS

Dear Boon Sen,

Please conduct PRS for SML7197C.

Note : DOA – 26.06.2019.

*** Officer-In-Charge – Chong Boon Sen – 63896171 (file with OIC).

 Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: Wednesday, 3 July, 2019 4:20 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Our Ref: L.19.0853.AT//Your Ref: PA 3524R//PRS

Dear Sirs

ACCIDENT INVOLVING SML 7197C & PA 3524R ON 27.06.2019

ALONG NICOLL HIGHWAY TOWARDS CITY

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Rent & Drive Pte Ltd**, whose vehicle registration number **SML 7197C** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5359D
Vehicle Details	
Vehicle No.:	SML7197C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	G4FGKU140573
Chassis No.:	KMHD841CMKU905302
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,689.00
Original Registration Date:	31 May 2019
First Registration Date:	31 May 2019
Transfer Count:	0
Actual ARF Paid:	\$12,689.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2029
PARF Rebate Amount:	\$9,516.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$27,000.00
COE Rebate Amount:	\$26,731.00
Total Rebate Amount:	\$36,247.00

The information contained herein is correct as at 05 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2019 15:36
Date Of Accident	27/06/2019 08:10
Exact Location Of Accident	NICOLE HIGHWAY TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML7197C
Insured/Policyholder	
Name Of Registered Owner	RENT & DRIVE PTE LTD
Co Reg No	201535359D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91139611
Alternative Phone No	OFFICE-91139611

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5107900484 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	NG SIEW CHEUN
NRIC No	S7613263A
Date Of Birth	28/07/1976
Occupation	INDOOR
Date Of Driving Pass	09/02/2018
Driving Experience	1 YEAR AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91139611
Fax Number	
Contact Number	OTHERS-91139611
EEmail Address	NOEMAIL

Address	BLK 120 POTONG PASIR AVE 1 #06-826
Postcode	350120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA3524R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



A : SML 7197C

B : PA 3524R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS ON NICHOLZ HIGHWAY @ 2nd LANE FROM THE RIGHT. MAKING A RIGHT TURN AT THE JUNCTION. IN THE MIDDLE OF TURNING, A VEHICLE HIT ME FROM THE REAR.

AFTER THE ACCIDENT, I STOPPED AT THE ROAD SIDE AND REALISED THAT THE VEHICLE HAD MADE A WIDE TURN WHICH CAUSED THE ACCIDENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



27 JUN 2019



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

27 JUN 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SML 7197C

Name (as shown in NRIC) : _____ NRIC/FIN/Passport No : _____

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore ()

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 27/6/19 Time of Accident : 08.10



Place of Accident : Nicole Highway twds city

Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Claiming third party

Policyholder / Driver's Signature
Date:

03 JUL 2019



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date: 03 JUL 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:36 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	RENT & DRIVE PTE LTD , Co. Reg. No.: 201535359D								
Vehicle Reg. No.:	SML7197C	Date of Loss:	27/06/2019 08:00 - :59 [27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203003C02	Policy/Cover Note No.:	DMB1SN15452818033						
Vehicle Reg. No. (Insured):	PA3524R	Policy No. (Claimant):	5107900484 (DRIVO CLASSIC)						
		Excess:	S\$0.00						
Repairer:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML7197C (SNM19D203003C02)

[PA3524R]

TP

RENT & DRIVE PTE LTD

Jun 27 2019 8:00AM

[-]





King's Auto Air-Conditioning Service

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	27/06/19 17:43	Accident Statement							Load HTM		
2	03/07/19 16:16	Addendum Sheet							Load TIF		
3	03/07/19 16:17	Accident Statement Addm. #1							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	27/06/19 15:42	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	27/06/19 15:42	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	27/06/19 15:42	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	27/06/19 15:42	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	27/06/19 15:42	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
2	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
3	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
4	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
5	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
6	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
7	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
8	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
9	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
10	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
11	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
12	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
13	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
14	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
15	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
16	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
17	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
18	02/08/19 10:33	General View							Load JPG	<input checked="" type="checkbox"/>	
19	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
20	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
21	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
22	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
23	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
24	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
25	02/08/19 10:33	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
26	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 10:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	02/08/19 10:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	27/06/19 17:31	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	27/06/19 17:31	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	27/06/19 17:31	Sketch Plan #3 [Linked Accident Report Documents]	Load TIF	
4	27/06/19 17:31	Sketch Plan #4 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	27/06/19 17:43	Accident Statement	Load HTM	
2	03/07/19 16:16	Addendum Sheet	Load TIF	
3	03/07/19 16:17	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	27/06/19 15:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	27/06/19 15:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	27/06/19 15:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	27/06/19 15:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	27/06/19 15:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	27/06/19 17:31	Sketch Plan	 Load TIF	
2	27/06/19 17:31	Sketch Plan #2	 Load TIF	
3	27/06/19 17:31	Sketch Plan #3	 Load TIF	
4	27/06/19 17:31	Sketch Plan #4	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT19011867/GCD3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN15452818033

Claimant Vehicle
No : SML7197CInsured Vehicle
No : PA3524R

Date of Loss: 27/06/2019

Nature of Claim: TP

Claim
No: SNM19D203003C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML7197C

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A)

Engine No: G4FGKU140573

Reg. Date: 31/05/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU905302

Colour: Silver

Odometer: 2184 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 9 mm	Rear Left Side:	Nexen 9 mm
Front Right Side:	Nexen 9 mm	Rear Right Side:	Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 04/07/2019 Inspected At:

King's Auto Air-Conditioning Service (HQ)
Block 176 Sin Ming Drive, #02-10
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 -\$2,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML7197C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >