

12/03/2002

ASS. REC. BY:

REF: CS/ATG 190119001 KS d302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

min

From (Person): TAN BENNIE W=

of ATG

Date/Time: 5.7.19 10.03A.M

Estimated Cost: Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 1915C

Insured: SLIP 7740A

at Workshop m/s CHUAN HO

Tel: 90691985

of 160 Sin Ming Drive # 07-09

Policy No: 1700017528

Claim No: 41477158 2359

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

rup'

H.O.D. Endorsement:

Date/Time: 5.7.19 10.30A.M

Person Contacted: sherin

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 1915C - X
	SLIP 7740 A - X
16/7	LLDy @ 2100 email & confirmed (\$ 8,956.00 Red - 81%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 14:37		05 Jul 2019 10:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Teo Geok Kuan, ID: S1300654G, Tel: +6592271108								
Main Claimant:	TAN CHENG HAI, ID: S1433183B								
Vehicle Reg. No.:	SKD1915C	Date of Loss:	27/06/2019 08:00 - :59 [91 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4147715822SG	Policy/Cover Note No.:	1700017528 (Comprehensive) Coverage: 17/06/2019 - 16/06/2020						
Vehicle Reg. No. (Insured):	SLP7740A	Policy No. (Claimant):	2100278762-07						
		Excess:							
Repairer:	Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/07/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All									
Search Tasks									
Create New Task									
Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/06/2019 14:33
Date Of Accident	27/06/2019 08:00
Exact Location Of Accident	ALONG UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD1915C
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG HAI
NRIC No	S1433183B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96693833
Alternative Phone No	OFFICE-96693833

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180 CGI COUPE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100278762-07
Cover Note Number	

Driver

Name of Driver	ENG HWEE LEE
NRIC No	S1438380H
Date Of Birth	09/03/1960
Occupation	INDOOR
Date Of Driving Pass	24/08/1984
Driving Experience	34 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96673323
Fax Number	
Contact Number	
EEmail Address	EHWEELEE@GMAIL.COM

Address	10 FUDU WALK
Postcode	2678
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ENG HWEE LEE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7740A
Vehicle Make/Model/Colour	SUBARU
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	S1300654G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:
 28 JUN 2019

CP-33 hrs


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 28 JUN 2019

CP-33 hrs


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

CHUAN HO

28 JUN 2019

Submitted:

SINGAPORE ACCIDENT STATEMENT

ALG - SKD1915C

BASIC INFORMATION			
Date of Accident:	27/06/2019	Time of Accident:	0800 HRS
Exact Location:	Upper bukit Timah Road		

Driver Email: ehweelee@gmail.com

DETAILS OF OWN VEHICLE			
Vehicle Registration No.	SKD 1915C		
Name of Registered Owner:	Tan Cheng Hai	owner HP: 9669 3833	
NRIC / FIN / Passport no:	S1433 183 B		
Vehicle Make:	Mercedes Benz	Vehicle Model:	C180
Type of Claim:	Own Damage / <u>Third Party</u> / Reporting Only		
Vehicle Category:	<u>Private</u> Commercial / Motorcycle / Private Hire		
Name of Insurance Co:	ALG Insurance.		
Type of Policy:	<u>Comprehensive</u> / Third Party / Third Party, Fire & Theft		
Policy Number:	210027 8762 - 07		

DRIVER			
Name of Driver:	Eng Hwee Lee	<input type="checkbox"/> same as owner	
NRIC / FIN / Passport no:	S1438380H	Date of Birth:	09-03-1960
Occupation:	<u>Indoor</u> / Outdoor	Driving Pass Date:	24 Aug 1984
Contact Number:	9667 69 3323	Gender:	Male / <u>Female</u>
Address:	10 Fudu Walk S (2678)		
Relationship with Owner:	Owner / Employee / <u>Spouse</u> / Child / Hirer / Other: <i>Wife - No.</i>		

GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision:	Chain collision / <u>Side Swipe</u> / Front to Rear / Others:		
Weather Condition:	<u>Clear</u> / Raining / Others:		
Road Surface:	<u>Dry</u> / Wet / Others:		
Was anybody injured?	Yes / <u>No</u>	Police Report Made?	Yes / <u>No</u>
No. of passenger onboard (including driver):	1 female: Eng Hwee Lee		

DETAILS OF OTHER VEHICLE			
	Vehicle 1	Vehicle 2	Vehicle 3
Vehicle Registration No:	SLP 7740 A		
Vehicle Make / Model:	Subaru		
Name of Driver:			
NRIC / FIN / Passport no:	S1300654 G		
Contact Number:			
Name of Insurance Co:			

DETAILS OF WITNESS	
Name:	Contact Info:

DETAILS OF INJURED PERSON			
	Person 1	Person 2	Person 3
Name / in which vehicle?:			

Driver's Declaration: I declare that the information given in this report are true and accurate to the best of my collection and I bear full responsibility for any consequences arising from incomplete or inaccurate information that are submitted.


Signature of Driver

Date and time

SKETCH PLAN

→ Along Upper Bukit Timah Road

- Ⓐ SKD 1915C
- Ⓑ SLP 7740 A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/06/2019 at around 0800 HRS, I was driving my vehicle (SKD 1915C) along upper Bukit Timah Road when suddenly vehicle B ^(SLP 7740 A) came into my lane and hit onto the left side portion of my car.

No one was injured.

I was in full control of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 28 JUN 2019


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 28 JUN 2019


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

CHUAN HO AUTO SERVICE
 SIN MING AUTO CITY
 160 SIN MING DRIVE #07-09
 SINGAPORE 575722

Vehicle & Document Information

ESTIMATE : SKD 1915 C

Date: 04/07/2019
 Vehicle No: SKD 1915 C
 Make/Model: MERCEDES BENZ C180

S/N	Description	Qty	Repairer's Est	Revised Est
1	LHF FENDER	1	\$ 1,200.00	\$ 2,100.00
2	LH DOOR	1	\$ 2,075.00	\$ 2,075.00
3	LHR FENDER	1	\$ 1,200.00	\$ 1,200.00
4	LHF FENDER CHROME <i>45</i>	1	\$ 80.00	\$ 80.00
5	LH DOOR CHROME <i>115</i>	1	\$ 190.00	\$ 190.00
6	LHR FENDER CHROME <i>60.</i>	1	\$ 80.00	\$ 80.00
7	LH DOOR HANDLE	1	\$ 95.00	\$ 95.00
8	LHR RIM <i>900</i>	1	\$ 1,055.00	\$ 1,055.00
9	LHR RIM	1	\$ 1,055.00	\$ 1,055.00
10	REAR BUMPER	1	\$ 1,300.00	\$ 1,300.00
11	REAR BUMPER CHROME <i>145</i>	1	\$ 220.00	\$ 220.00
12	LH SIDE SKIRT	1	\$ 895.00	\$ 895.00

Total :	\$ 10,345.00
<i>10-20%</i>	\$ 2,069.00
Parts Total :	\$ 8,276.00

1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	\$ 200.00	X
1	TO CHECK LIGHTING, WIRING & FUSES	\$ 280.00	201
1	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS	\$ 800.00	400
1	TO PUTTY, PRIMER, RE-SPRAY LHF FENDER, LH DOOR, LHR FENDER AND REAR BUMPER	\$ 1,500.00	1100

Labour Total :	\$ 2,780.00
Parts Total :	\$ 8,276.00
Total :	\$ 11,056.00
-20%	\$ 2,211.20
Grand Total :	\$ 8,844.80
Lump Sum :	\$ 8,800.00



Not Authorize
Pruning After Paint
12090-5U
6/20p 8 2100p
4 days

WARRANTY
 the Parts
 • To ensure
 • All work done
 • on a
 • basis
 • and
 • many

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 14:37		05 Jul 2019 10:03 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Teo Geok Kuan , ID: S1300654G, Tel: +6592271108								
Main Claimant:	TAN CHENG HAI , ID: S1433183B								
Vehicle Reg. No.:	SKD1915C	Date of Loss:	27/06/2019 08:00 - :59 [91 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4147715822SG	Policy/Cover Note No.:	1700017528 (Comprehensive) Coverage: 17/06/2019 - 16/06/2020						
Vehicle Reg. No. (Insured):	SLP7740A	Policy No. (Claimant):	2100278762-07						
		Excess:							
Repairer:	Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD1915C (4147715822SG)**
[SLP7740A]
TP
TAN CHENG HAI
Jun 27 2019 8:00AM
[Teo Geok Kuan]
Chuan Ho Auto Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print					
1	04/07/19 10:11	OI Video - Accident											Load MP4					
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)										Thumbnail	Print					
1	28/06/19 18:02	Accident Statement											Load HTM					
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)										Thumbnail	Print					
1	28/06/19 18:02	Accident Photo <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
2	28/06/19 18:02	Accident Photo <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
3	28/06/19 18:02	Accident Photo <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
4	28/06/19 18:02	Accident Photo <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
5	28/06/19 18:02	Accident Photo <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
6	28/06/19 18:02	CHASSIS NUMBER <small>[Linked Accident Report Documents]</small>											Load JPG	<input checked="" type="checkbox"/>				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
2	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
3	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
4	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
5	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
6	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
7	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
8	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
9	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
10	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
11	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
12	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
13	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
14	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
15	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
16	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
17	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
18	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
19	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
20	17/07/19 10:25	General View											Load JPG	<input checked="" type="checkbox"/>				
21	17/07/19 10:28	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
22	17/07/19 10:28	Reinspection Photo											Load JPG					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
23	17/07/19 10:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/07/19 14:38	Accident Scene	Load PDF	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/06/19 17:05	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	28/06/19 17:06	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
3	28/06/19 17:06	OWNER'S NRIC [Linked Accident Report Documents]	Load TIF	
4	28/06/19 17:06	DRIVER'S NRIC + DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/06/19 18:02	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/06/19 18:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	28/06/19 18:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	28/06/19 18:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	28/06/19 18:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/06/19 18:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/06/19 18:02	CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/06/19 17:05	Sketch Plan	Load TIF	
2	28/06/19 17:06	CERTIFICATE OF INSURANCE	Load TIF	
3	28/06/19 17:06	OWNER'S NRIC	Load TIF	
4	28/06/19 17:06	DRIVER'S NRIC + DRIVING LICENCE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG19011900/KSD3E2**Date:** 19/07/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700017528
Claimant Vehicle No : SKD1915C **Insured Vehicle No :** SLP7740A
 Date of Loss: 27/06/2019 Nature of Claim: TP Claim No: 4147715822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD1915C**
 Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27182030282601
 Reg. Date: 04/11/2011 (Man. Year: 2011) Chassis No: WDD2043492F713447
 Colour: Metallic Grey Odometer: 165721 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,310.50	1,138.50	8,172.00	87.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,520.00	1,260.00	45.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,090.50	2,658.50	9,432.00	78.01
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	12,090.50	2,100.00	9,990.50	82.63

INSPECTION

Date of Assignment: 05/07/2019
 Date Inspected: 09/07/2019 Inspected At: Chuan Ho Auto Service (Sin Ming)
 160 Sin Ming Drive, #07-09, Sin Ming
 AutoCity
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHF FENDER	Repair	2,100.00 FL	*- FL
2	1		*LH DOOR	Repair	2,075.00 FL	*- FL
3	1		*LHR FENDER	Repair	1,200.00 FL	*- FL
4	1		*LHF FENDER CHROME	Necessary	80.00 FL	*45.00 FL
5	1		*LH DOOR CHROME	Necessary	190.00 FL	*115.00 FL
6	1		*LHR FENDER CHROME	Necessary	80.00 FL	*60.00 FL
7	1		*LH DOOR HANDLE	Repair	95.00 FL	*- FL
8	1		*LHR RIM	Dented	1,055.00 FL	*900.00 FL
9	1		*LHR RIM	Serviceable	1,055.00 FL	*- FL
10	1		*REAR BUMPER	Repair	1,300.00 FL	*- FL
11	1		*REAR BUMPER CHROME	Necessary	220.00 FL	*145.00 FL
12	1		*LH SIDE SKIRT	Repair	895.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	10,345.00	1,265.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,034.50	126.50
Total Parts (S\$)	9,310.50	1,138.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	New	200.00	0.00
2	TO CHECK LIGHTING, WIRING & FUSES	New	280.00	20.00
3	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS	New	800.00	400.00
4	TO PUTTY, PRIMER, RE-SPRAY LHF FENDER, LH DOOR, LHR FENDER AND REAR BUMPER	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			2,780.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >