

ASS. REC. BY:

REF: (S3/AIG 10/11903/NL d30)

Special Instruction:

Surveyor: MAZ ASSIGNMENT (Office)

From (Person): Chin Lu Ying of AIG Date/Time: 5-7-2019 10:52 a.m

Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCQ 83K Insured: SJD 130T

at Workshop m/s Eng Soon Painting Tel: 67606271

of Block 4 Yew Tee Industrial Estate 393-J

Policy No: _____ Claim No: 909077926486

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27.6.2019

(Client's Record)

8.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 5.7.19 12:00 pm Person Contacted: _____ Vehicle IN / OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|-----------------------------------|
| | SCQ 83K - X |
| | SJT 130T - X |
| | Dismantle: 9/7/2019. |
| | |
| | |
| | |

Minimum

"up"

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|---------|---------------|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 28 Jun 2019 Edit Reg | | 05 Jul 2019 00:00 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | [Created by adjuster] | | | | | | | |
|---|---|--|------------|---------|---------|-------------|--------------|------------|-------|
| Insured: | LEO KWONG JONG, ID: S6834219H | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SCQ83K | Date of Loss: 27/06/2019 00:00 - :59 | | | | | | | |
| Claim Type: | TP / 9090779264SG | Policy/Cover Note No.: (Comprehensive) | | | | | | | |
| Vehicle Reg. No. (Insured): | SJD130T | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 16/07/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (08/07/2019): Request To Upload TP GIA Report AIG_SG (08/07/2019): No OI GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 7/5/2019 10:52:16 AM

Hi LKK,

Kindly assist to survey.

Kindly contact the repairers, M/s Eng Soon Painting Services at 6760 6271 for pre-repair inspection arrangements.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Wednesday, July 03, 2019 3:19 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] Urgent: Pre-Repair Inspection: Your Vehicle: SJD 130 T; EngSoon's Vehicle: SCQ 83 K; Accident Involving SCQ 83 K & SJD 130 T on 27 June 2019

This message is from an external sender; be cautious with links and attachments.

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SCQ 83 K at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 556E |
| Vehicle Details | |
| Vehicle No.: | SCQ83K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 29 Jul 2019 |
| Vehicle Make: | CITROEN |
| Vehicle Model: | GRAND C4 PICASSO 1.6 BLUEHDI EAT6 S/R |
| Primary Colour: | Red |
| Manufacturing Year: | 2017 |
| Engine No.: | 10JBHD3085968 |
| Chassis No.: | VF73ABHZTHJ752278 |
| Maximum Power Output: | 88.0 kW (118 bhp) |
| Open Market Value: | \$27,069.00 |
| Original Registration Date: | 27 Sep 2017 |
| First Registration Date: | 27 Sep 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$14,897.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 26 Sep 2027 |
| PARF Rebate Amount: | \$11,172.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 26 Sep 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$42,801.00 |
| COE Rebate Amount: | \$34,929.00 |
| Total Rebate Amount: | \$46,101.00 |

The information contained herein is correct as at 29 Jul 2019

OK

Base report correctly the details of the accident to speed up the claims process.
 This Form must be completed by the Policyholder and/or the Authorised Driver.
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to
 disavow policy liability.
 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for
 archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
 as said.

ACCIDENT STATEMENT

Date Of Report 27/06/2019 13:13
 Date Of Accident 27/06/2019 07:30
 Exact Location Of Accident ALONG KJE TOWARDS TUAS
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCQ83K
 Insured/Policyholder
 Name Of Registered Owner TAN POO YONG
 IC No S1476556E
 Email Address PYTAN_61@YAHOO.COM.SG
 Mobile Phone No (LOCAL) +65-96794367
 Alternative Phone No OTHERS-96794367

Vehicle Particulars

Manufacturer CITROEN
 Model GRAND C4 PICASSO 1.6 BLUEHDI EAT6 S/R
 Intended Purpose for which vehicle was being used at
 time of accident
 Are you claiming under your own insurance policy
 to repair to your vehicle? NO
 Action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Policy NO
 Policy Number 17000054961-01
 Claim Note Number

Driver

Name of Driver TAN POO YONG
 IC No S1476556E
 Date Of Birth 20/03/1961
 Occupation INDOOR
 Date Of Driving Pass 22/06/1984
 Driving Experience 35 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96794367
 Alternative Number OTHERS-96794367
 Email Address PYTAN_61@YAHOO.COM.SG

Vehicle Registration Number of Driver's Own Vehicle
Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : CHOW HOU WAN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD130T
Vehicle Make/Model/Colour TOYOTA ESTIMA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LEO KWONG JONG
NRIC/Passport Number S6834219H
Contact Number 96178013
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

ETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along KJE lane 1 on 27/6/19 at about 730hrs at the speed of 85 km per hr. Traffic was heavy at that time, the car in front of me jam brake and I also do so and stop in time. But SJD 130T was travelling behind me knock my rear bumper and come to a stop.

| | | |
|--|---|----------------------------------|
| <p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p> | | - Reporting Only |
| | | - Claim OD |
| | | - Claim TP |
| | ✓ | - Claim OD/ TP at other workshop |

DECLARATION
I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time
27/6/19

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (A) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (i) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Condition (CON)

- (01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
- (07) Deformed (08) Shifted (09) Duckled (10) Broken (11) Necessary
- (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

- (1) Replace (2) ...
- (4) Not Consistent (NC)

Vehicle No: **SCQ 83K**

Rear Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-------------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper <i>CRK</i> | | | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower <i>CRK</i> | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips <i>NEC - 6</i> | | | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement <i>BT</i> | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor <i>Short DM</i> | | | |
| 1159 | 993327 | Rear End Panel <i>K DD R</i> | | | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp <i>SCR</i> | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp <i>SCR</i> | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | | | |
| 1171 | 991328 | Bootlid Emblem | | | |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1255 | 990247 | Sticker | | | |
| | | Lock Sensor <i>CRK</i> | | | |
| | | Reinforcement Retainer <i>CRK</i> | | | |

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 28 Jun 2019 Edit Reg | | 05 Jul 2019 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | LEO KWONG JONG , ID: S6834219H | | | | | | | | |
| Main Claimant: | TAN POO YONG , ID: S1476556E | | | | | | | | |
| Vehicle Reg. No.: | SCQ83K | Date of Loss: | 27/06/2019 00:00 - :59 [21 Months From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 9090779264SG | Policy/Cover Note No.: | (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SJD130T | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 16/07/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (08/07/2019): Request To Upload TP GIA Report AIG_SG (08/07/2019): No OI GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SCQ83K (9090779264SG)
[SJD130T]
TP
TAN POO YONG
Jun 27 2019 12:00AM
[LEO KWONG JONG]
Eng Soon Painting Services

| Upload Documents | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View | View in Browser | |
|----------------------|-----------------|-----------------------------------|--|--------------------|--|--------------|--|--------------|--|-------------------------------------|-----------------|-------------------------------------|
| Photos/Images | | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | | |
| 1 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 17 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 18 | 22/07/19 17:19 | General View | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 19 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 20 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 21 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 22 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 23 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 24 | 22/07/19 17:19 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 25 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 26 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 27 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 28 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 29 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 30 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 31 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 32 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 33 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 34 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 35 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 36 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |
| 37 | 22/07/19 17:20 | Photographs of Damaged Parts | | | | | | |  Load JPG | <input checked="" type="checkbox"/> | | |

| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 38 | 22/07/19 17:20 | Photographs of Damaged Parts | | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 22/07/19 17:20 | Photographs of Damaged Parts | | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 22/07/19 17:20 | Photographs of Damaged Parts | | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 22/07/19 17:20 | Photographs of Damaged Parts | | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 22/07/19 17:20 | Photographs of Damaged Parts | | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail | Print |
| 1 | 08/07/19 09:50 | OI GIA REPORT | | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19011903/NCD3E2**Date:** 31/07/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SCQ83K**Insured Vehicle No :** SJD130T

Date of Loss: 27/06/2019

Nature of Claim: TP

Claim No: 9090779264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCQ83K

Make & Model:

CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI
EAT6 (A)

Engine No:

10JBHD3085968

Reg. Date:

27/09/2017 (Man. Year: 2017)

Chassis No:

VF73ABHZTHJ752278

Colour:

Red

Odometer:

36777 km

Engine Capacity:

1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment:

05/07/2019

Date Inspected:

08/07/2019

Inspected At:

Eng Soon Painting Services (HQ)
BLK 4 YEW TEE IND EST 393 - J
WOODLANDS ROAD
SINGAPORE 677969

Estimated Period of Repair:

4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|-------------------|------------|--------|
| 1 | 1 | | *REAR BUMPER | Cracked | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER LOWER | Cracked | 0.00 F | *- F |
| 3 | 6 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 0.00 F | *- F |
| 5 | 2 | | *REVERSE SENSOR | Shorted / Damaged | 0.00 F | *- F |
| 6 | 1 | | *REAR END PANEL | Repair | 0.00 F | *- F |
| 7 | 1 | | *REAR LH TAILLAMP | Scratched | 0.00 F | *- F |
| 8 | 1 | | *REAR RH TAILLAMP | Scratched | 0.00 F | *- F |
| 9 | 1 | | *LOCK SENSOR | Cracked | 0.00 F | *- F |
| 10 | 1 | | *REINFORCEMENT RETAINER | Cracked | 0.00 F | *- F |

F=Franchise part.

Total Parts (S\$) 0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >