

ASS. REC. BY:

REF: AAA1916/KC/P

ASSIGNMENT

Kenneth

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$55k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SOU8228AYr Regn: 05, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS Almerisc.c. 1498Colour: M. Red

A/C: Insured / Std / NI / NA

Sp. Reading: 102294

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: HNTPBBAN1780005391Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 155/70R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Handbook

Front

Rear

R/Bal. 2

mm

R/Bal. 7

mm

L/Bal. 2

mm

L/Bal. 7

mm

D.O.A. 4/7/19D.O.I. 15/7/19Survey held at ✓Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$

) S + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7260A
Vehicle Details	
Vehicle No.:	SDU8228A
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	ALMERA 1.5 5MT AIRBAG 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HR15929322D
Chassis No.:	MNTBBAN17Z0005591
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,828.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$12,828.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$9,621.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$33,045.00
Total Rebate Amount:	\$42,666.00

The information contained herein is correct as at 04 Jul 2019

OK