

CWS

2019 000
REQ. REC. BY: Marcus REF: CS/FCI19011929/uwd302 Special Instruction:

ASSIGNMENT (Office)

From (Person): Perene of FBI Date/Time: 5/7/2019

Estimated Cost: _____ FBI to: _____

OI: PM / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: EH1038J Insured: SHA2319T

at Workshop in/s: Fastech Auto Tel: 67465405

of: 1 Kaki Bukit Ave 6 #01-46

Policy No: _____ Claim No: D19004383MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/7/2019
(CB ul's Record)

CA / REV / REP. / REV 24 HRS _____ B.O.D. Endorsement: _____

Date/Time: 5/7 Person Contacted: _____ Vehicle: TOUT

Date/Time	Action/Instruction
	✓
	EH1038J Ref NA/MISG19011845/h4 DOA = 3/7/19
	SHA2319T X
8/7/19	Informed FCI pending repaver est by email
31/7/19	Send preli revised by email

08/11/13 wef


ASS. REC. BY: Marcus

REF:

TRIP

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: EH 1038J
 at Workshop m/s: RL
 of _____
 Insured: S/A 23197
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 60k
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LTA 49094
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: EH 1038J Yr Regn: 6118
 Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota Corolla Altis 15-98
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 60671 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR 003REH 104534238
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 3/7/19 D.O.I. 5/7/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
30/7/19 confirm n/s \$3500 with AG. (Red 7438, 6870)

RECEIVED 31 JUL 2019

Date/Time, File Pass to?

: Prel. Report
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

1) Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

170
50
50 to 50
49
369



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004383MFSH

Our ref: CS/FCI19011929/Uvd3

DATE: 31/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO EH 1038J


We thank for your instruction on 5/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 5/7/2019 at the premises of M/s FASTECH AUTO PTE LTD

Workshop Estimate Amount	: S\$10,938.00
Revised Estimate Amount	: S\$3,500.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-07-2019	Our Ref No. D19004383MFSH
Accident Date	03-07-2019	Claim Type. Third Party
Insured Vehicle	SHA2319T	Third Party Vehicle. EH 1038J
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veli In

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 31 July 2019 8:52 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19004383MFSH/1, EH 1038J
Attachments: EH 1038J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle EH 1038J
Date of survey: 5/7/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 8 July 2019 10:50 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004383MFSH/1, EH 1038J

Dear Sir/Madam,

Please be informed that we have inspected the vehicle EH 1038J on 4/7/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 5 July, 2019 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004383MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 8 July 2019 10:50 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19004383MFSH/1, EH 1038J

Dear Sir/Madam,

Please be informed that we have inspected the vehicle EH 1038J on 4/7/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 5 July, 2019 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004383MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

BIDDED CARPLATE NUMBERS FOR SALE
Find and buy your favourite car plate number here!

START SEARCH NOW!

k3 Price Range Depreciation 2016 Vehicle Type Submit Advanced Search

Home > Used Cars > Motor-Way Credit Pte Ltd > Kia Forte K3 1.6A EX

Kia Forte K3 1.6A EX

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$63,800	Reg Date	04-Aug-2016 (7yrs 29days COE left)
Depreciation	\$8,000 /yr View models with similar depre	Manufactured	2016
Mileage	70,070 km (24k /yr)	Transmission	Auto
Road Tax	\$738 /yr	OMV	\$14,303
Dereg Value	\$47,782 as of today (change)	ARF	\$14,303
COE	\$52,301	Power	95.3 kW (127 bhp)
Engine Cap	1,591 cc	No. of Owners	2
Curb Weight	1,295 kg		
Type of Vehicle	Mid-Sized Sedan		



Features

Responsive And Efficient 1.6L 4 Cylinders Inline 16 Valves DOHC Dual CVT Engine Producing 127Bhp, 157Nm Torque, 6-Speed Auto Transmission. FWD. View specs of the Kia Cerato K3 (2013-2018)

Accessories

16" Sports Rims, Multi-Function Steering Wheel, Factory Fitted Infotainment Audio System, Leather Seats, Fog Lights, Multi Zone/Rear Aircon.

Description

Low Fuel Consumption And Reasonable Price Korean Kia K3 In Town! Styling Black Body With A Like New Black Interior Design. Don't Miss This Good Deal! Come With 2 Years Third Party Warranty. Low Depreciation! Trade-in Welcome! Easy And Flexible Finance Options Available! Contact Our Friendly Sales Person For More Information.

Category

PREF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started


Posted on: 16-Jun-2019 | Last Updated on: 02-Jul-2019

Upfront Payment

> more Financial info

Transfer Fee	\$25
Down Payment	\$19,140 (change) <small>Maximum 70% Loan</small>

Price Chart Summary



Click on the point to view the vehicle

Shortlist Compare Add note
Report Error More Actions

Seller Information

Company	Motor-Way Credit Pte Ltd » dealer's pricelist » 27 vehs sold 99 vehs available	
Address	1094 Lower Delta Road Search cars nearby this location	
Location	Motorway Building	
Office No	64682200	
Contact Person(s)	Desmond Koh	92398586
	Rick Hong	84674440
	J Tang	83741233
	Joyce Wong	81987778

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3837H
Vehicle Details	
Vehicle No.:	EH1038J
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRX515485
Chassis No.:	MR053REH104534238
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	10 Jun 2015
First Registration Date:	10 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$12,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2025
PARF Rebate Amount:	\$9,603.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,590.00
COE Rebate Amount:	\$39,491.00
Total Rebate Amount:	\$49,094.00

The information contained herein is correct as at 04 Jul 2019

OK

Date of Accident : 3/7/19 Accident Time: 2:30pm (24-HR-Format)

Accident Place : at chong valley carpark

Vehicle No. (Car Plate No.) : EH 10385 Make/Model: Toyota corolla

Insurance Company : MSIG Policy No: A 80461037

Owner or Company Name /IC No. : Hong Hock Global Pte Ltd / 20133837H

Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____

DRIVER'S Name / IC No. : Ang Lye Hock / 57525905J

DRIVER'S Date Of Birth : 8/9/1975 DRIVER'S License Pass Date 4/01/1997

Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____

DRIVER'S Address : Blk 274 Yishun St 22 # 08-158

DRIVER'S Contact No./ Alt No. : 1) 9009 7833 2) 5760274

DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address : _____

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1 Driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: <u>SHA 2319T</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time I was driving my car into changi village carpark I drove my car straight into the carpark lot. suddenly a taxi reversed and hit on my LH side passenger door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
 BLK1 KAKI BUKIT AVE 6
 #01-46,48,50 AUTOBAY
 SINGAPORE 417883

Not Authorized
 with means
 take photo after repair
 1/5 = 3500 / Hoby

VEHICLE NO : SH1038J

QTY	PARTICULAR			
1 PCS	REAR DOOR N/S	1371.10	Body 20	\$1,688.10 ✓
1 SET	REAR DOOR FRAME BLACK STICKER N/S	85.00	11	\$180.00 ✓
1 PCS	REAR DOOR INNER LOCK N/S	376.50	Shuttl 1/2m	\$366.50 ✓
1 PCS	REAR DOOR GLASS OUTER MOULDING N/S		11	\$166.50 X
1 PCS	REAR DOOR GLASS REGULATOR & MOTOR N/S	498.75	Body 1/2m	\$650.00 ✓
1 PCS	REAR DOOR INNER TRIM BOARD N/S	510.50	Del 1/14	\$1,041.10 ✓
1 PCS	REAR DOOR RUBBER N/S	178.10	11	\$211.30 ✓
1 PCS	REAR FENDER N/S		11	\$1,422.30 X
1 PCS	ROCKER PANEL N/S		11	\$899.10 X
1 PCS	REAR BUMPER		11	\$533.10 X
1 PCS	REAR SPORT RIM N/S	650 S.N	11/set	\$1,050.00 ✓
				\$8,208.00 650 S.N
	LABOUR CHARGES			
	TO CHECK WIRING			\$50.00 20
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY			\$120.00 80
	TO CONDUCT WHEEL ALIGNMENT			\$80.00 60
	TO SPRAY RUST PROOFING			\$50.00 30
	TO DISMANTLE & REFIX REAR REVERSE SENSOR			11 \$50.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$880.00 180
	TO PUTTY & SPRAY PAINTING			\$1,500.00 800
	TOTAL			\$10,938.00 800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3009.95
 252

 2257.46
 4377.46



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011929/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2319T	Veh. Inspected	EH 1038J
Policy No.		Coverage (\$)	0.00
Claim No.	D19004383MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	05/07/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104534238	Colour	GREY
Odometer	60671	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	6 mm
L/H Front Tyre	205/55 R16	DUNLOP	6 mm
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/07/2019	Inspection Date	05/07/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EH 1038J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR N/S	BADLY DENTED	1,688.10	1,371.10
1	SET REAR DOOR FRAME BLACK STICKER N/S	NECESSARY	180.00	85.00
1	REAR DOOR INNER LOCK N/S	SHORTED / JAMMED	366.50	366.50
1	REAR DOOR GLASS OUTER MOULDING N/S	NOT NECESSARY	166.50	-
1	REAR DOOR GLASS REGULATOR & MOTOR N/S	BANT / JAMMED	650.00	498.75
1	REAR DOOR INNER TRIM BOARD N/S	DEFORMED / CRACKED	1,041.10	510.50
1	REAR DOOR RUBBER N/S	NECESSARY	211.30	178.10
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,422.30	-
1	ROCKER PANEL N/S	TO REPAIR SEE LABOUR	899.10	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	533.10	-
	LESS 25% DISCOUNT		-	-752.49
			7,158.00	2,257.46
SPECIAL NETT ITEMS				
1	REAR SPORT RIM N/S (SN)	DENTED / BENT	1,050.00	650.00
			1,050.00	650.00
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S,ROCKER PANEL N/S AND REAR BUMPER.		880.00	480.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			2,730.00	1,470.00
GRAND TOTAL			10,938.00	4,377.46



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CS/FC119011929/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.