

22/03/2019

ASS. REC. BY:

Surveyor: MARCUS

REF: CS3/AIG/19011930/1608302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 5/7/2019

Estimated Cost:

Bill to:

OD/TP/WWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM4345E

Insured: STR 8753U

at Workshop m/s A S Auto

Tel: 9738 8183 Ah Soon

of 1 Kaki Bukit Ave 6 #0106

Policy No: 2100489912

Claim No: 331590591786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5/7

Person Contacted: Ah Soon

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SKM4345E - X</u>
	<u>STR 8753U - X</u>
	<u>Dismantle: 5/7/2019</u>
	<u>After repair: 9/7/2019</u>

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKM 4345C
at Workshop m/s: AS Ave
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SKM 4345C Yr Regn: 2 14
Type: Car / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: BMW 320i c.c. 1997
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 100274 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: W1BA3B16020NS50344
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50 R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. mm L/Bal. mm
D.O.A. 2/7/19 D.O.I. 5/7/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
PRS No settled. AS.A car rental

Date/Time, File Pass to? : Preli. Report
 : Final Report
Date/Time, File Return to?

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
Photos _____
Others _____

Report Format : DAR
Lump Sum / I.B.I: (\$ _____)

180
11
TOTAL 191

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR8753U AND SKM4345E ON 02/07/...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 7/5/2019 10:31:46 AM
Attachments:  20190704154913.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Wednesday, July 03, 2019 2:25 PM

To: Hor, Yinrul

Cc: 'Lily.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Baljit.Kaur@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShengYang.Lim@aig.com'; 'Darshene.Supramaniam@aig.com'; 'Syazairdina.Azlan@aig.com'; 'yokeshi.chan@aig.com'; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] PRE REPAIR SURVEY --- YOUR REF: SJR 8753 U --- ACCIDENT INVOLVING SKM 4345 E AND SJR 8753 U ON 2 JULY 2019 ALONG CTE TO KEPPEL ROAD AT ABOUT 1545 HOURS

Importance: High

This message is from an external sender; be cautious with links and attachments.

Our Ref: SKM 4345 E (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by [ASIA CAR RENTAL](#) to notify you of a road traffic accident on 2 July 2019 at about 1545 hours along CTE to Keppel Road involving our client's motor vehicle registration number SKM 4345 E and motor vehicle registration number SJR 8753 U driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SKM 4345 E - By email only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
SELWYN TAN YINGXIAN
CLARISSA CHEONG YUNHUI
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

✓HEAD OFFICE
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SKM 4345 E (et)
Your Ref: 3315905917SG003

4 July 2019

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

BY EMAIL ONLY

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SKM 4345 E AND SJR 8753 U ON 2 JULY 2019 ALONG CTE TO KEPPEL ROAD AT ABOUT 1545 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Venue: **A S AUTO SERVICE**
1 Kaki Bukit Avenue 6
#01-106 Autobay@Kaki Bukit
Singapore 417883
Contact: **Ah Soon @ 9738 8183 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



DIANE ANG
(HEAD OFFICE)

cc: SKM 4345 E – By email only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2390J
Vehicle Details	
Vehicle No.:	SKM4345E
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	320I SEDAN AT D/AB 4DR ABS HID
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	A8110580N20B20B
Chassis No.:	WBA3B16020NS50344
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,862.00
Original Registration Date:	28 Feb 2014
First Registration Date:	28 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$32,207.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2024
PARF Rebate Amount:	\$22,544.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,300.00
COE Rebate Amount:	\$34,988.00
Total Rebate Amount:	\$57,532.00

The information contained herein is correct as at 05 Jul 2019

OK

500+ dealers competed to buy my car!

- Sell ur Car for **More Cash**
- Highest Price or **Get \$100 Free**
- Get Paid Now, Handover Later**

SELL YOUR CAR

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

3/2014 Bmw 428i Coupe @ \$108 K



One Of The Best Unit In Town, Seeing To Believed.
Bellamy Trading StarAd

HIN LUNG AUTO
HoBee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

320

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	320		Any	Any	2014	Any	Any	Any	Available
	BMW	3 Series 320i	\$83,800	\$14,570 /yr	26-Feb-2014	1,997 cc	27,000 km	Luxury	Available
100% Loan Available! Special Interest Rate 2.28%, Fully Agent (PML) Serviced, Low Mileage Done, Flexible Bank/In House Loan Availabl... Autotruster Traders Pte Ltd Posted: 01-Jul-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW									
	BMW	3 Series 320i	\$80,600	\$13,860 /yr	28-Feb-2014	1,997 cc	135,555 km	Luxury	Available
Fully Agent Maintained! Not Your Usual 167 BHP F30 Model! High Spec Unit Brewing A 181 BHP! Original Condition With Low Petrol Con... Posted: 29-Jun-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW									
	BMW	3 Series 320i Efficient Dynamics	\$79,800	\$12,170 /yr	30-Sep-2014	1,598 cc	83,000 km	Luxury	Available
5 Years/200,000Km Warranty From Agent PML, Attractive Financing And Free Titan X! Gorgeous Mineral White Metallic Paintwork And Bl... Supreme Cars Pte Ltd Posted: 29-Jun-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW									
	BMW	3 Series 320D M-Sport	\$85,000	\$13,500 /yr	31-Mar-2014	1,995 cc	86,000 km	Luxury	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Extremely Rare BMW 320d M Sport! Full Factory M-Sport Options, PML Unit With Full Agent Service History, Immaculate In And Out. Mu... Posted: 27-Jun-2019 Tags: 2014 BMW 320D, 2014 bmw 320d, BMW 320D, bmw 320d, BMW, 320D, 320d, Used BMW									
	Updated Honda Civic continues to impress With improvements to its design and user-friendliness, the fun-to-drive Honda Civic Turbo continues to impress. Find out more!								
	BMW	3 Series 320i	\$85,000	\$14,340 /yr	24-Apr-2014	1,997 cc	68,317 km	Luxury	Available
\$1288 Cash Back! High Spec Unit Brewing A 181Bhp! 1 Owner Fully Agent Maintained! Not Your Usual 167Bhp F30 Model! Original Cond... Posted: 26-Jun-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW									
	BMW	3 Series 320i	\$78,800	\$13,480 /yr	28-Feb-2014	1,997 cc	110,017 km	Luxury	Available
One Owner, Most Valued Buy, Beautiful White Unit With Original Condition! 100% Accident Free! Well Taken Care Of, As Good As New!... Posted: 25-Jun-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW									
	BMW	3 Series 320i Efficient Dynamics	\$83,800	\$12,590 /yr	28-Nov-2014	1,598 cc	68,000 km	Luxury	Available
Compare STA Evaluation Graded. Showroom Condition. Bank Lower Interest Rate Only 2.28% And Flexible Loan Schemes Available!, Any Offer Co...									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jul 2019 Edit Reg		05 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by adjuster]				
Insured:	KIM SEONG GIL , ID: G0978323M			
Main Claimant:	NA			
Vehicle Reg. No.:	SKM4345E	Date of Loss:	02/07/2019 00:00 - :59 [64 Months and 4 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 3315905917SG	Policy/Cover Note No.:	2100489912 (Comprehensive)	
Vehicle Reg. No. (Insured):	SJR8753U	Policy No. (Claimant):		
		Excess:		
Repairer:	As Auto Service (HQ) Blk 1 Kaki Bukit Avenue 6 #01-106 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/07/2019]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Request To Upload TP GIA Report 				
ALL ASSOCIATED TASKS <input type="checkbox"/>				
			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

*SKM4345E (3315905917SG)
 [SJR8753U]
 TP
 NA
 Jul 2 2019 12:00AM
 [KIM SEONG GIL]
 As Auto Service

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>
Assessment Reports										1 per page <input type="button" value="v"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print	
1	15/07/19 10:20	Accident Statement From: SC - Reg. No: SJR8753U, Claimant: KIM SEONG GIL						Load HTM		
Photos/Images										3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
2	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
3	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
4	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
5	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
6	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
7	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
8	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
9	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
10	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
11	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
12	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
13	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
14	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
15	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
16	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
17	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
18	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
19	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
20	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
21	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
22	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
23	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
24	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
25	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
26	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
27	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
28	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
29	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
30	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
31	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
32	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	
33	15/07/19 14:18	General View						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 14:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/07/19 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	15/07/19 14:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	15/07/19 14:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	15/07/19 14:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19011930/UCF3E2**Date:** 18/07/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100489912
Claimant Vehicle No : SKM4345E **Insured Vehicle No :** SJR8753U
 Date of Loss: 02/07/2019 Nature of Claim: TP Claim No: 3315905917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM4345E**
 Make & Model: BMW 320I, 2.0 AT D/AB 4DR ABS HID NAV (A) Engine No: A8110580N20B20B
 Reg. Date: 28/02/2014 (Man. Year: 2013) Chassis No: WBA3B16020NS50344
 Colour: Blue Odometer: 100274 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/07/2019
 Date Inspected: 05/07/2019 Inspected At: As Auto Service (HQ)
 Blk 1 Kaki Bukit Avenue 6 #01-106
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Distorted	0.00 F	*- F	
2	1		*REAR BUMPER SIDE HOLDER O/S	Cracked	0.00 F	*- F	
3	1		*REAR BUMPER REFLECTOR O/S	Broken	0.00 F	*- F	
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
5	1		*REAR BUMPER TOP RETAINER	Cracked	0.00 F	*- F	
6	1		*REAR BUMPER PDC SENSOR O/S	Shorted	0.00 F	*- F	
7	1		*REAR BUMPER PDC SENSOR WIRE HARNESS	Damaged	0.00 F	*- F	
8	1		*REAR BUMPER LOWER	Distorted	0.00 F	*- F	
9	1		*TAILLAMP O/S	Scratched	0.00 F	*- F	
10	1		*REAR END PANEL	Dented	0.00 F	*- F	
11	1		*REAR FENDER O/S	Repair	0.00 F	*- F	
12	1		*REAR SPORT RIM	Cut	0.00 F	*- F	
13	1		*REAR BOOTLID MODULE UNIT	Shorted	0.00 F	*- F	
14	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
15	1		*BOOTLID	Repair	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >