

22/02/2019

ASS. REC. BY:

REF:

003 / AIG19011932 / GCSB02

Special Instruction:

Surveyor: GCS

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time:

5/7/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STY1181D

Insured:

STA 230D

at Workshop m/s Khok Joo Motor.

Tel:

9616 6658

of Blk 900H Tampines St. 93 #01-94.

Policy No:

1700045233

Claim No:

816779952686

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5/7

Person Contacted:

Mr Ng

Vehicle IN/OUT

Date/Time

Action/Instruction

Telephone (X)

STY1181D-X

STA 230D-X

Dismantle: 8/7/2019

ASSIGNMENT

(-2020)

From

Date

Veh No:

STY11810

Yr Regn:

02 Aug 2010

Estimated Cost:

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No:

STY11810

Make:

Toyota

C.C

1497

at Workshop m/s

Kiah Joo

Colour:

Silver

A/C:

Insured / Std / NI / NA

of

Blk9004 Rampine St 93 #01-94

Sp. Reading

115003

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

MROS 3HY 9305170695

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)


Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$18K

Tyre Size:

F: 185/60R15

R:

11

IDAC Accident Rpt:

Consistent? : Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

GIA / PR Seen:

Consistent? : Yes or No

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

10

days

Res.:

Yes or No

D.O.A.

D.O.I.

05-07-19

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

W/S

4pm

CA / REV / REP. / 24 HRS

Des. of Damages ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COE: 10130

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

3 + RS. 51

Filings

Other:

0-10

Report Format: DAR

Emp. Sign ALP

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Reel end (\$

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jul 2019 Edit Reg		12 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MS CHEN YEN KHIM , ID: S1524379A									
Main Claimant: NA									
Vehicle Reg. No.: SJY1181D		Date of Loss: 04/07/2019 00:00 - :59							
Claim Type: TP / 8167799526SG		Policy/Cover Note No.: 1700045233 (Comprehensive) Coverage: 26/07/2018 - 25/07/2019							
Vehicle Reg. No. (Insured): SJA230D		Policy No. (Claimant):							
		Excess:							
Repairer: Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/07/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

.PRE-REPAIR INSPECTION - ACCIDENT INVOLVING YOUR INSURED VEHI...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 7/5/2019 11:41:44 AM
Attachments:  PRI-SJY1181D-KJM.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veh In

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref : TCMG/SJY1181D/0719/KJM

Your Ref : SJA 230 D

4 July 2019

M/s AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way#07-16
AIG Building
Singapore 079120

BY E-MAIL ONLY
(shengyang.lim@aig.com)

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Leslie Chia Jia Ling**, the owner and/or driver of motor vehicle no. **SJY 1181 D**, which was involved in an accident along PIE before Clementi Road Exit on 4 July 2019 at 07:20 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SJA 230 D** for damages and/or injuries, costs and disbursements as a result of your Insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Khek Joo Motor, (9004, Tampines Street 93 #01-94, Singapore 528838 – Mr Ng Wee Khiang @ 9616 6658).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,


MR LING LEONG HUI

cc. cc. M/s Khek Joo Motor
(Yref: SJY1181D)

BY E-MAIL ONLY

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0843A
Vehicle Details	
Vehicle No.:	SJY1181D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	1NZY109286
Chassis No.:	MR053HY9305170695
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,306.00
Original Registration Date:	02 Aug 2010
First Registration Date:	02 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$12,306.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2020
PARF Rebate Amount:	\$6,768.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$3,294.00
Total Rebate Amount:	\$10,062.00

The information contained herein is correct as at 15 Jul 2019

OK

Toyota Vios Used Vehicle List (8 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Vios 1.5A E	\$16,888	-	07-Jan-2010	1,497 cc	61,000 km		Available

New Tyre, New Roadtax. No Repair Needed. Perfect For COE Renewal. Genuine Low Mileage Of 60k Km. Not The Cheapest, But Worry Free Purchase From Direct Owner. Can Immediate Transfer For Cash Payment. W...

Office No. - -

Goh - 96454645

Toyota Vios 1.5A E	\$16,800	\$19,750 /yr	25-Jan-2010	1,497 cc	142,000 km	Cars 19	Available
--------------------	----------	--------------	-------------	----------	------------	---------	-----------

New 5 Years COE At \$31,800/New 10 Years COE At \$46,800. Low Mileage Done. Well Kept. In House Loan/Bank Loan Available.

Office No. - 63385723

Brandon - 90034566 | Wilson - 90067020

Toyota Vios 1.5A E	\$15,800	\$11,200 /yr	25-May-2010	1,497 cc	-	77 Motors Pte Ltd	Available
--------------------	----------	--------------	-------------	----------	---	-------------------	-----------

High Loan! High Trade In! Popular Car Suitable For COE Renewal! Make Use Of The Low COE Prices! Call Now!

Office No. - -

RC - 87145435

Toyota Vios 1.5A E	\$18,000	\$13,760 /yr	25-May-2010	1,497 cc	103,098 km		Available
--------------------	----------	--------------	-------------	----------	------------	--	-----------

Accident-Free. Very Well Maintained. Genuine Low Mileage. Immaculate Condition, Easy Maintenance And Very Good Fuel Consumption. Female Owner. Call Us For A Viewing Anytime!

Office No. - -

Sumera Anwar - 92388356

Toyota Vios 1.5A E	\$16,300	\$11,090 /yr	14-Jun-2010	1,497 cc	116,890 km	Starise Automobile	Available
--------------------	----------	--------------	-------------	----------	------------	--------------------	-----------

High Paper Value! Ideal For Short Term Drive Or Renew 5/10 Years COE! Full/High Loan Are Available At Low Interest Rate! Original Stock Condition! High Trade-In Are Welcome! 100% Accident Free! View T...

Office No. - 64697277

Louis - 98163963 | Eric - 93863999 | Desmond - 93839158 | Milo - 84483721

Toyota Vios 1.5A E Sports	\$20,800	\$12,730 /yr	08-Sep-2010	1,497 cc	93,000 km	Jie Heng Motoring	Available
---------------------------	----------	--------------	-------------	----------	-----------	-------------------	-----------

100% Loan Approval With Low Interest Rate! Interest As Low As 2.78%, Coolest Low Mileage Unit, Definitely Not The Cheapest But For Sure One Of The Better Condition Unit, Quality Is The Key Not The Pri...

Office No. - 64693350

Tan Simpson - 88000787 | Kenneth Chua - 83387618 | Keith Khoo - 97973753 | Roy Chua (Hao) - 90121363

Toyota Vios 1.5A E	\$22,555	\$12,740 /yr	28-Oct-2010	1,497 cc	-	Cars Premium	Available
--------------------	----------	--------------	-------------	----------	---	--------------	-----------

Owner Consign Unit. High Paper Value! Ideal For Short Term Drive Or Renew 5/10 Years COE! Full/High Loan Are Available At Low Interest Rate! Original Stock Condition! High Trade-In Are Welcome! 100% A...

Office No. - 63654321

Jonathan Toh - 85006363 | Chan - 93387838

Toyota Vios 1.5A E	\$19,800	\$10,060 /yr	22-Nov-2010	1,497 cc	-	Boeki Auto Pte Ltd	Available
--------------------	----------	--------------	-------------	----------	---	--------------------	-----------

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Office No. - 67555005

Boeki - 82180500

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 13:31
Date Of Accident	04/07/2019 07:20
Exact Location Of Accident	ALONG PIE BF CLEMENTI ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY1181D
Insured/Policyholder	
Name Of Registered Owner	LESLEY CHIA JIA LING
NRIC No	S8870843A
Email Address	LESLEY.CHUAJL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93232210
Alternative Phone No	OTHERS-93232210

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29103790QMX
Cover Note Number	

Driver

Name of Driver	LESLEY CHIA JIA LING
NRIC No	S8870843A
Date Of Birth	18/04/1988
Occupation	INDOOR
Date Of Driving Pass	07/12/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93232210
Fax Number	
Contact Number	OTHERS-93232210
Email Address	LESLEY.CHUAJL@GMAIL.COM

Address	BLK11 CHAI CHEE ROAD #08-15
Postcode	460011
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA230D
Vehicle Make/Model/Colour	MAZDA 3
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEW PIN EVN DWIGHT
NRIC/Passport Number	S9050253J
Contact Number	93362445
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJV4263Y
-----------------------------	----------

Vehicle Make/Model/Colour	HONDA JAZZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

4 July 19
125pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


4 July 19
125pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 7.20am, while driving to Tufts South Ave 20 to work along PIE about 400m before Clementi Road/Dunearn Road exit, black Mazda car (SJA 230D), hit my car (SJY 1181D) with a loud bang @ lane 1!
My car was stationary as the traffic is slow and roads are in process of widening. With the huge impact, my car was pushed forward and hit on to silver Honda Jazz (SJV 4263Y). This Honda car moved a distance and came to a stop, while my car was pushed a distance, I stopped immediately & on my hazard lights and got out of the car.
The front driver of (SJV 4263Y), took picture of both mine & his car, exchanged number and confirmed that he will be filing against insurance. He left at about 0730am.
I took videos and pictures for the 3 cars involved.
The driver of black Mazda car (SJA 230D), claimed that he was not familiar with the road and was looking for signs to exit and did not notice the road (as per whatsapp conversation).
The 3 of us acknowledged that we will individually file report for the claim.
Honda Jazz driver had filed his claim at Sing Ah Tee (Blk 3 Pioneer Rd North #01-18) @ 1010am with his camera footage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 4 July 19
1 25pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 4 July 19
125pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Addendum Sheet Pg. 1

GENERAL
INSURANCE
ASSOCIATION
OF SINGAPORE

For the use of the Reporting Centre only. This form is to be filled out by the Reporting Centre.
For the use of the Reporting Centre only. This form is to be filled out by the Reporting Centre.
For the use of the Reporting Centre only. This form is to be filled out by the Reporting Centre.
For the use of the Reporting Centre only. This form is to be filled out by the Reporting Centre.

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: 19F4319087069 Vehicle Registration No: SJY1181D
Name (as shown in NRIC): _____ NRIC/FIN/Passport No.: _____
(* Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: _____ Singapore ()
Contact (Tel): _____ Mobile No.: 93232210
Email Address: _____
Date of Accident: 4/7/2019 Time of Accident: 0720
Place of Accident: Along PIE bf Clementi Road Exit
Insurance Company: MSIG / NS

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

email should be lesley.chua@egmni.com

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: 4/7/19



Front Portion

Vehicle No:

53Y11810

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	/	
1002	991887	Frt Number Plate Base	BT	/	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	RE	/	
1005	992341	Frt Bumper Clips	MC	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	RE	/	2
1008	991433	Frt Bumper Reinforcement	BT	/	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector Emblem	MC	/	
1012	991420	Frt Bumper Pad Garnish	RE	/	
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CCA	/	
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	X Repair		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	X Repair		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Finge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(0) (3)Check (0)
(4)Not Consistent (NC)

Vehicle No:

51YU810

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	/	
1138	993627	Rear Number Plate Base	BT	/	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	Re	/	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RM	/	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	PM	/	
1159	993327	Rear End Panel	Buc	/	
1160	993339	Rear End Panel Top Garnish	Re	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	Repair	X	
1166	995116	Rear RH Taillamp	CRA	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	Repair	X	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BT	/	
1171	991328	Bootlid Emblem	NC	/	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding	Re	/	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	/	
1178	990377	Bootlid Rubber	Tw	/	
1179	990382	Bootlid Hinge	BT	/	2
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	Repair	X	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	Repair	X	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

07/12/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019 Edit Reg		05 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MS CHEN YEN KHIM , ID: S1524379A									
Main Claimant: NA									
Vehicle Reg. No.: SJY1181D		Date of Loss: 04/07/2019 00:00 - :59 [107 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8167799526SG		Policy/Cover Note No.: 1700045233 (Comprehensive) Coverage: 26/07/2018 - 25/07/2019							
Vehicle Reg. No. (Insured): SJA230D		Policy No. (Claimant):							
		Excess:							
Repairer: Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY1181D (8167799526SG)

[SJA230D]

TP



















































NA


Jul 4 2019 12:00AM

[MS CHEN YEN KHIM]

Khek Joo Motor Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			v		
Assessment Reports															1 per page			v			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)															Thumbnail			Print		
1	15/07/19 10:12		Accident Statement From:OD - Reg. No: SJA230D, Claimant: CHEN YEN KHIM															Load HTM					
Photos/Images															3 per page			v			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail			Print		
1	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
2	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
3	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
4	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
5	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
6	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
7	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
8	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
9	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
10	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
11	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
12	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
13	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
14	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
15	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
16	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
17	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
18	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
19	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
20	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
21	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
22	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
23	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
24	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
25	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
26	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
27	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
28	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
29	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
30	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
31	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
32	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		
33	15/07/19 18:23		General View															Load JPG			<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	15/07/19 18:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011932/GCF3E2

Date: 18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700045233
Claimant Vehicle No : SJY1181D **Insured Vehicle No :** SJA230D
 Date of Loss: 04/07/2019 Nature of Claim: TP Claim No: 8167799526SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY1181D**
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY109286
 Reg. Date: 02/08/2010 (Man. Year: 2010) Chassis No: MR053HY9305170695
 Colour: Silver Odometer: 115003 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/07/2019
 Date Inspected: 05/07/2019 Inspected At: Khek Joo Motor Workshop (HQ)
 BLK 9004 TAMPINES STREET 93 #01-94
 Singapore 528838
 Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Bent	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER EMBLEM	Necessary	0.00 F	*- F
8	1		*FRT BUMPER GARNISH	Deformed	0.00 F	*- F
9	1		*FRT GRILLE	Cracked	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
11	1		*BONNET	Repair	0.00 F	*- F
12	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
13	1		*REAR NUMBER PLATE BASE	Bent	0.00 F	*- F
14	1		*REAR BUMPER	Deformed	0.00 F	*- F
15	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
16	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
17	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
18	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
19	1		*REAR END PANEL	Buckled	0.00 F	*- F
20	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
21	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
22	1		*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
23	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
24	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
25	1		*BOOTLID	Bent	0.00 F	*- F
26	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
27	1		*BOOTLID MOULDING	Deformed	0.00 F	*- F
28	1		*BOOTLID LOCK	Bent	0.00 F	*- F
29	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
30	2		*BOOTLID HINGE	Bent	0.00 F	*- F
31	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
32	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >