

ASS. REC. BY:

Surveyor: N12

REF:

CS31AIG 19011969/Ncf352

Special Instruction:

ASSIGNMENT (Office)

From (Person): chin lee ying

of

AIG

Date/Time: 5/7/19 @ 5.02pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

FBH 7373L

Insured:

SFK 58E

at Workshop m/s:

Vicious Cycle parts

Tel:

8159 2263 / 87565535

of

71 woodland Avenue 10 #01-13

Policy No:

2100382060

Claim No:

8074876779SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:35am 8/7/19

Person Contacted:

Matthews

Vehicle

☒ IN

OUT

Date/Time

Action/Instruction

Inspected (X)

SFK 58E - CBIAIG 09009679/g2

D.O.A. 30/6/2019

FBH 7373L: X

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jul 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DR TAN SU-HERN, ID: S7403851D			
Main Claimant:	PHUA POH CHIN, ID: S7422987E			
Vehicle Reg. No.:	FBH7373L	Date of Loss:	30/06/2019 17:00 - :59	
Claim Type:	TP / 8074876779SG	Policy/Cover Note No.:	2100382060 (Comprehensive)	
Vehicle Reg. No. (Insured):	SFK58E	Policy No. (Claimant):		
		Excess:		
Repairer:	Vicious Cycles Parts & Service (HQ) 71 Woodlands Ave 10, #01-13 Woodlands Ind. Xchange, 737743 Woodlands - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 18/07/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (10/07/2019): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 7/5/2019 5:02:21 PM
Attachments:  472019947 PRI Notice (SFK 58E).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Mail office [mailto:mail@gohjpwong.com]

Sent: Friday, July 05, 2019 4:11 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin

Subject: [EXTERNAL] Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFK58E AND FBH7373L ON 01/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Our client's motorcycle is now at Vicious Cycles Parts & Service LLP located at 71 Woodlands Avenue 10, Woodlands Industrial Xchange #01-13 Singapore 737743 (Tel: Matthew- 8159 2263 / 87555535)

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days. Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection, if required.

Kindly extend to us a copy of your surveyor's pre-repair inspection report once the report has been completed.

Lee Wee Ka

for and on behalf of Goh Teck Wee

GOH JP & WONG LLC

Advocates & Solicitors

Commissioner for Oaths

133 New Bridge Road #16-09

Chinatown Point

Singapore 059413

Tel : 6538 5868

Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



GOH JP & WONG LLC

advocates & solicitors
commissioner for oaths & notary public

GOH TECK WEE

WONG TZE ROY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413
Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com
Goh JP & Wong LLC is a law corporation with limited liability. GST/UEN: 201406078M

YOUR REF:

OUR REF: GTW.ACC.7072.19.wk

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE: 4th July 2019

Tan Su-Hern
22 Woollerton Park
#05-28 Singapore 257526

Dear Sirs

NOTIFICATION OF ACCIDENT

SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBH 7373L & SFK 58E ON 01.07.2019 SHD 1025G ON 30.06.2019 AT 253 ALEXANDRA ROAD OUTSIDE #01-04

We act for Phua Poh Chin in the above matter.

We are instructed to notify you of the above accident on 30th June 2019 at 5.00 pm at 253 Alexandra Road outside #01-04 involving our client's motorcycle FBH 7373L and motorcar SFK 58E driven by you at the material time. A copy of the Traffic Accident Report filed is enclosed.

As a result of the accident, our client's motorcycle FBH 7373L has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection, if required.

Yours faithfully

Goh Teck W

Enc.

Cc **AIG Asia Pacific Insurance Pte Ltd**
Attention: Motor Claims Department

Cc **Vicious Cycles Parts & Service LLP**
Please do not proceed with repairs until further notice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2019 14:56
Date Of Accident	30/06/2019 17:00
Exact Location Of Accident	HARLEY DAVIDSON SHOWROOM, ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH7373L
Insured/Policyholder	
Name Of Registered Owner	PHUA POH CHIN
NRIC No	S7422987E
Email Address	POHCHINPHUA@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92338458
Alternative Phone No	OTHERS-92338458
Vehicle Particulars	
Manufacturer	HARLEY-DAVIDSON
Model	FLTRXSE2 CVO ROAD GLIDE CUSTOM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MC/00483170/01
Cover Note Number	NA

Driver

Name of Driver	PHUA POH CHIN
NRIC No	S7422987E
Date Of Birth	19/07/1974
Occupation	INDOOR
Date Of Driving Pass	31/03/1993
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92338458
Fax Number	
Contact Number	
EMail Address	POHCHINPHUA@HOTMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DAY AND TIME MENTIONED, I HAD PARKED MY MOTORCYCLE AT THE SAID LOCATION, WHEN IT WAS HIT AT THE REAR RIGHT, BY A MOVING VEHICLE B, WHILST PARKING. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFK58E
Vehicle Make/Model/Colour	LEXUS GS450H AUTO
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

(FBH7373L)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
Hashim Kamari

Witnessed by Reporting Centre
Personnel

03/07

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

ON THE DAY AND TIME MENTIONED, I HAD PARKED MY MOTORCYCLE AT THE SAID LOCATION, WHEN IT WAS HIT AT THE REAR RIGHT, BY A MOVING VEHICLE B, WHILST PARKING. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

3 July 2019 at 11:33 AM

Date/Time:

3 July 2019 at 11:33 AM

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Vehicle Fee

Vehicle Details			
Vehicle No. :	FBH7373L		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HARLEY DAVIDSON		
Vehicle Model :	FLTRXSE2 CVO ROAD GLIDE CUSTOM		
Chassis No. :	5HD1TC8C7DB958615		
Propellant :	Petrol		
Engine No. :	TC8D958615		
Engine Capacity :	1802 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	617 kg		
Unladen Weight :	367 kg		
Year Of Manufacture :	2013		
Original Registration Date :	16 May 2013		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,700.00		
COE Expiry Date :	15 May 2023		
Road Tax Expiry Date :	15 Nov 2019		
Inspection Due Date :	15 May 2020		
Intended Transfer Date :	24 Jul 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2987E
Vehicle Details	
Vehicle No.:	FBH7373L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	HARLEY DAVIDSON
Vehicle Model:	FLTRXSE2 CVO ROAD GLIDE CUSTOM
Primary Colour:	Gold
Manufacturing Year:	2013
Engine No.:	TC8D958615
Chassis No.:	5HD1TC8C7DB958615
Maximum Power Output:	-
Open Market Value:	\$30,030.00
Original Registration Date:	16 May 2013
First Registration Date:	16 May 2013
Transfer Count:	0
Actual ARF Paid:	\$4,505.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,700.00
COE Rebate Amount:	\$651.00
Total Rebate Amount:	\$651.00

The information contained herein is correct as at 15 Jul 2019

OK

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

1. Replace ($\sqrt{}$) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

Vehicle No:

[illegible][illegible]

No of Items: _____ Assessor: _____

ORIGINAL COPY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jul 2019 Edit Reg		05 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	DR TAN SU-HERN, ID: S7403851D		
Main Claimant:	PHUA POH CHIN, ID: S7422987E		
Vehicle Reg. No.:	FBH7373L	Date of Loss:	30/06/2019 17:00 - :59 [73 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8074876779SG	Policy/Cover Note No.:	2100382060 (Comprehensive)
Vehicle Reg. No. (Insured):	SFK58E	Policy No. (Claimant):	
		Excess:	
Repairer:	Vicious Cycles Parts & Service (HQ) 71 Woodlands Ave 10, #01-13 Woodlands Ind. Xchange, 737743 Woodlands - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 18/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (10/07/2019): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBH7373L (8074876779SG)**
[SFK58E]

TP

PHUA POH CHIN

Jun 30 2019 5:00PM

[DR TAN SU-HERN]

Vicious Cycles Parts & Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports















1 per page ▼ ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/07/19 14:06	Accident Statement From: SC - Reg. No: SFK58E, Claimant: DR TAN SU-HERN	Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/07/19 13:44	General View photos taken by insured	Load JPG	<input checked="" type="checkbox"/>
2	18/07/19 13:44	General View photos taken by insured	Load JPG	<input checked="" type="checkbox"/>
3	18/07/19 13:44	General View photos taken by insured	Load JPG	<input checked="" type="checkbox"/>
4	18/07/19 13:44	General View photos taken by insured	Load JPG	<input checked="" type="checkbox"/>
5	18/07/19 13:44	General View photos taken by insured	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
6	18/07/19 13:44	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
7	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
8	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
9	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
10	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
11	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
12	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
13	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
14	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
15	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
16	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
17	18/07/19 13:45	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
18	18/07/19 13:46	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
19	18/07/19 13:46	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
20	18/07/19 13:46	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
21	18/07/19 13:46	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
22	18/07/19 13:46	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
23	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
24	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
25	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
26	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
27	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>
28	18/07/19 14:11	General View photos taken by insured	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011969/NCF3S2

Date: 06/08/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100382060
Claimant Vehicle No :	FBH7373L	Insured Vehicle No :	SFK58E
Date of Loss:	30/06/2019	Nature of Claim:	TP
		Claim No:	8074876779SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH7373L	Engine No:	TC8D958615
Make & Model:	HARLEY-DAVIDSON FLTRX, 1.7 Road Glide Custom	Chassis No:	5HD1TC8C7DB958615
Reg. Date:	16/05/2013 (Man. Year: 2013)	Odometer:	31960 km
Colour:	Gold		
Engine Capacity:	1802 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	130/60 R23	Rear Tyre Size:	200/55 R17
Front Left Side:	Metzeler 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/07/2019

Date Inspected: 08/07/2019 Inspected At:

Vicious Cycles Parts & Service (HQ)

71 Woodlands Ave 10, #01-13 Woodlands Ind.

Xchange

Singapore 737743

Estimated Period of Repair: 1.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE BOX BRACKET	Bent	0.00 F	*-F
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >