

FORM 6

ASS. REC. BY:

REP: CS[AIG 19011973 14ff302

Special Instructions:

Mei men
Invoys: Marked

ASSIGNMENT (Office)

From (Person): Hür Yinnul

of AIG

Date/Time:

8/7/19 @ 10:00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 6127T

Insured:

GBG 5297S

at Workshop n/s

Kaizen Motor

Tel:

9150 0670

of

68 Kaki Bukit Ave 6 #02-12

Policy No:

1700039044

Claim No:

664212825959

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:36am @ 8/7/19

Person Contacted:

Shawn

Vehicle IN/OUT

Date/Time

Action/Instruction

Initials ✓

GBG 5297S x

SKT 6127T x

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
To Inspect Vehicle No: SKT61277
at Workshop m/s: kaizen
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKT61277 Yr Regn: 6, 15
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or A/
Make: Toyota carrier c.c. 1986
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 58137 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZSU60 0031317
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/55 R18
R: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 3/7/19 D.O.I. 9/7/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
all O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
16/7/19 worked 1/5 @ 3250 with shown. (Red: 9545; 74%)

RECEIVED BY J.M. [Signature]

Date/Time, File Pass to? : Preli. Report
1) 17/7 Typist : Final Report
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip: 1

Survey Fee: _____
Transportation: _____

Add Fee: : Site Insp (\$ _____)) \$ + RS \$
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))

Report Format : TP
Lump \$0m / I.B.I: (\$ 3250/-)

TOTAL

250
11
261

PRE-REPAIR INSPECTION REQUEST – SKT6127T vs GBG5297S (OJ) on D.O.A.: 03/07/2019

From: Hor, Yiru
To: 'assignments@lkkauto.com', Admin & (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariessa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin
Sent: 7/8/2019 10:20:12 AM
Attachments: 2333_901.pdf; 3432_901.pdf

Hi,

Please refer to the enclosed request from **Vision Law LLC**.

Claim no : 6642123259SG003
Case Owner : Loh Choo Heng

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Yvrsane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yiru.Hor@aig.com | www.aig.sg

IMPORTANT NOTICE
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yiru.Hor@aig.com
To: jactan@visionlawllc.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baijit.Kaur@aig.com, NoorMariessa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeishi.chen@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG5297S AND SKT6127T ON 03/07/2019
Date: Fri, 5 Jul 2019 07:13:27 +0000

Without Prejudice

Your Reference : AM.jt.lns.K88.SKT6127t.19 (sj)
Our Reference : GBG5297S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han,Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiang	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Yvrsane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yiru.Hor@aig.com | www.aig.sg

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENORA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.K88.110925.19 (sj)
Your Ref: **GBG 5297 S**

08 July 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attention: Motor Claims Department

Email: claimsdcmangement@aig.com
Email: noormariesa.abukassim@aig.com
Email: shengyang.lim@aig.com
Email: Syazairdina.Azlan@aig.com
Email: yinrul.hor@aig.com

Dear Sirs,

**ACCIDENT INVOLVING SKT 6127 T & GBG 5297 S ON 03 JULY 2019 ALONG 683 HOUGANG AVENUE 8 OPEN CARPARK AT ABOUT 1205 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email 05 July 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Kaizen Motors Pte Ltd
68 Kaki Bukit Avenue 6
#02-12 ARK@KB
Singapore 417896
Contact Person: Shawn Yap 9150-0670 /6384-1956

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: SKT 6127 T- Email: claims@kaizenmotors.com.sg only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7394A

Vehicle Details

Vehicle No.: SKT6127T

Vehicle to be Exported: No

Intended Deregistration Date: 10 Jul 2019

Vehicle Make: TOYOTA

Vehicle Model: HARRIER PREMIUM 2.0 A

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 3ZRB479162

Chassis No.: ZSU600031317

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$29,498.00

Original Registration Date: 17 Jun 2015

First Registration Date: 17 Jun 2015

Transfer Count: 1

Actual ARF Paid: \$23,298.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Jun 2025

PARF Rebate Amount: \$17,473.00

Intended COE Rebate Details

COE Expiry Date: 16 Jun 2025

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$75,000.00

COE Rebate Amount: \$44,500.00

Total Rebate Amount: \$61,973.00

The information contained herein is correct as at 10 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2019 17:17
Date Of Accident	03/07/2019 12:05
Exact Location Of Accident	683 HOUGANG AVE 8 - OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT6127T
Insured/Policyholder	
Name Of Registered Owner	LUA SIEN JING
NRIC No	S8717394A
Email Address	SIENJING@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96778954
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10084751R00
Cover Note Number	16/08/2018 TO 16/07/2019

Driver

Name of Driver	LUA SIEN JING
NRIC No	S8717394A
Date Of Birth	27/06/1987
Occupation	INDOOR
Date Of Driving Pass	01/07/2008
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96778954
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	SIENJING@GMAIL.COM

Address	APT BLK 432 HOUGANG AVE 6 #10-198
Postcode	530432
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHUA SEOK KENG GENDER: : FEMALE
Passenger 2	NAME: : CLAWSSA LUA ZI HUI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG5297S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN TIONG LOO
NRIC/Passport Number	S1533290E
Contact Number	96357622
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

Budget Direct
Vehicle: SKT
6127 T

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 3/7/19 4:30pm.


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Mei Li
 NRIC/FIN No.: 3/7/19


Sketch Plan Pg. 2

Date of accident: 03/07/19 Time: 12.05pm Location: 683 Hougang Ave 8 Carpark.
 My Vehicle A: SKT 6127T Vehicle B: G8G9 52975 Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle B stopped and reversed into vehicle A. Vehicle B did not indicate parking or turn hazard lights on. Vehicle A sounded the horn but vehicle B proceeded to reverse. Vehicle B right rear hit vehicle A front ~~and~~ right bumper. Vehicle A was stationary at point of impact.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address : sienjing@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 3/7/19 4:30pm

SKT 6127T
 Vehicle:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Person's Signature
 Name: _____
 NRIC/FIN No.: _____

 AH LIM MOTOR COMPANY

**Budget
Direct
insurance**
Certificate of Insurance

 Comprehensive Car Policy
 Policy Number: P10084751R00

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.


Certificate Number P10084751R00 (Comprehensive / Named Driver Plan)

1) Vehicle Registration Number	:	SKT6127T
Chassis Number	:	ZSU600031317
2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	16/08/2018 (13:14)
3) Date / Time of Expiry of Insurance	:	16/07/2019 (23:59)
4) Excess (i) Policy	:	S\$ 700.00
(ii) Windscreen	:	S\$ 100.00
5) Policyholder	:	Lua Sien Jing
6) Persons or Classes of Persons Entitled to Drive*		
Drivers named as a Main / Named Driver in this Certificate of Insurance only.		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.		
Main Driver / Date of Birth	:	Lua Sien Jing (27/06/1987)
Named Driver(s) / Date of Birth	:	Tan Wei Yu (27/09/1987)
7) Limitation as to use*		
Use only for social, domestic and pleasure purposes. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
8) Finance Company	:	LAKE VIEW CREDIT PTE LTD

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

 Issued in Singapore on
 10/06/2019

 Auto & General Insurance (Singapore) Pte. Limited
 Trading as Budget Direct Insurance



Simon Birch

Policy Holder-Driver's Particulars Pg. 2



Accident Photo



KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H GST Reg No. 201502816H

Tel: (+65) 6384 1956 Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>

 kaizenmotorsingapore

 kaizen_motors

 kaizenmotors

not Authorized
 1/54 3250
 3dy
 The price is 11/14/19

Date : 07/07/2019
 Vehicle No : SKT6127T
 Model : Toyota Harrier
 Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	FRONT R/H HEADLAMP ASSY <i>holder</i>	1	\$ 3,300.00	\$ 3,300.00 ✓
2	FRONT R/H HEADLAMP BRACKET <i>117</i>	1	\$ 125.00	\$ 125.00 X
3	FRONT R/H HEADLAMP PANEL <i>2</i>	1	\$ 195.00	\$ 195.00 X
4	FRONT R/H HEADLAMP SPONGE <i>11</i>	1	\$ 58.00	\$ 58.00 X
5	FRONT BUMPER ASSY <i>20/21</i>	1	\$ 1,450.00	\$ 1,450.00 ✓
6	FRONT BUMPER BRACKET <i>117</i>	1	\$ 120.00	\$ 120.00 X
7	FRONT R/H BUMPER TOW COVER <i>117</i>	1	\$ 38.00	\$ 38.00 X
8	FRONT UPPER GRILLE ASSY <i>117</i>	1	\$ 765.00	\$ 765.00 X
9	FRONT LOWER GRILLE ASSY <i>117</i>	1	\$ 250.00	\$ 250.00 X
10	FRONT SUPPORT PANEL <i>2</i>	1	\$ 1,200.00	\$ 1,200.00 X
11	FRONT SUPPORT PANEL SPONGE <i>117</i>	1	\$ 301.00	\$ 301.00 X
12	FRONT BUMPER REINFORCEMENT <i>117</i>	1	\$ 425.00	\$ 425.00 X
13	FRONT BUMPER REINFORCEMENT SPONGE <i>117</i>	1	\$ 135.00	\$ 135.00 X
14	BRACE PANEL <i>117</i>	1	\$ 225.00	\$ 225.00 X
15	LICENSE PLATE & BRACKET <i>117</i>	1	\$ -	\$ - X
16	FRONT R/H FOGLAMP ASSY <i>117</i>	1	\$ 338.00	\$ 338.00 X
17	FRONT R/H FOGLAMP COVER <i>117</i>	1	\$ 125.00	\$ 125.00 X
18	FRONT PARKING SENSOR <i>117</i>	1	\$ 425.00	\$ 425.00 X
19	LABOUR FOR CHECKING ON WIRING		\$ 120.00	\$ 120.00 - 20
20	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT BUMPER, HEADLAMP, GRILLE & FOGLAMP, REINFORCEMENT PANEL & SUPPORT PANEL		\$ 2,300.00	\$ 2,300.00 - 250
21	SPRAYPAINTING & PUTTY OF FRONT BUMPER ASSY		\$ 900.00	\$ 900.00 250

KAIZEN MOTORS PTE. LTD.
 68 KAKI BUKIT AVENUE 6, #02-12 ARK@KB, SINGAPORE 417896
 UEN: 201502816H GST REG NO. 201502816H
 TEL: (+65) 6384 1956 FAX: (+65) 6384 1957
 WWW.KAIZENMOTORS.COM.SG

P = 4750
 252
 P = 358250
 1000 - 520.00
 408250
 209
 3266

Sub-Total	\$ 12,795.00
GST 7%	\$ 895.65
Grand Total	\$ 13,690.65

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19011973/UTF3N2

Date: 18/07/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700039044
Claimant Vehicle No :	SKT6127T	Insured Vehicle No :	GBG5297S
Date of Loss:	03/07/2019	Nature of Claim:	TP
		Claim No:	6642123259SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6127T	Engine No:	3ZRB479162
Make & Model:	TOYOTA HARRIER, 2.0 Premium Sunroof (A)	Chassis No:	ZSU600031317
Reg. Date:	17/06/2015 (Man. Year: 2015)	Odometer:	58137 km
Colour:	White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,475.00	3,562.50	5,912.50	62.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	520.00	2,800.00	84.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,795.00	4,082.50	8,712.50	68.09
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	12,795.00	3,250.00	9,545.00	74.60
+ GST 7.00/7.00% (S\$)	895.65	227.50	668.15	74.60
Nett Amount (S\$)	13,690.65	3,477.50	10,213.15	74.60

INSPECTION

Date of Assignment:	08/07/2019		
Date Inspected:	09/07/2019	Inspected At:	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H HEADLAMP ASSY	Holder Cracked	3,300.00 F	*3,300.00 FL
2	1		*FRONT R/H HEADLAMP BRACKET	Not Necessary	125.00 F	*- FL
3	1		*FRONT R/H HEADLAMP PANEL	Repair	195.00 F	*- FL
4	1		*FRONT R/H HEADLAMP SPONGE	Not Necessary	58.00 F	*- FL
5	1		*FRONT BUMPER ASSY	Dented/Deformed	1,450.00 F	*1,450.00 FL
6	1		*FRONT BUMPER BRACKET	Not Necessary	120.00 F	*- FL
7	1		*FRONT R/H BUMPER TOW COVER	Not Necessary	38.00 F	*- FL
8	1		*FRONT UPPER GRILLE ASSY	Not Necessary	765.00 F	*- FL
9	1		*FRONT LOWER GRILLE ASSY	Not Necessary	250.00 F	*- FL
10	1		*FRONT SUPPORT PANEL	Repair	1,200.00 F	*- FL
11	1		*FRONT SUPPORT PANEL SPONGE	Not Necessary	301.00 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	425.00 F	*- FL
13	1		*FRONT BUMPER REINFORCEMENT SPONGE	Not Necessary	135.00 F	*- FL
14	1		*BRACE PANEL	Not Necessary	225.00 F	*- FL
15	1		*LICENSE PLATE & BRACKET (NPA)	Not Necessary	0.00 F	*- FL
16	1		*FRONT R/H FOGLAMP ASSY	Not Necessary	338.00 F	*- FL
17	1		*FRONT R/H FOGLAMP COVER	Not Necessary	125.00 F	*- FL
18	1		*FRONT PARKING SENSOR	Not Necessary	425.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	9,475.00	4,750.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,187.50
Total Parts (S\$)	9,475.00	3,562.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING	New	120.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF FRONT BUMPER,HEADLAMP,GRILLE & FOGLAMP,REINFORCEMENT PANEL & SUPPORT PANEL	New	2,300.00	250.00
3	SPRAYPAINTING & PUTTY OF FRONT BUMPER ASSY	New	900.00	250.00
Gross Labour Cost (\$\$)			3,320.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >