

Surveyor

Raisul

ASSIGNMENT (Office)

From (Person)

Motor Insurance

of

INC

Date/Time

5/07/2019

Estimated Cost

Billed for

OD / IT / WS / TP / RST / OD / RST / EVA / INV / MV / C

To Inspect Vehicle No:

SLG 3195Y

Insured:

SGH 3856C

at Workshop no:

My Car Consultant

Tel:

8866 8832

of

53 ubi Ave 1 #01-25

Policy No:

Claim No:

M7/1041177-001

Sum Insured:

Excess:

Make of Veh:

D.O.A

19/4/19

(Claim's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

10:43am @ 23/4/19

Person Contacted

Huiain

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLG 3195Y - X

SGH 3856C - CS1A1G12006507/116143Y

Don 2/4/2012

Dismantle: 24/4/2019

After repair: 27/4/2019

10/07/19

Submit H/s \$ 4,050/- @ 5 days
(\$ 2,150/- Red - 35%)



10/7/2019

RECEIVED 15 JUL 2019

Nivitha (LKK Auto)

From: do_not_reply@income.com.sg
Sent: Friday, 5 July 2019 5:01 PM
To: assignments@lkkauto.com
Subject: MT/1041177-001 - Claim Involving SGH3856C / SLG3195Y on 19 Apr 2019
Attachments: LOD2 2019-6-14.pdf.PDF; TP Survey Report .PDF;
EBGI-300002866-0000135643-1562316516850_EBAOGICLM_DLET_MT.pdf

Dear Sir / Madam,

We refer to the above claim.

Enclosed is the letter / document for your necessary attention.

Yours sincerely

Motor Insurance
Income

Note: This is a system generated email. Please do not reply to this email.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2019 13:30
Date Of Accident	19/04/2019 20:05
Exact Location Of Accident	SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG3195Y
Insured/Policyholder	
Name Of Registered Owner	AFIDADEWI BINTI ADIMAN
NRIC No	S13595561
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97583035
Alternative Phone No	OFFICE-97583035

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Excess Policy	NO
Policy Number	DMPG18003601
Cover Note Number	

Driver

Name of Driver	AHMAD RUSYAIID BIN RUSLAN
NRIC No	S9906453F
Date Of Birth	03/03/1999
Occupation	INDOOR
Date Of Driving Pass	21/02/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91899453
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 543 SERANGOON NORTH AVE 3 #04-178
 Postcode 550543
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : AFIDAEWI
 GENDER: : FEMALE
 Passenger 2
 NAME: : NUR RAFHANAHDEWI BINTE RUSLAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
 Police Station Contact TEL NO. 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20190419/7019.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGH3856C
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE1041A
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name AHMAD RUSYAI DI BIN RUSLAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLG3195Y
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date

I was driving my mother's car bearing SLG 3195Y my car is completely stopped at the traffic light. Suddenly I felt a huge impact from the rear. I alighted and discovered there was two other cars involved. The car that hit me from the rear was SGH 3856C and another vehicle hit SGH 3856C was GBE 1041A. My mother name is Afidadewi binte Adiman and my sister Nur Rafhanahdewi binte Ruelan was in the car with me. My mother and me and sister was injured. I went to see doctor and get 5 days MC.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/ID No.:

Schedule of Surveyor's Attendance for Conducting PRS

This document indicates that the 3rd party surveyor has inspected the vehicle as follows :

Workshop : My Car Consultant Pte Ltd
Vehicle No. : _____
Date of Accident : _____
Name of TP Insurer Co. : _____
Surveyor's Firm & Name : _____
Contact No. : _____
Date of Vehicle Send In : _____

1st PRS Conducted.

Date & Time of Inspection : 23/04/19 , 1525

Require of Resurvey Hidden/Check Items : YES / NO



Rabeul CLKK

Signature / Name


2nd PRS Conduct Hidden/Check Damages Items.

Date & Time Informed Surveyor : _____ / _____ (By Repairer)

Date & Time of Inspection : 25/04/19 , @ 1345

Require of Resurvey After Repair : YES / NO

Remarks : _____



Signature / Name

3rd PRS Conduct After Repairs.

Date & Time Informed Surveyor : _____ / _____ (By Repairer)

Date & Time of Inspection : _____ / _____

Signature / Name

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9906453F



Name

AHMAD RUSYAI BIN RUSLAN

أحمد روشيدي بن رسلان

Race

JAVANESE

Date of birth

03-03-1999

Sex

M

S9906453F

Country/Place of birth

SINGAPORE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1359556I



Name

AFIDADEWI BINTI ADIMAN

أفيدةوي بنت أديمان

Race

JAVANESE

Date of birth

07-07-1959

Sex

F

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9441815A



Name

NUR RAFHANAHEWI BINTE
RUSLAN

Race

JAVANESE

Date of birth

17-11-1994

Sex

F

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



AFIDADEWI BINTI ADIMAN

Birth Date: 07 Jul 1959

Issue Date: 17 Dec 2002



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S9906453F

AHMAD RUSYAI BIN RUSLAN

Birth Date: 03 Mar 1999

Issue Date: 21 Feb 2018



NRIC No. S9906453F



Date of issue

22-01-2014

Address

APT BLK 543 SERANGOON NORTH AVENUE 3
#04-17B
SINGAPORE 550543

5261218



NRIC No. S1359556I



Blood Group: Date of issue

B+ 25-06-1993

Address

APT BLK 543 SERANGOON NORTH AVENUE 3 #04-17B
SINGAPORE 550543

NRIC No: S1359556I

Date: 28-12-1998

No: 2163625

1062481



NRIC No. S9441815A



Date of issue

09-01-2009

Address

APT BLK 543 SERANGOON NORTH AVENUE 3
#04-17B
SINGAPORE 550543


4336276

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

18 Jan 1999



Licence No: S1359556I

NP 428A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles < 200 CC
Class 3 Motor cars < 2000 kg with < 7 passengers, excluding of the
driver; and motor tractors < 2000 kg

25 Nov 1998

24 Feb 2009

S / No. 9000306577

S9906453F



Licence No: S9906453F

NP 628A

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Apr 2019 / 11:22:53

Receipt Date/Time : 22 Apr 2019 / 11:22:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190422-001018

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SGH3856C				
As at 19 Apr 2019/20:05:00				
Insurance Co: NTUC INCOME INS CO-OP LTD				
1	Insurance Enquiry - SGH3856C Enquiry Fee 20190422112130487451	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - GBG340H				
As at 15 Apr 2019/13:30:00				
Insurance Co: MSIG INSURANCE (SINGAPORE) PTE LTD				
2	Insurance Enquiry - GBG340H Enquiry Fee 20190422112130522412	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		14.00	0.98	14.98
Rounding Difference				0.03
Total Amount Payable				14.95
Paid By				
	xxxxxxxxxxxx9904	Credit Card; Visa/MasterCard		14.95
Total				14.95
Cash Change				0.00
Tendered Amount				14.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

Your Ref: SLG3195Y

Our Ref: MT/CA/TP/036/1041177-001/RD

05 Jul 2019

LKK AUTO CONSULTANTS PTE LTD
51 UBI AVENUE 1
#02-25 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408933

**WITHOUT PREJUDICE
SAVE AS TO COSTS
BY FAX & POST**

Dear Sir/Madam

CLAIM NUMBER: MT/1041177-001

ACCIDENT INVOLVING SGH3856C / SLG3195Y on 19 Apr 2019

We refer to the claim.

Please let us have your complete PRS report/recommendation.

If you have any queries, please contact Rajeswary Doraisamy at 6430 7934 or email us at rajeswary.doraisamy@income.com.sg.

Yours sincerely



Jenny Pe
Deputy Vice President
Motor Insurance

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2019-183
Invoice No: TP/TWG/2019-183
Vehicle No: SLG3195Y
Attn: AFIDADEWI BINTI ADIMAN
Company: MY CAR CONSULTANT PTE LTD
Address: 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

Date 17 May 2019

Invoice

Surveyor Fee:	S\$290
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$70/- (@ \$1 per photo, total 70 photos)
Total:	S\$460

Surveyor:
Signature:
Date:



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : AFIDADEWI BINTI ADIMAN
C/O MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Date : 17 May 2019
Our Ref : WG/IP/2019-183

REFERENCE PARTICULARS

Date of Accident : 19 April 2019
Date of Inspection : 23 April 2019

Type of Inspection : Third Party Claim
Date of Re-Inspn : 24 April 2019

VEHICLE PARTICULARS

Registration No : SLG3195Y
Make : HONDA
Model : VEZEL 1.5X CVT
Year : 2016

Engine No : L15B4404582
Chassis No : RU11204583
Odometer : 45601km
Colour : Red

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Dunlop	215/60R16
Front Off Side	Dunlop	215/60R16
Rear Near Side	Dunlop	215/60R16
Rear off Side	Dunlop	215/60R16

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,200.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed Seventy (70) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

In accordance to your instruction, we have **not** authorise repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SLG3195Y
MODEL : VEZEL 1.5X CVT

Our Ref : WG/TP/2019-183

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 TAILGATE	1	DENTED	\$ 1,098.25	\$ 1,098.25
2 TAILGATE GLASS MOULDING	1	NECESSARY	\$ 140.00	\$ 140.00
3 TAILGATE LOGO	1	NECESSARY	\$ 38.30	\$ 38.30 XAN
4 TAILGATE EMBLEM -VEZEL	1	NECESSARY	\$ 49.50	\$ 49.50
5 TAILLAMP LH	1	NOT NECESSARY	\$ 483.00	\$ - XAN
6 TAILLAMP RH	1	CRACKED	\$ 483.00	\$ 483.00 XAN
7 TAILGATE OUTER GARNISH	1	NOT NECESSARY	\$ 143.75	\$ - XAN
8 TAILGATE LOCK	1	JAMMED	\$ 186.35	\$ 186.35
9 TAILGATE LOCK STRIKER	1	BENT	\$ 35.00	\$ 35.00 XAN
10 TAILGATE RUBBER	1	DEFORMED	\$ 120.75	\$ 120.75
11 TAILGATE DAMPER	2	NOT NECESSARY	\$ 210.22	\$ -
12 TAILGATE INNER PULL COVER	1	DEFORMED	\$ 35.01	\$ 35.01
13 TAILGATE INNER TRIM	1	DEFORMED	\$ 291.53	\$ 291.53
14 REAR BUMPER	1	DEFORMED	\$ 741.30	\$ 741.30
15 REAR BUMPER SIDE RETAINER @60.15	21PC	NECESSARY	\$ 120.30	\$ 120.30 60.15
16 REAR BUMPER REFLECTOR LH	1	NOT NECESSARY	\$ 151.00	\$ -
17 REAR BUMPER REFLECTOR RH	1	CRACKED	\$ 151.00	\$ 151.00
18 REAR EXHAUST SILENCER	1	BENT	\$ 628.51	\$ 628.51 588
19 REAR EXHAUST MOUNTING	2	NECESSARY	\$ 40.00	\$ 40.00
20 REAR INNER LAMP LH	1	NOT NECESSARY	\$ 265.30	\$ -
21 REAR INNER LAMP RH	1	NOT NECESSARY	\$ 265.30	\$ -
22 END PANEL	1	DENTED	\$ 585.20	\$ 585.20 Repair
23 END PANEL TOP GARNISH	1	DEFORMED	\$ 165.62	\$ 165.62
24 REAR SPARE TYRE UNDER COVER	1	CRACKED	\$ 201.30	\$ 201.30
25 REAR RH FENDER OUTER GARNISH	1	CRACKED	\$ 177.02	\$ 177.02 XAN
26 REAR BUMPER CORNER BUMPER RH	1	CRACKED	\$ 210.12	\$ 210.12
		4078.88	\$ 7,016.63	\$ 5,498.06
		20%	\$ 1,403.32	\$ 1,099.61
		3263.10	\$ 5,613.31	\$ 4,398.45
B) S/NET ITEM				
27 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
28 REAR REVERSE SENSOR	1 SET	MAFUNCTION	\$ 400.00	\$ 300.00 200
29 TAILGATE INNER TRIM CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
30 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 XAN 310
31 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 60
			\$ 770.00	\$ 610.00
Parts Total :			\$ 6,383.31	\$ 5,008.45
C) LABOUR CHARGES & MISC				
32 CHECK REAR WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00 XAN
33 REMOVE AND REFIT REAR REVERSE SENSOR			\$ 120.00	\$ 100.00 60
34 REMOVE, REFIT REAR LINING, TRIM AND GARNISH			\$ 200.00	\$ 180.00 60
35 REMOVE AND RENEW REAR EXHAUST			\$ 150.00	\$ 130.00 60
36 REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 120.00
37 TRANSFER PARS. ATTACHMENT FROM OLD TAIL GATE TO NEW			\$ 200.00	\$ 180.00 60
38 PANEL BEATING ON AFFECTED AREAS @			\$ 1,000.00	\$ 900.00 600
39 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,200.00	\$ 1,000.00 500
40 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00 60
			\$ 3,230.00	\$ 2,790.00
Labour Total :			\$ 3,230.00	\$ 2,790.00
Total Parts and Laboure :			\$ 9,613.31	\$ 7,798.45
FINAL LUMP SUM ADJUSTMENT				\$ 6,200.00

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$6,200.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES

Wingshagh
Automotive Appraiser





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19007163/R1sf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 15-07-2019

189556

ATTN: JARED LIU

Code : INC



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGH 3856C	Veh. Inspected	SLG 3195Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1041177-001	Excess (\$)	0.00
Assign From	MOTOR INSURANCE	Assign Date	05/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11204583	Colour	RED
Odometer	045602	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	5 mm
L/H Front Tyre	215/60R16	DUNLOP	5 mm
R/H Rear Tyre	215/60R16	DUNLOP	5 mm
L/H Rear Tyre	215/60R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/04/2019	Inspection Date	23/04/2019
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3195Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	1,098.25	1,098.25
1	TAILGATE GLASS MOULDING	NECESSARY	140.00	140.00
1	TAILGATE LOGO	NOT NECESSARY	38.30	-
1	TAILGATE EMBLEM - VEZEL	NECESSARY	49.50	49.50
1	TAILLAMP LH	NOT NECESSARY	483.00	-
1	TAILLAMP RH	NOT NECESSARY	483.00	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	143.75	-
1	TAILGATE LOCK	JAMMED	186.35	186.35
1	TAILGATE LOCK STRIKER	SERVICEABLE	35.00	-
1	TAILGATE RUBBER	DEFORMED	120.75	120.75
2	TAILGATE DAMPER	NOT NECESSARY	210.22	-
1	TAILGATE INNER PULL COVER	DEFORMED	35.01	35.01
1	TAILGATE INNER TRIM	DEFORMED	291.53	291.53
1	REAR BUMPER	DEFORMED	741.30	741.30
2	REAR BUMPER SIDE RETAINER	NECESSARY 1PC ONLY	120.30	60.15
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	151.00	-
1	REAR BUMPER REFLECTOR RH	CRACKED	151.00	151.00
1	REAR EXHAUST SILENCER	BENT	628.51	588.00
2	REAR EXHAUST MOUNTING	NECESSARY	40.00	40.00
1	REAR INNER LAMP LH	NOT NECESSARY	265.30	-
1	REAR INNER LAMP RH	NOT NECESSARY	265.30	-
1	END PANEL	TO REPAIR SEE LABOUR	585.20	-
1	END PANEL TOP GARNISH	DEFORMED	165.62	165.62
1	REAR SPARE TYRE UNDER COVER	CRACKED	201.30	201.30
1	REAR RH FENDER OUTER GARNISH	SERVICEABLE	177.02	-
1	REAR BUMPER CORNER BUMPER RH	CRACKED	210.12	210.12
	LESS 20% DISCOUNT		-1,403.32	-815.78
			5,613.31	3,263.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET REAR REVERSE SENSOR (SN)	MALFUNCTION	400.00	200.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	30.00	20.00

Report Ref No. CS3/INC19007163/R1sf3s2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	JOINT SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	60.00
			770.00	310.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	60.00
	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.		200.00	60.00
	REMOVE AND RENEW REAR EXHAUST.		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL.		1,000.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	500.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	60.00
			3,230.00	1,520.00
GRAND TOTAL			9,613.31	5,093.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CS3/INC19007163/R1sf3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.