

DATE:

ASS. REC. BY:

REF: CS3 / AIG19011974 / Acf362

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 8/7/19 @ 10.06am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 4485A

Insured:

SFL 1M

at Workshop m/s

Hock Motor

Tel:

9784 5529

of

1 kark; Bukit Ave 6 # 02-38 Autobay

Policy No:

Claim No:

416572663386

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 1020am 8/7/19

Person Contacted:

Kelvin

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction
	Initials <input checked="" type="checkbox"/> #02-38
	SFL 1M: CS/AIG10007543/Rtg1 D.O.A: 13/04/2010
	SLC 4485A-X
	Dismantle: 8/7/2019
	After repair: 12/7/2019

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLC4485A Yr Regn: 2007 / OctType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1339Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 175933 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMF0362075213028Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 08/07/19Survey held at: Hock MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG PRS.

COE Expiry: 09/10/22

MV: 19.5K. (Depreciation \$6.5K)

PV: 13.5K

Nett: 6K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) DAR

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

18011191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2019 <a href="#">Edit Reg</a>		08 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	ONG SAN SAN, ID: S7711217J		
Main Claimant:	HEW YOON LING, ID: S7072215A		
Vehicle Reg. No.:	SLC4485A	Date of Loss:	04/07/2019 00:00 - :59
Claim Type:	TP / 4165726633SG	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SFL1M	Policy No. (Claimant):	
		Excess:	
Repairer:	Hock Motors Workshop (HQ) NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 68469707		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 17/07/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)



There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc:  
Sent: 7/8/2019 10:06:58 AM

Attachments:  2019.7.8-PRI letter to AIG for SLC4485A.PDF  2019.7.8-GIA of our client SLC4485A.PDF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** lua\_siewhui@rssolomon.com [mailto:lua\_siewhui@rssolomon.com]

**Sent:** Monday, July 08, 2019 9:36 AM

**To:** Hor, Yinrul; wendy\_jiang@rssolomon.com; natalie\_ng@rssolomon.com

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; lua\_siewhui@rssolomon.com

**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFL1M AND SLC4485A ON 04/07/2019

Dear Yinrul,

We refer to your email of even date.

We write to inform that our client will be appointing her own Surveyor.

In this respect, please arrange your surveyors to contact Mr. Kelvin Khoo of Hock Motors Workshop at Mobile No. 9784 5529 for a pre-repair survey of our client's vehicle located at 1 Kaki Bukit Avenue 6 #02-22 /#02-38 (Main) Singapore 417883.

Thank you and Best Regards

Lua Siew Hui | Legal Executive

**R. S. Solomon LLC | 正氣律師事務所**

**Advocates & Solicitors | Commissioner for Oaths**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [lua\\_siewhui@rssolomon.com](mailto:lua_siewhui@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2215A
<b>Vehicle Details</b>	
Vehicle No.:	SLC4485A
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC IMA A
Primary Colour:	Purple
Manufacturing Year:	2007
Engine No.:	LDA22048120
Chassis No.:	JHMF36207S213028
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$26,366.00
Original Registration Date:	10 Oct 2007
First Registration Date:	10 Oct 2007
Transfer Count:	2
Actual ARF Paid:	\$18,457.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Oct 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,282.00
COE Rebate Amount:	\$13,844.00
<b>Total Rebate Amount:</b>	<b>\$13,844.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jul 2019

OK

X GO FROM THIS ...



✓ TO A BELLROY



Both the s

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



3.18% P.A \$0 Admin Fees At GV  
Finance. 2 Years Warranty.  
Monthly From \$488  
GV Credit Pte Ltd StarAd






Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

honda civic 1.3

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	honda civic 1.3		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Honda Civic Hybrid 1.3A (COE till 01/2024)		\$31,800	\$7,010 /yr	19-Jan-2009	1,339 cc	115,261 km	Sedan	Available
	<b>Fuel Type:</b> Petrol-Electric Loan Flexible Package Bank And In-House Are Available.Super Fuel Economy To Drive Around Powered By Hybrid (Battery) Changed. Beautiful Interior And Exterior. Price Exclude Booking Fee. Warranty Provided. Very Well Maintain By Previous Owner. Bank And In-Hous...								COMBINATION
	Car Search								
	Posted: 23-Jun-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic Hybrid 1.3A (New 5-yr COE)		\$31,800	\$6,350 /yr	09-Jun-2009	1,339 cc	-	Sedan	Available
	<b>Fuel Type:</b> Petrol-Electric Full Loan Available At \$700 Plus, We Can Help To Conver To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test D...								PREMIUM AD
	88 Motor Trading								
	Posted: 08-Jul-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic Hybrid 1.3A (New 5-yr COE)		\$35,888	\$7,170 /yr	07-Jul-2009	1,339 cc	138,644 km	Sedan	Available
	<b>Fuel Type:</b> Petrol-Electric We Are The COE Specialist. No Gimmicks, Honest Dealing, 1 Owner With Low Mileage Clocked, Car In Good Condition, Full Loan Available 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Showroom Today.								PREMIUM AD
	Posted: 29-Jun-2019 Tags: 2009 Honda Civic, 2009 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used honda civic 1.3, honda civic 1.3 Singapore, used honda civic 1.3 Singapore, used honda civic 1.3, used vehicles Singapore or even buy used honda civic 1.3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)  
©2004-2019 sgCarMart. All rights reserved.

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2019 14:07
Date Of Accident	04/07/2019 20:00
Exact Location Of Accident	JLN EUNOS TWD SIMS AVE EAST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC4485A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HEW YOON LING
NRIC No	S7072215A
Email Address	DANIELPEK22@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97854187
Alternative Phone No	OFFICE-97854187

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.3 IMA (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00468912/01
Cover Note Number	

### Driver

Name of Driver	PEK CHIN KEE
NRIC No	S1689338B
Date Of Birth	12/04/1965
Occupation	INDOOR
Date Of Driving Pass	01/04/1987
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97863820
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 98 BEDOK NORTH AVE 4 #22-1900
Postcode	460098
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HEW YOON LING
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFL1M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG SAN SAN
NRIC/Passport Number	S7711217J
Contact Number	97348336
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



### SKETCH PLAN



1 WAS STATIONARY WHILE WAITING FOR TRAFFIC  
LIGHT TO TURN GREEN. VEHICLE B SLAM HIT ONTO MY REAR  
OF THE VEHICLE.

I/We declare the foregoing particulars are true in every respect.

Date &amp; Time: \_\_\_\_\_

Date &amp; Time: \_\_\_\_\_

NRIC/FIN No.:

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

(1) Beat (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

# MOTORCAR (Rear)

(1) Replace (✓) (2) Repaired (3) Check (✓)  
(4) Not Consistent (N/C)

## Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	De	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	N/C	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	N/C	✓	02
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	De	✓	
1159	993327	Rear End Panel	De	✓	
1160	993339	Rear End Panel Top Garnish	De	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	De	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	De	✓	
1171	991328	Bootlid Emblem	N/C	✓	03
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH	De	✓	
1177	995243	Bootlid Lock	De	✓	
1178	990377	Bootlid Rubber	De	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

04 Days

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items:

Assessor:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2019 <a href="#">Edit Reg</a>		08 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>








































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>ONG SAN SAN</b> , ID: S7711217J								
Main Claimant:	<b>HEW YOON LING</b> , ID: S7072215A								
Vehicle Reg. No.:	<b>SLC4485A</b>	Date of Loss:	04/07/2019 00:00 - :59 [140 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4165726633SG</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SFL1M</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Hock Motors Workshop (HQ)</b> NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 68469707								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 17/07/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (09/07/2019): <b>TP GIA REPORT</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLC4485A (4165726633SG)  
[SFL1M]  
TP  
HEW YOON LING  
Jul 4 2019 12:00AM  
[ONG SAN SAN]  
Hock Motors Workshop

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		▼	
Photos/Images										3 per page		▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print			
1	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
2	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
3	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
4	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
5	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
6	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
7	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
8	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
9	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
10	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
11	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
12	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
13	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
14	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
15	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
16	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
17	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
18	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
19	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
20	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
21	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
22	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
23	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
24	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
25	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
26	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
27	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
28	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
29	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
30	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
31	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
32	08/07/19 16:13	General View									Load JPG	<input checked="" type="checkbox"/>			
33	15/07/19 12:39	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>			
34	15/07/19 12:39	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>			
35	15/07/19 12:39	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>			
36	15/07/19 12:39	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>			
37	15/07/19 12:39	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/07/19 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	15/07/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011974/ACF3E2

Date: 18/07/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLC4485A

Insured Vehicle No : SFL1M

Date of Loss: 04/07/2019

Nature of Claim: TP Claim No: 4165726633SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLC4485A

Make &amp; Model: HONDA CIVIC, 1.3 IMA (A)

Engine No: LDA22048120

Reg. Date: 10/10/2007 (Man. Year: 2007)

Chassis No: JHMFD36207S213028

Colour: Purple

Odometer: 175933 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Grenlander 6 mm

Rear Left Side: Grenlander 6 mm

Front Right Side: Grenlander 6 mm

Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 08/07/2019

Date Inspected: 08/07/2019 Inspected At:

Hock Motors Workshop (HQ)  
 NO 1 KAKI BUKIT AVENUE 6, #02-38  
 AUTOBAY @ KAKI BUKIT  
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
8	1		*BOOTLID	Dented	0.00 F	*- F
9	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
10	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
11	1		*BOOTLID LOCK	Damaged	0.00 F	*- F
12	1		*BOOTLID RUBBER	Cut	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >