



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:WINNIE HO

Ref: CC4/ASM19011984/Kpa3q2
Date: 20/05/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 3785P	Veh. Inspected	SLE 7886X
Policy No.	GA362780	Coverage (\$)	0.00
Claim No.	S9M01T5P	Excess (\$)	0.00
Assign From		Assign Date	08/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610016497	Colour	WHITE
Odometer	210495 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	AGENDA	9 mm
L/H Front Tyre	185/60 R15	AGENDA	9 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2019	Inspection Date	08/07/2019
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**