

7/20/2017

ASS. REC. BY:

REF: CS3/AIG19011928/Ecf3^{SV}

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): chin lee ying

of

AIG

Date/Time: 8/7/19 @ 2.25pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC4238R

Insured:

8LZ 9291 M

at Workshop m/s

Elites Performances

Tel:

90999558.

of

NO. S1 Defu June 9

Policy No:

Claim No:

474353259786

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.21pm @ 8/7/19

Person Contacted:

kalvin

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Vehicle X
	SLZ9291M : X
	GBC4238R : X
	Dismantle: 10/7/2019

SAFARI

Steve

REF:

A16

ASSIGNMENT

From:

Date:

Estimated Cost:

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop with:

at:

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time / Action / Instruction

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/Nr:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Modi: Nil / S/Rlm. / STD A/Rlm. or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SU TOYO / YOKO or

Front:

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooflop

The UIC / Chassis frame / Body Structure affected due


in Regn:

12

c.c. 1548

A/C Insured / Std

T/Rvlin: Insured / Std



3 days

Date/Time, File Pass to:

Date/Time, File Return to:

21

Report Format: DAR

Lump Sum / I.B. / 12

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weigh-and (\$

Survey Fee:

Transportation

) S.R. 24

) Insur

) Labor

) Other

Total

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019 Edit Reg		08 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: **GOLDBELL CAR RENTAL PTE LTD**, Co. Reg. No.: 200710651D

Main Claimant: **F&A TRADING**

Vehicle Reg. No.: GBC4238R	Date of Loss: 01/07/2019 00:00 - :59
Claim Type: TP / 4743532597SG	Policy/Cover Note No.: (Comprehensive)
Vehicle Reg. No. (Insured): SLZ9291M	Policy No. (Claimant):
Excess:	

Repairer: **Elites Performance (HQ)** 51 DEFU LANE 9, 539291 Defu Lane - Tel:

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Loh, Chee-Heng**] Chee-Heng.Loh@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... **[Final Rpt due 17/07/2019]**

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (09/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments Admin A

Cc:

Sent: 7/8/2019 2:20:47 PM

Attachments: 10807-GIA report of GBC4238R(new).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards,

Lee Ying

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Yvonne [<mailto:yvonne@ealc.com.sg>]

Sent: Monday, July 08, 2019 12:15 PM

To: Hor, Yinrul; AIG SGP, Claims-Survey

Cc: Fong, Andy-SY; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Chin, Lee-Ying

Subject: [EXTERNAL] [PRI] AIG Insured SLZ9291M [EAL.2019.6385.MK.ya - GBC4238R]

This message is from an external sender; be cautious with links and attachments.

Our ref : 2019 6385.MK.ya - GBC4238R

Your ref : SLZ9291M

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd

Vehicle **GBC4238R** inspected as follows by Name:

Before repair

Parts removed

After repair

Signature

Signature

Signature

Date/ Time:

Date/ Time:

Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: F&A TRADING

ACCIDENT INVOLVING GBC4238R & SLZ9291M ON 01 JULY 2019 ALONG BLOCK 297 PUNGGOL CENTRE PUNGGOL GROVE AT ABOUT 1800 HOURS

We refer to the above matter wherein we are instructed to act for **F&A TRADING**, the owner of vehicle no. **GBC4238R**.

Further to your email dated 7/8/2019 11:39:05 AM (copy enclosed), there is no agreement to the surveyors proposed by parties.

Our client's vehicle GBC4238R is available as follows, **please call prior appointment** for the pre-repair inspection:

M/s Elites Performance
No. 51 Defu Lane 9,
Singapore 539291
Tel: 90999558 (Mr Calvin)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Yvonne
Sent: Monday, 8 July 2019 10:40 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Subject: AIG Insured SLZ9291M [EAL.2019.6385.MK.ya - GBC4238R]

Our ref : 2019.6385.MK.ya - GBC4238R
Your ref : SLZ9291M

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **SLZ9291M**
Goldbell Car Rental Pte Ltd
10 Raeburn Park
#02-01
Singapore 088702

Dear Sir/Madam,

CLAIMANT: F&A TRADING

ACCIDENT INVOLVING GBC4238R & SLZ9291M ON 01 JULY 2019 ALONG BLOCK 297 PUNGGOL CENTRE PUNGGOL GROVE AT ABOUT 1800 HOURS

We are instructed by F&A TRADING to notify you (the insurer of **SLZ9291M**) of a road traffic accident on **01 JULY 2019 ALONG BLOCK 297 PUNGGOL CENTRE PUNGGOL GROVE AT ABOUT 1800 HOURS** involving our client's vehicle registration number **GBC4238R** and vehicle registration number **SLZ9291M** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **GBC4238R** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. How Andrew (Prominent Appraiser Services)

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2019 14:21
Date Of Accident	01/07/2019 18:00
Exact Location Of Accident	BLOCK 297 PUNGGOL CENTRE PUNGGOL GROVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4238R
Insured/Policyholder	
Name Of Registered Owner	F&A TRADING
Co Reg No	53398346X
Email Address	BLACK18SKIN@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98363411

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO CARGO MAXI-1.6 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110007161
Cover Note Number	11/06/2019 TO 10/06/2020

Driver

Name of Driver	TAN DE XUN AARON
NRIC No	S9350283C
Date Of Birth	25/04/1993
Occupation	OUTDOOR
Date Of Driving Pass	04/04/2013
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98363411
Fax Number	
Contact Number	
EMail Address	BLACK18SKIN@GMAIL.COM

Address	BLOCK 297 PUNGGOL CENTRAL #16-481
Postcode	820297
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : BRIANA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report: F/20190702/2033

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ9291M
Vehicle Make/Model/Colour	
Details Of Properties	SALOON CAR
Vehicle Category	PRIVATE CAR
Name of Driver	LOI CHIN PHENG
NRIC/Passport Number	
Contact Number	9791 8198

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/07/19 15:40/12

Reporting Centre Personnel's Signature
Name: Lum Wei Sheng
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report - F/20190702/2033

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02/07/19 01:54pm

Reporting Centre Personnel's Signature
Name: Lam Wai Shun
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



F/20190702/2033

1 of 2

POLICE REPORT (NP299)

Report No. F/20190702/2033

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Date/Time Report Made 02/07/2019 11:49	Vide Report No.	Station Diary No. 46
Name Of Informant TAN DE XUN AARON	Address APT BLK 297 PUNGGOL CENTRAL #16-481 SINGAPORE 820297	
ID Type / ID No. NRIC NO / S9350283C	Contact No. Home/Office	Mobile 98363411
Nationality SINGAPORE CITIZEN	Email Address	
Occupation FREELANCE DELIVERY	Sex Male	Age 26
Institution/School Name	Date of Birth 25/04/1993	Race Chinese
Date/Time Of Incident 01/07/2019 18:00	Location Of Incident APT BLK 297 PUNGGOL CENTRAL PUNGGOL GROVE SINGAPORE 820297	

Brief details.

On 01/07/2019 at about 1800hrs, I was driving my vehicle bearing registration plate number GBC4238R and I exited from the loading bay. I stopped at the stop line and suddenly felt an impact from the rear, I went down my car and realized that one vehicle of registration plate number SLZ9291M had hit onto my vehicle right rear bumper. The driver has exited the round about and hit onto my vehicle which caused my vehicle to inch forward. There were some scratches and slight dent at the rear bumper. The rim of the wheel had also came off.

Signature Of Officer Recording The Report: F / Sgt 3 CHUA KAI LING	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/07/2019 11:49
Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Staff Sgt SHAHRIL RASHIDI BIN SADLI Contact No.: 64849999	Classification Of Case:

Authentication Stamp



SINGAPORE
POLICE FORCE



F/20190702/2033

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190702/2033

We exchange our particulars. The other party is Loi Chin Pheng, HP: 97918198 and we discuss to settle the matter privately.

I am lodging this report for my own record purpose.

Signature Of Officer Recording The Report:

F / Sgt 3 CHUA KAI LING

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt SHAHRIL RASHIDI BIN SADLI
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
02/07/2019 11:49

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8346X
Vehicle Details	
Vehicle No.:	GBC4238R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2019
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6MJ SMT TURBO 6DR
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	263A50006744890
Chassis No.:	ZFA26300009147020
Maximum Power Output:	-
Open Market Value:	\$22,184.00
Original Registration Date:	26 Apr 2012
First Registration Date:	26 Apr 2012
Transfer Count:	2
Actual ARF Paid:	\$1,110.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,989.00
COE Rebate Amount:	\$15,041.00
Total Rebate Amount:	\$15,041.00

The information contained herein is correct as at 12 Jul 2019

OK

VAN / TRUCK (Rear)

Vehicle No: **GBC 4238R**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993676	Rear Number Plate			
1138	993677	Rear Number Plate Base			
2044	993678	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT	✓	
1142	993408	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side <i>clip</i>	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	995165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel	RH	CUT R	
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	BT	✓	
1236	994025	Rear RH Rim Cover	BR	✓	
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		Rear RH wheel bearing			
		Fender shield		CUT	

9/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)






CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jul 2019 Edit Reg		08 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: GOLDBELL CAR RENTAL PTE LTD , Co. Reg. No.: 200710651D									
Main Claimant: F&A TRADING									
Vehicle Reg. No.: GBC4238R		Date of Loss: 01/07/2019 00:00 - :59 [86 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4743532597SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLZ9291M		Policy No. (Claimant):							
		Excess:							
Repairer: Elites Performance (HQ) 51 DEFU LANE 9, 539291 Defu Lane - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (09/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC4238R (4743532597SG)
[SLZ9291M]
TP
F&A TRADING
Jul 1 2019 12:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Elites Performance

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	08/07/19 18:12	General View														Load JPG		
2	08/07/19 18:12	General View														Load JPG		
3	08/07/19 18:12	General View														Load JPG		
4	08/07/19 18:12	General View														Load JPG		
5	08/07/19 18:12	General View														Load JPG		
6	08/07/19 18:12	General View														Load JPG		
7	08/07/19 18:12	General View														Load JPG		
8	08/07/19 18:12	General View														Load JPG		
9	08/07/19 18:12	General View														Load JPG		
10	08/07/19 18:12	General View														Load JPG		
11	08/07/19 18:12	General View														Load JPG		
12	08/07/19 18:12	General View														Load JPG		
13	08/07/19 18:12	General View														Load JPG		
14	08/07/19 18:12	General View														Load JPG		
15	08/07/19 18:12	Odometer Reading														Load JPG		
16	08/07/19 18:12	Chassis Number														Load JPG		
17	08/07/19 18:12	General View														Load JPG		
18	08/07/19 18:12	General View														Load JPG		
19	08/07/19 18:12	General View														Load JPG		
20	08/07/19 18:12	General View														Load JPG		
21	08/07/19 18:12	General View														Load JPG		
22	08/07/19 18:12	General View														Load JPG		
23	08/07/19 18:12	General View														Load JPG		
24	08/07/19 18:12	General View														Load JPG		
25	08/07/19 18:12	General View														Load JPG		
26	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
27	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
28	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
29	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
30	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
31	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
32	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
33	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
34	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		
35	12/07/19 16:44	Photographs of Damaged Parts														Load JPG		

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	12/07/19 16:44	Photographs of Damaged Parts	 Load JPG	✓
37	12/07/19 16:44	Photographs of Damaged Parts	 Load JPG	✓
38	12/07/19 16:44	Photographs of Damaged Parts	 Load JPG	✓
39	12/07/19 16:44	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/19 09:15	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19011998/ECF3S2
Date: 19/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBC4238R **Insured Vehicle No :** SLZ9291M
Date of Loss: 01/07/2019 **Nature of Claim:** TP **Claim No:** 4743532597SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC4238R**
 Make & Model: FIAT DOBLO CARGO MAXI, 1.6 (M) Engine No: 263A50006744890
 Reg. Date: 26/04/2012 (Man. Year: 2011) Chassis No: ZFA26300009147020
 Colour: Silver Odometer: 121290 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R16 Rear Tyre Size: 225/60R16
 Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
 Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/07/2019
 Date Inspected: 08/07/2019 Inspected At: Elites Performance (HQ)
 51 DEFU LANE 9
 Singapore 539291
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIP	Necessary	0.00 F	*- F
3	1		*REAR BODY PANEL RH	Repair	0.00 F	*- F
4	1		*REAR RH WHEEL RIM	Bent	0.00 F	*- F
5	1		*REAR RH RIM COVER	Broken	0.00 F	*- F
6	1		*REAR RH WHEEL BEARING	Jammed	0.00 F	*- F
7	1		*REAR RH FENDER INNER SHIELD	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >