Our Ref	:
Your Ref:	
Date	

T 0719 /3HA7681M /KS(st)

9-Jul-19



AIG Building

CDGE Taxi Claims Dept 59 Loyang Drive 4th Floor

Sub Total: \$ 6,202.54

7

pcs.

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Workshops

Braddell

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Wa Singapore 728791

Yishun 501 Yishun Industrial Park A Singapore 768732

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way

WITHOUT PREJUDICE

Singapore 079120

Attn: Motor Claims Department

Dear Sir

#07-16

ACCIDENT INVOLVING OUR TAXI SHA7681M YOUR INSURED SMG4227X AND OTHER ON 04.07.19

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle NoSHA7681M which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SMG4227X** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 4,922.00
2	7.5days Loss of Rental @_\$ 169.74 per day	\$ 1,273.05
3	Survey Report Fees (Surveyed by M/s LKK)	\$ _
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$
6	Towing / Medical / Transporation	\$

HIRER'S CLAIM

7	7.5	_lays Loss of Income @ \$	80.00	per days	\$ 600.00
				Total Claims:	\$ 6,802,54

We enclose herewith the following documents to support the claims: -

a) Original repair bill and photocopies of photographs: b)

LTA search slip/s of: SMG4227X c) GIA / Police report/s of : SHA7681M

d) Letter of authority from owner / hirer / operator

(X) Photograph/s of Accident Scene

() Certificate of Insurance () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel : 6214 8736 Fax : 6214 Email : kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

COMFORTDELGRO







LETTER OF AUTHORISATION

(NAF / PAF)

ALONG

ACCIDENT INVOLVING MERCEDES E220 SHA7681M , SMG4227X

ON 04-Jul-19 17:40 PIE TWDS CHANGI ON JALAN ANAK BUKIT FLYOVER

I / We

NGIAM CHONG TECK (Y... (Hirer) NRIC No.: SXXXX904E

and/or

(Relief) NRIC No.: SXXXX904E

Taxi Number

SHA7681M

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

05-Jul-2019

Name of Hirer

NGIAM CHONG TECK (YAN CHONGDE)

Hirer NRIC

SXXXX904E

Signature:

Address

210 CHOA CHU KANG CENTRAL #11...

680210

Contact No.

93271020



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

801.0004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.AIG BUILDING #07-16 SINGAPORE 079120

CONTACT NO: 64193000

3225094

SHA7681M

Workshops

NO/DATE 91454862 12.07.2019

MAKE MERCEDES BENZ

132 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

M()1)KI, E220CDI(E6) OIXMETER READING

DATE OF REG 13.05.2015

CHASSIS CODE WDD2120012B171365

JOB TYPE

Description: 3P 04.07.2019

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt Add GST @ 7.000 %

4,600.00

Total Invoice amount

4,922.00

Issued by : KATHERINETAN 12
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days : KATHERINETAN 12.07.2019 15:03:19

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No.

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19070112

Date: 12 July 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

04/07/2019 @ 17:40 hrs

ALONG

PIE TWDS CHANGI ON JALAN ANAK BUKIT FLYOVER

INVOLVING

SMG4227X

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA7681M (the "Taxi"). The Taxi was hired to NGIAM CHONG TECK (YAN CHONGDE) IC NO S7406904E a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$169.74 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	HOURS OPERATED (TIME)	FROM TO	(855	- 1007				
	MILEAGE	(KM)	(N	OMT				
DERATED (TIM	2	04:0/19 According	(1.07.19) Raport 12					

Enquire Vehicle Insurance Details

Vehicle No. Incident Date/Time

SMG4227X 04 Jul 2019 / 17:40:00

Successful

A04

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

SHA7681M































