

AND REC. BY:

REF: CS/ALG/10/2021 / Ktf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

• Member

From (Person): chin lee ying

of ALG

Date/Time: 8/7/19 @ 3.51pm

Estimated Cost:

Bill to:

OD / PIP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 4227X

Insured:

at Workshop n/s

Lea Hui Meng Kee

Tel:

64538110

of

160 Sin Ming Drive #04-01

Policy No:

Claim No:

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A

4/7/2019

(Client's Record)

9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 102pm @ 8/7/19

Person Contacted:

jenny

Vehicle: IN/OUT

Date/Time	Action/Instruction
	Vehicle ✓
	SMG 4227X - Call Maigui/19/19/19/hb3
8/7 @ 2.23pm	inform Dabra authorise repair
6/8	6576.65 Confirm by email (Ref: 323; 4%)

ASS. REC. BY:

REF: MG

CS/AIG/90/2021/K43

ASSIGNMENT

From: _____ Date: 9/7/19

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 4227X

at Workshop m/s: Tai Huent Mung Kee

of 160 Sn Ming Drive # 04-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Munning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 89dk

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMG 4227X Yr Regn: 12 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon 1685

Make: Kip Cars CC

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 48660 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA14U815VJ7211460

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front Rear

R/Bal. 7 mm R/Bal. 6 mm

L/Bal. 7 mm L/Bal. 6 mm

D.O.A. 4/7/19 D.O.I. 9/7/19

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 AUG 2019

13/8/2019

Date/Time, File Pass to?

1) 13/8 Typist

Date/Time, File Return to?

2) _____

Report Format: OD

Lump Sum / I.B.I: 6576.65

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee: 700

Transportation: S + RS \$ _____

Photos 11

Others _____

TOTAL 711

Nivitha (LKK Auto)

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Monday, 8 July 2019 3:51 PM
To: assignments; Admin A
Subject: Request for Survey (OD) SMG4227X - Kia Carens (Date of Accident: 04.07.2019)

Hi LKK,

Kindly assist to survey, will assign case to LKK in Merimen later.

Thanks.

Best Regards

Lee Ying Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel + (65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Monday, July 08, 2019 3:31 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Request for Survey (OD) SMG 4227X - Kia Carens (Date of Accident: 04.07.2019)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We refer to the above matter.

Please arrange to survey our client's vehicle no. SMG 4227X?

The vehicle is in workshop and supporting documents have uploaded in Merimen.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or

- printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5055D
Vehicle Details	
Vehicle No.:	SMG4227X
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	D4FDJD025917
Chassis No.:	KNAHU815VJ7211460
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$20,088.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$20,124.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2028
PARF Rebate Amount:	\$15,093.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$30,211.00
Total Rebate Amount:	\$45,304.00

The information contained herein is correct as at 09 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/07/2019 10:21
 Date Of Accident 04/07/2019 17:40
 Exact Location Of Accident PIE TOWARDS PASIR RIS
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG4227X
Insured/Policyholder
 Name Of Registered Owner BIS MOTORING PTE LTD
 Co Reg No 201735055D
 Email Address DENNIS.DENG@MUNICHAUTO.COM.SG
 Mobile Phone No (LOCAL) +65-96826300
 Alternative Phone No OFFICE-96826300

Vehicle Particulars

Manufacturer KIA
 Model CARENS 1.7 DCT DIESEL 5DR FWD

Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number 999994322
 Cover Note Number

Driver

Name of Driver SEOW KIAN SENG
 NRIC No S1195174J
 Date Of Birth 18/11/1955
 Occupation OUTDOOR
 Date Of Driving Pass 08/01/1974
 Driving Experience 45 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-86184940
 Fax Number
 Contact Number
 Email Address DENNIS.DENG@MUNICHAUTO.COM.SG

Address	BLK 11 PINE CLOSE #12-115
Postcode	391011
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

The incident happened on Thursday 4/7/2019 at about 5.40pm. I was driving along the PIE towards Pasir Ris when vehicle no. SHA 7681M stopped suddenly. I could not stop in time and collided into the back of vehicle no. SHA 7681M.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7681M
Vehicle Make/Model/Colour	MERCEDES BENZ / WHITE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	NGIAM CHONG TECK (YAN CHONGDE)
NRIC/Passport Number	S7406904E
Contact Number	94393588
Address	BLK 210 CHO A CHU KANG CENTRAL #11-172
Postcode	680210
Insurance Company Name	
Nature Of Damage	

- No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN PASSENGER

Approximate Age

Injuries Sustain CUT LIPS

Injured person in which vehicle? SMG4227X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 5 JUL 2019

Reporting Centre Personnel's Signature
Name: Deborah Lai
NRIC/FIN No.: S7332811Z

SHA 7681M

B A SMG 4227X

The Incident happened on Thursday 4/7/2019 at about 5.40 pm.

I was driving along the PIE towards Passir Ris when vehicle no. SHA 7681M stopped suddenly. I could not stop in time and collided into the back of vehicle no. SHA 7681M.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: Deborah Lai
NRIC/FIN No.: S7332811Z

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S1195174J**

Name **SEOW KIAN SENG**

DOB Date **18 Nov 1955**

Issue Date **19 Apr 2013**

0021712960

REPUBLIC OF SINGAPORE

IDENTITY CARD NO **S1195174J**

Name **SEOW KIAN SENG**

籍 建 成

Race **CHINESE**

Issuing State **18-11-1955** Sex **M**

Country of Birth **SINGAPORE**

Land Transport Authority

VOCATIONAL LICENCE

Licence No **S1195174J**

Name **SEOW KIAN SENG**

Issue Date **30/6/2011**

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	21 May 1974
Class 2A	Motorcycles between 201 cc and 400 cc	21 May 1974
Class 2	Motorcycles > 400 cc	21 May 1974
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	05 Jan 1974
Class 4	*Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg	14 Sep 1977
	*Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	
Class 5	Motor vehicles not constructed to carry any load and the unladen weight > 7250kg	01 Mar 1978

NP 423A



0724488

S1195174J

APR 12 2013

APT BLK 11 PINE CLOSE #12-11E
SINGAPORE 361011

S1195174J 23-08-2002 4251089

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
03	BUS VI	25/06/2003
02	TAXI VI	21/04/1997
04	BUS ATTENDANT	25/06/2003





HOTLINE TEL: (65) 6419-3000

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1968

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M 2.400

(The below excess is subject to GST)

COMPREHENSIVE	COMMERCIAL MOTOR	POLICY EXCESS	S\$1500.00 (Sect I & Sect II)
CERTIFICATE NO.	SMG4227X	WINDSCREEN EXCESS	S\$100.00
POLICY NO.	999904322		

1) VEHICLE REGISTRATION NO.	SUM INSURED	Market Value
2) NAME OF INSURED	INSURING WITH COE/PARF	YES
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	SMG4227X	
4) DATE OF EXPIRY OF INSURANCE	BIS MOTORING PTE LTD	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*	26 December 2018	
	25 December 2019	

Any person who is driving on the Insured's order or with their permission.

Authorized driver must be between age 21 to 65 with at least 2 years driving experience.

Accident repair can be carried out at Munich Auto Care in the condition that all repairs have to be surveyed, appointed by AIG surveyors before proceeding with repair.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

- 1) Use for social, domestic, pleasure purposes and business purposes of insured
- 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.
- 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.

LOSS OF USE Not Included

HIRE PURCHASE COMPANY HONG LEONG FINANCE

*Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 28 Dec 2018

AIG Asia Pacific Insurance Pte. Ltd.

500656-000
Cowell Insurance (Agency) Pte. Ltd.
8 Burn Road
#09-09 Trivex
Singapore 369977

AUTHORISED REPRESENTATIVE

SSPOEC

ORIGINAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5055D

Vehicle Details

Vehicle No.: SMG4227X

Vehicle to be Exported: No

Intended Deregistration Date: 05 Jul 2019

Vehicle Make: KIA

Vehicle Model: CARENS 1.7 DCT DIESEL 5DR FWD

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: D4FDJD025917

Chassis No.: KNAHU815VJ7211460

Maximum Power Output: 104.0 kW (139 bhp)

Open Market Value: \$20,088.00

Original Registration Date: 19 Dec 2018

First Registration Date: 19 Dec 2018

Transfer Count: 0

Actual ARF Paid: \$20,124.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Dec 2028

PARF Rebate Amount: \$15,093.00

Intended COE Rebate Details

COE Expiry Date: 18 Dec 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$32,001.00

COE Rebate Amount: \$30,246.00

Total Rebate Amount: \$45,339.00

The information contained herein is correct as at 05 Jul 2019

OK



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : Seow Kian Seng
VEHICLE NUMBER : SMG 4227X
DATE/ TIME OF ACCIDENT : 4/7/2019 ; 1740 Hours
PLACE OF ACCIDENT : PIE towards Pasir Ris
THIRD PARTY VEHICLE (IF ANY) : SHA 7681M

.....
WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

From 2 Pandan Loop heading towards Pasir Ris Drive 1.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

No, I did not.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Head to rear collision.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

Yes, my passenger suffered a small cut on the lip. Not conveyed to hospital and I was not taken to the Traffic Police for investigation.

NAME: Seow Kian Seng

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: AIG Asia Pacific Insurance Pte. Ltd. (SG)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	70664
Policy No:	999994322	Date of Loss:	04/07/2019
Vehicle Reg. No.:	SMG4227X	Driveable?	
Driver Age/Info:	63 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD	Contact No:	+6596826300
Driver:	SEOW KIAN SENG		

Make/Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Vehicle Reg. Date:	19/12/2018
Vehicle Colour:	Red		
Engine No:	D4FDJD025917	Chassis No:	KNAHUB15VJ7211460
Odometer:	48660 KM		

Paint Type:

Total Loss?

Est. Duration of Repair (day) *NO 7 days*

*For Notarise
Munir Bt paim
Ex TBA
Fax 62564315*

Description of Accident/Loss THE INCIDENT HAPPENED ON THURSDAY 4/7/2019 AT ABOUT 5.40PM. I WAS DRIVING ALONG THE PIE TOWARDS PASIR RIS WHEN VEHICLE NO. SHA 7681M STOPPED SUDDENLY. I COULD NOT STOP IN TIME AND COLLIDED INTO THE BACK OF VEHICLE NO. SHA 7681M.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / VICTOR FAN

COST OF CLAIMS

	Amount
Parts	3,747.70
Miscellaneous Items	46.00
Labour	1,020.00
Paintwork Labour	1,300.00
Towing	0.00
Gross Total (S\$)	6,113.70
+ GST 7.00% (S\$)	427.96
Nett Amount (S\$)	6,541.66

This claim is handled by: VICTOR FAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jul 2019)
Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMG4227X/08/07/2019 15:29
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front bonnet	0.00	0.00	A ₇ *320.00 F	—
2	1		*Front bonnet hinge LH	0.00	0.00	D11 *22.00 F	—
3	1		*Front bonnet hinge RH	0.00	0.00	D11 *22.00 F	—
4	1		*Front headlamp LH	Mgcm 0.00	0.00	*680.00 F	—
5	1		*Front headlamp RH	u 0.00	0.00	*680.00 F	—
6	1		*Front bumper	CM 0.00	0.00	*300.00 F	—
7	1		*Front bumper sponge	CM 0.00	0.00	*50.00 F	—
8	1		*Front bumper reinforcement	A ₁ 0.00	0.00	*220.00 F	—
9	1		*Front bumper lower grille	D11 0.00	0.00	*120.00 F	—
10	1		*Front radiator grille	CM 0.00	0.00	*210.00 F	—
11	1		*Front radiator	1 hour CM 0.00	0.00	*320.00 F	—
12	1		*Front radiator top cover	CM 0.00	0.00	*35.00 F	—
13	1		*Front fog lamp cover RH	RJ 0.00	0.00	*58.00 F	—
14	1		*Front KIA emblem	RM 0.00	0.00	*40.00 F	—
15	1		*Front support panel	0.00	0.00	CM *300.00 F	—
16	1		*Radiator coolant (4 litres)	0.00	0.00	RM *30.00 F	—
Sub Total (S\$)						3,407.00	
+ Margin on L,N Items 10.00% (S\$)						340.70	
Total Parts (S\$)						3,747.70	

F=Franchise part

Lai Huat (Meng Kee) Motor Pte Ltd/SMG4227X/08/07/2019 15:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front number plate	35.00
2	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			46.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (including blend of front door LH & RH)	New	1,300.00
<u>Labour Items</u>			
2	To remove + refix air con condenser and refill gas	New	120.00
3	To straighten front body, to knock dents on windscreen side frame and renew of parts	New	900.00
Gross Labour Cost (S\$)			2,320.00

Lai Huat (Meng Kee) Motor Pte Ltd/SMG4227X/08/07/2019 15:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SUPPLEMENTARY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2019)
 Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMG4227X/01/08/2019 12:55
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front fender LH	0.00	0.00	Bu	*165.00 F —
2	1		*Front fender RH	0.00	0.00	Bu	*165.00 F —
3	1		*Air filter box air duct	0.00	0.00	nd	*38.00 F —
4	2		*Radiator top cover clips	0.00	0.00	nd	*3.00 F —
5	5		*Front bumper lower clips	0.00	0.00	nd	*7.50 F —
6	1		*Air guide RH	CM	0.00	nd	*18.00 F —
7	1		*Radiator fan assy	0.00	0.00	CM	*280.00 F —
8	1		*Front headlamp bracket LH	0.00	0.00	CM	*10.00 F —
9	1		*Front headlamp bracket RH	0.00	0.00	CM	*10.00 F —
10	1		*Front air duct	0.00	0.00	nd	*18.00 F —

F=Franchise part.

Sub Total (S\$)	714.50
+ Margin on L,N Items 10.00% (S\$)	71.45
Total Parts (S\$)	785.95

Lai Huat (Meng Kee) Motor Pte Ltd/SMG4227X/01/08/2019 12:55. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

63926

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO:M2-0072042-3 CO. REG NO: 198502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113549

Page:1

A/C CODE: 3L01

DATE: 09 Jul 2019

TERMS: 60Days

SALESMAN: 0007

M/S : LAI HUAT (MENG KEE) MOTOR PTE LTD

160 SIN MING DRIVE#04-01 (OFFICE)

SIN MING AUTOCITY #04-02 & #07-03

SINGAPORE 575722

SMG 4227X

VICTOR ORDER

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
1	ZZ66400-A4000	RCR	1	320.00		320.00✓
2	ZZ79110-A4000	RCR	1	22.00		22.00✓
3	ZZ79120-A4000	RCR	1	22.00		22.00✓
4	ZZ92101-A4160	RCR	1	680.00		680.00✓
5	ZZ92102-A4160	RCR	1	680.00		680.00✓
6	ZZ86511-A4800	RCR	1	300.00		300.00✓
7	ZZ86520-A4800	RCR	1	50.00		50.00✓
8	86530-A4000	RWH	1	220.00		220.00✓
9	ZZ86561-A4810	RCR	1	120.00		120.00✓
10	ZZ86350-A4810	RCR	1	210.00		210.00✓
11	ZZ25310-A4560	RCR	1	320.00		320.00✓
12	ZZ86366-A4000	RCR	1	35.00		35.00✓

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO:M2-0072042-3 CO. REG NO: 198502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113549

Page:2

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
13	86522-A4810	RCR	1	58.00		58.00✓
14	ZZ86320-A4000	RCR	1	40.00		40.00✓
15	ZZ64101-A4000	RCR	1	300.00		300.00✓

TOTAL SIN 3,377.00

ADD GST @ 7% 236.39

GRAND TOTAL SIN 3,613.39

CONFIRMED & ACCEPTED BY
Received in Good Order & Condition
Goods Sold Are Not Returnable

E. & O. E.

SOLD BY LING

Original/0007/09/07/2019 2:46:35 PM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-3 CO. REG NO: 198502696R

62 RACE COURSE ROAD SINGAPORE 218568

TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113572

Page:1

A/C CODE: 3L01

DATE: 11 Jul 2019

TERMS: 60Days

SALESMAN: 0007

M/S: LAI HUAT (MENG KEE) MOTOR PTE LTD

160 SIN MING DRIVE#04-01 (OFFICE)

SIN MING AUTOCITY #04-02 & #07-03

SINGAPORE 575722

SMG 4227X

VICTOR ORDER

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
1	ZZ28210-A4000	RCR	1	38.00		38.00✓
2	86595-2T500	RCR	2	1.50		3.00✓
3	86590-28000	RCR	5	1.50		7.50✓

TOTAL SIN 48.50

ADD GST @ 7% 3.40

GRAND TOTAL SIN 51.90

CONFIRMED & ACCEPTED BY

Received in Good Order & Condition
Goods Sold Are Not Returnable

E. & O. E.

SOLD BY LING

Reprint:1/0007/11/07/2019 3:54:45 PM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-3 CO. REG NO: 198502696R

62 RACE COURSE ROAD SINGAPORE 218568

TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113559

Page:1

A/C CODE: 3L01

DATE: 10 Jul 2019

TERMS: 60Days

SALESMAN: 0007

M/S: LAI HUAT (MENG KEE) MOTOR PTE LTD

160 SIN MING DRIVE#04-01 (OFFICE)

SIN MING AUTOCITY #04-02 & #07-03

SINGAPORE 575722

SMG 4227X

VICTOR ORDER

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
1	ZZ66311-A4000	RCR	1	165.00		165.00✓
2	ZZ66321-A4000	RCR	1	165.00		165.00✓

TOTAL SIN 330.00

ADD GST @ 7% 23.10

GRAND TOTAL SIN 353.10

CONFIRMED & ACCEPTED BY

Received in Good Order & Condition
Goods Sold Are Not Returnable

E. & O. E.

SOLD BY LING

Reprint:1/0007/10/07/2019 1:25:42 PM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO:M2-0072042-3 CO. REG NO: 198502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113565
A/C CODE: 3L01
DATE: 11 Jul 2019
TERMS: 60Days

Page:1

M/S : LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE#04-01 (OFFICE)
SIN MING AUTOCITY #04-02 & #07-03
SINGAPORE 575722

SALESMAN: 0007

SMG 4227X
VICTOR ORDER

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
✓ 86551-A4000	BRACKET LH/H LAMP LOW	RCR	1	10.00		10.00 ✓
✓ 86552-A4000	BRACKET RH/H LAMP LOW	RCR	1	10.00		10.00 ✓
✓ 28221-A4100	DUCT--AIR	RCR	1	18.00		18.00 ✓

TOTAL **SIN 38.00**

ADD GST @ 7% 2.66

GRAND TOTAL **SIN 40.66**
CONFIRMED & ACCEPTED BY

Received in Good Order & Condition
Goods Sold Are Not Returnable

E. & O. E.


SOLD BY LING

Original/0007/11-07-2019 9:33:02 AM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO:M2-0072042-3 CO. REG NO: 198502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0113568
A/C CODE: 3L01
DATE: 11 Jul 2019
TERMS: 60Days

Page:1

M/S : LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE#04-01 (OFFICE)
SIN MING AUTOCITY #04-02 & #07-03
SINGAPORE 575722

SALESMAN: 0007

SMG 4227X
VICTOR ORDER

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
1 29134-A4000	GUARD-AIR RH	RCR	1	18.00		18.00 ✓
2 ZZ25380-A4510	FAN ASSY	RCR	1	280.00		280.00 ✓

TOTAL **SIN 298.00**

ADD GST @ 7% 20.86

GRAND TOTAL **SIN 318.86**
CONFIRMED & ACCEPTED BY

Received in Good Order & Condition
Goods Sold Are Not Returnable

E. & O. E.


SOLD BY LING

Reprint:2/0007/11-07-2019 11:47:49 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jul 2019 15:15 Sendback Est	08 Jul 2019 15:29 S\$6,113.70	09 Jul 2019 11:09 Edit Adj Rpt	S\$6,576.65 Edit Estimates	S\$6,576.65 View Rpt		Pending for Survey Report Cancel Case
	01 Aug 2019 12:54	01 Aug 2019 12:55 S\$785.95	01 Aug 2019 12:55			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D, Tel: +6596826300		
Vehicle Reg. No.:	SMG4227X	Date of Loss:	04/07/2019 17:00 - :59 [6 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1904729659SG	Policy/Cover Note No.:	0999994322 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/07/2019]		
Driver/Custodian:	SEOW KIAN SENG (63 / Male), NRIC: S11951741, Tel: +6586184940 Email: dennis.deng@munichauto.com.sg		
Repair Tracker:	Pending Start Work - 0%		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.














































ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SMG4227X (1904729659SG)
OD
Jul 4 2019 5:00PM
[BIS MOTORING PTE LTD]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print		
1	05/07/19 13:25	Accident Statement		Load HTM			
2	08/07/19 15:29	Repairer Estimates		Load HTM			
3	01/08/19 12:55	Repairer Estimates Suppl. #1		Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print		
1	05/07/19 13:25	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
2	05/07/19 13:25	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
3	05/07/19 13:25	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
4	05/07/19 13:25	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
5	05/07/19 13:25	Chassis Number [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
6	05/07/19 13:25	Accident Scene [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>		
7	08/07/19 15:19	Foto Selesai		Load JPG	<input checked="" type="checkbox"/>		
8	08/07/19 15:19	Front View Left		Load JPG	<input checked="" type="checkbox"/>		
9	08/07/19 15:19	Front View Right		Load JPG	<input checked="" type="checkbox"/>		
10	08/07/19 15:19	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
2	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
3	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
4	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
5	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
6	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
7	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
8	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
9	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
10	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
11	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
12	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
13	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
14	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
15	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
16	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
17	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
18	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
19	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
20	13/08/19 15:59	General View		Load JPG	<input checked="" type="checkbox"/>		
21	13/08/19 15:59	General View		Load JPG			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
22	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
29	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
30	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/08/19 15:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	13/08/19 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	13/08/19 16:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	05/07/19 13:21	Sketch Plan	Load TIF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
		[Linked Accident Report Documents]	1		
2	05/07/19 13:22	Insurance Certificate [Linked Accident Report Documents]	1	Load TIF	
3	05/07/19 13:22	Driver NRIC and Driving Licence [Linked Accident Report Documents]	1	Load TIF	
4	08/07/19 15:28	E-filed GIA report	1	Load PDF	
5	08/07/19 15:28	Driver's NRIC & Driving Licence	1	Load PDF	
6	08/07/19 15:28	Certificate of Insurance	1	Load PDF	
7	08/07/19 15:28	Enquire PARF / COE Rebate for Registered Vehicle	1	Load PDF	
8	08/07/19 15:28	Motor Accident Interview Form	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/08/19 09:38	Supplementary	1	Load PDF	
2	26/08/19 09:38	Parts Invoice	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	05/07/19 13:25	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	05/07/19 13:25	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	05/07/19 13:25	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	05/07/19 13:25	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	05/07/19 13:25	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	05/07/19 13:25	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
6	05/07/19 13:25	Accident Scene	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	05/07/19 13:21	Sketch Plan	1	Load TIF	
2	05/07/19 13:22	Insurance Certificate	1	Load TIF	
3	05/07/19 13:22	Driver NRIC and Driving Licence	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19012021/KTF3E2
Date: 26/08/2019

REFERENCE

Insured/Claimant: BIS MOTORING PTE LTD Policy No: 0999994322
Date of Loss: 04/07/2019 Nature of Claim: OD Claim No: 1904729659SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG4227X**
Make & Model: KIA CARENS; 1.7 D DCT 5DR FWD (A) Engine No: D4FDJD025917
Reg. Date: 19/12/2018 (Man. Year: 2018) Chassis No: KNAHU815VJ7211460
Colour: Red Odometer: 48660 km
Engine Capacity: 1685 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Nexen 7 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 7 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,533.65	4,530.65	3.00	0.07
Miscellaneous Items	46.00	46.00	0.00	0.00
Labour	1,020.00	800.00	220.00	21.57
Paintwork Labour	1,300.00	1,200.00	100.00	7.69
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,899.65	6,576.65	323.00	4.68
+ GST 7.00/7.00% (S\$)	482.98	460.37	22.61	4.68
Nett Amount (S\$)	7,382.63	7,037.02	345.61	4.68

INSPECTION

Date of Assignment: 09/07/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 09/07/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet (WCP)	Bent	320.00 F	*320.00 F
2	1		*Front bonnet hinge LH (WCP)	Distorted	22.00 F	*22.00 F
3	1		*Front bonnet hinge RH (WCP)	Distorted	22.00 F	*22.00 F
4	1		*Front headlamp LH (WCP)	Mtg Cracked	680.00 F	*680.00 F
5	1		*Front headlamp RH (WCP)	Mtg Cracked	680.00 F	*680.00 F
6	1		*Front bumper (WCP)	Cracked	300.00 F	*300.00 F
7	1		*Front bumper sponge (WCP)	Cracked	50.00 F	*50.00 F
8	1		*Front bumper reinforcement (WCP)	Bent	220.00 F	*220.00 F
9	1		*Front bumper lower grille (WCP)	Distorted	120.00 F	*120.00 F
10	1		*Front radiator grille (WCP)	Cracked	210.00 F	*210.00 F
11	1		*Front radiator (WCP)	Housing Cracked	320.00 F	*320.00 F
12	1		*Front radiator top cover (WCP)	Cracked	35.00 F	*35.00 F
13	1		*Front fog lamp cover RH (WCP)	Dented	58.00 F	*58.00 F
14	1		*Front KIA emblem (WCP)	Necessary	40.00 F	*40.00 F
15	1		*Front support panel (WCP)	Cracked	300.00 F	*300.00 F
16	1		*Radiator coolant (4 litres)	Necessary	30.00 F	*30.00 FS
Supplementary #1						
17	1		*Front fender LH (WCP)	Buckled	165.00 F	*165.00 F
18	1		*Front fender RH (WCP)	Buckled	165.00 F	*165.00 F
19	1		*Air filter box air duct (WCP)	Dented	38.00 F	*38.00 F
20	2		*Radiator top cover clips (WCP)	Necessary	3.00 F	*3.00 F
21	5		*Front bumper lower clips (WCP)	Necessary	7.50 F	*7.50 F
22	1		*Air guide RH (WCP)	Cracked	18.00 F	*18.00 F
23	1		*Radiator fan assy (WCP)	Cracked	280.00 F	*280.00 F
24	1		*Front headlamp bracket LH (WCP)	Cracked	10.00 F	*10.00 F
25	1		*Front headlamp bracket RH (WCP)	Cracked	10.00 F	*10.00 F
26	1		*Front air duct (WCP)	Dented	18.00 F	*18.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,121.50	4,121.50
+ Margin on L,N Items 10.00/10.00% (\$\$)	412.15	409.15
Total Parts (\$\$)	4,533.65	4,530.65

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front number plate (BENT)	35.00	35.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			46.00	46.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	To spray paint (including blend of front door LH & RH)	New	1,300.00	1,200.00
Labour Items				
2	To remove + refix air con condenser and refill gas	New	120.00	120.00
3	To straighten front body, to knock dents on windscreen side frame and renew of parts	New	900.00	680.00
Gross Labour Cost (S\$)			2,320.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >