

REPORT

ASS. REC. BY:

REF:

CSL III 19012057/Eyl3⁷²

Special Instruction:

Conveyer:

Steve

ASSIGNMENT (Office)

Minimen

From (Person):

Cabnet wee

of

M

Date/Time:

8/7/2019 9:23am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 1917C

Insured:

SHG 8752A

at Workshop m/s

Car pro Auto

Tel:

93382859

of

8th 6 woodlands Road 3995

Policy No:

MCOM0015

Claim No:

MCT19070049

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:05am 8/7/19

Person Contacted:

Ms-Sire

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

18/9/19 pending estimate from Repurser. Ms-Sire say will email the estimate.

Surveyor *Steve*

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SMH 1917C* Yr Regn: *16/11/2006*
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Toyota Wish* C.C. *1794*
 Colour: *Grey* A/C: Insured / Std / NI / NA
 Sp. Reading: *316356* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *ZNE/0 - 0324720*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *195/65R15*
 R: *"*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Goodride*
 Front R/Bal. *5* mm R/Bal. *5* mm
 L/Bal. *5* mm L/Bal. *5* mm
 D.O.A. *3/7/19* D.O.I. *9/7/19*
 Survey held at *Car Pro*
 Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>19/9/19</i>	<i>Finalize confirm \$4950, 4 days (Si ni) (Redt \$5977-73, 59%)</i>

RECEIVED 20 SEP 2019

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) *19/9/19 Typist*

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others:

) ..

TOTAL

350
11

361

Report Format :

Lump Sum / I.B.I. (\$)

L/S = \$4050f

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 8 July 2019 9:23 AM
To: Cheonghoh Law; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sherini Pillai
Subject: RE: PRS for SMH 1917 C accident involvign vehicle SHC 8752 A on 3 July 2019 at Junction of Steven Road / Steven Drive (Our ref: LCH.lg/W8CPA-90492.19)
Attachments: 0806_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMH1917C and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: 05 July, 2019 4:39 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRS for SMH 1917 C accident involvign vehicle SHC 8752 A on 3 July 2019 at Junction of Steven Road / Steven Drive (Our ref: LCH.lg/W8CPA-90492.19)

Dear Sirs,

We refer to the above matter and your email of 4 July 2019.

Our client hereby nominate LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, Car Pro Auto, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008 for the said survey of SMH 1917 C.

Contact Person : Ms Sini / Jason
Telephone : 9338 2859

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 4 Jul 2019, at 5:21 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

<image001.jpg>

64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: 04 July, 2019 3:14 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: PRS for SMH 1917 C accident involvign vehicle SHC 9752 A on 3 July 2019 at Junction of Steven Road / Steven Drive (Our ref: LCH.lg/W8CPA-90492.19)

Dear Sirs,

We enclosed herewith our letter of PRS and await your urgent reply.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: roaming26@singtel.com.sg
Subject: Attached Image
Date: 4 July 2019 at 3:00:46 PM SGT
To: "mail@cheonghoh" <mail@cheonghoh.sg>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Steve Chen (LKK Auto)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Thursday, September 19, 2019 1:31 PM
To: Steve Chen (LKK Auto)
Subject: Re: SMH1917C

Dear Steve,

Ok to accept.

Thanks

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Wed, Sep 18, 2019 at 6:17 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sini,

Kindly refer our marked estimate.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 13:31
Date Of Accident	03/07/2019 08:20
Exact Location Of Accident	JUNCTION OF STEVEN ROAD AND STEVEN DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH1917C
Insured/Policyholder	
Name Of Registered Owner	UNITED AUTO LEASING PTE LTD
Co Reg No	201630548K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93843368
Alternative Phone No	OFFICE-93843368
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107236872
Cover Note Number	
Driver	
Name of Driver	CHUA SIN LIANG
NRIC No	S1746329B
Date Of Birth	31/07/1966
Occupation	OUTDOOR
Date Of Driving Pass	11/07/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93843368
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 836 YISHUN STREET 81 #04-348
Postcode	2776
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8752A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NR-C/P/R No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I'm moving after I turn out from Steven Drive onto Steven road, the taxi making a U-turn and bang into my side doors, my car already straighten along Steven road. Taxi number plate: SHE 8752A. My Car plate: SMH 1919C.

Accident happen at 3/7/2019 around 0820 am.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Polyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NR/C/SIN No.:

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO:SMH1917C
TOYOTA WISH**

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Estimated by workshop	Disc. (%)	Adjusted cost
1	1pc	Front door (RH) / DD	1515.50 1077/	25	1136.63
2	1pc	Front door outer moulding X NN	245.85	25	184.39
3	1pc	Front window rubber moulding X NN	233.85	25	175.39
4	2pcs	Door window black sticker X NN	170.00	25	127.50
5	1pc	Rear door (RH) / DD	1515.50 1122/	25	1136.63
6	1pc	Rear door outer moulding X NN	245.85	25	184.39
7	1pc	Rear door regulator / DD	383.00 /	25	287.25
8	1pc	Rear door inner trim board / BR	458.90 /	25	344.18
9	1set	Rear door inner trim board clips / APC	38.00 30/	25	28.50
10	1pc	Door window rubber moulding / TN	233.85 /	25	175.39
11	2pcs	Door window black sticker X NN	170.00	25	127.50
12	1pc	Rear bumper X NN	515.00	25	386.25
13	1pc	Rear bumper retainer X NN	32.00	25	24.00
14	1pc	Rear fender RH X R	898.00	25	673.50
15	1pc	Rear fender inner shield X NN	310.00	25	232.50
16	1set	Rear fender inner shield clips X NN	38.00	25	28.50
17	1pc	Rear lower arm X NN	487.00	25	365.25
18	1pc	Rear knuckle arm X NN	345.00	25	258.75
19	1pc	Rear shock absorber X NN	385.00	25	288.75
20	1pc	Rear wheel bearing / Jammed	390.00 /	25	292.50
Total			8610.30		6457.73

SPECIAL NET ITEMS

1	Windscreen sealant X NN	3694.75	60.00
2	Rim (Rear R+L) - CUT	- 25%	350.00 300/
3	Tyre X NN	2771.96	280.00

Repairs

To remove and replaced damaged parts including straightening and repositioning	1200.00 800
Supply paint material and to respray replaced and other affected panels.	950.00 800
To check wiring at the damaged section for proper functions.	50.00 30

Dismantle/refix door components

120.00 100

To carry out anti-rust treatment on affected

80.00 30

To dismantle & refix undercarriage

200.00 150

To perform wheel alignment

80.00 60

To remove & refix side winscreen

120.00 X

To remove & refix reverse sensor

80.00 X

2880.00

1970

Total = \$10027.73

Total

[Signature]
19/9/19

Steve (LKK) wit Arnold 9/7/19

4 days

L/S

Rev AL spy

P- 2771.06

NI- 300

L- 1970

5041.06

L/S - 4032.84

= 4050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19012057/EYF3N2

Date: 26/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SMH1917C Insured Vehicle No: SHC8752A
 Date of Loss: 03/07/2019 Nature of Claim: TP Claim No: MCT19070049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH1917C Engine No: 1ZZ2688931
 Make & Model: TOYOTA WISH, 1.8 (A) Chassis No: ZNE100324720
 Reg. Date: 16/11/2006 (Man. Year: 2006) Odometer: 316356 km
 Colour: Grey
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Goodride 5 mm Rear Left Side: Goodride 5 mm
 Front Right Side: Goodride 5 mm Rear Right Side: Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,147.72	3,071.06	4,076.66	57.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,970.00	910.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,027.72	5,041.06	4,986.66	49.73
Approved Total (Overridden) (S\$)		4,050.00		
Nett Amount (S\$)	10,027.72	4,050.00	5,977.72	59.61

INSPECTION

Date of Assignment: 08/07/2019

Date Inspected: 09/07/2019 Inspected At:

Car Pro Auto (HQ)
 Blk 6 Yew Tee Industrial Estate 399-J,
 Woodlands Road
 Singapore 678008

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2019)	
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMH1917C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR (RH)	Dented	1,515.50 FL	*1,077.00 FL
2	1	*FRONT DOOR OUTER MOULDING	Not Necessary	245.85 FL	*- FL
3	1	*FRONT WINDOW RUBBER MOULDING	Not Necessary	233.85 FL	*- FL
4	2	*DOOR WINDOW BLACK STICKER	Not Necessary	170.00 FL	*- FL
5	1	*REAR DOOR (RH)	Dented	1,515.50 FL	*1,122.00 FL
6	1	*REAR DOOR OUTER MOULDING	Not Necessary	245.85 FL	*- FL
7	1	*REAR DOOR REGULATOR	Dented	383.00 FL	*383.00 FL
8	1	*REAR DOOR INNER TRIM BOARD	Broken	458.90 FL	*458.90 FL
9	1	*SET REAR DOOR INNER TRIM BOARD CLIPS	Necessary	38.00 FL	*30.00 FL
10	1	*DOOR WINDOW RUBBER MOULDING	Torn	233.85 FL	*233.85 FL
11	2	*DOOR WINDOW BLACK STICKER	Not Necessary	170.00 FL	*- FL
12	1	*REAR BUMPER	Not Necessary	515.00 FL	*- FL
13	1	*REAR BUMPER RETAINER	Not Necessary	32.00 FL	*- FL
14	1	*REAR FENDER RH	Repair	898.00 FL	*- FL
15	1	*REAR FENDER INNER SHIELD	Not Necessary	310.00 FL	*- FL
16	1	*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	38.00 FL	*- FL
17	1	*REAR LOWER ARM	Not Necessary	487.00 FL	*- FL
18	1	*REAR KNUCKLE ARM	Not Necessary	345.00 FL	*- FL
19	1	*REAR SHOCK ABSORBER	Not Necessary	385.00 FL	*- FL
20	1	*REAR WHEEL BEARING	Jammed	390.00 FL	*390.00 FL
21	1	*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
22	1	*RIM	Cut	350.00 FS	*300.00 FS
23	1	*TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,300.30	3,994.75
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,152.58	923.69
Total Parts (\$\$)	7,147.72	3,071.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING	New	1,200.00	800.00
2	SUPPLY PAINT MATERIAL AND TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	950.00	800.00
3	TO CHECK WIRING AT THE DAMAGED SECTION FOR PROPER FUNCTIONS	New	50.00	30.00
4	DISMANTLE/REFIX DOOR COMPONENTS	New	120.00	100.00
5	TO CARRY OUT ANTI-RUST TREATMENT ON AFFECTED	New	80.00	30.00
6	TO DISMANTLE & REFIX UNDERCARRIAGE	New	200.00	150.00
7	TO PERFORM WHEEL ALIGNMENT	New	80.00	60.00
8	TO REMOVE & REFIX SIDE WINDSCREEN	New	120.00	0.00
9	TO REMOVE & REFIX REVERSE SENSOR	New	80.00	0.00
Gross Labour Cost (\$\$)			2,880.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >