

22/03/2002

ASS. REC. BY:

REF:

CS8/SMO19012097/TICF302

Special Instruction:

Surveyor: Taufigh**ASSIGNMENT (Office)**From (Person): Hwang Shiang Yi of SMODate/Time: 9.7.19 1258pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLP 9534 RInsured: SLV 2443Pat Workshop in/s Spraysmiths Pte LtdTel: 69090886 / 91111129of 1 Kaki Bukit Ave 6, #01-22Policy No: D18MTPV01018247Claim No: CMTD 1903269

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9.7.19 1.17pmPerson Contacted: Daniel

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLV 2443P: X
	SLP 9534R: X
	Disassemble: 11/7/2019
	After repair: 16/7/2019

ASS. REC. BY:

PRS

ASSIGNMENT

From: Date: 9.7.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 9534R

at Workshop m/s Spraysmiths Rte LTD
of 1 Kati Bukit Ave 6 - #01-22

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP9534R Yr Regn: Jun, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel, c.c 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 52275 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RY31218373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

DS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. D.O.I. 9/7/19 @ 4:15pm

Survey held at Spraysmith

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no GLA.

\$6000 - \$7000, 7 days.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I. (\$))

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

100

60460

11

231

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jul 2019		09 Jul 2019 12:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	NOOR SHAEDAH BINTE DAWOOD, ID: S1580832B																							
Main Claimant:	ABDUL RAHMAN BIN SAID, ID: S1266359E																							
Vehicle Reg. No.:	SLP9534R	Date of Loss:	07/07/2019 14:00 - :59																					
Claim Type:	TP / CMTD1903269	Policy/Cover Note No.:	D18MTPV01018247 (Comprehensive)																					
Vehicle Reg. No. (Insured):	SLU2443P	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Spraysmiths Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6, #01-22, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 69090886																							
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/07/2019]																							
Driver/Custodian (Insured):	BADARUDDIN BIN MOHD IBRAHIM (), NRIC: S1542705A, Tel: +6591191911 Email: -																							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	359E
Vehicle Details	
Vehicle No.:	SLP9534R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	LEB5918382
Chassis No.:	RU31218373
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$30,693.00
Original Registration Date:	22 Jun 2017
First Registration Date:	22 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$37,601.00
Total Rebate Amount:	\$41,351.00

The information contained herein is correct as at 22 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 10:20
Date Of Accident	07/07/2019 14:25
Exact Location Of Accident	TAMPINES ST 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP9534R
Insured/Policyholder	
Name Of Registered Owner	ABDUL RAHMAN BIN SAID
NRIC No	S1266359E
Email Address	OYO08@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98262715
Alternative Phone No	OFFICE-98262715

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00008727
Cover Note Number	

Driver

Name of Driver	ABDUL RAHMAN BIN SAID
NRIC No	S1266359E
Date Of Birth	11/01/1957
Occupation	INDOOR
Date Of Driving Pass	12/03/1979
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98262715
Fax Number	
Contact Number	OFFICE-98262715
EMail Address	OYO08@YAHOO.COM.SG

Address	BLK 345 TAMPINES ST 33 #02-362
Postcode	520345
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JURIAH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU2443P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BAHARUDDIN BIN MOHD IBRAHIM
NRIC/Passport Number	S1542705A
Contact Number	91191911
Address	NA NA
Postcode	NA
Insurance Company Name	

Nature Of Damage NA

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJD1618L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SEAH TSIN PEI CINDY

NRIC/Passport Number S7931460I

Contact Number 85881618

Address NA

Postcode NA

Insurance Company Name

Nature Of Damage NA

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Tampines ST 31.
Traffic light was red so I stopped my
vehicle. Suddenly the vehicle behind me
~~was~~ hit the rear of my vehicle.
~~If~~ then realised that the vehicle was
hit by the vehicle behind him.

DECLARATION

I, HEREBY DECLARE that:-

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.

Name, Signature & Company Stamp (if applicable)

Source: Co.

Vehicle No. _____ Date of Accident _____

- ☐ Reporting Only
☐ Own Damage Claim
☒ Third Party Claim

@ Hanp Automobiles

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1266359E

ABDUL RAHMAN BIN SA'AD

Eye Date: 11 Jan 1957
Valid Date: 07 Feb 2003

0001B3704H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1266359E

Name
ABDUL RAHMAN BIN SA'AD

عبدالرحمن بن سعد
Races
MALAY
Date of Birth
11-01-1957
Country of Birth
SINGAPORE

Sex
M

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Valid Date
Class 2B	Motorcycles not exceeding 200 cc	12 Nov 1980
Class 2A	Motorcycles between 201 cc and 400 cc	06 Jan 2002
Class 2	Motor Cars and Motor Tractors the weight of which (including load) does not exceed 2500 kilograms	12 Mar 1979
Class 4	Heavy Motor Cars and Motor Tractors the weight of which (including load) exceeds 2500 kilograms	04 Feb 1980
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which (including load) exceeds 7250 kilograms	20 Jan 1983

Licence No: S1266359E

S1266359E

S1266359E

Valid Date: 04-02-1994

S1266359E

S1266359E

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

About this policy

About you (As the policyholder)

About your car

Car make and model : HONDA VEZEL 1.5 HYBRID
Year of first registration : 2017
Car plate number : SLP9534R
Issued on: : 12/05/2019

Please immediately inform us at 1-800-862-2323 or email us to carinsurancesummary@hyundai.com if any details in this Car Insurance Summary need to be changed.






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2019		09 Jul 2019 12:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NOOR SHAEDAH BINTE DAWOOD , ID: S1580832B								
Main Claimant:	ABDUL RAHMAN BIN SAID , ID: S1266359E								
Vehicle Reg. No.:	SLP9534R	Date of Loss:	07/07/2019 14:00 - :59 [24 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903269	Policy/Cover Note No.:	D18MTPV01018247 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLU2443P	Policy No. (Claimant):							
		Excess:							
Repairer:	Spraysmiths Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6, #01-22, AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 69090886								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 18/07/2019]								
Driver/Custodian (Insured):	BADARUDDIN BIN MOHD IBRAHIM (), NRIC: S1542705A, Tel: +6591191911 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP9534R (CMTD1903269)
[SLU2443P]
TP
ABDUL RAHMAN BIN SAID
Jul 7 2019 2:00PM
[NOOR SHAEDAH BINTE DAWOOD]
Spraysmiths Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
v	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/07/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	22/07/19 17:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	22/07/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
88	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
89	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
90	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
91	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
92	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
93	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
94	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
95	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
96	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
97	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
98	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
99	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
100	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
101	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
102	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
103	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
104	22/07/19 17:39	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	09/07/19 10:21	Letter from W/S		Load JPG <input checked="" type="checkbox"/>
2	09/07/19 10:21	Third Party E-filed GIA report		Load PDF
3	09/07/19 10:50	PRI - ACK		Load HTM
4	09/07/19 12:58	PRI - LKK (No Consensus)		Load HTM

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19012097/T1CF3E2

Date: 22/08/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01018247

Claimant Vehicle No : SLP9534R

Insured Vehicle No : SLU2443P

Date of Loss: 07/07/2019

Nature of Claim: TP

Claim No: CMTD1903269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP9534R

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: LEB5918382

Reg. Date: 22/06/2017 (Man. Year: 2016)

Chassis No: RU31218373

Colour: Blue

Odometer: 52275 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/07/2019

Date Inspected: 09/07/2019 Inspected At:

 Spraysmiths Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6, #01-22,
 AUTOBAY @ KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9534R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >