

22/03/2002

ASS. REC. BY:

REF: CS/FCI 19012115 ^N Ref 302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Serina

of FCI

Date/Time: 9.7.19 3:14pm

Estimated Cost:

bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 319T

Insured: SHA 1439L

at Workshop m/s Yew Ta Automobile

Tel: 6256 2281

of 39 Woodland close, #01-12

Policy No:

Claim No: D1900 7453 MP5H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.7.19 3:52pm

Person Contacted: Yew Meng

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 1439L CC31AIG15018241/H1pb3q2 D.O.A: 26/10/2015
	STR 319T: X
18/7/19	Email preli revised to FCI
23/7/19	LS \$ 1200 confirmed by email (Red 2870.26, 7170)
Note	mv: \$ 42K (EST) LTA: \$ 25,709 NV: \$ 16,291

REF: FCI

ASSIGNMENT

From: _____ Date: 15. 7. 2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR 319T

at Workshop m/s Yew Tee Automobile

of 37 woodland close #01-12

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 10.30.9.M

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 42K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: SJR 319T Yr Regn: 5 JUN 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA VIOS C.C. 1497

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 173,690 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053H Y9305116311

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/55 R15
R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 5 mm	R/Bal. 6 mm
L/Bal. 5 mm	L/Bal. 6 mm
D.O.A. 4/7/19	D.O.I. 15/7/19

Survey held at YEW TEE AUTOMOBILE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE RENEW 10 YRS EXP 30 APR 2029

STEVE / PLS SEE MY REMARKS

RECEIVED 23 JUL 2019

FCI L/S

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 23/7 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$ 1200/-)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee: 135

Transportation: 50

50+RS, \$ 50450

Photos: 26

Others: _____

TOTAL: 311

MOTOR SURVEY ASSIGNMENT

Date	08-07-2019	Our Ref No. D19004453MFSH
Accident Date	04-07-2019	Claim Type. Third Party
Insured Vehicle	SHA1439L	Third Party Vehicle. SJR319T
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	MS LAI YEE MENG	
Contact No.	62562281/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR \$4,355.18)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 18 July 2019 11:22 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19004453MFSH/1-SJR 319T
Attachments: SJR 319T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJR 319T
Date of survey: 15/7/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 9 July 2019 3:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004453MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 9 July, 2019 3:14 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004453MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 19960719E

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: D19004453MFSH

Our ref: CS/FCI19012115/Evf3

Date : 18/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJR 319T


We thank you for your instruction on 9/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/7/2019 at the premises of M/s YEE TEE AUTOMOBILE TECH PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,070.26
Revised Estimate Amount	: S\$1,652.75
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 9348Z

Vehicle Details

Vehicle No.: SJR319T
 Vehicle to be Exported: No
 Intended Deregistration Date: 04 Jul 2019
 Vehicle Make: TOYOTA
 Vehicle Model: VIOS G AUTO
 Primary Colour: Black
 Manufacturing Year: 2009
 Engine No.: 1NZX918056
 Chassis No.: MR053HY9305116311
 Maximum Power Output: 80.0 kW (107 bhp)
 Open Market Value: \$13,876.00
 Original Registration Date: 05 Jun 2009
 First Registration Date: 05 Jun 2009
 Transfer Count: 1
 Actual ARF Paid: \$13,876.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2029
 COE Category: A - Car (1600cc & below)
 COE Period(Years): 10
 PQP Paid: \$26,175.00
 COE Rebate Amount: \$25,709.00
Total Rebate Amount: \$25,709.00

The information contained herein is correct as at 04 Jul 2019

OK



Toyota Vios 1.5A E
(COE till 07/2024)

\$30,800

\$6,180 /yr

14-Jul-2009

1,497 cc

120,000 km

Sedan

Available

2 Owners Only. 90% Loan Available. Super Low Mileage Done At 12000km Per Year. Owner Service Every 8000km. New Paint/Tyres/Road Tax. No Repair Needed. Perfect Gearbox, Smooth Engine With Super Undercarriage. Extremely Neat And Clean Interior And Exterior. This Sh...

Posted: 16-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E
(COE till 05/2024)

\$27,800

\$5,710 /yr

31-Jul-2009

1,497 cc

112,000 km

Sedan

Available

Full Loan Available! \$2500 Driveaway! Low Mileage. Vehicle In Excellent Condition And Clean Interior. On The Road Condition, No Repairs Needed! WhatsApp Or Call Us For Viewing And Test Drive Today.

Car (S) Pte Ltd

Posted: 16-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD



Toyota Vios 1.5A E
(COE till 07/2024)

\$29,800

\$6,000 /yr

08-Jul-2009

1,497 cc

117,229 km

Sedan

Available

100% Loan Available. Providing Good Services. Free 6 Months Warranty. No Repairs Needed. Having Our Own Workshop. 100% Accident-Free. Well Maintained. Bank Loan And In House Loan Available. Low Monthly Installment. Trade In Welcome. View Now To Believe It!

Posted: 16-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Don't be fooled by these car insurance myths!

Is it true that my NCD will still be affected even if the accident is not my fault? Let's find out what is true and false about car insurance in Singapore.

Find out more!



Toyota Vios 1.5A E
(New 5-yr COE)

\$28,800

\$5,750 /yr

27-Jul-2009

1,497 cc

102,000 km

Sedan

Available

Very Well Maintained By Previous Owner! Engine/Gearbox Problem Free! Buy With A Peace Of Mind! Installment As Low As \$474/mth. Flexible Loan Packages With Up To 100% Loan Available! No Intro Needed For This Reliable And Fuel Efficient Vehicle! Definitely One Of...

Car (S) Pte Ltd

Posted: 15-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD



Toyota Vios 1.5A G
(New 5-yr COE)

\$31,800

\$6,350 /yr

22-Jun-2009

1,497 cc

138,000 km

Sedan

Available

Highest Specs Vios 1.5A ("G" Model) Of Superb Condition, See To Certify! Low Mileage Clocked Of 13800km Annually. No Repairs Needed. New Paintwork, Ideal For Daily Commute. Flexible Bank And In House Loan Available With Low Monthly Installment. Call Us Now For Vie...

Tay Motor & Credit Pte Ltd

Posted: 15-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E
(COE till 06/2029)

\$43,800

\$4,410 /yr

26-Jun-2009

1,497 cc

123,704 km

Sedan

Available

Genuine Mileage. Ex OPC Unit Hence E Low Miles. STA Graded. Trade In Welcome. High Loan Available.

Posted: 14-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD



Toyota Vios 1.5A G Sports
(COE till 05/2029)

\$43,800

\$4,440 /yr

12-Jun-2009

1,497 cc

145,200 km

Sedan

Available

New 10 Years COE, G Sport Model, Dual Airbags, Excellent Condition, Low Depreciation. Low Fuel Consumption, Regular Serviced. Leather Seats, Sports Rims, Reverse Sensors, No Repairs Needed, Bank Or In House Loan Available.

Posted: 14-Jul-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

Toyota Vios 1.5A G
(New 5-yr COE)

\$45,000

\$8,990 /yr

12-Aug-2009

1,497 cc

138,000 km

Sedan

Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 13:06
Date Of Accident	04/07/2019 10:30
Exact Location Of Accident	ALONG COMMONWEALTH AVE WEST > ALEXANDRA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR319T
Insured/Policyholder	
Name Of Registered Owner	NI TECK MING
NRIC No	S1689348Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98766994
Alternative Phone No	OFFICE-98766994

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109306706
Cover Note Number	

Driver

Name of Driver	NI TECK MING
NRIC No	S1689348Z
Date Of Birth	13/06/1965
Occupation	OUTDOOR
Date Of Driving Pass	26/09/1991
Driving Experience	27 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98766994
Fax Number	
Contact Number	OFFICE-98766994
EMail Address	NOEMAIL

Address 85 ROSEWOOD DRIVE #04-77
 Postcode 737790
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : MUHAMMAD ZAHID BIN BAHARUDIN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA1439L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver KOO CHONG HENG
 NRIC/Passport Number S0366312D
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Red Traffic light, I stop my car completely
 A few minutes later, I feel impact from
 behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1907/006
Policy No:	5109306706	Date of Loss:	04/07/2019
Vehicle Reg. No.:	SJR319T	Driveable?	no
Driver Age:	13/06/1965	Third Party Vehicle No.:	SHA1439L
Any Injuries?	no	Contact No:	98766994
Insured/Claimant:	NI TECK MING	Driver:	NI TECK MING

Make/Model:	Toyota, Vios	Vehicle Reg. Date:	05/06/2009
Vehicle Colour:	BLACK	Engine Number:	1NZX918056
Chassis No:	MR053HY9305116311	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	1,745.26
Miscellaneous Items	685.00
Labour	910.00
Paintwork Labour	730.00
Towing	0.00
Gross Total(S\$):	4,070.26
GST 7.00%(S\$):	284.92
Nett Amount(S\$):	4,355.18

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	383.66	-25.00	287.75 / CRK
2	1	REAR BUMPER SIDE RETAINER LH	0.00	56.70	-10.00	51.03 X SVL
3	1	REAR BUMPER SIDE RETAINER RH	0.00	56.70	-10.00	51.03 X SVL
4	1	REAR BUMPER BRACKET LH	0.00	95.90	-10.00	86.31 X SVL
5	1	REAR BUMPER BRACKET RH	0.00	95.90	-10.00	86.31 X SVL
6	1	REAR END PANEL	0.00	595.85	-25.00	446.89 X R
7	1	REAR END PANEL INNER GARNISH	0.00	177.72	-10.00	159.95 X SVL
8	1	BOOT LID	0.00	0.00	0.00	0.00 X SVL
9	1	REAR TAILLAMP LH	0.00	320.00	-10.00	288.00 X SVL
10	1	REAR TAILLAMP RH	0.00	320.00	-10.00	288.00 X SVL

Total Parts (\$\$) 1,745.26

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	0.00	45.00	0.00	45.00 / NBL
2	1	REAR BUMPER SENSORS (1 SET)	0.00	260.00	0.00	260.00 X SVL
3	1	REAR BUMPER LOWER SKIRT	0.00	380.00	0.00	380.00 / DEF

Sub Total (\$\$) 685.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 30
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00 400

Gross Labour Cost (\$\$) 910.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 ✓
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00 ✓
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	650.00	650.00	0.00	650.00 400

Gross Labour Cost (\$\$) 730.00

< END OF ESTIMATES >

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Gross Labour Cost (\$\$) is allowed 730.00

Acknowledged by Repairer
Signature:
Date:

NAZUKK
5/7/19 1700
LIS
3 DAYS
FATER REPAIR PHOTOS

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1907/006
Policy No:	5109306706	Date of Loss:	04/07/2019
Vehicle Reg. No.:	SJR319T	Driveable?	no
Driver Age:	13/06/1965	Third Party Vehicle No.:	SHA1439L
Any Injuries?	no	Contact No:	98766994
Insured/Claimant:	NI TECK MING	Driver:	NI TECK MING

Make/Model:	Toyota, Vios	Vehicle Reg. Date:	05/06/2009
Vehicle Colour:	BLACK	Engine Number:	1NZX918056
Chassis No:	MR053HY9305116311	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	287.75 1,745.26
Miscellaneous Items	435.00 685.00
Labour	460.00 910.00
Paintwork Labour	480.00 730.00
Towing	0.00
Gross Total(S\$):	1652.75 4,070.26
GST 7.00%(S\$):	284.92
Nett Amount(S\$):	4,355.18

This claim is handled by: Sky Toh T C

\$ 1652.75
-20% \$ 330.55

\$ 1322.20

LIS \$1320f
(PLS CONFIRM)

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	383.66	-25.00	287.75 / CRK
2	1	REAR BUMPER SIDE RETAINER LH	0.00	56.70	-10.00	51.03 / XSVL
3	1	REAR BUMPER SIDE RETAINER RH	0.00	56.70	-10.00	51.03 / XSVL
4	1	REAR BUMPER BRACKET LH	0.00	95.90	-10.00	86.31 / XSVL
5	1	REAR BUMPER BRACKET RH	0.00	95.90	-10.00	86.31 / XSVL
6	1	REAR END PANEL	0.00	595.85	-25.00	446.89 / CR
7	1	REAR END PANEL INNER GARNISH	0.00	177.72	-10.00	159.95 / XSVL
8	1	BOOT LID	0.00	0.00	0.00	0.00 / XSVL
9	1	REAR TAILLAMP LH	0.00	320.00	-10.00	288.00 / XSVL
10	1	REAR TAILLAMP RH	0.00	320.00	-10.00	288.00 / XSVL

Total Parts (\$\$) 287.75 1,745.26

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	0.00	45.00	0.00	45.00 / NEL
2	1	REAR BUMPER SENSORS (1 SET)	0.00	260.00	0.00	260.00 / XSVL
3	1	REAR BUMPER LOWER SKIRT	0.00	380.00	0.00	380.00 / DEF

Sub Total (\$\$) 425.00 685.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 30
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00 400

Gross Labour Cost (\$\$) 460.00 910.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 ✓
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00 ✓
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	650.00	650.00	0.00	650.00 400

Gross Labour Cost (\$\$) 480.00 730.00

< END OF ESTIMATES >

1A2 LK
17/19 1700

LIS

. DAYS

FREE REPAIR PHOTOS.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 23 July 2019 3:03 PM
To: YT(MG); SUR
Cc: 'YTKB'; 'YTHQ'; YTHQ; YTKB
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19004453MFSH ; YOUR REF: SJR319T

Dear Sky,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(MG) <info@yewteegroup.com>
Sent: Tuesday, 23 July 2019 2:47 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>; YTKB <utauto2@singnet.com.sg>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19004453MFSH ; YOUR REF: SJR319T

Hi Veron,

Ok confirm Lump sum \$1200/- with 3 repair days.

Best Regards

Sky Teh

Mobile: 9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6762 2081 (3 Lines)
Fax: 6760 4895
Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines)
Fax: 6702 3773
Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands
39 Woodlands Close #01-12
Singapore 737856
DID: 6256 2081 (3 Lines)
Fax: 6256 2533
Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Tuesday, 23 July, 2019 2:05 PM

To: YT(MG); SUR

Cc: YTKB; YTHQ

Subject: RE: SURVEYOR APPOINTED; OUR REF : D19004453MFSH ; YOUR REF: SJR319T

Dear Yee Meng,

WITHOUT PREJUDICE

Offer Lump Sum \$1200 @ 3 working days

PARTS-\$383.66 (less 25%)=\$287.75

SN-\$345

LABOUR-\$900

TOTAL-\$1532.75 (less 20%)=\$1226.20

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(MG) <info@yewteegroup.com>

Sent: Tuesday, 23 July 2019 9:18 AM

To: SUR <sur@lkkauto.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D19004453MFSH ; YOUR REF: SJR319T

Hi Veron,

Attached after repair photos.

Kindly finalise COR at lump sum \$1,320/- with 3 repair days.

Thank You 😊

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Tuesday, 9 July 2019 3:14 PM

To: INFO@YEWTEEGROUP.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <SereneLer@msfirstcapital.com.sg>

Subject: SURVEYOR APPOINTED; OUR REF : D19004453MFSH ; YOUR REF: SJR319T

Dear Sir/Madam

PRI Request For **SJR319T** Accident Involving **SHA1439L** On 04-07-2019 AT 10:45:00HRS.

Please find below details for your reference

- **Claim number** : D19004453MFSH
- **Insured vehicle number** : SHA1439L
- **Accident date** : 04-07-2019
- **Third-party vehicle number** : SJR319T
- **Assignment type** : DIRECT SETTLEMENT
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : SERENE

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19012115/Nvf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-07-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1439L	Veh. Inspected	SJR 319T
Policy No.		Coverage (\$)	0.00
Claim No.	D19004453MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	09/07/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305116311	Colour	BLACK
Odometer	173690	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	MICHELIN	5 mm
L/H Front Tyre	195/55 R15	MICHELIN	5 mm
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2019	Inspection Date	15/07/2019
Survey held at	YEW TEE AUTOMOBILE-39 WOODLAND CLOSE #01-12		
Repairer	-		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 319T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	383.66	383.66
1	REAR END PANEL	TO REPAIR SEE LABOUR	595.85	-
1	BOOT LID (NPA)	SERVICEABLE	-	-
	LESS 25% DISCOUNT		-244.88	-95.92
			734.63	287.74
NETT ITEMS				
1	REAR BUMPER SIDE RETAINER LH (N)	SERVICEABLE	56.70	-
1	REAR BUMPER SIDE RETAINER RH (N)	SERVICEABLE	56.70	-
1	REAR BUMPER BRACKET LH (N)	SERVICEABLE	95.90	-
1	REAR BUMPER BRACKET RH (N)	SERVICEABLE	95.90	-
1	REAR END PANEL INNER GARNISH (N)	SERVICEABLE	177.72	-
1	REAR TAILLAMP LH (N)	SERVICEABLE	320.00	-
1	REAR TAILLAMP RH (N)	SERVICEABLE	320.00	-
	LESS 10% DISCOUNT		-112.29	-
			1,010.63	-
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
1	SET REAR BUMPER SENSORS (SN)	SERVICEABLE	260.00	-
1	REAR BUMPER LOWER SKIRT (SN)	DEFORMED	380.00	300.00
			685.00	345.00
LABOUR				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00

Report Ref No. CS/FCI19012115/Nvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY-OUT BODY CAVITY PRESERVATION.)		40.00	40.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.)		40.00	-
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		650.00	400.00
			1,640.00	900.00
GRAND TOTAL			4,070.26	1,532.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI19012115/Nvf3e2

MARKET VALUE: \$42,000.00(EST)-LTA REIMBURSEMENT VALUE: \$25,709.00=NETT VALUE: \$16,291.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.