



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Ref: CC4/ASM19012131/Kga3q2 Date: 01/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 8025U	Veh. Inspected	SMD 1019R	
Policy No.	VPA/P1965300	Coverage (\$)	0.00	
Claim No.	S9M01T5N	Excess (\$)	0.00	
Assign From		Assign Date	09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 528i (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAXG32070C593411	Colour	METALLIC PEARL WHITE	
Odometer	122596 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40Z R19	YOKOHAMA	7 mm	
L/H Front Tyre	245/40Z R19	YOKOHAMA	7 mm	
R/H Rear Tyre	275/35Z R19	YOKOHAMA	7 mm	
L/H Rear Tyre	275/35Z R19	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2019	Inspection Date	09/07/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	