

22/04/2019

ASS. REC. BY:

REF:

CS/CTI/9012146/TIC/302

Special Instruction:

Surveyor: Taufiq

ASSIGNMENT (Office)

From (Person): Chong Boonsen of CTI

Date/Time: 8/7/19 @ 5.14pm

Estimated Cost: Bill to:

OD/FP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YM7326A

Insured:

YN5471X

at Workshop m/s

Carport Auto

Tel:

62685390 / 94557972

of Blk 3 Pioneer Rd North #01-24

Policy No: DMCVSN30416319022

Claim No:

SNM19D203097C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:10pm 9/7/19

Person Contacted:

James

Vehicle IN/OUT

Date/Time

Action/Instruction Estimated (X)

YM7326A : X

YN5471X - X

Dismantle: 19/7/2019

After repair: 2/8/2019

Surveyor *Tanfer*

REF: C71

ASSIGNMENT

CoR 2022 Apr / 2007, Sep

From: Date: 17.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Ym 7326A
at Workshop m/s Carport Auto Service
of BIK 3 Pioneer Road North #01-24

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

sup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

ym 7326A

Yr Regn:

2007, Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hino GH8JRNA c.c 7084

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

445022

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GH8JRNA K10206.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

10.00 - 120

R:

ii 1(0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Good tyre

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

17/7/19CSP

Survey held at

Carport Pioneer

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 4 Days

\$8000 - \$9000

8 days

[Signature]
2/8/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

150

Transportation:

___ S + RS ___ SI

Photos

Others

TOTAL

150

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

PRE

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2019		01 Aug 2019 18:21 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	HONG KONG DE HE LOGISTICS LIMITED SINGAPORE BRANCH, Co. Reg. No.: T13FC0156K								
Vehicle Reg. No.:	YM7326A	Date of Loss:	02/07/2019 13:00 - :59						
Claim Type:	TP / SNM19D203097C02	Policy/Cover Note No.:	DMCVSN30416319022						
Vehicle Reg. No. (Insured):	YN5471X	Policy No. (Claimant):	5107555943						
		Excess:	S\$0.00						
Repairer:	Carport Auto Service (HQ) Block 3, Pioneer Road North, #01-24, 628457 Pioneer - Tel: 62685390								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 8 July 2019 5:14 PM
To: Jacqueline Tan
Cc: jeromesoh@visionlawllc.com; assignments
Subject: RE: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]
Sent: Monday, 8 July, 2019 1:49 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>;
jeromesoh@visionlawllc.com
Subject: RE: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

Dear Mr Chong,

Let us have your answer by today. Thank you.

Regards

Jacqueline Tan
Secretary

Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Friday, 5 July, 2019 1:39 PM
To: Jacqueline Tan
Subject: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged

and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Jerome Soh <jeromesoh@visionlawllc.com>
Sent: Tuesday, 9 July 2019 3:35 PM
To: 'Admin-D (LKKAuto)'; 'Chong Boon Sen'; 'Jacqueline Tan'
Cc: 'assignments'
Subject: RE: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

Dear all,

Carport Auto Service
Blk 3 Pioneer Road North
#01-24
Singapore 628457
Mr Lawrence Lim (6268 5390)

Jerome Soh
Assistant Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 Fax: 6535-6802

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 9 July, 2019 3:23 PM
To: 'Chong Boon Sen'; 'Jacqueline Tan'
Cc: jeromesoh@visionlawllc.com; assignments
Subject: RE: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

Dear All,

Kindly assist

BEST REGARDS,

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Tuesday, 9 July 2019 10:22 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Jacqueline Tan' <jactan@visionlawllc.com>
Cc: jeromesoh@visionlawllc.com; assignments <assignments@lkkauto.com>
Subject: RE: YOUR REF: AM.JT.INS.C10.YM7326A.19(SJ) / OUR REF: SNM19D203097

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Foreign Company
Owner ID:	156K
Vehicle Details	
Vehicle No.:	YM7326A
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Aug 2019
Vehicle Make:	HINO
Vehicle Model:	GH8JRKA
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	J08EUB10501
Chassis No.:	GH8JRK10206
Maximum Power Output:	-
Open Market Value:	\$54,762.00
Original Registration Date:	18 Sep 2007
First Registration Date:	18 Sep 2007
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,005.00
COE Rebate Amount:	\$13,189.00
Total Rebate Amount:	\$13,189.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 01 Aug 2019

OK

MSI319086477 / STA INSPECTION PTE LTD - Boon Lay
 ENTRY DATE & TIME: 03/07/2019 12:30
 SUBMITTED BY: Woodford Richard Vincent

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/07/2019 12:30
 Date Of Accident 02/07/2019 13:00
 Exact Location Of Accident ANG MO KIO AVE 5 TOWARDS YIO CHU KANG
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YM7326A
Insured/Policyholder
 Name Of Registered Owner HONG KONG DE HE LOGISTICS LIMITED SINGAPORE BRANCH
 Co Reg No T13FC0156K
 Email Address CATHERINE@FURUKAWALOGHK.COM
 Mobile Phone No
 Alternative Phone No Office-62666982

Vehicle Particulars

Manufacturer HINO
 Model GH8
 Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5107555943
 Cover Note Number

Driver

Name of Driver LEOW TIAU
 NRIC No S0193046Z
 Date Of Birth 28/01/1951
 Occupation OUTDOOR
 Date Of Driving Pass 14/10/1969
 Driving Experience 49 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93956364

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 465 UPPER SERANGOON ROAD
#13-1195

Postcode

530465

Was driver an employee of the Insured's Company

YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved
in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by
ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YN5471X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

KOH YONG CHERN

NRIC/Passport Number

S6848169D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/7/19 at about 1300hrs, I was ^{waiting} ~~waiting~~ along ANG MO KIO AVES on the right lane to turn right into ANG MO KIO Industrial Park 2. While waiting for my turn to turn right, Veh B collided into the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	HONG KONG DE HE LOGISTICS LIMITED SINGAPORE BRANCH , Co. Reg. No.: T13FC0156K								
Vehicle Reg. No.:	YM7326A	Date of Loss:	02/07/2019 13:00 - :59 [141 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203097C02	Policy/Cover Note No.:	DMCVSN30416319022						
Vehicle Reg. No. (Insured):	YN5471X	Policy No. (Claimant):	5107555943						
		Excess:	S\$0.00						
Repairer:	Carport Auto Service (HQ) Block 3, Pioneer Road North, #01-24, 628457 Pioneer - Tel: 62685390								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YM7326A (SNM19D203097C02)

[YN5471X]

TP


















































HONG KONG DE HE LOGISTICS LIMITED SINGAPORE BRANCH





















Jul 2 2019 1:00PM

[-]

















Carport Auto Service



Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail		Print			
1	03/07/19 13:32	Accident Statement									Load HTM			
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail		Print			
1	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
2	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
3	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
4	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
5	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
6	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
7	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
8	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
9	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
10	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
11	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
12	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
13	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
14	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
15	03/07/19 13:29	Accident Photo [Linked Accident Report Documents]									Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
2	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
3	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
4	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
5	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
6	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
7	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
8	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
9	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
10	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
11	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
12	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	
13	02/08/19 11:02	General View									Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
				<input checked="" type="checkbox"/>
14	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
63	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/19 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	02/08/19 11:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/07/19 13:24	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	03/07/19 13:24	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/07/19 13:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	03/07/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)		Thumbnail Print
1	03/07/19 13:24	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	03/07/19 13:24	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012146/T1CF3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30416319022

Claimant Vehicle
No : YM7326AInsured Vehicle
No : YN5471X

Date of Loss: 02/07/2019

Nature of Claim: TP

Claim
No: SNM19D203097C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM7326A

Make & Model: HINO GH8JRKA, 7.7 D (M)

Engine No: J08EUB10501

Reg. Date: 18/09/2007 (Man. Year: 2007)

Chassis No: GH8JRK10206

Colour: White

Odometer: 445022 km

Engine Capacity: 7684 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	10.00-R20	Rear Tyre Size:	10.00-R20 (D)
Front Left Side:	GoodTyre 8 mm	Rear Left Side:	GoodTyre 8/8 mm
Front Right Side:	GoodTyre 8 mm	Rear Right Side:	GoodTyre 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 17/07/2019 Inspected At:

Carport Auto Service (HQ)
Block 3, Pioneer Road North, #01-24
Singapore 628457

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$9,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Aug 2019)	
Parts:	N/A	HINO GH8JRKA 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM7326A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >