

ASS. REC. BY:

REF: CS/AGI/901247/Etf302

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

From (Person): My Rakha

of

AGI

Date/Time: 9.7.19 3.57 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No: SHC 4590B

Insured: SFV 73815

at Workshop m/s SMRT

Tel: 68 6 62671

of 60' woodland Industri Park E

Policy No:

Claim No: C10003437/AH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.7.19 5:55 p.m

Person Contacted: Shanti

Vehicle(IN)OUT

Date/Time

Action/Instruction	(✓)	Estimate
--------------------	-------	----------

SFV 73815: X

SHC 45905: X

ASSIGNMENT

12/09/14

From: _____ Date: 10-7-2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SH C 4590Bat Workshop m/s SMARTof 60 woodland Industrial Park E

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS my

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH C 4590BYr Regn: 11/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 540788

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD KN364305748234

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fin29

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 6/7/19D.O.I. 10/7/19Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/7/19Finalize confirm \$3850, 5 days (Red: 12318.55; 76%)07/19/2021SFV-73815

RECEIVED 02 AUG 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

1) 113 Typist

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 3850)150

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Tuesday, 9 July 2019 3:57 PM
To: Admin-D (LKKAuto)
Cc: SUR; Albert Hong
Subject: FW: TPPD Survey: Claim ref:C10003437/AH || OI- SFV7381S (Red) TP- SHC4590B || Est:0.00 || SMRT Depot
Attachments: 2021 - 4590.pdf; OI GIA Report SFV7381S .pdf

Hi team,

TP Survey for SHC4590B please.

Vehicle is in.

Kindly Acknowledge.

Regards,

Ivy
Admin Executive, Claims

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>
Sent: Tuesday, 9 July 2019 2:32 PM
To: 'claims@budgetdirect.com.sg'
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis) <ngsiuching@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis) <kimming.chin@smrt.com.sg>
Subject: RE: SHC4590S - SURVEY (AUTO & GENERAL INSURANCE)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4590S** within 48 hours according to GIA guide line, involving your insured **SFV7381S**

Vehicle in Woodlands SMRT Depot

Regards
Shanti
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2671/2 | bthaiyaln@smrt.com.sg



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 08:08
Date Of Accident	06/07/2019 13:15
Exact Location Of Accident	MIDDLE ROAD JUNCTION WATERLOO STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4590B
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	SITHAMBARAM MOHAN S/O M SITHAMBARAM
NRIC No	S3034541Z
Date Of Birth	16/12/1964
Occupation	OUTDOOR
Date Of Driving Pass	03/02/2005
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	246
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190707/2025

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFV7381S
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	WEE SOON KHAI
NRIC/Passport Number	S7325276H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MIDDLE RD

REFER TO POLICE REPORT - 7/20190707/225

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

J. Mohan 08/07/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

chr 8/7/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

S. Mohan 08/07/2019
Driver's Signature
(If driver is not the policyholder)
Date & Time:

ch 8/7/19
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190707/2025

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

1 of 3

Report No. T/20190707/2025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/07/2019 08:46	Vide Report No.:	Station Diary No.: 55
--	------------------	--------------------------

Informant's Particulars

Name of Informant: SITHAMBARAM MOHAN S/O M SITHAMBARAM			Address: APT BLK 246 YISHUN AVENUE 9 #03-259 SINGAPORE 760246		
ID Type / ID No.: NRIC NO / S3034541Z			Contact No.: Home/Office: Mobile: 93924230		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 16/12/1964	Type of Informant: Driver		
Race: Indian			Language:	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 06/07/2019 13:15	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 MIDDLE ROAD WATERLOO STREET Junction of Middle Road and Waterloo Street.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFV7381S	Car	MAZDA		Red	Slightly Damaged	3
SHC4590B	Car	TOYOTA		Maroon	Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190707/2025

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

2 of 3

Report No. T/20190707/2025

CONTINUATION OF REPORT

Driver			
Name	WEE SOON KHAI		ID No. S7325276H
Related Vehicle	SFV7381S (Car)		Contact No. 90239413
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SITHAMBARAM MOHAN S/O M SITHAMBARAM		ID No. S3034541Z
Related Vehicle	SHC4590B (Car)		Contact No. 93924230
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 06/07/2019 at 1244hrs, I picked up 3 passengers from Changi Airport Terminal 4 towards Gateway Jem Hotel at Somerset in my taxi SHC4590B(SMRT). On the same day between 1300hrs-1330hrs, I was travelling along Middle Road on the 3rd lane. There was a jam and traffic was slow; at the junction of Waterloo Street, another vehicle SFV7381S(Mazda) then wanted to turn right from Middle Road into Waterloo Street. The traffic light was green in my favour and the other vehicle then turned abruptly and as such I was unable to stop in time. As such I scrapped past the front of his vehicle. My taxi suffered damages to the front right bumper, right side of the vehicle and rear right side. I do not know the cost of repairs and as far as I know, there are no injuries to any parties at the moment.



**SINGAPORE
POLICE FORCE**



T/20190707/2025

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

3 of 3

Report No. T/20190707/2025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
A /
Sgt 3 TOW HUANMIN, WILSON

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
07/07/2019 08:46

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU-LUI
Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP168



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4590B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6119971
Chassis No.:	JTDKN36U305748234
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	12 Sep 2014
First Registration Date:	12 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$20,087.00
Total Rebate Amount:	\$26,153.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Jul 2019

OK

Case Details

Case Reference Number : TAX/07/19/2021

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4590B

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7612-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Accident Date and Time : 06/07/2019 05:15 AM

Vehicle Age(In Months) : 58

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	✓
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	✓
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	✓
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	✓
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Giver	✓
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Giver	✓
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	✓
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Giver	✓
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✓
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	1	38.92	Replace	✓
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.78	Replace	1	128.78	Replace	✓
One Time Key In	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Giver	✓
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Not Giver	✓

Total Spare Part Cost 8,688.38

Surveyor Total 2,201.20

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Item Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			WHEEL DISC, FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	R X
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ N/C
One Time Key In	Main			HINGE LOWER RHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			HINGE UPPER RHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			CHECK ASSY, FR DOOR	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	X R
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	X R
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ N/C
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ N/C
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	1	0	Repair	X R
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	X R
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Giver	X NMI
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ N/C
Total Spare Part Cost									8,688.38	Surveyor Total		2,201.20		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									6,950.70	Final Sur Total		1,760.96		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

1	Main	TO REPAIR RH PORTION	1,014.00	600	
Total:			1,014.00	600.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	360.00	50	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
5	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
6	Main	TO RESPRAY RH REAR DOOR	378.00	200	
7	Main	TO RESPRAY REAR FENDER RH	378.00	200	
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			2,808.00	1,350.00	✓

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ N/C
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	✓ N/A
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	✓ N/C
4	Main	TO TRANSFER DOOR MECHANISM	240.00	0	✓ N/A
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	0	✓ N/A
6	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	✓ N/C
7	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ N/C
8	Main	TO WASH AND VACUUM	60.00	0	✓ N/A
Total:			1,240.00	120.00	✓

Summary

16243.04

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,950.70	1,760.96
Total Labour Cost	1,014.00	600.00
Total Spray Painting	2,808.00	1,350.00
Other	1,240.00	120.00
Overall Total	12,012.70	3,830.96
Lump Sum Repair Option	16,163.55	✓

Lump Sum Total	12,000.00	3,850.00
Surveyor Approved Amount		3,850.00
No of Repair Days*	7	5
Remarks		U/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	10/07/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Section A - Accident Details

Registration Number	SHC4590B
Case Reference Number	TAX/07/19/2021
Registration Date	12/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SITHAMBARAM MOHAN S/O M SITHAMBARAM
Type of Accident	Head To Side
Accident Date and Time	6/7/2019 1:15 PM
Accident Reported Date and Time	8/7/2019 8:08 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102305
Special Instruction to ARC, if any	TP
Prepared Date and Time	9/7/2019 11:48 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$2,808.00	\$1,350.00
Total Spare Part Cost	\$6,950.70	\$1,760.98
Total Other Cost	\$1,240.00	\$120.00
TOTAL COST	\$12,012.70	\$3,830.98
Lump Sum Total	\$12,000.00	\$3,850.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	10/07/2019 3:56 PM	10/07/2019 2:26 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0442	Invoice Number	
Quotation Date	25.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,808.00	\$1,350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,240.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Check X
		81519-47060	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Check X
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
Fax Number 63655592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 27/07/2019

User ID : PohSuan

52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	
85315-47140	WIPER WASHER JAR	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	
53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Not Given	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
67001-47070	DOOR FRT/RH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	
68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X
68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X
68610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
42611-47140	WHEEL, DISC	1.00	\$1,490.20	100.00	\$0.00	Replace	Repair	R
65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	R
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	
Total			\$11,106.55		\$2,201.22			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2201.22
- 202
1760.98
+ 600.00
+ 1470.00

3830.98

4/5 \$3850/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19012147/Etf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 05-08-2019	
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFV 7381S	Veh. Inspected	SHC 4590B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003437/AH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U305748234	Colour	MAROON	
Odometer	540788	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FIRENZA	5 mm	
L/H Front Tyre	195/65 R15	FIRENZA	5 mm	
R/H Rear Tyre	195/65 R15	FIRENZA	5 mm	
L/H Rear Tyre	195/65 R15	FIRENZA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2019	Inspection Date	10/07/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4590B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 25%)	CUT	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/RH (DISC 25%)	BROKEN	76.40	57.30
1	FENDER FRT/RH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER LINER FRT/RH (DISC 25%)	CRUSHED	171.70	128.78
1	HEAD LAMP RH (DISC 10%)	CUT	945.20	850.68
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	BRACKET, FR TURN LOWER RH	NOT NECESSARY	26.00	-
1	BRACKET, FR TURN UPPER RH	NOT NECESSARY	24.40	-
1	LENS & BODY, FR TURN RH	NOT NECESSARY	511.80	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	WIPER WASHER JAR	NOT NECESSARY	180.10	-
1	FENDER LINER PAD, FR WHEEL, RH	NOT NECESSARY	49.30	-
1	FENDER PROTECTOR FRT/RH SIDE	NOT NECESSARY	113.90	-
1	TYRE	NOT NECESSARY	126.74	-
1	HINGE LOWER RHF, DOOR	NOT NECESSARY	90.10	-
1	HINGE UPPER RHF, DOOR	NOT NECESSARY	80.50	-
1	CHECK ASSY, FR DOOR	NOT NECESSARY	150.30	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	WHEEL DISC.FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	DOOR FRT/RH	TO REPAIR SEE LABOUR	894.40	-
1	MOULDING BODY, RH	TO REPAIR SEE LABOUR	673.60	-
1	DOOR RR/RH	TO REPAIR SEE LABOUR	954.50	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-

Report Ref No. CS/AGI19012147/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL, DISC	TO REPAIR SEE LABOUR	1,490.20	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			11,181.04	2,201.22
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC.FRONT, DOOR FRT/RH, MOULDING BODY, RH, DOOR RR/RH, FENDER RR/RH, WHEEL, DISC AND BUMPER REAR.		1,014.00	600.00
	SPRAY PAINT.		2,808.00	1,350.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT WIRE HARDESS.		200.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,062.00	2,070.00
GRAND TOTAL			16,243.04	4,271.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,850.00

Report Ref No. CS/AGI19012147/Etf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.