

ASS. REC. BY:

Surveyor: AND Chung

REF:

CS/INC19012159/Gsf3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of

INC

Date/Time: 9/7/19 @ 10:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SML1145S

Insured:

YL 78452

at Workshop m/s

Thiam Hong Huet

Tel:

8263 6295

of

176 Sin Ming Drive #05-14

Policy No:

Claim No:

MT/1052031-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/7/2019

(Client's Record)

9639 # 1626 Juy

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:13am @ 9/7/19

Person Contacted:

Steven

Vehicle

IN/OUT

Date/Time

Action/Instruction

Johny!! (✓) ✓

SML 1145S = X

ASS. REC. BY: Enl. REF: INC

ASSIGNMENT

2019

From: PRS Date: 9/7/19
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SML11455
 at Workshop m/s Thiam Heng Huet
 of 176 Sin Ming Drive # 05-14
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS ^(up)
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SML11455 Yr Regn: _____
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Opel Insignia c.c. 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 12553 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W0VZM6EF9K1035229
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD / R/Rim or _____
 Tyre Size: F: 225/55R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 8 mm Rear R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. _____ D.O.I. 09-07-19
 Survey held at w/s 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$5000 - \$6000

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / L&L: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS _____ SI
 Photos _____
 Others _____
 TOTAL _____

Celine Fong (LKKAuto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Wednesday, 10 July 2019 8:39 AM
To: assignments; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Kindly refer below for the full details.


Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 9 July 2019 10:09 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Clarence Richard Anthony <clarence.anthony@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eng Huey Huey	MT/1052486-001	SLU1663C	TEAM AUTOPRO PTE LTD	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	Peach Ang / 6258 1955		SGS3819C	06/07/2019	
2	Chryllis Quah	MT/1052455-001	SJJ671S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGK2950D	06/07/2019	
3	Fiona Shen	MT/1052031-002	SML1145S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		YL7845Z	04/07/2019	
4	Eric Tang	MT/1049590-002	SLE2735G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLW1005S	31/05/2019	
5	Eng Huey Huey	MT/1052137-002	SME1876C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46	Chris / 6702 1555		FBP8126K	05/07/2019	

					PREMIER@KAKI BUKIT					
6	Jared Liu	MT/1052296-002	SJT8373Y	TORQUE 5 PTE LTD	8 KAKI BUKIT AVE 4 #01-50 PREMIER @ KAKI BUKIT	Lucas / 8131 6318		WC5674J	06/07/2019	
7	Chryllis Quah	MT/1052398-002	SBM131M	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 6341 6789		SJF4431M	06/07/2019	
8	Azhari	MT/1033901-001	FBL7115U	HOME ADDRESS	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY @ KB SINGAPORE 417800	Li Tian / 90054320		SKM1972P	17/02/2019	WORKSHOP NAME IS TUCK LIFE
9	Muhammad Airwan	MT/1050613-002	SJB9855L	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		FBM4589A	24/06/2019	
10	Chryllis Quah	MT/1034631-002	FBK8414E	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SJW8544E	01/03/2019	
11	Serene Lim	MT/1052122-003	GP3838M	SM AUTOMOTIVE	BLOCK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883	Suky Chong / 6747 9241		SMG722J	05/07/2019	
12	Serene Lim	MT/1052247-002	SKQ7188B	ZOOM AUTOWERKS PTE LTD	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53	Elin Cai / 9450 7920		SJU7717R	07/07/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.


Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 9 July 2019 3:44 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/07/2019


Dear LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 9 July 2019 10:09 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Clarence Richard Anthony <clarence.anthony@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eng Huey Huey	MT/1052486-001	SLU1663C	TEAM AUTOPRO PTE LTD	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	Peach Ang / 6258 1955		SGS3819C	06/07/2019	
2	Chryllis Quah	MT/1052455-001	SJG671S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGK2950D	06/07/2019	
3		Pending advice	SML1145S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				
4	Eric Tang	MT/1049590-002	SLE2735G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLW1005S	31/05/2019	
5	Eng Huey Huey	MT/1052137-002	SME1876C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Chris / 6702 1555		FBP8126K	05/07/2019	
6	Jared Liu	MT/1052296-002	SJT8373Y	TORQUE 5 PTE LTD	8 KAKI BUKIT AVE 4 #01-50 PREMIER @ KAKI BUKIT	Lucas / 8131 6318		WC5674J	06/07/2019	
7	Chryllis Quah	MT/1052398-002	SBM131M	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 6341 6789		SJF4431M	06/07/2019	
8	Azhari	MT/1033901-001	FBL1715U	HOME ADDRESS	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY @ KB SINGAPORE 417800	Li Tian / 90054320				WORKSHOP NAME IS TUCK LIFE
9	Muhammad Airwan	MT/1050613-002	SJB9855L	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SKM1972P	17/02/2019	
10	Chryllis Quah	MT/1034631-002	FBK8414E	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		FBM4589A	24/06/2019	
11		Pending advice	GP3838M	SM AUTOMOTIVE	BLOCK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883	Suky Chong / 6747 9241		SJW8544E	01/03/2019	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5055D
Vehicle Details	
Vehicle No.:	SML1145S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	OPEL
Vehicle Model:	INSIGNIA GRANDSPORT B16DTH
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	A3183378JSUX0557
Chassis No.:	W0VZM6EF9K1035229
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$25,667.00
Original Registration Date:	06 May 2019
First Registration Date:	06 May 2019
Transfer Count:	0
Actual ARF Paid:	\$27,934.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 May 2029
PARF Rebate Amount:	\$20,950.00
Intended COE Rebate Details	
COE Expiry Date:	05 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,403.00
COE Rebate Amount:	\$34,713.00
Total Rebate Amount:	\$55,663.00

The information contained herein is correct as at 15 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2019 18:33
Date Of Accident	04/07/2019 16:30
Exact Location Of Accident	JOO CHIAT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML1145S
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	201735055D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81641811
Alternative Phone No	OFFICE-81641811

Vehicle Particulars

Manufacturer	OPEL
Model	INSIGNIA-1.6 TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994322
Cover Note Number	

Driver

Name of Driver	HO KAH SHUANG ALVIN
NRIC No	S6935092E
Date Of Birth	08/10/1969
Occupation	INDOOR
Date Of Driving Pass	30/11/1987
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90039275
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	APT BLK 247 TAMPINES STREET 21 #04-279 SINGAPORE 521247
Postcode	521247
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attachment for the circumstance of accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	YL7845Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	KONG SIANG WEI
NRIC/Passport Number	G8579442L
Contact Number	84795280
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	HO KAH SUANG ALVIN
Approximate Age	49
Injuries Sustain	
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	APT BLK 247 TAMPINES STREET 21 #04-279 SINGAPORE 521247
Postcode	521247

Accident Sketch Plan



SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE NO: 2M11152

TYPE OF ACCIDENT: 300 (HIT) COMP

DATE: 01-01-11 TIME: 12:30 PM

340 (HIT) VEHICLE NO: YL74552

PLEASE REFER TO POLICE REPORT NO: 1204/2106/2054

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature _____ Date & Time: 05-01-11

Driver's Signature _____ Date & Time: 05-01-11

Reporting Centre Personnel's Signature _____ Name: HP: 90089215


Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: OPEL INSIGNIA TURBO DIESEL
 Engine/Chassis No.: WOVZM6EF9K1035229
 Date of accident:
 Damaged area: N/S

Date: 09/07/2019
 Claim Type: TP
 VRN: SML1145S



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door n/s	1	\$ 1,980.00	\$ 1,980.00
2	Front door top hinge n/s	1	\$ 136.00	\$ 136.00
3	Front door lower hinge n/s	1	\$ 136.00	\$ 136.00
4	Front door inner trim board n/s	1	\$ 683.00	\$ 683.00
5	Front door outer handle n/s	1	\$ 296.00	\$ 296.00
6	Front door outer handle lock switch n/s	1	\$ 195.00	\$ 195.00
7	Front door lock n/s	1	\$ 285.00	\$ 285.00
8	Front door lock striker n/s	1	\$ 69.00	\$ 69.00
9	Front door window regulator n/s	1	\$ 336.00	\$ 336.00
10	Front door window motor n/s	1	\$ 286.00	\$ 286.00
11	Front door window outer channel n/s	1	\$ 113.00	\$ 113.00
12	Front door window outer chrome moulding n/s	1	\$ 265.00	\$ 265.00
13	Rear door n/s	1	\$ 1,895.00	\$ 1,895.00
14	Rear door top hinge n/s	1	\$ 136.00	\$ 136.00
15	Rear door lower hinge n/s	1	\$ 136.00	\$ 136.00
16	Rear door inner trim board n/s	1	\$ 694.00	\$ 694.00
17	Rear door outer handle n/s	1	\$ 296.00	\$ 296.00
18	Rear door outer handle lock switch n/s	1	\$ 195.00	\$ 195.00
19	Rear door lock n/s	1	\$ 385.00	\$ 385.00
20	Rear door lock striker n/s	1	\$ 88.00	\$ 88.00
21	Rear door window regulator n/s	1	\$ 436.00	\$ 436.00
22	Rear door window motor n/s	1	\$ 386.00	\$ 386.00
23	Rear door window outer channel n/s	1	\$ 145.00	\$ 145.00
24	Rear door window outer chrome moulding n/s	1	\$ 295.00	\$ 295.00
25	Rear fender n/s	1	\$ 1,129.00	\$ 1,129.00
26	Rear fender cowling n/s	1	\$ 237.00	\$ 237.00
27	Rear shock absorber n/s	1	\$ 467.00	\$ 467.00
28	Rear shock absorber mounting n/s	1	\$ 102.00	\$ 102.00
29	Rear lower arm n/s	1	\$ 387.00	\$ 387.00
30	Rear wheel knuckle n/s	1	\$ 469.00	\$ 469.00
31	Rear wheel bearing n/s	1	\$ 214.00	\$ 214.00
32	Rear bumper	1	\$ 893.00	\$ 893.00
33	Rear bumper side retainer	2	\$ 75.00	\$ 150.00

Repair Estimate

34	Taillamp n/s	1	\$ 685.00	\$ 685.00
35	Rocker panel n/s	1	\$ 884.00	\$ 884.00
36	Rocker panel rubber strip n/s	1	\$ 318.00	\$ 318.00
Subtotal				\$ 15,802.00
List discount				10.00%
Total				\$ 14,221.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips n/s	12	\$ 6.50	\$ 78.00
2	Rear door inner trim board clips n/s	12	\$ 6.50	\$ 78.00
3	Rear fender cowling clips n/s	8	\$ 6.50	\$ 52.00
4	Rear bumper clips	10	\$ 6.50	\$ 65.00
5	Rocker panel sealant n/s	1	\$ 100.00	\$ 100.00
6	Rear bumper side sensor n/s	1	\$ 380.00	\$ 380.00
7	Rear bumper side sensor holder n/s	1	\$ 47.00	\$ 47.00
8	Rear alloy wheel 17"	1	\$ 550.00	\$ 550.00
9	Rear tyre 225/55R17	1	\$ 380.00	\$ 380.00
10	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,780.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect n/s doors wire harness of electrical components to facilitate repairs, reconnect and check functions of power windows.	0.5	\$ 100.00
3	To remove and refit n/s doors components to replace both n/s doors, check alignment.	1	\$ 200.00
4	To remove and refit n/s rear fender glass to facilitate repair.	0.75	\$ 150.00
5	To remove and replace n/s rear tyre & rim. To perform tyre balancing.	0.25	\$ 50.00
6	To conduct computerized wheel alignment.	0.75	\$ 150.00
7	To remove and refit n/s rear undercarriage for replacement of parts.	1	\$ 200.00
8	Supply spray paint material and necessary items to respray both n/s doors, n/s rear fender, n/s rocker panel, rear bumper and other affected area / panel.	8	\$ 1,600.00
9	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 4,150.00

Estimate Grand Total	\$ 20,151.80
-----------------------------	---------------------