

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/72 1901261/44d3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA/PR Seen: 1

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 70

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

LTA 34139 343

1/5 MC
2900

Sen. Age

LRA 65186, 64%

Veh No:

SKF 7436T

Yr Regt:

6, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Volkswagen new golf c.c

1390

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

1.00 95.7

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ1KZCW265942

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

R/Bal.

mm

mm

L/Bal.

L/Bal.

mm

mm

D.O.A.

27/4/19

D.O.I.

9/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

9/5 Mees &

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

3

1) 12/7 12/18

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

2900

TOTAL

160
50
50
38
80

378

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

ESCAPE NOW TO OVER
60 CITIES!

ALL-IN FARE FROM

\$56*

ScootBiz from \$177*

Book Now

*Terms & conditions apply



golf

Price Range

Depreciation

2012

Vehicle Type

Home » Used Cars » Inchcape Pre-Owned » Volkswagen Golf 1.4A TSI

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$42,000

Depreciation ?

\$10,770 /yr

View models with similar depre

Reg Date

15-May-2012

(2yrs 10mths 4days COE left)

Mileage

155,680 km (21.8k /yr)

Manufactured ?

2012

Road Tax ?

\$620 /yr

Transmission

Auto

Dereg Value ?

\$29,697 as of today (change)

OMV ?

\$22,665

COE ?

\$56,551

ARF ?

\$22,665

Engine Cap

1,390 cc

Power

90.0 kW (120 bhp)

Curb Weight ?

1,241 kg

No. of Owners ?

2

Type of Vehicle

Hatchback

Features

Punchy 1.4L TSI Turbocharged Engine Producing 120Bhp And 200Nm Torque, Coupled With 7 Speed DSG Gearbox. Paddle Shifter, Multi-Function Steering. View specs of the Volkswagen Golf GTI (2003-2009)

Accessories

Original Factory Audio Sound System, Sports Rims, Reverse Sensors, Auto Headlights, Auto Side Mirrors, Fog Lamps.

Description

Experience The Agility, Comfort And Frugal Running Cost Of This Beautiful Hatchback, This Is A Versatile Car For Any Driving Needs. Call Our Sales Consultants For A Viewing Today!


Category

PARF Car

Compare



Price Chart



Click on the point to view

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Home » Used Cars » Autorol Pte Ltd » Volkswagen Golf 1.4A TSI

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$40,200**Depreciation** ⓘ

\$9,880 /yr

View models with similar depre

Reg Date

12-Jun-2012

(2yrs 11mths 1day COE left)

Mileage

92,000 km (13k /yr)

Manufactured ⓘ

2012

Road Tax ⓘ

\$620 /yr

Transmission

Auto

Dereg Value ⓘ

\$30,846 as of today (change)

OMV ⓘ

\$22,663

COE ⓘ

\$59,003

ARF ⓘ

\$22,663

Engine Cap

1,390 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,241 kg

No. of Owners ⓘ

1

Type of Vehicle

Hatchback



Location Map

Price Chart



Click on the point to view

Features

Powerful 1.4L TSI Turbocharged Engine Producing 120Bhp And 200Nm Torque, Coupled With 7 Speed DSG Gearbox. Paddle Shifter, Multi-Function Steering. View specs of the Volkswagen Golf GTI (2003-2009)

Accessories

Original Factory Audio Sound System, Sports Rims, Reverse Sensors, Auto Headlights, Solar Film, Auto Side Mirrors, Fog Lamps.

Description

Pristine Condition Both Inside And Outside, Full Servicing Just Done By Agent! Fully Agent Maintained. Enjoy Free Road Tax Renewal! Drive With Passion. Trade In And Loan Available. Also Available For Leasing! Contact For Appointment!

Category

PARF Car

Status

Available

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2410E
Vehicle Details	
Vehicle No.:	SKF7436T
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 TSI AT 5K14Q5
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	CAV396481
Chassis No.:	WVWZZZ1KZCW265942
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$27,754.00
Original Registration Date:	28 Jun 2012
First Registration Date:	28 Jun 2012
Transfer Count:	1
Actual ARF Paid:	\$27,754.00 13877
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2022
PARF Rebate Amount:	\$16,652.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$59,003.00
COE Rebate Amount:	\$17,487.00
Total Rebate Amount:	\$34,139.00

The information contained herein is correct as at 10 Jul 2019

OK

MARCUS

MOCA13052507 / Qian W Goh Motor - AMK
ENTRY DATE & TIME: 23/04/2019 15:17
SUBMITTED BY: Liu Yan Jing

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report: 23/04/2019 15:17
Date Of Accident: 22/04/2019 06:45
Exact Location Of Accident: PUNGGOL ROAD
Country/State of Loss: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SKF7436T
Insured/Policyholder
Name Of Registered Owner: LEE YEW KWONG HENRY
NRIC No: S7812410E
Email Address: HENRY.LEE_78@HOTMAIL.COM
Mobile Phone No: (LOCAL) +65-81336597
Alternative Phone No: OTHERS-81336597

Vehicle Particulars

Manufacturer: VOLKSWAGEN
Model: NEW GOLF 1.4 TSI AT 5K14Q5
Exact Purpose for which vehicle was being used at time of accident: PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken: THIRD PARTY

Vehicle Category: PRIVATE CAR

Insurance Company

Name of Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage: COMPREHENSIVE
Fleet Policy: NO
Policy Number: 5106520288
Cover Note Number:

Driver

Name of Driver: LEE YEW KWONG HENRY
NRIC No: S7812410E
Date Of Birth: 07/05/1978
Occupation: INDOOR
Date Of Driving Pass: 12/06/2012
Driving Experience: 6 YEARS AND 10 MONTHS
Gender: MALE
Mobile Number: (LOCAL) +65-81336597
Fax Number:
Contact Number: OTHERS-81336597
Email Address: HENRY.LEE_78@HOTMAIL.COM

Address BLK 168D PUNGGOL FIELD #16-665
 Postcode 824168
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4

Passenger 1 NAME: : LEE WEI MEI

GENDER: : FEMALE

Passenger 2 NAME: : LEE XUAN YU HINSLEY

GENDER: : MALE

Passenger 3 NAME: : LEE XIN EN HILARY

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY CAR WAS TRAVELLING STRAIGHT IN THE MOST LEFT LANE AND A VAN HIT ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GQ8208T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver WOO SIEW KHUEN DERRICK
 NRIC/Passport Number S1394671B
 Contact Number

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 25 APR 19

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was travelling straight in the most left lane and
a van hit onto my vehicle.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time 23 APR 19

Driver's Signature

(if driver is not the policyholder)

Date & Time


Reporting Centre Personnel's Signature

Name:

NRIC/PTN No.:



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	BLUWEL	DATE	Jul 9, 2019 11:29:38 AM
LICENSE NO.	SKF 7436 T		
MILEAGE	180951		
REFERENCE	CUSTOM	MODEL	VOLKSWAGEN GOLF (Z1K)

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.50	0.00	1.00			-0.40				0.00		
PARTIAL TOE	-0.50	0.00	0.50		-1.00		0.50		0.00		0.00	
SET BACK	---	---	---			0°04"				0°04"		
CAMBER	-1°30"	-0°30"	0°30"		-0°56"		-1°02" 0°04"		-0°54"		-1°06" 0°12"	
CASTER	6°48"	7°48"	8°48"		7°30"		7°16" 0°12"		7°30"		7°16" 0°12"	
KING-PIN	---	---	---		14°36"		14°50" 0°14"		14°36"		14°50" 0°14"	
INCL. ANGLE	---	---	---		13°38"		13°48"		13°42"		13°44"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	1.00	2.00	3.10			2.50				2.00		
PARTIAL TOE	0.50	1.00	1.50		2.20		0.30		1.00		1.00	
SET BACK	---	---	---			0°06"				0°06"		
CAMBER	-1°44"	-1°00"	-0°14"		-1°06"		-1°20" 0°14"		-1°10"		-1°10" 0°00"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°00"		



BLUWEL AUTOMOTIVE SERVICE PTE LTD


Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-33/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Not A/M
 4/5 #2900
 32.

SKF 7436T

Rear fender o/s	R	1125.00	X
Rear door o/s	R	955.00	X
Rear wheel hub bearing o/s	2x	485.00	/
Rear knuckle arm o/s	Set	625.00	/
Rear bumper	R	866.00	X
Rear sport rim o/s	Woped	1800.00	12005.00
		5856.00	
To check wiring		50.00	-20
To Dismantle & refix reverse sensor		80.00	-50
To conduct wheel alignment		150.00	-120
To Dismantle & replacing rear undercarriage		150.00	-✓
To Dismantle & refix seat cushion upholstery		120.00	-80
Labour for panel beating & replacing parts		600.00	-400
To putty & spray painting		1080.00	-600
		TOTAL	8086.00

P-1110
 57
 1054.5
 3674.5



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP19012161/Uqd3n2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 16-07-2019		
ON BEHALF OF LEE YEW KWONG HENRY		Code : TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SKF 7436T	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN NEW GOLF (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVWZZZ1KZCW265942	Colour	RED	
Odometer	180957	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/04/2019	Inspection Date	09/07/2019	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 7436T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,125.00	-
1	REAR DOOR O/S	TO REPAIR SEE LABOUR	955.00	-
1	REAR WHEEL HUB BEARING O/S	DAMAGED	485.00	485.00
1	REAR KNUCKLE ARM O/S	BENT	625.00	625.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	866.00	-
	LESS 5% DISCOUNT		-	-55.50
			4,056.00	1,054.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR SPORT RIM O/S (SN)	WARPED	1,800.00	1,200.00
			1,800.00	1,200.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REVERSE SENSOR.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	120.00
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE.		150.00	150.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S,REAR DOOR O/S AND REAR BUMPER.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	600.00
			2,230.00	1,420.00
GRAND TOTAL			8,086.00	3,674.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/TP19012161/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.