

22/01/2003

ASS. REC. BY:

Surveyor: Adnan

REF:

CS/INC19012167/Avf307

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Cynthia Aney

of

INC

Date/Time:

9/7/19 @ 10:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 8414E

Insured:

SIW 8544E

at Workshop m/s

Pro-Jax 121

Tel:

8668 7666

of

25 lalki Butut Rd 4 # 03-13

Policy No:

Claim No:

MT/1034631-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:43am @ 9/7/19

Person Contacted:

Edmund

Vehicle IN (OUT)

Date/Time	Action/Instruction
	estimate (x)
	SIW 8544E : X
	FBK 8414E : X
	Dismantle! 21/8/2019.
12/9/19	Adrian confirmed LS \$ 1250 (Red 7910, 8690)



## Celine Fong (LKKAUTO)

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Wednesday, 10 July 2019 8:39 AM  
**To:** assignments; Admin-D (LKKAUTO)  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Kindly refer below for the full details.

Thank you.

With Regards

**Cynthia Ang**  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Cynthia Ang  
**Sent:** Tuesday, 9 July 2019 10:09 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Cc:** Clarence Richard Anthony <clarence.anthony@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eng Huey Huey	MT/1052486-001	SLU1663C	TEAM AUTOPRO PTE LTD	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	Peach Ang / 6258 1955		SGS3819C	06/07/2019	
2	Chryllis Quah	MT/1052455-001	SJJ671S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGK2950D	06/07/2019	
3	Fiona Shen	MT/1052031-002	SML1145S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		YL7845Z	04/07/2019	
4	Eric Tang	MT/1049590-002	SLE2735G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLW1005S	31/05/2019	
5	Eng Huey Huey	MT/1052137-002	SME1876C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46	Chris / 6702 1555		FBP8126K	05/07/2019	

					PREMIER@KAKI BUKIT					
6	Jared Liu	MT/1052296-002	SJT8373Y	TORQUE 5 PTE LTD	8 KAKI BUKIT AVE 4 #01-50 PREMIER @ KAKI BUKIT	Lucas / 8131 6318		WC5674J	06/07/2019	
7	Chryllis Quah	MT/1052398-002	SBM131M	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 6341 6789		SJF4431M	06/07/2019	
8	Azhari	MT/1033901-001	FBL7115U	HOME ADDRESS	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY @ KB SINGAPORE 417800	Li Tian / 90054320		SKM1972P	17/02/2019	WORKSHOP NAME IS TUCK LIFE
9	Muhammad Airwan	MT/1050613-002	SJB9855L	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		FBM4589A	24/06/2019	
10	Chryllis Quah	MT/1034631-002	FBK8414E	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SJW8544E	01/03/2019	
11	Serene Lim	MT/1052122-003	GP3838M	SM AUTOMOTIVE	BLOCK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883	Suky Chong / 6747 9241		SMG722J	05/07/2019	
12	Serene Lim	MT/1052247-002	SKQ7188B	ZOOM AUTOWERKS PTE LTD	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53	Elin Cai / 9450 7920		SJU7717R	07/07/2019	

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

With Regards

**Cynthia Ang**  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8647D
<b>Vehicle Details</b>	
Vehicle No.:	FBK8414E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CBR1000RR FIREBLADE
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	SC59E2507026
Chassis No.:	JH2SC59A4GK800010
Maximum Power Output:	-
Open Market Value:	\$12,049.00
Original Registration Date:	22 Feb 2016
First Registration Date:	22 Feb 2016
Transfer Count:	2
Actual ARF Paid:	\$1,808.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Feb 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,353.00
COE Rebate Amount:	\$4,430.00
<b>Total Rebate Amount:</b>	<b>\$4,430.00</b>

The information contained herein is correct as at 02 Mar 2019

OK

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.**
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available (whereas).

**ACCIDENT STATEMENT**

Date Of Report: 05/03/2019 11:19  
 Date Of Accident: 01/03/2019 14:40  
 Exact Location Of Accident: ALONG MANILA STREET  
 Country/State of Loss: SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number: FBK8414E  
**Insured/Policyholder**  
 Name Of Registered Owner: MOHAMMAD HIDAYATTULLAH BIN MOHAMMAD MUNAWIR  
 NRIC No: S9608647D  
 Email Address: NOEMAIL  
 Mobile Phone No: (LOCAL) +65-86110521  
 Alternative Phone No: OFFICE-86110521

**Vehicle Particulars**

Manufacturer: HONDA  
 Model: CBR1000RR-998CC

Exact Purpose for which vehicle was being used at time of accident:

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken: THIRD PARTY  
 Vehicle Category: MOTORCYCLE

**Insurance Company**

Name of Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage: THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy: NO  
 Policy Number: 5106639593  
 Cover Note Number:

**Driver**

Name of Driver: MOHAMMAD HIDAYATTULLAH BIN MOHAMMAD MUNAWIR  
 NRIC No: S9608647D  
 Date Of Birth: 07/03/1996  
 Occupation: INDOOR  
 Date Of Driving Pass: 17/12/2018  
 Driving Experience: 0 YEAR AND 2 MONTH  
 Gender: MALE  
 Mobile Number: (LOCAL) +65-86110521  
 Fax Number:  
 Contact Number: OFFICE-86110521  
 Email Address: NOEMAIL

Address: BLK 520 BEDOK NORTH AVENUE 1 #04-360  
 Postcode: 460520

Was driver an employee of the Insured's Company: NO  
 If No, Relationship of the Driver with the Insured: OWNER  
 Vehicle Registration Number of Driver's Own Vehicle: -  
 Insurance Company of Driver's Own Vehicle: -

**General Information of the Accident**

Type Of Accident: COLLISION - HEAD TO REAR  
 Weather Conditions: CLEAR  
 Road Surface: DRY

**Other Information**

Was any foreign vehicle involved in this accident?: NO  
 Number of vehicles (including own vehicle) involved in the accident: 2  
 Was any body injured in the Accident?: YES  
 Was any injured conveyed to hospital by ambulance?: NO  
 Was any other material or property damaged?: YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance: NO  
 Number of Passengers (including Driver): 2  
 Passenger 1: NAME: : FIRSHA  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police?: YES  
 If Yes, Please state which Police Station: KAKI BUKIT NEIGHBOURHOOD POLICE POST  
 Police Station Name: ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526  
 Police Station Address: COUNTRY: SINGAPORE  
 Police Station Contact: TEL NO: 1800-4429999 - FAX NO: 62444377  
 Was notice of intended Prosecution given?: NO  
 If Yes, against whom?:

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?: YES  
 Was there any video captured by Car Camera?: YES  
 Was there any audio recorded?: NO

**Details of Witness 1**

Name: RAJAMANICKAM  
 Phone Number: 96501974  
 Email Address:

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number: SJW8544E  
 Vehicle Make/Model/Colour:  
 Details Of Properties:  
 Vehicle Category: PRIVATE CAR



Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No. 1800-4429999



T7201903042086

2 of 3

Report No. T7201903042086

CONTINUATION OF REPORT

Details of Person Involved	
Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	
Rider:	
Name	MOHAMMAD HIDAYATULLAH BIN MOHAMMAD MUNAWIR
ID No.	S9608647D
Related Vehicle	FBK8414E (Motorcycle)
Contact No.	86110521
Hospital/Clinic	CHANGI GENERAL HOSPITAL
Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	01/03/2019
No. of Days granted Medical Leave	04
Date Discharge	01/03/2019
Degree of Injury	Slight
Driver:	
Name	LIM PENG HWA
ID No.	S1623539E
Related Vehicle	SJW6544E (Car)
Contact No.	96972104
Hospital/Clinic	NIL
Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL
No. of Days granted Medical Leave	NIL
Date Discharge	NIL
Degree of Injury	NIL


**Brief Details.**

On 01/03/2019 at about 1440hrs, I was riding along Mania Street on a two lane road. I was on the left lane behind another vehicle (SJW6544E). As there were road works on the lane I was travelling on, the vehicle in front of mine wanted to move to the lane on the right. One of the workmen then directed the driver of the vehicle to reverse, however the vehicle just reversed without checking and collided onto me. The driver came out afterwards to check on me. Ambulance came to scene and make a check on me but I was not conveyed. We exchanged details on the spot.

I went to CGH myself to seek medical assistance and I was given 4 days MC dated from 01/03/2019 to 04/03/2019. I have a witness who is the workman namely Rajamanickam Sathoshkumar and his supervisor contact details as (HP-96501974). I have a video of what happened after the accident. I also believed that the vehicle might have an in-car CCTV.

I wish to state that upon contact my pillion slipped and fell on her back. She went to receive medical attention today on 04/03/2019 and was given one day MC.

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER POLICE REPORT.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
IRIC/FIN No.:

# Estimate

TP INC.  
Veron

Vehicle: FBK 8414E

Make & Model: HONDA CB1000RR Year: 2016

Chassis no: \_\_\_\_\_

Qty	Parts / Labour	Cond	Part \$
1	FR7 FENDER R/L	+	300
1	FR7 wheel	+	980
1	disc set	+	1,350
1	bearing (set)	+	120
1	slider	+	80
2	FR7 Forks (a) 900	+	1,800
1	FR7 Fork stem	+	350
1	bearing	+	20
1	upper bracket	+	180
1	Head lamp	+	850
1	visor	+	180
1	fairing	+	450
1	garnish	+	90
2	Side fairing L & R @ 680	+	1,360
2	garnish L & R @ 95	+	190
			1180
			1062
1	Labour	200	350
1	Spray paint & Sticker	300	450
			9160

LKK Aut. Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

PROJECT V2D MOTOR PTE LTD.  
ACRA  
201600429G

Adrian G  
4/5 20/08/19.  
03 days.

total: 1562  
4/5: 1250



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012167/Avf3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 17-09-2019



ATTN: CHRYLLIS QUAH

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 8544E	Veh. Inspected	FBK 8414E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1034631-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	09/07/2019

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA CBR1000	c.c	999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JH2SC59A4GK800010	Colour	RED / WHITE
Odometer	50560 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55 R17	PIRELLI	6 mm
L/H Rear Tyre			mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	01/03/2019	Inspect Date / Time	20/08/2019 ( 12:55 PM )
Survey held at	PRO-JEX V2D MOTOR PTE LTD 25 KAKI BUKIT ROAD 4 #03-94 SYNERGY @ KB SINGAPORE 417800		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 8414E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT FENDER	TO REPAIR SEE LABOUR	300.00	-
1	FRT WHEEL	NOT NECESSARY	980.00	-
1	SET FRT WHEEL DISC	NOT NECESSARY	1,350.00	-
1	SET FRT WHEEL BEARING	NOT NECESSARY	120.00	-
1	FRONT WHEEL SLIDER	NOT NECESSARY	80.00	-
2	FRT FORK @\$900.00	NOT NECESSARY	1,800.00	-
1	FRT FORK STEM	NOT NECESSARY	350.00	-
1	FRT FORK STEM BEARING	NOT NECESSARY	80.00	-
1	FRT FORK UPPER BRACKET	NOT NECESSARY	180.00	-
1	HEAD LAMP	NOT NECESSARY	850.00	-
1	HEAD LAMP VISOR	NOT NECESSARY	180.00	-
1	HEAD LAMP FAIRING	NOT NECESSARY	450.00	-
1	HEAD LAMP FAIRING GARNISH	CRACKED	90.00	90.00
2	SIDE FAIRING L&R @\$680.00	CRACKED	1,360.00	900.00
2	SIDE FAIRING GARNISH L&R @\$95.00	CRACKED	190.00	190.00
	LESS 10% DISCOUNT		-	-118.00
			8,360.00	1,062.00
<b>LABOUR</b>				
	LABOUR. INCLUSIVE OF THE REPAIR OF FRT FENDER.		350.00	200.00
	SPRAY PAINT & STICKER.		450.00	300.00
			800.00	500.00
<b>GRAND TOTAL</b>			<b>9,160.00</b>	<b>1,562.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,250.00</b>

Report Ref No. CS/INC19012167/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**