

22/03/2018

A.S. REC. BY:

REF:

CS1SPF19012184/Ksf352

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hafizul Farhan of SPFDate/Time: 9/7/19 @ 4:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGR 1903KInsured: TP 67Lat Workshop m/s K. Kim Hin AutoTel: 64527018of 160 Sin Ming Drive #02-20

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A. 4/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:34pm @ 10/7/19

Person Contacted:

SandraVehicle IN OUT

Date/Time

Action/Instruction

Soliman/11/5TP 67L : CS1/SPF19005000/K1qd352 D.O.A. 04/11/2018SGR 1903K : X19/8/19 @ 3:53pm Meng Huat will check & call us.**Do Not Finalise**

ASS. REC. BY:

REF:

SPF/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

11/27

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SGR1903K

Yr Regn: _____

02, 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

NIS Latio

c.c

1498

Colour: _____

M.D. Brown

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

192330

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JN1BAAC1180003947

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

Rear

R/Bal. _____

4

mm

R/Bal. _____

7

mm

L/Bal. _____

6

mm

L/Bal. _____

7

mm

D.O.A. _____

4/7/19

D.O.I. _____

9/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

11/27 812506

@ 09:28 am

RECEIVED 13 SEP 2019

12/09/19 Range - \$1,100/- - \$1,500/- checked with Kenneth

3 days (0 weekends) = 3 days

Date/Time, File Pass to?

13/09/19

☐

: Prell. Report

1)

Type: 4

☒

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

3

Resurvey No. of Trip: _____

Survey Fee: _____

220

Transportation: _____

S + RS. \$

Fees

Others

TOTAL

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

1,250/- US

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 9 July 2019 4:40 PM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF)
Subject: Pre-Repair survey of SGR1903K (vs TP67L DOA: 4/7/2019)

Hi,

Kindly conduct pre-repair survey of SGR1903K at:

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive
#02-20 Sin Ming Autocity
Singapore 575722
CONTACT NO: 6452 7018

Best Regards,

Hafizul Farhan Bin Rahmat
AEMD / PLD
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4850



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 17:39
Date Of Accident	04/07/2019 08:10
Exact Location Of Accident	PIE TOWARDS TUAS NEAR EXIT 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR1903K
Insured/Policyholder	
Name Of Registered Owner	PANG TENG SENG
NRIC No	S7928725C
Email Address	DPANGTS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81277295
Alternative Phone No	OFFICE-81277295

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S52200033SMF
Cover Note Number	

Driver

Name of Driver	PANG TENG SENG
NRIC No	S7928725C
Date Of Birth	15/09/1979
Occupation	INDOOR
Date Of Driving Pass	05/03/1999
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81277295
Fax Number	
Contact Number	OFFICE-81277295
EMail Address	DPANGTS@GMAIL.COM

Address 772 BEDOK RESERVOIR ROAD #07-14
 Postcode 479251
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : TAN ZHEN DIAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 1 TOH YI DRIVE , POSTCODE: 590001 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4689999 - FAX NO: 64623782
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN & POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH TRAFFIC POLICE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number TP67L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PANG TENG SENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SGR1903K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name TAN ZHEN DIAN
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

C-Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT.

MY WIFE AND I WILL SEE DOCTOR LATER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Company Chop (if applicable)

1. *Hydroglaea* *hydroglaea* (Linn.)

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Name:

NR/C/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20190704/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

1 of 3

Report No. T/20190704/2060

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/07/2019 12:59		Vide Report No.: G/20190704/0067		Station Diary No.: 12	
Informant's Particulars					
Name of Informant: PANG TENG SENG			Address: APT BLK 772 BEDOK RESERVOIR ROAD #07-14 SINGAPORE 479251		
ID Type / ID No.: NRIC NO / S7928725C			Contact No.: Home/Office: Mobile: 81277295		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 15/09/1979	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Accountant			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/07/2019 08:10	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Tuas, near Exit 12				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGR1903K	Car				Slightly Damaged	1
TP67L	Motorcycle				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190704/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 3

Report No. T/20190704/2060

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date and time, I was driving my black Nissan Latio bearing the plate number SGR1903K along PIE towards Tuas. At this juncture there was heavy traffic along PIE and the weather was clear with dry roads. I was driving along the second lane of the expressway.

Subsequently, I noticed that there was a Traffic Police Motorcycle bearing the plate number TP67L moving towards my direction from the rear. I observed that the said Traffic Police Motorcycle was attempting to move to the first lane on the right, as I also observed that there was an ambulance ahead in the congested traffic with blinker turned on. I wish to state that at this juncture, the traffic was slow moving, and I had to constantly apply brakes when the vehicle ahead of me has applied brakes.

Subsequently, when the vehicle ahead of me applied brakes, I also followed suit and applied brakes. However, I believe that while I was doing this along the slow moving traffic, the said Traffic Police Motorcycle was trying to move through the congested traffic, and as I had applied the brakes, he subsequently collided onto the right side of my vehicle.

As a result of the collision, the right rear side of my vehicle had sustained slight damages which includes scratches to the right rear bumper. The rear right bumper was also broken. On the other hand, there were also some slight damage to the left front of the Traffic Police Motorcycle. Both parties then made a check and no one informed that they were injured at the material moment, including my wife who was on board my vehicle, namely, Tan Zhen Dian, NRIC: S8403639J, H/P: 81216879.

Subsequently this incident was attended by another Traffic Police resource. No one was conveyed by ambulance to hospital. As there were in-car cameras installed in my vehicle, the Traffic Police Officer who attended to the scene had obtained the video footages from me. I am unaware if there were any CCTV installed around the incident location.

I was then informed by IO Afiq Tel: 65476171 of the Traffic Police to lodge this Police Report. That is all.



**SINGAPORE
POLICE FORCE**



T/20190704/2060

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 3
Report No. T/20190704/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 2 LIM WEI SHENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/07/2019 12:59
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Contact No.:	
Authentication Stamp NP168	SN 38
SIGNATURE	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8725C
Vehicle Details	
Vehicle No.:	SGR1903K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	HR15075221A
Chassis No.:	JN1BAAC11Z0003947
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,752.00
Original Registration Date:	01 Feb 2007
First Registration Date:	01 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$15,128.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,645.00
COE Rebate Amount:	\$38,351.00
Total Rebate Amount:	\$38,351.00

The information contained herein is correct as at 04 Jul 2019

OK

*Pls kindly
analyse for
honesty*
6/7/19

CO. REG. NO: 199402370D
GST NO: M2-0123250-3



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

SPF
Fax: 64784848

Vehicle Insured : TP 67 L
Accident Date : 04-Jul-2019

No. : 30549

Date : 06-Jul-2019

Our Ref : 190371 (SPF) / SANDRA

PAGE : 1

PANG TENG SENG (MR)
Singapore

Not wharfed
Runner 1/1 Run & ?
After Paint 3 days

ESTIMATED COST OF REPAIR FOR NISSAN LATIO 1.5L A (2007) SGR1903K

1 pc rear bumper
1 pc o/s rear bumper side retainer

Bulim 532.40 n —
D.I 35.20 n —

567.60

Less 10% : -56.76

510.84

10 pcs rear bumper clips
1 pc o/s rear tyre
1 pc o/s rear sport rim

@ S\$ 2.60

RM 26.00 sn ✓
CR 180.00 sn *70Wm*
RD 450.00 sn *250Wm*

300.00 *2001*

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

580.00 *4001*

To putty and respray on affected
portions.

To conduct front wheel alignment
test.

1572.84
1/1 \$1,230/-
80.00 *601*

Total : S\$ 2,126.84

Singapore Dollars Two Thousand One Hundred and
Twenty Six and Cents Eighty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF19012184/Ksf3s2

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 16-09-2019



ATTN: HAFIZUL FARHAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	TP 67L	Veh. Inspected	SGR 1903K
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/075	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	09/07/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JN1BAAC11Z0003947	Colour	METALLIC DARK BROWN
Odometer	192330	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	TOYO	4 mm
L/H Front Tyre	205/50 R16	TOYO	4 mm
R/H Rear Tyre	205/50 R16	TOYO	7 mm
L/H Rear Tyre	205/50 R16	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/07/2019	Inspection Date	09/09/2019
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 1903K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	BUCKLED / CRACKED	532.40	532.40
1	O/S REAR BUMPER SIDE RETAINER (N)	DISTORTED	35.20	35.20
	LESS 10% DISCOUNT		-56.76	-56.76
			510.84	510.84
SPECIAL NETT ITEMS				
10	REAR BUMPER CLIPS @ \$2.60 (SN)	NECESSARY	26.00	26.00
1	O/S REAR TYRE (70%) (SN)	CUT	180.00	126.00
1	O/S REAR SPORT RIM (SN)	DENTED	450.00	250.00
			656.00	402.00
LABOUR				
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		300.00	200.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		580.00	400.00
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		80.00	60.00
			960.00	660.00
GRAND TOTAL			2,126.84	1,572.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/SPF19012184/Ksf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,100.00 - \$1,500.00

RECOMMENDED REPAIR DAYS : 3
WEEKENDS : 0
TOTAL DAYS : 3

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.