

22/03/2019

ASS. REC. BY:

REF: CS3/ASG19012185/Ref302

Special Instruction:

Surveyor: Lim Chong

ASSIGNMENT (Office)

From (Person): ehin lee ying

of

MG

Date/Time:

3.46pm @ 8/7/2019

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 7404T

Insured:

SMH 8013P

at Workshop m/s

Yeow Koon Auto

Tel:

64482700

of

1 kaki Bukit Ave 6 # 01-38

Policy No:

0999994142

Claim No:

125762682186

Sum Insured:

Excess:

Make of Veh:

D.O.A.

6/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:41am @ 10/7/19

Person Contacted:

Mavis

Vehicle IN

OUT

Date/Time

Action/Instruction Estimate (X)SMH 8013P - XGBA 7404T: NA/INC1100/1862/AW1D.O.A: X/10/2011After repair: 15/7/2019

Surveyor

PRS  
62.

REF:

AIG

B 2832 K

ASSIGNMENT

(-2022)

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s Klaw Koon Auto  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \$30K  
IDAC Accident Rpt.: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: 6 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 6BA2404 T Yr Regn: 27 Nov 2007  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Toyota Hiace C.C. 2982  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 264978 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JT FHT 02P 20003 6653  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195 R15  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or CST  
Front R/Bal. 5 mm Rear R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. \_\_\_\_\_ D.O.I. 10-07-19  
Survey held at w/s 4:15pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000  
16/7 3.30pm Sindy said will fax over the GIA to us.  
COB: 10/13

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : DAR

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: 180

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

|     |
|-----|
| 180 |
| 11  |
| 191 |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |   |               |  |         |               |            |   |
|--------------------------|---|---------------|--|---------|---------------|------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt | Adj Submitted | Ins Auth'd | Status  |
| Main                     | 01 Aug 2019<br><a href="#">Edit Reg</a> |               | 24 Jul 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> |         |               |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |  |                        |                            |
|-----------------------------|--|------------------------|----------------------------|
| Insured:                    | Daimler South East Asia, Co. Reg. No.: 199000355E, Tel: +6599999999  |                        |                            |
| Main Claimant:              | UNKNOWN, Co. Reg. No.: NA  |                        |                            |
| Vehicle Reg. No.:           | GBA7404T   | Date of Loss:          | 06/07/2019 00:00 - :59     |
| Claim Type:                 | TP / 1257626821SG  | Policy/Cover Note No.: | 0999994142 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SMH8013P   | Policy No. (Claimant): |                            |
|                             |  | Excess:                |                            |
| Repairer:                   | Yeow Koon Auto Care Pte Ltd (HQ) BLK 3012 BEDOK INDUSTRIAL PARK E #01-2016, 489978 Bedok - Tel: 64483039 /93202773 |                        |                            |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000   |                        |                            |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/08/2019]  |                        |                            |


**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc:  
Sent: 7/8/2019 3:46:28 PM  
Attachments:  9693 . PRI.PDF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** admin@bsalaw.com.sg [mailto:admin@bsalaw.com.sg]  
**Sent:** Monday, July 08, 2019 2:52 PM  
**To:** Hor, Yinrul  
**Cc:** admin@bsalaw.com.sg  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMH8013P AND GBA7404T ON 06/07/2019

Dear Madam ,

We refer to the captioned matter and your email dated today.

Kindly take note that we have instructions to reject your panel of motor surveyors.

Our client would be conducting a survey with their surveyor, Mr T THIYAGARAJAN @ ROGER T. If you disagree with our clients's choice of surveyor, please arrange for your own surveyor to also survey the vehicle.

On a separate note, kindly contact our client's workshop **Yeow Koon Auto Care Pte Ltd**, Tel : 98596222 (Ms Crystal) before you send your surveyor down if you choose your own surveyor.

The vehicle would be at :-

**Yeow Koon Auto Care Pte Ltd**

1 Kaki Bukit Avenue 6

#01-38

[AutoBay@Kaki Bukit](mailto:AutoBay@KakiBukit)

Singapore 417883

Contact person: Ms Crystal

HP: 98596222 Tel: 64482700 (office) Fax: 64482086

Thank you.

Regards

Ms Mavis

For and on behalf of

M/s BSA Law Chambers LLC

DID: 6435 0019

Email: [admin@bsalaw.com.sg](mailto:admin@bsalaw.com.sg)

---

M/s BSA LAW CHAMBERS LLC (UEN No. 201502330R)

133 New Bridge Road

#10-04 Chinatown Point

Singapore 059413

Tel : 6236 2001

Fax : 6532 0412

Email : [bala@bsalaw.com.sg](mailto:bala@bsalaw.com.sg)

Disclaimer:

This e-mail is confidential and may also be privileged. If you are not the intended recipient please notify us immediately at Telephone : 6236 2001 or Fax No. 6532 0412. You should not copy this e-mail or use it for any purpose nor disclose its contents to any other person.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# **BSA LAW CHAMBERS LLC**

Advocates & Solicitors

**Your Ref :**

**Our Ref :** BSA. 9693. mc

**Date :** 8<sup>th</sup> July 2019

133 New Bridge Road  
#10-04 Chinatown Point  
Singapore 059413

Tel : 6236 2001

Fax : 6532 0412

Email : bala@bsalaw.com.sg

UEN Regn No: 201502330R

Secretary's DID: 6435 0020 (Alice)  
6435 0019 (Mavis)

**BY EMAIL ONLY (Yinrul.Hor@aig.com)**

**AIG Asia Pacific Insurance Pte Ltd**  
Motor Claims Department

Dear Sir / Madam,

## **NOTICE OF ACCIDENT**

**YOUR INSURED VEHICLE REGISTRATION NO: SMH 8013P**


**ACCIDENT ON 06.07.2019 AT ABOUT 1550HRS INVOLVING GBA 7404T & SMH 8013P  
ALONG UPPER THOMSON ROAD TOWARDS SEMBAWANG**

We are informed by the repairers of vehicle registration no. GBA 7404T to notify you of the captioned road traffic accident.

Please note that State Court Practice Directions Amendment 1 of 2016 applies to this case. A copy of the accident statement / police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



f M/S BSA LAW CHAMBERS LLC  
Enc

cc **Yeow Koon Auto Care Pte Ltd**  
Contact person: Ms Crystal  
HP: 98596222  
Tel: 64482700 (office)  
Fax: 64482086

Email: [sm@idac.com.sg](mailto:sm@idac.com.sg)

Tel no: 6555 6888 Fax no: 6454 3279

**Personal Particulars of Owner & Driver (Vehicle A)**

Date of Accident: 06/07/2019 (dd/mm/yy) Time of Accident: 15:50 (24-HR-FORMAT)  
Vehicle No.: QBA 7404T Vehicle Make & Model: TOYOTA HIACE  
Exact location of Accident: ALONG UPPER THOMSON RD TOWARDS SEMBAWANG.  
Policyholder's Name / IC No.: JUST 4U SERVICE UEN: 53342832K  
Driver's Name / IC No.: LEE YAM SENG F7542901X (As Above) ☐  
Driver's Contact No.: 9452 8132 Company Contact No.: A: 8389 9248  
Driver's Address: BLK 114 ANG MO KIO AVE 4 #09-357 S (560114)  
Email address (if any): \_\_\_\_\_ Insurance Company: NTUC

**Relationship between Owner & Driver:** (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: \_\_\_\_\_

**What do you wish to claim?** (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle was being used at time of accident?**

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

☐ Private use / ☒ Work purpose

No. of Passengers (Including Driver): 02

**Weather condition & Road conditions?** (On the day of accident)

01 FEMALE PASSENGER

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: \_\_\_\_\_

**Was there any video captured by your Car Camera?** ☐ Yes / ☒ No

**Any Injuries:** ☐ Yes / ☒ No (If YES) Injured Person's Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

**Police Report filed:** ☐ Yes / ☒ No (If YES) Which Police Station: \_\_\_\_\_

**The Other Party(s) Details:**

1. Driver's Name / IC No.: ITAN SHUYI, CHARISSA S9148418H Vehicle No.: SMAH 8013P

Driver's Contact No.: 97515 615 Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No.: NICHOLAS TI YAN SHEN S9733352A Vehicle No.: SJX 5414L

Driver's Contact No.: 9878 1900 Insurance Company (If any): \_\_\_\_\_

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

### **JUST4U SERVICE**

UEN: 53342832K

218 Joo Chiat Road, #01-03 Soho Life

Singapore 427483

Email: just4uservice1@gmail.com

HP: 9452 8132

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



↑ ↓ UOB BANK



B: SMH 8013 P

C: SJX 54142.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On mentioned date and time, I was driving along <sup>UPP</sup> Thomson Road towards Sembawang direction. At the traffic junction near JAL TODAY I stopped due to the traffic light (RED LIGHT). While waiting I felt a jerk and my vehicle surge forward. When I got down to inspect I noticed there are two (2) vehicles behind my van. It was a chain collision involving three (3) vehicles. My vehicle has a lady passenger and no one injured. We exchange particulars and took some photos of the accident scene.

## JUST 4U SERVICE

~~UEN: 53342832K~~

2100 Declaration

I/We declare that the above particulars are true in every respect.

Email: [Just4uservice1@gmail.com](mailto:Just4uservice1@gmail.com)

HP: 9452 8132

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

**Date & Time:**

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No.:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|  |                         |
|--|-------------------------|
| Owner ID Type:   | Business                |
| Owner ID:  | 2832K                   |
| Vehicle No.:   | GBA7404T                |
| Vehicle to be Exported:  | No                      |
| Intended Deregistration Date:  | 10 Jul 2019             |
| Vehicle Make:  | TOYOTA                  |
| Vehicle Model:   | HIACE MANUAL            |
| Primary Colour:  | Blue                    |
| Manufacturing Year:  | 2007                    |
| Engine No.:  | 1KD1708572              |
| Chassis No.:   | JTFHT02P200006653       |
| Maximum Power Output:  | -                       |
| Open Market Value:   | \$24,690.00             |
| Original Registration Date:  | 27 Nov 2007             |
| First Registration Date:   | 27 Nov 2007             |
| Transfer Count:  | 5                       |
| Actual ARF Paid:   | \$0.00                  |
| PARF Eligibility:  | No                      |
| PARF Eligibility Expiry Date:  | -                       |
| PARF Rebate Amount:  | \$0.00                  |
| COE Expiry Date:   | 31 Jul 2022             |
| COE Category:  | C - Goods Vehicle & Bus |
| COE Period(Years):   | 5                       |
| PQP Paid:  | \$17,035.00             |
| COE Rebate Amount:   | \$10,413.00             |
| <b>Total Rebate Amount:</b>  | <b>\$10,413.00</b>      |
| Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle. |                         |

The information contained herein is correct as at 10 Jul 2019

OK

**► Hiace Used Vehicle List (20 vehicles)**

| Car Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Company | Availability |
|-----------|-------|--------------|----------|---------|---------|---------|--------------|
|-----------|-------|--------------|----------|---------|---------|---------|--------------|

|  |             |             |          |            |                                    |                  |
|--|-------------|-------------|----------|------------|------------------------------------|------------------|
| <b>Toyota Hiace Commuter 2.0M \$48,888</b><br>(New 10-yr COE) (Petrol) | \$4,880 /yr | 25-Mar-1999 | 1,998 cc | 208,000 km | William Lee Car Aircon Engineering | <b>Available</b> |
|--|-------------|-------------|----------|------------|------------------------------------|------------------|

With 10yr Coe Pte Plate 9 Seater With New Seat And Safety Belt Just Pass All Inspection. New Rim And Tyres Coe 5yr Selling \$29800. 10yr Selling \$45888. Loan Available Call For More Infor With Our Sale...

Office No. - 63821006

William - 94557994 | Ben - 98274488 | Keith - 98290368 | Erik Lee - 87778500

|                                   |                 |   |             |          |   |                  |
|-----------------------------------|-----------------|---|-------------|----------|---|------------------|
| <b>Toyota Hiace 3.0M (Diesel)</b> | <b>\$54,900</b> | - | 15-Apr-2003 | 2,985 cc | - | <b>Available</b> |
|-----------------------------------|-----------------|---|-------------|----------|---|------------------|

Toyota Hiace Has Always Been A Reliable Vehicle, Selling Due To Loss Of Contract Jobs. My Loss Is Your Gain. COE Till 2023.

Office No. - -

Tok Peng Cheng - 86868586

|  |                 |             |             |          |   |                  |
|--|-----------------|-------------|-------------|----------|---|------------------|
| <b>Toyota Hiace 3.0M (COE till 06/2023) (Diesel)</b> | <b>\$20,800</b> | \$5,230 /yr | 20-Aug-2003 | 2,986 cc | - | <b>Available</b> |
|--|-----------------|-------------|-------------|----------|---|------------------|

Office No. - -

Mr Ang - 94510993

|  |                 |             |             |          |   |                  |
|--|-----------------|-------------|-------------|----------|---|------------------|
| <b>Toyota Hiace 3.0M (COE till 02/2022) (Diesel)</b> | <b>\$18,000</b> | \$6,820 /yr | 14-Oct-2004 | 2,986 cc | - | <b>Available</b> |
|--|-----------------|-------------|-------------|----------|---|------------------|

Office No. - -

Francis Teo - 98222931

|  |                |   |             |          |   |                             |                  |
|--|----------------|---|-------------|----------|---|-----------------------------|------------------|
| <b>Toyota Hiace 3.0M (COE till 10/2019) (Diesel)</b> | <b>\$7,500</b> | - | 26-Jan-2005 | 2,986 cc | - | GF Motor Trading Enterprise | <b>Available</b> |
|--|----------------|---|-------------|----------|---|-----------------------------|------------------|

|  |                 |              |             |          |   |                       |                  |
|--|-----------------|--------------|-------------|----------|---|-----------------------|------------------|
| <b>Toyota Hiace 2.5M (COE till 03/2020) (Diesel)</b> | <b>\$16,838</b> | \$23,190 /yr | 04-Apr-2005 | 2,494 cc | - | Hoe Beng Auto Trading | <b>Available</b> |
|--|-----------------|--------------|-------------|----------|---|-----------------------|------------------|

In-House Loan Available. Many Parts Changed Already. New Clutch And Mountings.

Office No. - 62501831

Agnes - 93680138 | James - 98300138

|  |                 |              |             |          |   |              |                  |
|--|-----------------|--------------|-------------|----------|---|--------------|------------------|
| <b>Toyota Hiace 2.5M (COE till 04/2020) (Diesel)</b> | <b>\$13,800</b> | \$18,180 /yr | 13-Apr-2005 | 2,494 cc | - | Yes Motoring | <b>Available</b> |
|--|-----------------|--------------|-------------|----------|---|--------------|------------------|

Reliable Unit As It Is Condition. Good For Another 5 Years Renewal.

Office No. - -

CS Lim - 91915884 | Rahmat - 92471508

|  |                 |             |             |          |   |                           |                  |
|--|-----------------|-------------|-------------|----------|---|---------------------------|------------------|
| <b>Toyota Hiace 2.5M (COE till 04/2026) (Diesel)</b> | <b>\$44,800</b> | \$6,650 /yr | 05-Apr-2006 | 2,494 cc | - | Net Link Partners Pte Ltd | <b>Available</b> |
|--|-----------------|-------------|-------------|----------|---|---------------------------|------------------|

Cheap! Lowest Depreciation! 6.9 Yrs Usage! Rare License Plate! 133! Immaculate Condition! View To Believe! Call Fast Before It's Gone!

Office No. - 67531661

Peter - 84898866 | Jeremy - 83215291 | Teo - 92967266

|  |                 |              |             |          |   |                     |                  |
|--|-----------------|--------------|-------------|----------|---|---------------------|------------------|
| <b>Toyota Hiace 2.5M (COE till 05/2021) (Diesel)</b> | <b>\$19,800</b> | \$10,610 /yr | 22-May-2006 | 2,494 cc | - | Avil Motors Pte Ltd | <b>Available</b> |
|--|-----------------|--------------|-------------|----------|---|---------------------|------------------|

Cheaper In Town, 5 Doors Urvan! Then Rent. Well Kept Condition! Powerful Aircon! Easy In House Finance, High Trade In, Don't Miss! Call Us Now For Viewing To Believe!

Office No. - -

C K - 93869133 | Eric - 93848636 | C S Tan - 97293625

|  |                 |             |             |          |   |                  |                  |
|--|-----------------|-------------|-------------|----------|---|------------------|------------------|
| <b>Toyota Hiace 3.0M (COE till 01/2022) (Diesel)</b> | <b>\$22,800</b> | \$9,030 /yr | 18-Jan-2007 | 2,982 cc | - | SA Motor Trading | <b>Available</b> |
|--|-----------------|-------------|-------------|----------|---|------------------|------------------|

One Of The Best Commercial Van. Well Maintained By Careful Owner. Loan And Trade In Available. Call Now. Don't Miss.

Office No. - 65151328

Tang - 98893854 | Chai - 96868552

**Toyota Hiace 3.0M (COE till 01/2022) (Diesel)**    **\$21,800**    \$8,570 /yr    25-Jan-2007    2,982 cc    -    SG Motor Link Pte Ltd    **Available**

Spare Van Used For Light Office Items/Goods Delivery. Well-Maintained By Previous Owner, Low Mileage, Full Servicing Done, 100% Bank/In-House Loans Available, Offer High Trade-In Prices, Price Negotia...

Office No. - 62508527

Keegan Goh - 98578091 | James Tan - 92956506

**Toyota Hiace 3.0M (COE till 06/2022) (Diesel)**    **\$26,800**    \$9,220 /yr    06-Jun-2007    2,982 cc    -    William's Auto    **Available**

Very Well Maintained By Previous Owner. Most Importantly, Accident-Free! Buy With No Worries As Toyota Usually Doesn't Give Many Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Pro...

Office No. - 67436811

Mr Png - 97942630

**Toyota Hiace 2.5A (COE till 07/2022) (Diesel)**    **\$27,800**    \$9,260 /yr    11-Jul-2007    2,494 cc    158,376 km    KSL Automotive Pte Ltd    **Available**

Engine And Gearbox In Excellent Condition! Interior In Excellent Condition! New Paintwork! 14 Seater Bus! One Of The Most Reliable Bus In The Market! Drive Off Anytime With No Worries! 100% Loan Avail...

Office No. - 62660777

Dylan - 86886676 | Beh - 83532939 | Ah Wei - 83086254

**Toyota Hiace 3.0M (COE till 07/2022) (Diesel)**    **\$29,800**    \$9,740 /yr    13-Aug-2007    2,982 cc    200,000 km    Cars Select    **Available**

-

Office No. - -

Ken - 93388994

**Toyota Hiace 2.5A (COE till 08/2027) (Diesel)**    **\$49,800**    \$6,110 /yr    17-Oct-2007    2,494 cc    -    ABWIN Bus Pte Ltd    **Available**

Super Low Depreciation 14 Seater Hi-Roof. Well Maintenance. Over-trade, Over Loan All Ok. Free Gift And A Lot More. Call Now!

Office No. - 69339414

Dan - 83213033 | Zhi Wei - 91055246

**Toyota Hiace 2.5A (COE till 07/2027) (Diesel)**    **\$42,800**    \$5,310 /yr    24-Oct-2007    2,494 cc    -    YS Auto Pte Ltd    **Available**

Lowest Depreciation! \$5300 Per Year Very Good Condition! View To Believe! Come Down To Test Drive! Call Now Before It Gone!

Office No. - 64669792

Ken Wang - 88261199 | Teo - 97433225 | Shamir - 96629744 | Gary - 97222882

**Toyota Hiace Commuter 3.0A (COE till 05/2028) (Diesel)**    **\$49,800**    \$5,630 /yr    15-May-2008    2,982 cc    348,835 km    Think One Automobile & Trading    **Available**

-

Office No. - 65553300

Sheila - 93911969 | Wong - 96884305 | Eric - 91638879

**Toyota Hiace 2.5A (COE till 06/2023) (Diesel)**    **\$27,800**    \$7,080 /yr    13-Jun-2008    2,494 cc    147,000 km    COE Auto Trading    **Available**

Super Rare Auto 5 Door Hiace! Mint & Genuine Condition. Comes With Rear Aircon & 2 Glass Panel. Interior Upholstery Fully Done Up. New Paintwork Done. Probably The Best Hiace You Can Find.

Office No. - 64589833 / 64571902

Mr Liauw - 96718933 | Mr Chua - 98181643

**Toyota Hiace Commuter 3.0M (COE till 06/2028) (Diesel)**    **\$55,800**    \$6,230 /yr    20-Jun-2008    2,982 cc    -    **Available**

View To Offer. Driven By A Careful Driver. Regular Maintenance Done. Vehicle Is In Fantastic Condition.

Office No. - -

Eddie - 90079769

**Toyota Hiace Commuter 3.0A (New 5-yr COE) (Diesel)**    **\$30,800**    \$6,150 /yr    07-Aug-2008    2,982 cc    -    Valley Trading    **Available**

2 Owners. Durable Toyota Hiace 14 Seater PA Bus. Very Well Maintained And Powerful Euro 4 1KD Turbo Engine. Able To Renew 5 Or 10 Years COE.

Office No. - 63445088

Thomas - 96302490 | Patrick Teo - 96681822 | Richard Teo - 90251988

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT   |  |
|--|--|
| Date Of Report   | 08/07/2019 16:32                           |
| Date Of Accident   | 06/07/2019 15:50                           |
| Exact Location Of Accident   | ALONG UPPER THOMSON ROAD TOWARDS SEMBAWANG |
| Country/State of Loss  | SINGAPORE                                  |
| DETAILS OF OWN VEHICLE   |  |
| Vehicle Registration Number  | GBA7404T                                   |
| Insured/Policyholder   |  |
| Name Of Registered Owner   | JUST 4U SERVICE                            |
| Co Reg No  | 53342832K                                  |
| Email Address  | NOEMAIL                                    |
| Mobile Phone No  | (LOCAL) +65-94528132                       |
| Alternative Phone No   | OFFICE-94528132                            |
| Vehicle Particulars  |  |
| Manufacturer   | TOYOTA                                     |
| Model  | HIACE                                      |
| Exact Purpose for which vehicle was being used at time of accident           | WORK USE                                   |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO   |
| If No, Please state action to be taken                                       | THIRD PARTY                                |
| Vehicle Category   | COMMERCIAL VEHICLE                         |
| Insurance Company  |  |
| Name of Insurance Company  | NTUC INCOME INSURANCE CO-OPERATIVE LTD     |
| Type Of Coverage   | COMPREHENSIVE                              |
| Fleet Policy   | NO   |
| Policy Number  | 5107153387                                 |
| Cover Note Number  |  |
| Driver   |  |
| Name of Driver   | LEE YAM SENG                               |
| Passport No/FIN  | FF7542901X                                 |
| Date Of Birth  | 07/09/1977                                 |
| Occupation   | OUTDOOR                                    |
| Date Of Driving Pass   | 14/06/2010                                 |
| Driving Experience   | 9 YEARS AND 0 MONTHS                       |
| Gender   | MALE                                       |
| Mobile Number  | (LOCAL) +65-94528132                       |
| Fax Number   |  |
| Contact Number   |  |
| EMail Address  | NOEMAIL                                    |

|   |                                      |
|---|--------------------------------------|
| Address   | APT BLK 114 ANG MO KIO AVE 4 #09-357 |
| Postcode  | 560114                               |
| Was driver an employee of the Insured's Company     | YES                                  |
| If No, Relationship of the Driver with the Insured  |                                      |
| Vehicle Registration Number of Driver's Own Vehicle | -                                    |
|   | -                                    |
|   | -                                    |
| Insurance Company of Driver's Own Vehicle           | -                                    |
|   | -                                    |
|   | -                                    |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | CLEAR           |
| Road Surface       | DRY             |

#### Other Information

|   |                                     |
|---|-------------------------------------|
| Was any foreign vehicle involved in this accident?  | NO                                  |
| Number of vehicles (including own vehicle) involved in the accident                         | 3                                   |
| Was any body injured in the Accident?   | NO                                  |
| Was any injured conveyed to hospital by ambulance?  | NO                                  |
| Was any other material or property damaged?   | YES                                 |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                  |
| Number of Passengers (Including Driver)   | 2                                   |
| Passenger 1   | NAME: : UNKNOWN<br>GENDER: : FEMALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                     |
|-------------------------------------|---------------------|
| Vehicle Registration Number         | SMH8013P            |
| Vehicle Make/Model/Colour           |                     |
| Details Of Properties               |                     |
| Vehicle Category                    | PRIVATE CAR         |
| Name of Driver                      | HAN SHUYI, CHARISSA |
| NRIC/Passport Number                | S9148418H           |
| Contact Number                      | 97515615            |
| Address                             |                     |
| Postcode                            |                     |
| Insurance Company Name              |                     |
| Nature Of Damage                    |                     |
| No. Of Passenger (Including Driver) |                     |

## DETAILS OF OTHER VEHICLE PROPERTY 2

|                                     |                      |
|-------------------------------------|----------------------|
| Vehicle Registration Number         | SJX5414L             |
| Vehicle Make/Model/Colour           |                      |
| Details Of Properties               |                      |
| Vehicle Category                    | PRIVATE CAR          |
| Name of Driver                      | NICHOLAS TI YAN SHEN |
| NRIC/Passport Number                | S9733352A            |
| Contact Number                      | 98781900             |
| Address                             |                      |
| Postcode                            |                      |
| Insurance Company Name              |                      |
| Nature Of Damage                    |                      |
| No. Of Passenger (Including Driver) |                      |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

**JUST4U SERVICE**

(In compliance with requirements under any regulations, laws or court orders.)

UEN: 53342832K

215 Joo Chai Road, #01-03 Soho Life  
Singapore 427483

Email: just4uservice1@gmail.com

HP: 9452 8132

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





## VAN / LORRY (Rear)

Vehicle No:

GBA 7404T

## Rear Portion

| NAC  | INC    | Item                                      | CON | AC | Qty |
|------|--------|---|-----|----|-----|
| 1137 | 993626 | Rear Number Plate                         |     |    |     |
| 1138 | 993627 | Rear Number Plate Base                    |     |    |     |
| 2044 | 993628 | Rear Number Plate Bracket                 |     |    |     |
| 1140 | 993632 | Rear Number Plate Lamp                    |     |    |     |
| 1141 | 992958 | Rear Bumper                               | GRA | /  |     |
| 1142 | 993108 | Rear Bumper Upper                         |     |    |     |
| 1143 | 993017 | Rear Bumper Lower                         |     |    |     |
| 1144 | 993054 | Rear Bumper <del>Side Reflector</del> GRA |     | /  |     |
| 1147 | 992976 | Rear Bumper Bracket                       |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer                 |     |    |     |
| 1149 | 993045 | Rear Bumper Reinforcement                 |     |    |     |
| 2045 | 993081 | Rear Bumper Step Panel                    |     |    |     |
| 2046 | 993079 | Rear Bumper Step Garnish                  |     |    |     |
| 2047 | 993186 | Rear Crash Bar                            |     |    |     |
| 1158 | 994023 | Reverse Sensor                            | DM  | /  |     |
| 1159 | 993327 | Rear End Panel                            | DM  | /  |     |
| 1163 | 993851 | Rear LH Taillamp                          |     |    |     |
| 1164 | 993853 | Rear LH Taillamp Garnish                  |     |    |     |
| 1165 | 993859 | Rear LH Taillamp Panel                    |     |    |     |
| 1166 | 995116 | Rear RH Taillamp                          |     |    |     |
| 1167 | 993853 | Rear RH Taillamp Garnish                  |     |    |     |
| 1168 | 993859 | Rear RH Taillamp Panel                    |     |    |     |
| 1169 | 993554 | Rear Apron Panel                          |     |    |     |
| 1289 | 995156 | Rear LH Door                              |     |    |     |
| 1350 | 993201 | Rear RH Door                              |     |    |     |
| 2048 | 991328 | Rear Door Emblem                          |     |    |     |
| 2049 | 993274 | Rear Door Outer Handle                    |     |    |     |
| 2050 | 993228 | Rear Door Garnish                         |     |    |     |
| 2051 | 993294 | Rear Door Rubber                          |     |    |     |
| 1291 | 995194 | Rear LH Door Hinge                        |     |    |     |
| 1352 | 995307 | Rear RH Door Hinge                        |     |    |     |
| 1301 | 993261 | Rear LH Door Lock                         |     |    |     |
| 1362 | 993261 | Rear RH Door Lock                         |     |    |     |
| 2052 | 993232 | Rear Door Glass                           |     |    |     |
| 2053 | 993955 | Rear Door Glass Sealant                   |     |    |     |
| 1248 | 994729 | Third Brake Light                         |     |    |     |
| 1181 | 994543 | Tailgate                                  | DM  | /  |     |
| 2054 | 993700 | Rear Rubber Stopper                       |     |    |     |
| 2055 | 993701 | Rear Rubber Stopper Bracket               |     |    |     |
| 1182 | 991328 | Tailgate Emblem                           | NC  | /  |     |
| 1183 | 994643 | Tailgate Outer Handle                     |     |    |     |
| 1185 | 994545 | Tailgate Garnish                          |     |    |     |
| 1193 | 994602 | Tailgate Glass                            |     |    |     |
| 1194 | 994606 | Tailgate Glass Rubber                     |     |    |     |
| 1195 | 994604 | Tailgate Glass Moulding                   | NC  | /  |     |
| 1196 | 994607 | Tailgate Glass Sealant                    | NC  | /  |     |
| 2056 | 994597 | Tailgate Extension Mirror                 |     |    |     |
| 1197 | 994629 | Tailgate Lock                             |     |    |     |
| 1198 | 994651 | Tailgate Rubber                           | TN  | /  |     |
| 1199 | 994611 | Tailgate Hinge                            |     |    |     |
| 1200 | 994594 | Tailgate Damper                           |     |    |     |
| 1201 | 994613 | Tailgate Inner Board                      |     |    |     |
| 2057 | 993992 | Rear Wiper Arm                            |     |    |     |
| 2058 | 993995 | Rear Wiper Blade                          |     |    |     |
| 2059 | 993997 | Rear Wiper Motor                          |     |    |     |
| 2060 | 993484 | Rear Floor Panel                          |     |    |     |
| 1204 | 995065 | Spare Tyre                                |     |    |     |
| 2061 | 993785 | Spare Tyre Bracket                        |     |    |     |
| 1212 | 993364 | Rear Exhaust Pipe                         |     |    |     |
| 1214 | 993361 | Rear Exhaust Mounting                     |     |    |     |
| 1216 | 995223 | Rear LH Chassis Member                    |     |    |     |
| 1217 | 993165 | Rear RH Chassis Member                    |     |    |     |

| NAC  | INC    | Item                           | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 2062 | 993748 | Rear Sidegate                  |     |    |     |
| 2063 | 994225 | Rear Sidegate Lock             |     |    |     |
| 2064 | 993749 | Rear Sidegate Hinge            |     |    |     |
| 2065 | 994226 | Sidegate Lower Panel           |     |    |     |
| 2066 | 994227 | Sidegate Railing               |     |    |     |
| 2067 | 994208 | Side Cover Hook                |     |    |     |
| 2068 | 991965 | Side Step Panel                |     |    |     |
| 2069 | 994496 | Side Step Panel Stopper        |     |    |     |
| 2070 | 992857 | Rear Body Panel                |     |    |     |
| 2071 | 992866 | Rear Body Panel Inner          |     |    |     |
| 2072 | 995329 | Sliding Door LH                |     |    |     |
| 2073 | 995328 | Sliding Door RH                |     |    |     |
| 2074 | 994295 | Sliding Door Handle            |     |    |     |
| 2075 | 994300 | Sliding Door Lock              |     |    |     |
| 2076 | 994313 | Sliding Door Rubber            |     |    |     |
| 2077 | 994291 | Sliding Door Bottom Roller     |     |    |     |
| 2078 | 994317 | Sliding Door Top Roller        |     |    |     |
| 2079 | 994306 | Sliding Door Rail              |     |    |     |
| 2080 | 994315 | Sliding Door Stepboard         |     |    |     |
| 2081 | 994316 | Sliding Door Stepboard Garnish |     |    |     |
| 1224 | 993621 | Rear LH Mudflap                |     |    |     |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |     |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |     |
| 1227 | 995065 | Rear LH Tyre                   |     |    |     |
| 1234 | 993622 | Rear RH Mudflap                |     |    |     |
| 1235 | 993934 | Rear RH Wheel Rim              |     |    |     |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |     |
| 1237 | 995065 | Rear RH Tyre                   |     |    |     |
| 1252 | 992179 | Fuel Tank                      |     |    |     |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |     |
| 1136 | 990247 | Sticker                        |     |    |     |
|      |        | 170' sticker                   | NC  | /  |     |
|      |        | 18 pax' sticker                | NC  | /  |     |

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)
























| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |            |   |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'd | Status  |
| Main                     | 01 Aug 2019<br><a href="#">Edit Reg</a> |               | 08 Jul 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |  |                        |  |          |         |             |              |            |       |
| Insured:  | Daimler South East Asia, Co. Reg. No.: 199000355E, Tel: +6599999999  |                        |  |          |         |             |              |            |       |
| Main Claimant:  | UNKNOWN, Co. Reg. No.: NA  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | GBA7404T   | Date of Loss:          | 06/07/2019 00:00 - :59<br>[139 Months and 9 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | TP / 1257626821SG  | Policy/Cover Note No.: | 0999994142 (Comprehensive)   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | SMH8013P   | Policy No. (Claimant): |  |          |         |             |              |            |       |
|   |  | Excess:                |  |          |         |             |              |            |       |
| Repairer:   | Yeow Koon Auto Care Pte Ltd (HQ) BLK 3012 BEDOK INDUSTRIAL PARK E #01-2016, 489978 Bedok - Tel: 64483039 /93202773 |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000   |                        |  |          |         |             |              |            |       |
| Adjuster:   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/08/2019]  |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |  |          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*GBA7404T (1257626821SG)  
[SMH8013P]  
TP  
UNKNOWN  
Jul 6 2019 12:00AM  
[Daimler South East Asia]  
Yeow Koon Auto Care Pte Ltd

|                  |                 |                                   |               |  |  |                    |  |  |              |  |  |              |  |  |            |           |                                     |                                     |  |  |
|------------------|-----------------|-----------------------------------|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-----------|-------------------------------------|-------------------------------------|--|--|
| Upload Documents |                 |                                   | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       |           |                                     | View in Browser                     |  |  |
| Photos/Images    |                 |                                   |               |  |  |                    |  |  |              |  |  |              |  |  | 3 per page |           | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |  |  |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |  |                    |  |  |              |  |  |              |  |  |            | Thumbnail | Print                               |                                     |  |  |
| 1                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 2                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 3                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 4                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 5                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 6                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 7                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 8                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 9                | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 10               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 11               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 12               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 13               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 14               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 15               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 16               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 17               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 18               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 19               | 24/07/19 16:54  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 20               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 21               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 22               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 23               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 24               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 25               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 26               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 27               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 28               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 29               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 30               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 31               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 32               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 33               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 34               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 35               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 36               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 37               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 38               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 39               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 40               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 41               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 42               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |
| 43               | 24/07/19 16:55  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  |            | Load JPG  | <input checked="" type="checkbox"/> |                                     |  |  |

| Photos/Images |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 44            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 24/07/19 16:55  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 60            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 61            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 62            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 63            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 64            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG   | <input checked="" type="checkbox"/> |
| 65            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG  | <input checked="" type="checkbox"/> |
| 66            | 24/07/19 16:56  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012185/GCF3E2

Date: 23/10/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994142  
**Claimant**  
**Vehicle No :** GBA7404T **Insured Vehicle No :** SMH8013P  
**Date of Loss:** 06/07/2019 **Nature of Claim:** TP **Claim No:** 1257626821SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

**Reg No:** GBA7404T  
**Make & Model:** TOYOTA HIACE, 3.0 D (M) **Engine No:** 1KD1708572  
**Reg. Date:** 27/11/2007 (Man. Year: 2007) **Chassis No:** JTFHT02P200006653  
**Colour:** White **Odometer:** 264978 km  
**Engine Capacity:** 2982 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

## CONDITION OF TYRES

**Front Tyre Size:** 195 R15 **Rear Tyre Size:** 195 R15  
**Front Left Side:** CST 5 mm **Rear Left Side:** CST 5 mm  
**Front Right Side:** CST 5 mm **Rear Right Side:** CST 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

**Date of Assignment:** 08/07/2019  
**Date Inspected:** 10/07/2019 **Inspected At:** 1 Kaki Bukit Ave 6 #01-38  
 Repairer : Yeow Koon Auto Care Pte Ltd (HQ)  
**Estimated Period of Repair:** 6.0 days

**Adjuster:** XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No.                      | Qty | Part No. | Particulars              | Condition | Repairer's  | Amount      |
|--------------------------|-----|----------|--------------------------|-----------|-------------|-------------|
| 1                        | 1   |          | *REAR BUMPER             | Cracked   | 0.00 F      | *- F        |
| 2                        | 1   |          | *REVERSE SENSOR          | Damaged   | 0.00 F      | *- F        |
| 3                        | 1   |          | *REAR END PANEL          | Buckled   | 0.00 F      | *- F        |
| 4                        | 1   |          | *TAILGATE                | Buckled   | 0.00 F      | *- F        |
| 5                        | 1   |          | *TAILGATE EMBLEM         | Necessary | 0.00 F      | *- F        |
| 6                        | 1   |          | *TAILGATE GLASS MOULDING | Necessary | 0.00 F      | *- F        |
| 7                        | 1   |          | *TAILGATE GLASS SEALANT  | Necessary | 0.00 F      | *- F        |
| 8                        | 1   |          | *TAILGATE RUBBER         | Torn      | 0.00 F      | *- F        |
| 9                        | 1   |          | *70 STICKER              | Necessary | 0.00 F      | *- F        |
| 10                       | 1   |          | *8 PAX STICKER           | Necessary | 0.00 F      | *- F        |
| 11                       | 1   |          | *REAR BUMPER REFLECTOR   | Cracked   | 0.00 F      | *- F        |
| F=Franchise part.        |     |          |                          |           |             |             |
| <b>Total Parts (S\$)</b> |     |          |                          |           | <b>0.00</b> | <b>0.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >