

22/03/2012

ASS. REC. BY:

REF:

CS3/AIG/19012196/Ncf302

Special Instruction:

Surveyor: Naz

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time:

10/7/19 @ 12.04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFS 4219P

Insured:

SKP 8418L

at Workshop in/s

Xin Yun Auto

Tel:

98391555.

of

8 Kelki Bukit Ave 4 # 05-23 premier

Policy No:

0999994458

Claim No:

581908661786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.56pm @ 10/7/19

Person Contacted:

Yi xin

Vehicle: IN / OUT

Date/Time	Action/Instruction
	Tobin @ X
	SKP 8418L : X
	SFS 4219P : X
	Dismantle: 11/7/2019
	After repair: 12/7/2019

PRS

ASSIGNMENT

From

Date

10/7/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFS 4219P

at Workshop in/s

Xin Yun Auto

of

8 kaki Bukit Ave 4 # 05-23

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFS 4219P

Yr Regn:

2 MAR 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI LANCER 1.6A c.c. 1,584

Colour:

SILVER

A/C:

Insured / Std / NI / NA

Sp. Reading

282,126

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMYSTCS345W003750

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXU

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

9/7/19

D.O.I.

10/7/19

Survey held at

XIN YUN AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COE EXP 1 MAR 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Meal and (\$

Survey Fee:

Transportation:

3 + RS. St

Photos

Other:

Report Form 4:

DAR

Emp. Com / Mkt. G

180

20 11

101

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc:

Sent: 7/10/2019 12:04:36 PM

Attachments:  [Xin Yun- Pre-Repair Notice \(AIG\)\(SFS4219P\).pdf](#)

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.XY (SFS4219P)
Your Ref: SKP8418L

URGENT

10 July 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120

**BY FAX: 6415 3727 (PRI) &
EMAIL**

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSIH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: JAYARAM S/O SINNIAH PILLAI
TRAFFIC ACCIDENT ON 9 JULY 2019 AT 04:40 HRS ALONG BUANGKOK GREEN
INVOLVING VEHICLES NO. SFS4219P & SKP8418L

We are instructed by Jayaram S/O Sinniah Pillai to notify you of a road accident on 9 July 2019 at about 04:40 hrs along Buangkok Green involving our clients' vehicle registration number SFS4219P and vehicle registration number SKP8418L driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.


As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Xin Yun Auto Private Limited
Address: 8 Kaki Bukit Avenue 4
#05-23 Premier @ Kaki Bukit
Singapore 415875
Contact: Yi Xin (9839 1555)

Please liaise with the above workshop directly.

Yours faithfully


Crossborders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire Transfer Fee

Vehicle No.:	SFS4219P
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Chassis No.:	JMYSTCS3A5U003750
Propellant:	Petrol
Engine No.:	4G18GG7365
Engine Capacity:	1584 cc
Maximum Power Output:	79.0 kW (105 bhp)
Maximum Laden Weight:	1600 kg
Unladen Weight:	1162 kg
Year Of Manufacture:	2004
Original Registration Date:	02 Mar 2005
Lifespan Expiry Date:	-
COE Category:	E - Open Category
PQP Paid:	\$31,933.00
COE Expiry Date:	01 Mar 2020
Road Tax Expiry Date:	01 Sep 2019
Inspection Due Date:	01 Mar 2020
Intended Transfer Date:	11 Jul 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 01 Sep 2019. You may renew the road tax from 02 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 01 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	551.00	-	551.00
Total Amount Payable:			576.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	0398H
Vehicle Details	
Vehicle No.:	SFS4219P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	4G18GG7365
Chassis No.:	JMYSTCS3A5U003750
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,935.00
Original Registration Date:	02 Mar 2005
First Registration Date:	02 Mar 2005
Transfer Count:	1
Actual ARF Paid:	\$15,329.00
Intended PARF/Chattel Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE/Paraphrase Details	
COE Expiry Date:	01 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$31,933.00
COE Rebate Amount:	\$4,073.00
Total Rebate Amount:	\$4,073.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
The information contained herein is correct as at 11 Jul 2019	

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2019 16:49
Date Of Accident	09/07/2019 04:40
Exact Location Of Accident	BUANGKOK GREEN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFS4219P
Insured/Policyholder	
Name Of Registered Owner	JAYARAM S/O SINNIHAI PILLAI
NRIC No	S1730398H
Email Address	XINYUNAUTO1@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90696464
Alternative Phone No	OFFICE-90696464

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JAYARAM S/O SINNIHAI PILLAI
NRIC No	S1730398H
Date Of Birth	05/12/1965
Occupation	INDOOR
Date Of Driving Pass	13/10/1986
Driving Experience	32 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90696464
Fax Number	
Contact Number	OFFICE-90696464
Email Address	XINYUNAUTO1@GMAIL.COM

Address	BLK 221B SUMANG LANE #15-23
Postcode	822221
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I MR. JAYARAM S/O SINNIHAH PILLAI (SFS4219P) WAS DRIVING ALONG BUANGKOK GREEN TOWARDS A.M.K AVE 5. I STOPPED AT THE TRAFFIC LIGHT WHICH WAS RED. SUDDENLY THE VEHICLE SKP8418L HIT MY REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP8418L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : -

GENDER: : FEMALE

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number PC5913C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A: SFS 4219P

B: SKP 8418L

C: PC 5913C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At

I Mr. JAYARAM s/o SANNIAH SFS 4219P driving along Buangkok Green towards Anik Ave: S. I stop at the traffic light which was red.

~~for~~ Suddenly the vehicle SKP 8418L hit my rear

~~for~~ time of

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORCAR (Rear)

Vehicle No: **FS 4219P**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRK		1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	WBC		6
1147	992976	Rear Bumper Bracket	(LH) BT		1
1148	993068	Rear Bumper Side Retainer	LH DS		1
1149	993045	Rear Bumper Reinforcement	DD		1
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Shank DM		1
1159	993327	Rear End Panel	X R		
1160	993339	Rear End Panel Top Garnish	CRK		1
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRK		1
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD		1
1171	991328	Bootlid Emblem	WBC		
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	DD		
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish	TORN		1
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap	DEF		1
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			






































...CLAIM SUBFOLDER...(Pending for Survey Report)























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019 Edit Reg		10 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HOPE FIRST RESPONSE PTE LTD, Co. Reg. No.: 200915893N								
Main Claimant:	JAYARAM S/O SINNIHAI PILLAI, ID: S1730398H								
Vehicle Reg. No.:	SFS4219P	Date of Loss:	09/07/2019 04:00 - :59 [172 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5819086617SG	Policy/Cover Note No.:	0999994458 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKP8418L	Policy No. (Claimant):							
		Excess:							
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 19/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (11/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFS4219P (5819086617SG)**
[SKP8418L]
TP
JAYARAM S/O SINNIHA PILLAI
Jul 9 2019 4:00AM
[HOPE FIRST RESPONSE PTE LTD]
Xin Yun Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View In Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
2	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
3	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
4	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
5	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
6	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
7	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
8	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
9	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
10	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
11	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
12	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
13	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
14	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
15	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
16	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
17	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
18	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
19	11/07/19 15:26	General View											Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 14:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 14:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 14:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/07/19 09:34	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012196/NCF3E2

Date: 07/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994458
Claimant Vehicle No : SFS4219P **Insured Vehicle No :** SKP8418L
 Date of Loss: 09/07/2019 Nature of Claim: TP Claim No: 5819086617SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFS4219P**
 Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4G18GG7365
 Reg. Date: 02/03/2005 (Man. Year: 2004) Chassis No: JMYSTCS3A5U003750
 Colour: Silver Odometer: 282126 km
 Engine Capacity: 1584 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/07/2019
 Date Inspected: 10/07/2019 Inspected At: Xin Yun Auto Pte Ltd (HQ)
 BLK 8 KAKI BUKIT AVE 4 #05-23
 PREMIER @KAKI BUKIT
 Singapore 415675
 Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BRACKET (LH)	Bent	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REVERSE SENSOR	Shorted / Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*BOOTLID	Dented	0.00 F	*- F
11	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID RUBBER	Dented	0.00 F	*- F
13	1		*REAR LH FENDER INNER GARNISH	Torn	0.00 F	*- F
14	1		*REAR LH MUDFLAP	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >