

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI19012216/I	<1vf3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date: 23-07-2019 Code: GAI		
1. Policy Particulars :- THIRD PARTY CLAIM					
1.	Insured Veh.	GW 4195R	Veh. Inspected	SHA 9334C	
	Policy No.	OW 413010	Coverage (\$)	0.00	
	Claim No.	CLMOMVC000003690	Excess (\$)	0.00	
	Assign From	KELVYNA NGIAN	Assign Date	10/07/2019	
2.	Assign From		culars & Condition	10,01,2010	
Z.	Make & Model	HYUNDAI 140	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KMHLB41UMHU095350	Colour	YELLOW	
	Odometer	467379	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	HANKOOK	7 mm	
	L/H Front Tyre	205/60 R16	HANKOOK	7 mm	
	R/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
	L/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/07/2019	Inspection Date	10/07/2019	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				