

AXA - 45

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305309925
 REGN NO : SHA7383Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 02.04.2015
 DATE/TIME IN : 09.07.2019 12:15
 ACCIDENT DATE : 09.07.2019

1500

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	/
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	X
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/

SUB-TOTAL : 642.40

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	/
0001 20-05	Rear Bumper Adv.Sticker	50.00	/
0002 PB	PANEL BEATING	280.00	200
0003 SP	SPRAYPAINT CHARGE	250.00	200

SUB-TOTAL : 780.00

TOTAL : 1,422.40

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Kalvin 20/06/19
 10/7/19 10:26
 2 hrs
 40
 After Repair p 44

AUTHORISED : YES / NO hence notify
 the following:

- To inspect damaged parts during resurvey
- Parts prices are subject to confirmation
- Third Party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claims must be filed and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: