



ESTIMATE TO REPAIR

VEHICLE NO. : SLW 6757 Y
MAKE : MERCEDES BENZ
MODEL : E220D AUTO
YEAR : 2016
CHASSIS NO : WDD2130042A061017

SURVEYOR NAME : Kenneth (LKK)
DATE OF SURVEY : 16th July 2019
TIME OF SURVEY :

DATE : 9-Jul-19
DATE OF ACCIDENT : 8-Jul-19
THIRD PARTY REF : SLG 8921 K / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To putty and spray painting				\$ 500.00
	Wheel alignment				\$ 80.00
	Labour Charges				\$ 350.00
<i>Not Resurvey</i> <i>Resurvey After Paint</i> <i>2 days</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer					
TG/RA- Signal	Total				\$ 930.00
Date:					

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd