

**AIG INSURANCE**  
78 Shenton Way,  
#07-16, AIG Building  
Singapore 079120

Vehicle number SLQ9406Y  
Make / Model VOLKSWAGEN/  
Chassis number wvwzzz13zav4  
Accident date 06 July 2019  
Reference 1907-22

| Qty                                           | Particulars                                  | Ur       |
|-----------------------------------------------|----------------------------------------------|----------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                                              |          |
| 1                                             | FRONT BUMPER                                 | 147      |
| 1                                             | FRONT BUMPER LOWER GRILLE                    | 31       |
| 1                                             | FRONT RH FOG LAMP                            | 24       |
| 1                                             | FRONT RH FOG LAMP GARNISH                    | 19       |
| 1                                             | FRONT RH SIGNAL LAMP                         | 18       |
| 2                                             | FRONT BUMPER RETAINER                        | 13       |
| 1                                             | FRONT RH FENDER                              | 83       |
| 1                                             | FRONT RH FENDER INNER SHIELD                 | 19       |
| 1                                             | FRONT RH KNUCKLE ARM                         | 63       |
| 1                                             | FRONT RH KNUCKLE ARM BEARING                 | 49       |
| 1                                             | FRONT RH LOWER ARM                           | 35       |
| 1                                             | FRONT RH DRIVE SHAFT                         | 24       |
| 1                                             | STEERING RACK AND PINION                     | 48       |
| 1                                             | FRONT RH TIE ROD                             | 16       |
| 1                                             | FRONT RH ABS SENSOR                          | 18       |
|                                               |                                              | 1273     |
|                                               | Less 5 %                                     | 636      |
|                                               | Subtotal                                     | 1210     |
|                                               | Balance C/F                                  | 1210     |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                              |          |
|                                               | Balance B/F                                  | 1210     |
| 1 SET                                         | FRONT BUMPER CLIP                            | 40       |
| 1 SET                                         | FRONT FENDER INNER SHIELD CLIP               | 30       |
| 1                                             | FRONT RH HEADLAMP ( AFTER MARKET )           | 2500     |
| 1                                             | FRONT BONNET ( CARBON FIBER )                | 2500     |
| 1                                             | RIM (TSW)                                    | 2500     |
| 1                                             | TYRE                                         | 350      |
| 1 BOT                                         | BRAKE FULID                                  | 60       |
| 1 SET                                         | SHOCK ABSORBER ( AFTER MARKET )              | 4500     |
| 1 SET                                         | BRAKE KIT (SCIROCCO R) / BRAKE CALIPER       | 3500     |
| 1 SET                                         | DISC ROTOR                                   | 1600     |
| 1                                             | FENDER STICKER (2.0)                         | 50       |
| 1                                             | FRONT BUMPER STICKER                         | 100      |
|                                               |                                              | 17730    |
|                                               | Subtotal                                     | 17730    |
|                                               | Balance C/F                                  | 29831    |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |                                              |          |
|                                               | Balance B/F                                  | 29831    |
| 1                                             | CHECK FRONT WIRING AND LIGHTNING SYSTEM      | 60       |
| 2                                             | DIAGNOIS CHECK AND CLEAR FAULT CODE          | 300      |
| 3                                             | COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT | 150      |
| 4                                             | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS | 200      |
| 5                                             | PANEL BEATING ON AFFECTED AREAS              | 1000     |
| 6                                             | SPRAY PAINTING ON AFFECTED AREAS             | 800      |
| 7                                             | APPLY ANTI RUST ON AFFECTED AREAS            | 150      |
|                                               |                                              | 2660.00  |
|                                               | Subtotal                                     | 2660.00  |
|                                               | Grand total                                  | 32491.67 |

0 \* C  
1,475.94 +  
314.5 +  
245.95 +  
194.75 +  
832.12 +  
357.25 +  
=  
3,420.51 \*  
3,420.51 x  
90 %  
3,078.459 \*  
0 \* C  
40 \* +  
900 \* +  
1,500 \* +  
350 \* +  
600 \* +  
20 \* +  
40 \* +  
=  
3,450 \* \*  
0 \* C  
30 \* +  
150 \* +  
60 \* +  
600 \* +  
400 \* +  
50 \* =  
1,290 \* \*  
0 \* C  
3,078.46 +  
3,450 \* +  
1,290 \* =  
7,818.46 \*  
7,818.46 x  
80 %  
6,254.768 \*

459 6,250 \*  
CHECK ITEMS PHOTO  
AFTER REPAIR PHOTO