

Case Details

Case Reference Number : BUS07191005
 Type of Repair : Accident Repair
 Vehicle Registration Number : SM23067Y

Company Type : SMRT Buses Ltd
 Estimation ID : EST-7818-02
 Assigned By : Bus Claims Manager Team

Insurance Company Name : China Taping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 02/07/2019 08:39 AM
 Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents : 1

Estimation Details

Spares Part's Cost Detail

BOM Type	Coating Type	Partion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(\$)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Total Spares Part Cost						0.00	Surveyor Total			0.00				
Lump Sum Discount (%)						0.00	Lump Sum Dis (%)			0.00				
Final Spares Part Cost						0.00	Final Sur Total			0.00				

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION FRONT TO REAR	1,388.00	1,325.00	✓
Total:			1,388.00	1,325.00	

Spary Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,388.00	1,218.00	✓
Total:			1,388.00	1,218.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spares Part Detail	0.00	0.00
Total Labour Cost	1,388.00	1,325.00
Total Spary Painting	1,388.00	1,218.00
Other	0.00	0.00
Overall Total	2,976.00	2,543.00
Lump Sum Repair Option		
Lump Sum Total	3,000.00	2,643.00

Surveyor Approved Amount

2,550.00

No of Repair Days

4

4

Remarks

L/S repair take after survey. Finalize sent to stevechen@lkk.com, 5222 8813

Surveyor Name

STEVE CHEN

Signature

Survey Date

09/01/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

L/S - 2543
= 2550

4 days





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 80 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/07/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB3567Y
Case Reference Number	BUS/07/19/1005
Registration Date	2/1/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Tian Ya
Type of Accident	Side Swipe
Accident Date and Time	2/7/2019 4:30 PM
Accident Reported Date and Time	2/7/2019 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100340
Special Instruction to ARC, if any	SMB3567Y - LEFT CENTRE PORTION SUL3264R (TP) - INSURED WITH CHINA
Prepared Date and Time	8/7/2019 2:59 PM
Chassis Number	SFD76CLR8EMTL3525
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,325.00
Total Spray Cost	\$1,368.00	\$1,218.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,978.00	\$2,543.00
Lump Sum Total	\$3,000.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	09/07/2019 3:02 PM	09/07/2019 3:39 PM
Signature		
Remarks	LIS repair. take after spray. Finalize sent to stevechen@kkauto.com. 8322 8813	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 63680592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/07/2019

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope									
TO REPAIR LH PORTION FRONT TO REAR				Quotation from AR			Adjusted by Surveyor, if applicable		
Total Labour				\$1,590.00			\$1,325.00		
				\$1,690.00			\$1,228.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope									
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				Quotation from ARC			Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating				\$1,388.00			\$1,210.00		
				\$1,288.00			\$1,218.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope									
Total Other Costs				Quotation from ARC			Adjusted by Surveyor, if applicable		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									