

Case Details

Case Reference Number : BUS/07/19/1005
Type of Repair : Accident Repair
Vehicle Registration Number : SMB3567Y

Company Type : SMRT Buses Ltd
Estimation ID : EST-7618-ID
Assigned By : Bus Claims Manager Team

Insurance Company Name : China Taiping
Insurance (Singapore) Pte Ltd
Accident Date and Time : 02/07/2019 08:39 AM
Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Total Spare Part Cost									0.00	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									0.00	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION FRONT TO REAR	1,590.00	1,325.00	
Total:			1,590.00	1,325.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,388.00	1,218.00	
Total:			1,388.00	1,218.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	1,590.00	1,325.00
Total Spray Painting	1,388.00	1,218.00
Other	0.00	0.00
Overall Total	2,978.00	2,543.00
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,000.00	2,550.00

Surveyor Approved Amount

2,550.00

No of Repair Days*

5

4

Remarks

L/S repair, take after spray. Finalize sent to
stevechen@lkkauto.com, 8322 8813

Surveyor Name

STEVE CHEN

Signature



Survey Date

09/07/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during **resurvey**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: