

22/03/2020

AGE REC BY:

REF CS3 / CT1 19012260 / Aef32 Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 10/7/19 @ 4:29pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 7901T Insured: SKC 9962T

at Workshop in/s Motor Intelligence Tel: 62810087

of 13 Kaki Bukit Road 4 #01-20

Policy No: DMPCSN30224719011 Claim No: SNM19D203213002

Sum Insured: Excess:

Make of Veh: D.O.A. 7.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:16am @ 11/7/19 Person Contacted: Alex Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	1.31mali (X)
	SKT 7901T - X
	SKC 9962T - CS3 / AXA 12024321 / 49d1 DOA - 18/12/2012
	Dismantle: 11/7/2019
	After repair: 15/7/2019

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SKT7901T Yr Regn: 2015 / JuneType: Motor / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 c.c. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading 126155 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm6DJ2HAA01100330Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/07/19Survey held at Motor Int'lDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Claim PRS.Repair Cost Range : \$7K-\$8K. 08 DaysMV :PV :Nett :

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

190190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019		10 Jul 2019 16:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:

Main Claimant:

LIN MINJI, ID: S8400538Z

Vehicle Reg. No.:

SKT7901T

Date of Loss:

07/07/2019 01:00 - :59

Claim Type:

TP / SNM19D203213C02

Policy/Cover Note No.:

DMPCSN30224719011

Vehicle Reg. No. (Insured):

SKC9962T

Policy No. (Claimant):

D19MTPV01008620

Excess:

S\$500.00

Repairer:

- Not Applicable - (-)

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... **[Final Rpt due 19/07/2019]**

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 10 July 2019 4:29 PM
To: Wendy Jiang; assignments@lkkauto.com
Cc: lua_siewhui@rssolomon.com
Subject: RE: OUR REF: SNM19D203213/CHEONGML - SKC9962T - PRS SKT7901T - FW: Fax Message NO.1327[1907-7355(MI)(PD)]

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Wendy,

We refer to your email of 05.03.19 and telephone conversation with our colleague today.

We noted that you are not agreeable to our proposed surveyors as SJE and we will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: Wednesday, 10 July, 2019 3:43 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; lua_siewhui@rssolomon.com
Subject: Re: OUR REF: SNM19D203213/CHEONGML - SKC9962T - PRS SKT7901T - FW: Fax Message NO.1327[1907-7355(MI)(PD)]

Dear Elaine,

We refer to the above matter.

We have on 8th July 2019 at about 1225 hrs faxed to you,our notice for arrangement of pre-repair survey of our client's vehicle for the aforesaid accident. Please see attached the following:

1. Our PRI letter of 8th July 2019;
2. GIA report lodged by our client; and
3. The fascimile report on successful transmission of item (1) and (2) to your good-office..

Please let us hear from you before the close of business today,if you would intend to conduct a pre-repair of our client's vehicle. If we do not receive any reply from you within the stipulated timeline,our client shall proceed to repair his vehicle without further reference to you

Yours sincerely
Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Wed, Jul 10, 2019 at 2:07 PM Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:

Dear Elaine,

Please conduct PRS for SKT7901T.

Officer in charge - Elaine Cheong 63896530 (file with OIC).

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender

immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-16A-CL
Sent: Wednesday, 10 July, 2019 2:01 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: FW: Fax Message NO.1327

-----Original Message-----

From: FA-X5575C-19A
Sent: Monday, 8 July, 2019 1:07 PM
To: FA-X5575C-16A-CL <FA-X5575C-16A-CL@sg.cntaiping.com>
Subject: FW: Fax Message NO.1327

Maureen Ong
HR & Administration Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6111 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

-----Original Message-----

From: FA-RC6004F-16A-FN@sg.cntaiping.com [mailto:FA-RC6004F-16A-FN@sg.cntaiping.com]
Sent: Monday, 8 July, 2019 12:26 PM
To: FA-X5575C-19A
Subject: Fax Message NO.1327

This E-mail was sent from "RC6004F-16A-FN" (MP C6004ex).

Queries to: FA-RC6004F-16A-FN@sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Wendy Jiang <wendy_jiang@rssolomon.com>
Sent: Wednesday, 10 July 2019 4:40 PM
To: Elaine Cheong
Cc: assignments@lkkauto.com; lua_siewhui@rssolomon.com
Subject: Re: OUR REF: SNM19D203213/CHEONGML - SKC9962T - PRS SKT7901T - FW: Fax Message NO.1327[1907-7355(MI)(PD)]

Dear Elaine,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your surveyors to contact Ms. Ivy Pang of Motor Intelligence Automo Pte. Ltd. at tel no. 62810087 for a pre-repair survey of our client's vehicle located at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Yours sincerely
Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Wed, Jul 10, 2019 at 4:31 PM Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Wendy,

We refer to your email of 05.03.19 and telephone conversation with our colleague today.

We noted that you are not agreeable to our proposed surveyors as SJE and we will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0538Z
Vehicle Details	
Vehicle No.:	SKT7901T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	P520281717
Chassis No.:	JM6DJ2HAA01100330
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$15,072.00
Original Registration Date:	23 Jun 2015
First Registration Date:	23 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,000.00
COE Rebate Amount:	\$39,178.00
Total Rebate Amount:	\$42,928.00

The information contained herein is correct as at 15 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/07/2019 12:59
Date Of Accident	07/07/2019 01:10
Exact Location Of Accident	WOODLAND CHECKPOINT TOWARDS SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT7901T
Insured/Policyholder	
Name Of Registered Owner	LIN MINJI
NRIC No	S8400538Z
Email Address	MJLIN84@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96696074
Alternative Phone No	OFFICE-96696074

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01008620
Cover Note Number	

Driver

Name of Driver	LIN MINJI
NRIC No	S8400538Z
Date Of Birth	07/01/1984
Occupation	INDOOR
Date Of Driving Pass	20/05/2004
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96696074
Fax Number	
Contact Number	OFFICE-96696074
Email Address	MJLIN84@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : P1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My vehicle SKT7901T was stationary at woodlands checkpoints custom counter .As my vehicle was stationary at the counter suddenly I felt an hard impact coming from my rear vehicle,after the impact I immediately get down from my vehicle and discover that the 3rd party SKC9962T had collided onto my rear vehicle while my vehicle was stationary.I managed to take some photos and exchange particulars with the 3rd party,no injuries was involved at the scene.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC9962T
Vehicle Make/Model/Colour	VOLKSWAGEN / JETTA 1.4 TSI AT 1623Q5
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMED BIN ALI
NRIC/Passport Number	S0329782I
Contact Number	97657115
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver) 1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the process.
2. This Form must be completed by the Policyholder and/or the A.
3. Information provided must be as truthful and accurate as possible, allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records (GIA) of Singapore (GIA) for archiving and that copies of this report will be made available to the insurers, you hereby consent.
7. By the judgement of this report to the insurers, you hereby consent being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Representation or withholding of material facts may of policy liability on the part of insurance companies.

Established by the General Insurance Association available application by interested parties. If this report at the centre and to copies of the report

VERIFIED BY AJAX MARS
REPORTING OFFICER
MUHAMMAD SUMARDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SKT7401T

B: SKC9962T



WOODLANDS CHECKPOINT

ACCIDENT STATEMENT (2000 characters)

My vehicle SKT7901T was stationary at woodlands checkpoints custom counter .As my vehicle was stationary at the counter suddenly I felt an hard impact coming from my rear vehicle,after the impact I immediately get down from my vehicle and discover that the 3rd party SKC9962T had collided onto my rear vehicle while my vehicle was stationary.I managed to take some photos and exchange particulars with the 3rd party,no injuries was involved at the scene.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

7 July 2019 at 12:39 PM

Date/Time:

7 July 2019 at 12:39 PM

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019		10 Jul 2019 16:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LIN MINJI, ID: S8400538Z								
Vehicle Reg. No.:	SKT7901T	Date of Loss:	07/07/2019 01:00 - :59 [48 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203213C02	Policy/Cover Note No.:	DMPCSN30224719011						
Vehicle Reg. No. (Insured):	SKC9962T	Policy No. (Claimant):	D19MTPV01008620						
		Excess:	S\$500.00						
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



*SKT7901T (SNM19D203213C02)
[SKC9962T]
TP
LIN MINJI
Jul 7 2019 1:00AM
[-]
Motor Intelligence Automo Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print					
1	07/07/19 13:04	Accident Statement		Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print					
1	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
12	07/07/19 13:03	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
13	07/07/19 13:03	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
14	07/07/19 13:03	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
2	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
3	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
4	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
5	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
6	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
7	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
8	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
9	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
10	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
11	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
12	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
13	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					
14	15/07/19 13:57	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
15	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/07/19 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
65	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	15/07/19 13:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	02/08/19 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/19 16:51	PRS - SKT7901T	 Load PDF	
2	11/07/19 11:31	PRS - SKT7901T (WORKSHOP)	 Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/07/19 13:03	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	07/07/19 13:03	Common Statement [Linked Accident Report Documents]	 Load TIFF	

Linked Accident Report Documents

View				View in Browser
Assessment Reports				1 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/07/19 13:04	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images				3 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	07/07/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	07/07/19 13:03	Driving License	 Load JPG	<input checked="" type="checkbox"/>
14	07/07/19 13:03	Driving License	 Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/07/19 13:03	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/07/19 13:03	Common Statement	 Load TIFF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19012260/ACF3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30224719011

Claimant Vehicle
No : SKT7901TInsured Vehicle
No : SKC9962T

Date of Loss: 07/07/2019

Nature of Claim: TP

Claim
No: SNM19D203213C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT7901T

Make & Model: MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)

Engine No: P520281717

Reg. Date: 23/06/2015 (Man. Year: 2015)

Chassis No: JM6DJ2HAA01100330

Colour: White

Odometer: 126155 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/07/2019

Date Inspected: 11/07/2019 Inspected At:

Motor Intelligence Automo Pte Ltd (HQ)
13 KAKI BUKIT ROAD 4, #01-20
BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts:	144	MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7901T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >