

ASS. REC. BY:

REF:

CS3/11919012265/R/cd30

Special Instruction:

Surveyor: RAISU

ASSIGNMENT (Office)

From (Person):

Fan Winnie

of

ALG

Date/Time:

11/7/19 @ 9:20am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLD 9677A

Insured:

STU 7181K

at Workshop in/s

A. Auto Services

Tel:

9634 3776

of

5 Soon Lee Street #06-31

Policy No:

2100181499

Claim No:

588635202286

Sum Insured:

Process:

Make of Veh:

(Client's Record)

D.O.A.

9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:30am @ 11/7/19

Person Contacted:

Cheng

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

11/7/19 (X)

SLD 9677A - X

SLV 4886B - X

Dismantle: 12/7/2019

After repair: 19/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PAI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019 Edit Reg		11 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Liang Chay Kim Simon, ID: S7708849J, Tel: +6599999999								
Main Claimant:	A MOTOR LEASING LLP, Co. Reg. No.: T18LL1339D								
Vehicle Reg. No.:	SLD9677A	Date of Loss:	09/07/2019 15:00 - :59						
Claim Type:	TP / 5886352022SG	Policy/Cover Note No.:	2100181499 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJU7181K	Policy No. (Claimant):							
		Excess:							
Repairer:	A Auto Services (HQ) A AUTO SERVICES, 5 SOON LEE STREET #06-31 PIONEER POINT, 627607 Jurong East - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/07/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
AIG_SG (15/07/2019): No Policy Found for SLV4886B									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V...

From: Fan, Winnie-LW

To:

Cc:

Sent: 7/11/2019 9:21:33 AM

Attachments:  PRS 1 - SLD 9677A.PDF  SLV4886B090719.SAS.PDF

Hi LKK,

Kindly assist to survey.

Details of the workshop is as follows :

A Auto Services
5 Soon Lee Street
#06-31 Pioneer Point
Singapore 627607
Contact person/Tel : Cheng / 9634 3776

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref : SJU 7181K
Our Ref : SLD 9677A/AA/ms/sy
Date : 10 July 2019

Fax : 6538 3708
Tel : 3152 0981
Email : accident@kscgp.com

AIG Asia Pacific Insurance Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 9 JULY 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by A Motor Leasing LLP, the owner of SLD 9677A to notify you of a road traffic accident on 9 July 2019 at about 5.00pm along Balestier Road, involving our client's vehicle registration number SLD 9677A, other vehicle registration number SLV 4886B and vehicle registration number SJU 7181K which was insured by you at the material time. A copy of our client's Accident report and Police report are enclosed herein.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

SY

Enc.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	1339D
Vehicle Details	
Vehicle No.:	SLD9677A
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2ZR0429340
Chassis No.:	ZGE200009090
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,386.00
Original Registration Date:	23 Jul 2009
First Registration Date:	23 Jul 2009
Transfer Count:	6
Actual ARF Paid:	\$21,386.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2019
PARF Rebate Amount:	\$10,693.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$35,411.00
COE Rebate Amount:	\$34,673.00
Total Rebate Amount:	\$45,366.00

The information contained herein is correct as at 15 Jul 2019

OK

05/2029)

Max Loan Amount As Advertised! Meticulously Well Taken Care Of By Previous Owner With Smooth Running Engine! Immaculate Condition Assured! Depreciation Is Even Cheaper, Do Not Miss! Our Company Provid...

Office No. - -

Aaron - 98797788 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Wish 1.8A X (COE till 05/2029)	\$61,800	\$6,320 /yr	24-Jun-2009	1,794 cc	102,000 km	Creative Auto	Available
--	-----------------	--------------------	--------------------	-----------------	-------------------	----------------------	------------------

Max Loan Amount As Advertised! Meticulously Well Taken Care Of By Previous Owner With Smooth Running Engine & Comes With Nice Bidded Number! Immaculate Condition Assured! Depreciation Is Even Cheaper,...

Office No. - -

Alvin Chua - 84488354 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Wish 1.8A X (COE till 04/2029)	\$61,800	\$6,380 /yr	26-Jun-2009	1,797 cc	-	Top Carz	Available
--	-----------------	--------------------	--------------------	-----------------	----------	-----------------	------------------

No Gimmick On The Above Price And No Addition Deposit, Selling At Above Price, New Model Own By 1 Careful Lady Owner Only, Low Mileage And Accident Free, Regularly Serviced And Maintained, New Leather...

Office No. - 66849979

Thomas Tan - 93839533 | Jensen Chua - 97887307

Toyota Wish 1.8A X Sunroof (COE till 05/2029)	\$67,800	\$6,930 /yr	26-Jun-2009	1,797 cc	-	Carway	Available
--	-----------------	--------------------	--------------------	-----------------	----------	---------------	------------------

1 Year In House Warranty, Full Loan Available, 2 x Free Servicing, Warranty Not By 3rd Party Workshop, Price Stated Above Is Actual Selling Price, Our Company Renew COE Car Based On Condition Not On O...

Office No. - 68440777

Addy Ho - 88330777 | Peter Quek - 84840777

Toyota Wish 1.8A X (COE till 06/2029)	\$65,800	\$6,680 /yr	26-Jun-2009	1,797 cc	96,488 km	Car Guru.Com Pte Ltd	Available
--	-----------------	--------------------	--------------------	-----------------	------------------	-----------------------------	------------------

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...

Office No. - 67639595

Lawrence - 92228747 | Jimmy - 90079944

Toyota Wish 1.8A X (New 10-yr COE)	\$60,800	\$6,080 /yr	26-Jun-2009	1,797 cc	-	Classic Credit Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	-------------------------------	------------------

5 Years COE Renewal For \$42,800. Selling Cheap! Hurry! View Now. Up To 100% Flexible Loan. We Provide Lowest Interest Rate, Flexible Loan And High Trade In Are Available. Package With Unrivalled Warran...

Office No. - 68412076 / 68481203 / 68414849

Mr Chen - 90044461 | Roland - 97479331

Toyota Wish 1.8A X (COE till 05/2029)	\$62,800	\$6,420 /yr	26-Jun-2009	1,797 cc	120,000 km	Esprit Motor Trading	Available
--	-----------------	--------------------	--------------------	-----------------	-------------------	-----------------------------	------------------

-

Office No. - 64568623

Francis Goh - 96608623

Toyota Wish 1.8A X (COE till 06/2029)	\$62,800	\$6,370 /yr	29-Jun-2009	1,797 cc	108,000 km	Viking Motor Pte Ltd	Available
--	-----------------	--------------------	--------------------	-----------------	-------------------	-----------------------------	------------------

\$0 Drive Away! 100% Loan Approval! New Facelift! New 10 Years COE. Non Smoker Car! Very Well Kept Condition. Clean And Neat Interior. No Repairs Needed! Please Call Now Before Its Sold! High Trade In ...

Office No. - 63146133

Aaron - 96288965 | Ayden - 88151068 | Daryl - 88111812 | Jeffrey - 86601482

Toyota Wish 1.8A X (COE till 06/2024)	\$45,800	\$9,430 /yr	30-Jun-2009	1,797 cc	65,000 km	ABWIN (1994) Pte Ltd	Available
--	-----------------	--------------------	--------------------	-----------------	------------------	-----------------------------	------------------

100% Loan And Trade In Welcome! New Paintwork! No Repairs Needed At All! Guaranteed Satisfaction! Low Mileage Done! 1 Owner Only! Excellence Condition! PHV Welcome! Don't Wait! Contact Our Friendly Sa...

Office No. - -

Chee Weng - 82221739 | Jarrett Goh - 91013261

Toyota Wish 1.8A X (COE till 07/2024)	\$42,800	\$8,790 /yr	06-Jul-2009	1,797 cc	115,000 km	Crown Motoring Pte Ltd	Available
--	-----------------	--------------------	--------------------	-----------------	-------------------	-------------------------------	------------------

Only 1 Owner! Genuine Low Mileage Done! Road Tax Till Jan 2020! In House And Bank Loan Available! Call Now Before It's Gone!

Office No. - 68733133

Steve - 84250925 | Danny - 86833133

Toyota Wish 1.8A X (New 10-yr COE)	\$65,800	\$6,570 /yr	09-Jul-2009	1,797 cc	113,905 km	San Hup Bee (S) Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------------	------------------

Free 1 Years Warranty! 100% Loan At 100% Approval Rate. Best MPV Of Its League. 1 Owner Only. New 2k Metallic White Paint With All Wear And Tear Done. Great Leather Seat Condition. No Price Gimmicks! ...

Office No. - 69093556

Esther - 97129286 | Morning Wong - 86939109 | Dennis Huang - 91175113 | Paul Lee - 83133220

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/07/2019 13:33
Date Of Accident	09/07/2019 17:00
Exact Location Of Accident	ALONG BALESTIER ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLD9677A
Insured/Policyholder	
Name Of Registered Owner	A MOTOR LEASING LLP
Co Reg No	T18LL1339D
Email Address	AAUTOSERVICES0631@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-85115194
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102908560
Cover Note Number	
Driver	
Name of Driver	LOW CHUAN, VINCENT (LIU QUAN)
NRIC No	S7819265H
Date Of Birth	12/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	27/03/2009
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85115194
Fax Number	
Contact Number	
E-Mail Address	LIUQUESTO@GMAIL.COM

Address	BLK 81 COMMONWEALTH CLOSE #04-105
Postcode	140081
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TANGLIN POLICE DIVISIONAL HQ ('E' DIVISION)
Police Station Address	ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3910000 - FAX NO: 63964900
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU7181K
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED AND POLICE REPORT
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage REFER ATTACHED AND POLICE REPORT
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLV4886B
Vehicle Make/Model/Colour
Details Of Properties REFER ATTACHED AND POLICE REPORT
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REFER ATTACHED AND POLICE REPORT
No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name LOW CHUAN, VINCENT (LIU QUAN)
Approximate Age
Injuries Sustain REFER ATTACHED AND POLICE REPORT
Injured person in which vehicle? SLD9677A
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

A: SLD9677A E: SJ47181K C: SLV4886B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

POST NO-38

Please refer to police report E/20190710/7008

I would like to add that vehicle B also hit on to vehicle C (SLV4886B)

I was given 8 days MC by SHU A&Z department and went there by myself

DECLARATION

(We declare the above particulars are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC / ID No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be stored / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



E/20190710/7008

1 of 2

POLICE REPORT (NP299)

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No:1800-3910000

Report No. E/20190710/7008

Date/Time Report Made 10/07/2019 12:48		Vide Report No.		Station Diary No.	
Name Of Informant LOW CHUAN, VINCENT		Address APT BLK 81 COMMONWEALTH CLOSE #04-105 SINGAPORE 140081			
ID Type / ID No. NRIC NO / S7819265H		Contact No. Home/Office: Mobile: 85115194			
Nationality SINGAPORE CITIZEN		Email Address liuguesto@gmail.com			
Occupation Chauffeur		Sex Male	Age 40	Date of Birth 12/07/1978	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 09/07/2019 17:00 - 09/07/2019 17:15		Location Of Incident BALESTIER ROAD			
Brief details.					

I was driving (sld 9677a) along balestier road towards cte. A car (sju7181k) from the opposite side of the lane crashes into the centre divider barricade and hit my vehicle and hit the lamp post no.38

I was given 8 days of MC by SGH.

Subjects Involved	
Victim	
Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2019 12:48
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	



**SINGAPORE
POLICE FORCE**



E/20190710/7008

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20190710/7008

Person Name	LOW CHUAN, VINCENT		
ID Type	NRIC NO	ID No	S7819265H
Gender	Male	Age	40
Race	Chinese	Language	English
Occupation	Chauffeur	Address Type	
Address	APT BLK 81 COMMONWEALTH CLOSE #04-105 SINGAPORE 140081	Mobile No	85115194
Is Informant A Victim?	Yes		
Person Name	LOW CHUAN, VINCENT (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

10/07/2019 12:48

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019 Edit Reg		11 Jul 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Liang Chay Kim Simon, ID: S77088493, Tel: +6599999999		
Main Claimant:	A MOTOR LEASING LLP, Co. Reg. No.: T18LL1339D		
Vehicle Reg. No.:	SLD9677A	Date of Loss:	09/07/2019 15:00 - :59 [119 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5886352022SG	Policy/Cover Note No.:	2100181499 (Comprehensive)
Vehicle Reg. No. (Insured):	SJU7181K	Policy No. (Claimant):	
		Excess:	
Repairer:	A Auto Services (HQ) A AUTO SERVICES, 5 SOON LEE STREET #06-31 PIONEER POINT, 627607 Jurong East - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/07/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (15/07/2019): No Policy Found for SLV4886B

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD9677A (5886352022SG)
[SJU7181K]
TP
A MOTOR LEASING LLP
Jul 9 2019 3:00PM
[Liang Chay Kim Simon]
A Auto Services

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	05/08/19 16:50	General View										Load JPG	☒	
2	05/08/19 16:50	General View										Load JPG	☒	
3	05/08/19 16:50	General View										Load JPG	☒	
4	05/08/19 16:50	General View										Load JPG	☒	
5	05/08/19 16:50	General View										Load JPG	☒	
6	05/08/19 16:50	General View										Load JPG	☒	
7	05/08/19 16:50	General View										Load JPG	☒	
8	05/08/19 16:50	General View										Load JPG	☒	
9	05/08/19 16:50	General View										Load JPG	☒	
10	05/08/19 16:50	General View										Load JPG	☒	
11	05/08/19 16:50	General View										Load JPG	☒	
12	05/08/19 16:50	General View										Load JPG	☒	
13	05/08/19 16:50	General View										Load JPG	☒	
14	05/08/19 16:50	General View										Load JPG	☒	
15	05/08/19 16:50	General View										Load JPG	☒	
16	05/08/19 16:50	General View										Load JPG	☒	
17	05/08/19 16:50	General View										Load JPG	☒	
18	05/08/19 16:50	General View										Load JPG	☒	
19	05/08/19 16:50	General View										Load JPG	☒	
20	05/08/19 16:50	General View										Load JPG	☒	
21	05/08/19 16:50	General View										Load JPG	☒	
22	05/08/19 16:50	General View										Load JPG	☒	
23	05/08/19 16:50	General View										Load JPG	☒	
24	05/08/19 16:50	General View										Load JPG	☒	
25	05/08/19 16:50	General View										Load JPG	☒	
26	05/08/19 16:50	General View										Load JPG	☒	
27	05/08/19 16:50	General View										Load JPG	☒	
28	05/08/19 16:50	General View										Load JPG	☒	
29	05/08/19 16:50	General View										Load JPG	☒	
30	05/08/19 16:50	General View										Load JPG	☒	
31	05/08/19 16:50	General View										Load JPG	☒	
32	05/08/19 16:50	General View										Load JPG	☒	
33	05/08/19 16:50	General View										Load JPG	☒	
34	05/08/19 16:50	General View										Load JPG	☒	
35	05/08/19 16:50	General View										Load JPG	☒	
36	05/08/19 16:50	General View										Load JPG	☒	
37	05/08/19 16:50	General View										Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/08/19 16:50	General View	 Load JPG	☒
39	05/08/19 16:50	General View	 Load JPG	☒
40	05/08/19 16:50	General View	 Load JPG	☒
41	05/08/19 16:50	General View	 Load JPG	☒
42	05/08/19 16:50	General View	 Load JPG	☒
43	05/08/19 16:50	General View	 Load JPG	☒
44	05/08/19 16:50	General View	 Load JPG	☒
45	05/08/19 16:50	General View	 Load JPG	☒
46	05/08/19 16:50	General View	 Load JPG	☒
47	05/08/19 16:50	General View	 Load JPG	☒
48	05/08/19 16:50	General View	 Load JPG	☒
49	05/08/19 16:50	General View	 Load JPG	☒
50	05/08/19 16:50	General View	 Load JPG	☒
51	05/08/19 16:50	General View	 Load JPG	☒
52	05/08/19 16:50	General View	 Load JPG	☒
53	05/08/19 16:50	General View	 Load JPG	☒
54	05/08/19 16:50	General View	 Load JPG	☒
55	05/08/19 16:50	General View	 Load JPG	☒
56	05/08/19 16:50	General View	 Load JPG	☒
57	05/08/19 16:50	General View	 Load JPG	☒
58	05/08/19 16:50	General View	 Load JPG	☒
59	05/08/19 16:50	General View	 Load JPG	☒
60	05/08/19 16:50	General View	 Load JPG	☒
61	05/08/19 16:50	General View	 Load JPG	☒
62	05/08/19 16:50	General View	 Load JPG	☒
63	05/08/19 16:50	General View	 Load JPG	☒
64	05/08/19 16:50	General View	 Load JPG	☒
65	05/08/19 16:50	General View	 Load JPG	☒
66	05/08/19 16:50	General View	 Load JPG	☒
67	05/08/19 16:50	General View	 Load JPG	☒
68	05/08/19 16:50	General View	 Load JPG	☒
69	05/08/19 16:50	General View	 Load JPG	☒
70	05/08/19 16:50	General View	 Load JPG	☒
71	05/08/19 16:50	General View	 Load JPG	☒
72	05/08/19 16:50	General View	 Load JPG	☒
73	05/08/19 16:50	General View	 Load JPG	☒
74	05/08/19 16:50	General View	 Load JPG	☒
75	05/08/19 16:50	General View	 Load JPG	☒
76	05/08/19 16:50	General View	 Load JPG	☒
77	05/08/19 16:50	General View	 Load JPG	☒
78	05/08/19 16:50	General View	 Load JPG	☒
79	05/08/19 16:50	General View	 Load JPG	☒
80	05/08/19 16:50	General View	 Load JPG	☒
81	05/08/19 16:50	General View	 Load JPG	☒
82	05/08/19 16:50	General View	 Load JPG	☒
83	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
84	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
85	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
86	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
87	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
89	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
90	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
91	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
92	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
93	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
94	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
95	05/08/19 16:50	Photographs of Damaged Parts	 Load JPG	☒
96	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
97	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
98	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
99	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
100	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
101	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
102	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
103	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
104	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
105	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
106	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
107	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
108	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
109	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
110	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
111	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
112	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
113	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
114	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
115	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
116	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
117	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
118	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
119	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
120	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
121	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
122	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
123	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
124	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
125	05/08/19 16:51	Photographs of Damaged Parts	 Load JPG	☒
126	05/08/19 16:51	Photo After Spray	 Load JPG	☒
127	05/08/19 16:51	Photo After Spray	 Load JPG	☒
128	05/08/19 16:51	Photo After Spray	 Load JPG	☒
129	05/08/19 16:51	Photo After Spray	 Load JPG	☒
130	05/08/19 16:51	Photo After Spray	 Load JPG	☒
131	05/08/19 16:51	Photo After Spray	 Load JPG	☒
132	05/08/19 16:51	Photo After Spray	 Load JPG	☒
133	05/08/19 16:51	Photo After Spray	 Load JPG	☒
134	05/08/19 16:51	Photo After Spray	 Load JPG	☒
135	05/08/19 16:51	Photo After Spray	 Load JPG	☒
136	05/08/19 16:51	Photo After Spray	 Load JPG	☒
137	05/08/19 16:51	Photo After Spray	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	05/08/19 16:51	Photo After Spray		☒
139	05/08/19 16:51	Photo After Spray		☒
140	05/08/19 16:51	Photo After Spray		☒
141	05/08/19 16:51	Photo After Spray		☒
142	05/08/19 16:51	Photo After Spray		☒
143	05/08/19 16:51	Photo After Spray		☒
144	05/08/19 16:51	Photo After Spray		☒
145	05/08/19 16:51	Photo After Spray		☒
146	05/08/19 16:51	Photo After Spray		☒
147	05/08/19 16:51	Photo After Spray		☒
148	05/08/19 16:51	Photo After Spray		☒
149	05/08/19 16:51	Photo After Spray		☒
150	05/08/19 16:51	Photo After Spray		☒
151	05/08/19 16:51	Photo After Spray		☒
152	05/08/19 16:51	Photo After Spray		☒
153	05/08/19 16:51	Photo After Spray		☒
154	05/08/19 16:51	Photo After Spray		☒
155	05/08/19 16:51	Photo After Spray		☒
156	05/08/19 16:51	Photo After Spray		☒
157	05/08/19 16:51	Photo After Spray		☒
158	05/08/19 16:51	Photo After Spray		☒
159	05/08/19 16:51	Photo After Spray		☒
160	05/08/19 16:51	Photo After Spray		☒
161	05/08/19 16:51	Photo After Spray		☒
162	05/08/19 16:51	Photo After Spray		☒
163	05/08/19 16:51	Photo After Spray		☒
164	05/08/19 16:51	Photo After Spray		☒
165	05/08/19 16:51	Photo After Spray		☒
166	05/08/19 16:51	Photo After Spray		☒
167	05/08/19 16:51	Photo After Spray		☒
168	05/08/19 16:51	Photo After Spray		☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012265/R1CD3E2

Date: 30/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100181499
Claimant Vehicle No : SLD9677A **Insured Vehicle No :** SJU7181K
 Date of Loss: 09/07/2019 Nature of Claim: TP Claim No: 5886352022SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD9677A**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR0429340
 Reg. Date: 23/07/2009 (Man. Year: 2009) Chassis No: ZGE200009090
 Colour: Black Odometer: 184367 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/07/2019
 Date Inspected: 11/07/2019 Inspected At: A Auto Services (HQ)
 A AUTO SERVICES, 5 SOON LEE STREET #06-31 PIONEER POINT
 Singapore 627607

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Crumpled	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*FRT BUMPER SIDE RETAINER	Crumpled	0.00 F	*-F
4	1		*FRT BUMPER SPONGE	Crumpled	0.00 F	*-F
5	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*-F
6	1		*FRT GRILLE	Cracked	0.00 F	*-F
7	1		*FRT SUPPORT PANEL	Repair	0.00 F	*-F
8	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Crumpled	0.00 F	*-F
9	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
10	1		*BONNET	Bent	0.00 F	*-F
11	1		*BONNET RUBBER	Necessary	0.00 F	*-F
12	1		*AIR CON CONDENSER	Dented	0.00 F	*-F
13	1		*ENGINE UNDER COVER	Cut	0.00 F	*-F
14	1		*FRT RH DOOR	Repair	0.00 F	*-F
15	1		*FRT RH DOOR WING MIRROR	Cut	0.00 F	*-F
16	1		*FRT RH DOOR OUTER HANDLE	Cut	0.00 F	*-F
17	1		*FRT RH FENDER	Bent	0.00 F	*-F
18	1		*FRT RH FENDER INNER SHIELD	Cut	0.00 F	*-F
19	1		*FRT RH WHEEL RIM	Cut	0.00 F	*-F
20	1		*REAR RH DOOR	Repair	0.00 F	*-F
21	1		*REAR BUMPER	Crumpled	0.00 F	*-F
22	1		*REAR RH FENDER	Repair	0.00 F	*-F
23	1		*FRT RH LOWER ARM	Bent	0.00 F	*-F
24	1		*FRT RH KNUCKLE ARM	Distorted	0.00 F	*-F
25	1		*FRT RH WHEEL BEARING	Necessary	0.00 F	*-F
26	1		*FRT RH SHOCK ABSORBER	Bent	0.00 F	*-F
27	1		*BONNET LOCK	* Check	0.00 F	*-F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >