

ASS. REC. BY:

REF:

CS3/III19012266/Gcd302

Special Instruction:

Summary: undaringASSIGNMENT (Office)From (Person): Gabriel wee

of

IIIDate/Time: 11/7/19 @ 9:24am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKC 9660P

Insured:

SHC 3984E

at Workshop m/s

Eng Shing Mechanical

Tel:

6453 7380

of

160 Sin Ming Drive # 06-21

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:20am @ 11/7/19

Person Contacted:

Mr. TenVehicle: IN OUT

Date/Time	Action/Instruction
	<u>Johnny! (X)</u>
	<u>SKC 9660P - X</u>
	<u>SHC 3984E - (C3/AXA13007920/H1e3w2</u>
	<u>DOA: 28/4/2013</u>
	<u>Dismantle: 12/7/2019 0130pm</u>
	<u>After repair: 16/7/2019 0652pm</u>

PRS
Chl.

REF: IV

5750A


ASSIGNMENT

(2023)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Eng shing Mechanical
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$24K
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKC9660P Yr Regn: 07Jul/2008
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota U6S C.C. 1497
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 243291 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053H5930 S0 69339
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/45R17 CH BS Green Max
 R: 205/45R17 - Kapsen
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11-07-19
 Survey held at W/S 12:15pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$500 - \$6000
COB: 14812
12/7/2019

RECEIVED 24 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$)

Transportation:

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format : PRE.

Lump Sum / I.B.I. (\$) _____

120

11

131

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) Edit Reg		11 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	-		
Vehicle Reg. No.:	SKC9660P	Date of Loss:	09/07/2019 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC3984E	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 11 July 2019 9:24 AM
To: Oracle Law Corp; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Pooi Chin Han Daniel
Subject: RE: PRE-REPAIR INSPECTION Our Ref: SB/PO/Acc/2019-9039 Your Ref: Insurer of SHC 3984E
Attachments: 9039 - List of MS_20190710152544.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKC9660P
III INSURED VEHICLE NO. : SHC3984E
DATE OF LOSS : 09.07.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Daniel.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: 10 July, 2019 3:34 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION Our Ref: SB/PO/Acc/2019-9039 Your Ref: Insurer of SHC 3984E

Dear Gabriel,


PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SKC 9660P & SHC 3984E ALONG PIE NEAR KALLANG BAHRU SWIMMING COMPLEX ON 09-07-2019 @ 6.25 P.M.

Kindly refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong



• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 10 July 2019 3:23 PM

To: Oracle Law Corp <mail@oraclelaw.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKC9660P (Accident involving SKC9660P and SHC3984E on 09.07.2019)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

To	: India International Insurance Pte Ltd	Date	: 10 th July 2019
Attention	: Motor Claims (Gabriel Wee)	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SHC 3984E	Our Ref.	: SB/PO/Acc/2019-9039
Facsimile	: 6225-7743 / 6224-4174	No. of Pages	: 1 (including this page)

IMMEDIATE ATTENTION

Dear Gabriel,

PRE-REPAIR INSPECTION

**ACCIDENT INVOLVING SKC 9660P & SHC 3984E ALONG PIE NEAR KALLANG BAHRU SWIMMING COMPLEX
ON 09-07-2019 @ 6.25 P.M.**

1. We refer to your email of even date and your list of motor surveyors.
2. We are instructed by our clients that they are not agreeable to the appointment of any one of the surveyors named in your said list. We append herewith our list of our clients' proposed motor surveyors for your kind consideration to conduct a joint pre-repair survey:-
 - a. Oh Appraisal Services; or
 - b. Absolute Appraisal Services Pte Ltd
3. Kindly let us know **within the two (2) working days** whether you agree to any of the said proposed motor surveyors failing which you are deemed to have agreed to the appointment of any of the motor surveyors named in our said list.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong

Enc

cc. Eng Shing Mechanical Works

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	5750A
Vehicle No.:	SKC9660P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZX767361
Chassis No.:	MR053HY9305069339
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,344.00
Original Registration Date:	07 Jul 2008
First Registration Date:	07 Jul 2008
Transfer Count:	3
Actual ARF Paid:	\$12,344.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	06 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$14,812.00
Total Rebate Amount:	\$14,812.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2019

OK

► Vios Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Vios 1.5A J (COE till 05/2022)	\$23,555	\$8,340 /yr	08-May-2007	1,497 cc	138,248 km	Cars Premium	Available
Owner Well Maintain! Just Renew Road Tax Till Nov 2019! Don't Miss It! In House Financing Options Available. Buy With A Peace Of Mind. Well Maintained. Immaculate Condition. Free Car Spa Polishing, Fr...							
Office No. - 63654321 Chan - 93387838							
Toyota Vios 1.5M J (COE till 08/2022)	\$20,888	\$6,690 /yr	24-Aug-2007	1,497 cc	141,282 km		Available
Good Engine Response. Very Value For Money. Most Importantly Its Toyota.							
Office No. - - Serene Lim - 96852332							
Toyota Vios 1.5A E (COE till 11/2022)	\$19,800	\$5,840 /yr	30-Nov-2007	1,497 cc	-	Boeki Auto Pte Ltd	Available
Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.							
Office No. - 67555005 Boeki - 82180500							
Toyota Vios 1.5A J (COE till 10/2022)	\$19,888	\$6,010 /yr	23-Jan-2008	1,497 cc	132,500 km	007	Available
Good Buy! Best Deal! Call Now! \$0 Drive Away! Zero-Major Mishaps. Straight Chassis. Zero Oil Leakage. Superb Exterior Aesthetics And Clean Neat Interior With Almost No Scratches. Very Well Maintained ...							
Office No. - 65700770 Kenny Goh - 98334449 Tom Tan - 85002727 Ian Chan - 81180118 Kelvin Tay - 85353544							
Toyota Vios 1.5A E (COE till 11/2027)	\$40,800	\$4,860 /yr	30-Jan-2008	1,497 cc	51,000 km	Boeki Auto Pte Ltd	Available
Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.							
Office No. - 67555005 Boeki - 82180500							
Toyota Vios 1.5A E (COE till 02/2023)	\$21,800	\$6,010 /yr	25-Feb-2008	1,497 cc	-	88 Motor Trading	Available
Full Loan Available At \$600 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With ...							
Office No. - 62911187 Jeremy - 97625070 Ben - 90913551 Lek - 87555787 Nic - 81001945							
Toyota Vios 1.5A E (COE till 04/2023)	\$22,500	\$5,950 /yr	23-Apr-2008	1,497 cc	113,904 km		Available
New Paintwork! Well Maintained By Previous Owner, Call Now To View At Your Convenient Location!							
Office No. - - Mr Lim - 98163888							
Toyota Vios 1.5A J Sports (COE till 05/2023)	\$24,800	\$6,370 /yr	27-Jun-2008	1,497 cc	110,556 km	AB Zone	Available
1 Owner, Another Of Our Company Carefully Selected Range Of COE Renewal Cars! Wear And Tear All Replaced And Repaired, New Paint Work! 100% Accident Free! 100% Repair Free! Full Agent Fitted TRD Bodyk...							
Office No. - - Kelvin - 98500175 Mr Ong - 81163338							
Toyota Vios 1.5M E (COE till 04/2023)	\$25,800	\$6,780 /yr	16-Sep-2008	1,497 cc	135,000 km	San Hup Bee (S) Pte Ltd	Available
100% Full Loan At 100% Approval Rate! 100% Head Turner With Everything 100% Done Up By 100% Car Lover. Sports Rims, Bucket Seats, Coilover, Exhaust And Superb Sound System All Go Together With The Car...							
Office No. - 69093556 Esther - 97129286 Dennis Huang - 91175113 Paul Lee - 83133220 Morning Wong - 86939109							

Toyota Vios 1.5A E (COE till 11/2023) \$25,800 \$5,890 /yr 26-Nov-2008 1,497 cc 116,000 km Creative Auto **Available**
 Just Arrival, Selling Cheap, Full Loan Available, No Repairs Needed. New Paintwork, Trade In Welcome, Call For Viewing Or Test Drive Now.
 Office No. - -
 Eric Law - 98581241 | Aaron - 98797788 | Terence Leow - 90290899

Toyota Vios 1.5A E (COE till 01/2029) \$41,000 \$4,290 /yr 03-Feb-2009 1,497 cc 111,547 km Centro Auto Pte Ltd **Available**

Excellent Condition. Worn Parts Replaced. New Tyres. Road Tax Till Jan 2020. Original Clean And Fresh Fabric Testament To The Care Accorded. Flexible Loan. Please Call Us For A Test Drive Appointment!

Office No. - -
 Lee - 97664562 | Clement - 87255990

Toyota Vios 1.5A G Sports (COE till 02/2024) \$29,800 \$6,500 /yr 10-Feb-2009 1,497 cc 123,000 km Carway **Available**

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank And In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, ...

Office No. - 68440777
 Tanisha - 88665777 | Peter Quek - 84840777

Toyota Vios 1.5A E (COE till 02/2029) \$41,800 \$4,360 /yr 12-Feb-2009 1,497 cc 110,000 km Edmund Motor Pte Ltd **Available**

Well Maintained By Previous Owner! Flexible Loan Available, Trade In Welcome. Call Now To View The Car At Your Convenience!

Office No. - 62523339
 Joe Kek - 98326732 | David Lau - 93889178

Toyota Vios 1.5A E (COE till 02/2024) \$28,800 \$6,250 /yr 19-Feb-2009 1,497 cc - Prime Car Traders Pte Ltd **Available**

Excellent Condition. Very Well Maintained By Previous Owner. View To Believe. Bank Loan/Loan/In House Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Reps Today To Arrange ...

Office No. - 63166000
 Tony - 90885037 | Jessy - 91690999 | Nicolas Lim - 96849675

Toyota Vios 1.5A J (COE till 02/2024) \$27,777 \$6,000 /yr 25-Feb-2009 1,497 cc - Trans Express **Available**

Popular Vios 1.5A With New COE. Regularly Serviced, Good Engine. Bank Loan From \$451. Flexible Loan Packages. Most Practical, Reliable Engine, Yet Fuel Efficient. Call Us For A Viewing Appointment Tod...

Office No. - 67473818
 Adrian Chua - 98182884

Toyota Vios 1.5A G (COE till 03/2024) \$29,800 \$6,310 /yr 01-Apr-2009 1,497 cc 164,830 km Inchcape Pre-Owned **Available**

Low Risk Purchase, An Ideal Choice For Daily Commute. Call Our Sales Consultants For A Viewing Today!

Office No. - 63036303
 Jason Tan - 98882000 | Edmund Ng - 90212360 | Chris Tang - 81683557 | Jj Chua - 90037428

Toyota Vios 1.5A E (COE till 04/2024) \$28,800 \$6,040 /yr 17-Apr-2009 1,497 cc - Lei Fu Trading Co. **Available**

1 Owner Only, 100% Loan Available. No Gimmicks. Most Reliable Japanese Sedan Vios Ideally For Daily Drives Yet Fuel Efficient. Very Well Maintained In Tip Top Condition. New Paintwork. New Tyres. No R...

Office No. - 67469005
 Tee - 83052624 | Tan - 96942466

Toyota Vios 1.5A E (COE till 04/2024) \$30,500 \$6,380 /yr 21-Apr-2009 1,497 cc 177,600 km Inchcape Pre-Owned **Available**

One Owner Unit. Popular Sedan In The Market. Please Call Our Sales Consultant For More Enquiries Now!

Office No. - 63036303
 Chris Tang - 81683557 | Jason Tan - 98882000 | Kelvin Kee - 98719789 | JJ Chua - 90037428

Toyota Vios 1.5A E (COE till 04/2024) \$28,777 \$6,020 /yr 21-Apr-2009 1,497 cc - Trans Express **Available**

Popular Toyota Vios 1.5A. Low Mileage. Regularly Serviced. Good Engine, Low Maintenance. Full Loan Avail. New Paint. Most Practical, Reliable Engine, Yet Fuel Efficient. Call Us For A Viewing Appointment...

Office No. - 67473818
 Adrian Chua - 98182884

Toyota Vios 1.5A E (COE till 04/2024) **\$29,800** \$6,210 /yr 27-Apr-2009 1,497 cc 139,000 km Inchcape Pre-Owned **Available**

Low Risk Purchase, An Ideal Choice For Daily Commute. Call Our Sales Consultants For A Viewing Today!

Office No. - 63036303

Jj Chua - 90037428 | Jason Tan - 98882000 | Edmund Ng - 90212360 | Kelvin Kee - 98719789

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2019 13:32
Date Of Accident	09/07/2019 18:25
Exact Location Of Accident	PIE NEAR KALLANG BAHRU SWIMMING COMPLEX
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC9660P
Insured/Policyholder	
Name Of Registered Owner	SIM HAE SEE
NRIC No	S0905750A
Email Address	JASON_SCREAMER@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91857282
Alternative Phone No	OTHERS-91857282

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5101948766-01
Cover Note Number	

Driver

Name of Driver	JASON CHUA
NRIC No	S9319073D
Date Of Birth	28/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	25/04/2014
Driving Experience	5 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91857282
Fax Number	
Contact Number	
EEmail Address	JASON_SCREAMER@HOTMAIL.COM

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Address	BLK 226C SUMANG LANE #03-232
Postcode	823226
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3984E
Vehicle Make/Model/Colour	
Details Of Properties	FRONT
Vehicle Category	TAXI
Name of Driver	LOY LOONG TAK
NRIC/Passport Number	
Contact Number	91449399
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along PIE near Kallang Bahru swimming complex and I was driving in lane 4 and in front car stop so I slow down and stop so vehicle B bang me from the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

QIARMS SketchplanForm_V3

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 09:55 Edit Reg		11 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	-, Co. Reg. No.: -			
Main Claimant:	-			
Vehicle Reg. No.:	SKC9660P	Date of Loss:	09/07/2019 00:00 - :59 [132 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	SHC3984E	Policy No. (Claimant):		
		Excess:		
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/07/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC9660P
[SHC3984E]






































TP
















































-


























Jul 9 2019 12:00AM

[-]

Eng Shing Mechanical Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/07/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	24/07/19 14:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	24/07/19 14:01	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/07/19 08:31	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19012266/GCD3E2

Date: 30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKC9660P

Insured Vehicle No : SHC3984E

Date of Loss: 09/07/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC9660P

Make & Model: TOYOTA VIOS, 1.5 E (A)

Reg. Date: 07/07/2008 (Man. Year: 2008)

Colour: Black

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZX767361

Chassis No: MR053HY9305069339

Odometer: 243291 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/40Z R17

Rear Tyre Size: 205/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/07/2019

Date Inspected: 11/07/2019 Inspected At:

Eng Shing Mechanical Works (HQ)
160 Sin Ming Drive, #06-21 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC9660P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >