

REF: CITED 19012276/NC
ASS. REC. BY: SURVIVOR
ASSIGNMENT (Office)
From (Person): Kamalish Kamie of SPF Date/Time: 20/6/2019
Estimated Cost: Bill to:
OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: JRW 8414 Insured:
at Workshop m/s Tel:
of
Policy No: MHASPF06000020127 Claim No: TP/1P/36381/2019
Sum Insured: Excess:
Make of Veh: D.O.A 9/6/2019
(Client's Record)
CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:
Date/Time Person Contacted: Vehicle IN/OUT
Date/Time Action/Instruction () Estimate
JRW 8414 -X
4501/9

- v) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JSN1887 (TP/IP/36381/2019)
w) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JRW8414 (TP/IP/36381/2019)

On 09 June 2019 at about 12.02pm, the driver of SGQ1003M was driving his motor car on the right lane of 3 lanes, along BKE(PIE) slip road into PIE(AP). Whilst negotiating a downslope left bend, the driver lost control of his vehicle and skidded towards the right before the car plunges into a group of pedestrians (including TPO and Paramedic) and other vehicles which were involved in an accident earlier. As a result of the accident, multiple victims were conveyed with slight to serious injuries.

Vehicles to be inspected: SGQ1003M - Defendant
SJZ1789X - Involved Party
JSN1887 - Involved Party
JRW8414 - Involved Party

IO In-Charge: IO Dylan Ma

Cellar
Pls help me open reference.
-Naz.