

13010001

ASS. REC. BY:

REF: C/TPD19012280/NC

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Date/Time: 20/6/2019

From (Person): Kamalish Kanic

of SPF

Bill to:

Estimated Cost:

OD/TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JEN 1887

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPP06000020127

Claim No:

TP/IP/36381/2019

Sum Insured:

Excess:

D.O.A

9/6/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

JEN 1887 - X

45019

- v) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JSN1887 (TP/IP/36381/2019)
w) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JRW8414 (TP/IP/36381/2019)

On 09 June 2019 at about 12.02pm, the driver of SGQ1003M was driving his motor car on the right lane of 3 lanes, along BKE(PIE) slip road into PIE(AP). Whilst negotiating a downslope left bend, the driver lost control of his vehicle and skidded towards the right before the car plunges into a group of pedestrians (including TPO and Paramedic) and other vehicles which were involved in an accident earlier. As a result of the accident, multiple victims were conveyed with slight to serious injuries.

Vehicles to be inspected: SGQ1003M - Defendant
SJZ1789X - Involved Party
JSN1887 - Involved Party
JRW8414 - Involved Party

IO In-Charge: IO Dylan Ma

Celine

Pls help me open reference.

- Naz.