

7/27/2019

ASS. REC. BY:

REF: CS/FCI 19012291/69d327 Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

CWS

From (Person): Joanne Yong

of FCI

Date/Time: 10/7/19 @ 4:33pm

Estimated Cost:

Bill to:

OD/TP/FWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7436A

Insured:

SHC 28274

at Workshop m/s

Lex Build International

Tel:

6456 3533

9.0246574

Yong Sun

of

2 woodlands Ave. 1 #05-12

Policy No:

Claim No:

D19004509MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:07am @ 11/7/19

Person Contacted:

Kenny

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction
	Estimate (✓)
	PC 7436A X
	SHC 28274 NA/INC18019248/h4 23/10/18
18/7/19 @ 3:39am	revised to Joanne Yong by email.
20/8/19 @ 4:46pm	checked with Shirley, they still awaiting for Insurance's liability.
20/8/19	submit prev. report. - The vehicle has not send in for repair.

ASSIGNED BY: Steve

REF: FCI

ASSIGNMENT

From:

Date: 16/7/19

Veh No:

PC 7436A

Yr Regn:

14/9/18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

PC 7436A

Make:

Yutong 2K6119H

C.C.

6690

at Workshop m/s

LexBuild International

Colour

Multi-colour

A/C:

Insured / Std / NI / NA

of

2 woodlands sse 1 #05-12

Sp. Reading

56363

T/Radio:

Insured / Std / NI / NA

Insured:

9615 8280

Policy No.

Shirley

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9am-12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lwp

Vehicle: IN / OUT

Date:

Person Contacted:

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

11R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Double COIN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

29/6/19

D.O.I.

16/7/19

Survey held at

Lex build

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 AUG 2019

Date/Time, File Pass to?



: Preli. Report

21/8 12:00 PM



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R8. ST

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / L.B.L: 10

100

50

17

167

MOTOR SURVEY ASSIGNMENT

Date	09-07-2019	Our Ref No. D19004509MFSH
Accident Date	29-06-2019	Claim Type. Third Party
Insured Vehicle	SHC2827H	Third Party Vehicle. PC7436A
Survey Location	2 WOODLANDS SECTOR 1 #05-12(WOODLANDS SPECTRUM 1)	
Contact Person.	SHIRLEY LIM	
Contact No.	64563533/ 0	Fax No. 64563353
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEXBUILD INTERNATIONAL PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 17 July 2019 3:39 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004509MFSH/1
Attachments: CSFCI19012291Eqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of PC 7436A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 11 July 2019 10:14 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004509MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 10 July 2019 4:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004509MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004509MFSH
Our Ref: CS/FCI19012291/Eqd3

Date: 17 July 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. PC 7436A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/07/2019 at the premises of M/s LEXBUILD, and have the following to report:-

Workshop Estimate Amount	: S\$ 1,600.00 .
Revised Estimate Amount	: S\$ 600.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s portion.



Yours faithfully

Steve
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7110H
Vehicle Details	
Vehicle No.:	PC7436A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2019
Vehicle Make:	YUTONG
Vehicle Model:	ZK6119H AUTO
Primary Colour:	Multi-Colour
Manufacturing Year:	2018
Engine No.:	ISB67E6C29022308031
Chassis No.:	LZYTBT66J1019495
Maximum Power Output:	-
Open Market Value:	\$144,538.00
Original Registration Date:	14 Sep 2018
First Registration Date:	14 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$7,227.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,889.00
COE Rebate Amount:	\$28,293.00
Total Rebate Amount:	\$28,293.00

The information contained herein is correct as at 16 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2019 16:03
Date Of Accident	29/06/2019 09:35
Exact Location Of Accident	HAVELOCK ROAD TURNING INTO FOUR POINT SHERATON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC7436A
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE COACH SERVICES PTE LTD
Co Reg No	201227110H
Email Address	ADMIN@SINGAPORECOACHSERVICES.COM
Mobile Phone No	(LOCAL) +65-96204026
Alternative Phone No	OFFICE-66945458

Vehicle Particulars

Manufacturer	YUTONG
Model	ZK6119H AUTO
Exact Purpose for which vehicle was being used at time of accident	PICK UP PASSENGER FROM FOUR POINT SHERATON
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5092609656-01
Cover Note Number	

Driver

Name of Driver	ONG TAI SENG
NRIC No	S1730325B
Date Of Birth	19/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	24/04/1989
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90606648
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLOCK 411 PANDAN GARDENS #11-92
Postcode	600411
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 29/06/2019 around 0938 0hr, While I was driving my bus PC7436A along Havelock Road trying to turn Left Into Four Point Sheraton Hotel , i signal early before i making a wide turn into Four Point Sheraton hotel , I have make clear than no vehicle on my left suddenly I heard a bang sound and saw a Taxi SHC2827H trying to squeeze through my bus when I trying to make a wide angle turn At the material of time no one is injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2827H
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/06/2019 1350


Reporting Centre Personnel's Signature
Name: Shirley Lim
NRIC/FIN No: S15522081

An aerial photograph showing a small dark-colored car parked next to a much larger white truck. The truck is oriented diagonally, while the car is parallel to it. The truck has a large white box body and a dark cab area. The car is a standard sedan. The background is a light, textured surface, possibly a parking lot or road.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the material of time no one is injured.

I/we declare that foregoing particulars are true in every respect.

Reporting Centre Person's Signature
Name: Shirley Lim
NRIC/FIN No.: S1552700

09th July 2019

MS First Capital Insurance Limited
36, Robinson Road, #16-01
City House
Singapore 068877

Quotation No.: Q19-OPS-0909

Dear Sir

We are pleased to submit herein, our quotation for Accident Bus PC7436A - YuTong ZK6119H with SHC2827H on 29/06/2019

S/n	Description	Qty	UOM	Unit Price	Total Price
1	To supply skilled labour and material to putty, grinding and spray paint LHS rear 2nd last panel & wheelarc panel	2	days	\$ 800.00 300	\$ 1,600.00 600
TOTAL					\$ 1,600.00
GST					\$ 112.00
Total					\$ 1,712.00

Terms and Conditions:

Validity: 30 days

Yours faithfully

Shirley Lim

Shirley Lim

Steve (LKK) wil produce 16/7/19, 11.30am
83228813 2 days P/P
Steve chen@lkkcorp.com Roy AL Spj

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com | Email: claims@LexBuild.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer
Signature:
Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012291/Eqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2827H	Veh. Inspected	PC 7436A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004509MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	10/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	YUTONG ZK6119H	c.c	6690	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	LZYTBE66J1019495	Colour	MULTI COLOUR	
Odometer	56363	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	DOUBLE COIN	5 mm	
L/H Front Tyre	11 R22.5	DOUBLE COIN	5 mm	
R/H Rear Tyre	11 R22.5	DOUBLE COIN	5 mm	
L/H Rear Tyre	11 R22.5	DOUBLE COIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2019	Inspection Date	16/07/2019	
Survey held at	LEXBUILD INTERNATIONAL PTE LTD 2 WOODLANDS SECTOR 1 ,#05-12 (WOODLANDS SPECTRUM 1) SINGAPORE 738068			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. A)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7436A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO SUPPLY SKILLED LABOUR AND MATERIAL TO PUTTY, GRINDING AND SPRAY PAINT LHS REAR 2ND LAST PANEL & WHEELARC PANEL.		1,600.00	600.00
			-	-
			1,600.00	600.00
GRAND TOTAL			1,600.00	600.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				600.00

Report Ref No. CS/FCI19012291/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.