

ASS. REC. BY:

REF:

CS3/MSG 19012326/GCF352

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Christina Wong of MSG Date/Time: 11.7.19 12.24p.m

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJV 57C Insured: SJZ 7440 L

at Workshop m/s Hiap LeK Automobile Tel: 64531743

of 160 Sin Ming Drive #05-17

Policy No: 070225895MP Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 6.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 12.7.19 935a.m Person Contacted: An Huat Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJV 57C - MBA /LPC 19012036/19 D.O.A - 06/07/2019
	SJZ 7440 L - MBA /LPC 19012036/19 D.O.A - 06/07/2019

Marinon

PRs
GRL.

REF: MS19

ASSIGNMENT

From: Date: 12.7.19

Estimated Cost

OD (TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 57C
at Workshop n/s Hrap Lek Automobile
of 160 Sin Ming Drive #05-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection. ✓



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJU57C Yt Regn: (18 Aug 2019)

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota AXIO 1.5G c.c. 1496

Colour: white A/C: Insured / Std / Nil / NA

Sp. Reading: 15/27 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: NRE 161 0017873

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12-07-19

Survey held at w/s 12:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/7 w/s has dismantled parts already.

\$ 2000 - \$ 3000

RECEIVED 24 JUL 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. 31

Photos

Others

TOTAL

Report Format :

PRs

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2019 11:23		11 Jul 2019 16:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	PREMCHAND S/O PARSRAM DADLANI, ID: S1259331G [Created by insurer]		
Main Claimant:	GOH SIEW GEK, ID: S1553123A		
Vehicle Reg. No.:	SJV57C	Date of Loss:	06/07/2019 00:00 - :59 [22 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27022589SMP Coverage: 23/12/2018 - 22/12/2019
Vehicle Reg. No. (Insured):	SJZ7440L	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/07/2019]		
Adj Asg. Remarks:	on WP, Liab: dispute (OI NR) TP lawyer disagree- assign LKK. Contact: Hanwei @ 9660 1347		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 17:27
Date Of Accident	06/07/2019 13:20
Exact Location Of Accident	JUNCTION TOH GUAN ROAD AND TOH GUAN ROAD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV57C
Insured/Policyholder	
Name Of Registered Owner	GOH SIEW GEK
NRIC No	S1553123A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98891900
Alternative Phone No	OFFICE-98891900

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019730
Cover Note Number	

Driver

Name of Driver	GOH SIEW GEK
NRIC No	S1553123A
Date Of Birth	19/08/1962
Occupation	INDOOR
Date Of Driving Pass	19/01/1982
Driving Experience	37 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98891900
Fax Number	
Contact Number	OFFICE-98891900
Email Address	NOEMAIL

Address	58 JALAN REMAJA
Postcode	668712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ7440L
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PRASHANT PREMCHAND DADLAHI
NRIC/Passport Number	S9119965C
Contact Number	93899211
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

06/07/19 @ about 1.20pm, I am travelling along Toh Guan Rd on lane ①. The traffic light is red, I stopped my vehicle. Moments later, I felt an impact on my rear portion while my vehicle is stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	3123A
Vehicle No.:	SJV57C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5G A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2NR8621321
Chassis No.:	NRE1610017873
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,891.00
Original Registration Date:	18 Aug 2017
First Registration Date:	18 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$7,891.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Aug 2027
PARF Rebate Amount:	\$5,918.00
COE Expiry Date:	17 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$41,351.00
Total Rebate Amount:	\$47,269.00

The information contained herein is correct as at 14 Jul 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2019 11:23		11 Jul 2019 16:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PREMCHAND S/O PARSRAM DADLANI , ID: S1259331G		
Main Claimant:	GOH SIEW GEK , ID: S1553123A		
Vehicle Reg. No.:	SJV57C	Date of Loss:	06/07/2019 00:00 - :59 [22 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27022589SMP Coverage: 23/12/2018 - 22/12/2019
Vehicle Reg. No. (Insured):	SJZ7440L	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/07/2019]		
Adj Asg. Remarks:	on WP. Liab: dispute (OI NR) TP lawyer disagree- assign LKK. Contact: Hanwei @ 9660 1347		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV57C
[SJZ7440L]
TP
GOH SIEW GEK
Jul 6 2019 12:00AM
[PREMCHAND S/O PARSRAM DADLANI]
Hiap Lek Automobile Trading
















































Upload Documents Upload Photos Compose New Letter















View View in Browser ▼

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
25	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
26	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
27	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
28	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
29	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
30	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
31	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
32	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
33	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
34	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>
35	24/07/19 15:14	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
79	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
80	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
81	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
82	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
83	24/07/19 15:14	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
86	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
87	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
88	24/07/19 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
89	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	24/07/19 15:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/19 11:25	Notice of PRI	 Load PDF	
2	11/07/19 08:01	Disagree on SJE	 Load PDF	
3	11/07/19 08:01	Workshop details	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19012326/GCF3S2
Date: 24/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27022589SMP
Claimant Vehicle No :	SJV57C	Insured Vehicle No :	SJZ7440L
Date of Loss:	06/07/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV57C	Engine No:	2NR8621321
Make & Model:	TOYOTA COROLLA AXIO, 1.5 G (A)	Chassis No:	NRE1610017873
Reg. Date:	18/08/2017 (Man. Year: 2016)	Odometer:	15127 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/07/2019		
Date Inspected:	12/07/2019	Inspected At:	160 SIN MING DRIVE #05-17
Estimated Period of Repair:	4.0 days		Repairer: Hiap Lek Automobile Trading

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2019)

Parts: 143 TOYOTA COROLLA AXIO 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV57C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >