

ASS. REC. BY:

REF: CS/smu 14012328/ R14f3⁵²

Special Instruction:

Surveyor: RASU1

ASSIGNMENT (Office)

From (Person): GNOH PAU LOONG of SMO Date/Time: 12.7.19 10.10A.M

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBP 2861K Insured:

at Workshop m/s Albert Motor Supply Tel: 98452975

of BIK 1008 Bukit Merah Lane 3, #01-10

Policy No: D18MTMC 010006861 Claim No: CMTD1903077

Sum Insured: Excess: \$1500.00

Make of Veh: D.O.A. 21.6.19
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 12.7.19 10.25A.M Person Contacted: Andrew Vehicle: IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|--------------|------------------------------------|
| | FBP 2861K - X |
| 15/7@11:44am | Revert via menmen, Total loss |
| | Submit extensive total loss report |

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBP 2861Kat Workshop m/s ALBERT MOTORof 1008, BUKIT MERANT LN 3 #01-10Insured: SMO

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 30K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBP 2861K Yr Regn: 2016 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA 42F-R1 c.c. 998Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 34RN 32100000 3141Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 120/55R17R: 200/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 21/06/19 D.O.I. 12/07/19Survey held at ALBERTDes. of Damages: Fry / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TOTAL LOSS

MV: 30,000/-

LTA: 4184

NV: 25816/-

RECEIVED 16 JUL 2019

[Signature]
15/7/2019

Date/Time, File Pass to?

1) 16/7 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Survey Fee: 380

Transportation: _____

3 + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.i: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 26 Jun 2019 | | 12 Jul 2019 10:10 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | MOHAMMAD RIYAZ S/O SALIM, ID: S9447405A | | | | | | | | |
| Vehicle Reg. No.: | FBP2861K | Date of Loss: | 21/06/2019 15:00 - :59 [39 Months and 19 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / CMTD1903077 | Policy/Cover Note No.: | D18MTMC01006861 (Comprehensive) | | | | | | |
| | | Excess: | S\$1,500.00 | | | | | | |
| Repairer: | Albert Motor Supply Pte Ltd (Bukit Merah) BLK 1008 BUKIT MERAH LANE 3, #01-10, 159722 Bukit Merah - Tel: 98452975 | | | | | | | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/07/2019] | | | | | | | | |
| Driver/Custodian: | MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY (23 / Male), NRIC: S9617747Z, Tel: +6592481452 Email: NOEMAIL | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • SOMPO_SG (12/07/2019): Cancellation of Assignment: FBP2861K | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 15 Jul 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------|
| Vehicle No | : FBP2861K | Accident Date | : 21/06/2019 |
| Make | : YAMAHA 135LC | Policy No. | : D18MTMC01006861 |
| Assignment Date | : 12/07/2019 | Excess | : S\$1,500.00 |
| Date of Inspection | : 12/07/2019 | Est. Duration of Repair | : 0.00 |
| Inspection At | : ALBERT MOTOR SUPPLY PTE LTD (BUKIT MERAH) BLK 1008 BUKIT MERAH LANE 3, #01-10 SINGAPORE 159722 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s, n/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|------------|
| Repairer's Estimate (Gross) | :S\$ | TOTAL LOSS |
| Revised Amount | :S\$ | TOTAL LOSS |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 0.00 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 30,000.00 |
| COE / PARF Rebate | :S\$ | 4,184.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 25,816.00 |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Gnoh, Pau Loong

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 11 July, 2019 3:22 PM
To: Gnoh, Pau Loong
Subject: RE: Pls advise for pre-accident market value for motorcycle : FBBP2861K (Accident on 21.06.2019) ; Sompot ref : CMTD1903077

Dear Pau Loong,

Our surveyor has review the market value to \$30K – 33K(est) as at June 2019

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompot.com.sg>
Sent: Thursday, 11 July 2019 2:32 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: Pls advise for pre-accident market value for motorcycle : FBBP2861K (Accident on 21.06.2019) ; Sompot ref : CMTD1903077
Importance: High

Dear Denise,

With reference to your quote below, based on the website of Singapore bikes, there is an asking at \$ 38,800.00 (https://www.singaporebikes.com/bikemart/sg/search/used_bikes?keyword=YAMAHA&by_make=23&by_class=3&by_type%5B%5D=6&min_price=0) as screenshot below.

In view of this, may we reconfirm your quote is correct ?

MWHM19083352 / Wah Hong Motors & Credit Pte Ltd - HQ
 ENTRY DATE & TIME: 26/06/2019 17:17
 SUBMITTED BY: Sunny Tee Nam Sang

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 26/06/2019 17:38

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/06/2019 17:17
 Date Of Accident 21/06/2019 15:30
 Exact Location Of Accident ALONG EDL EXPRESSWAY TOWARDS KUALA LUMPUR
 Country/State of Loss MALAYSIA/SELANGOR DARUL EHSAN

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBP2861K
Insured/Policyholder
 Name Of Registered Owner MOHAMMAD RIYAZ S/O SALIM
 NRIC No S9447405A
 Email Address RIYAZ_1112@HOTMAIL.COM
 Mobile Phone No (LOCAL) +65-88181969
 Alternative Phone No Office-88181969

Vehicle Particulars

Manufacturer YAMAHA
 Model 135LC-134CC ES

Exact Purpose for which vehicle was being used at time of accident PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number D18MTMC01006861
 Cover Note Number

Driver

Name of Driver MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY
 NRIC No S9617747Z
 Date Of Birth 20/05/1996
 Occupation INDOOR
 Date Of Driving Pass 23/07/2015
 Driving Experience 3 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92481452

Fax Number
 Contact Number
 EMail Address NOEMAIL
 Address BLOCK 524 WOODLANDS DRIVE 14
 #03-411
 Postcode 730524
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured FRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number NOTAVAILABLE (COMMERCIAL VEHICLE)
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WOODLANDS EAST N.P.C
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan and Police Report for the accident details.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name HASSAN MOHD HASSAN
 Phone Number 90107745
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | NOTAVAILABLE |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|---|--|
| Name | MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY |
| Approximate Age | 23 |
| Injuries Sustain | SERIOUS INJURY |
| Injured person in which vehicle? | FBP2861K |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | YES |
| Address | BLOCK 524 WOODLANDS DRIVE 14 #03-411 |
| Postcode | 730624 |

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police report. Report no: L/20190622/2092

I owner and policy holder MOHAMMAD RYAZ , S9447405A is reporting on the behalf of Second rider MUHAMMAD SHAAIR DANIAL AS HE IS IN ICU unconscious AT KTPH .

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7405A |
| Vehicle Details | |
| Vehicle No.: | FBP2861K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 31 Jul 2019 |
| Vehicle Make: | YAMAHA |
| Vehicle Model: | YZF-R1 |
| Primary Colour: | Red |
| Manufacturing Year: | 2015 |
| Engine No.: | N526E005183 |
| Chassis No.: | JYARN321000003141 |
| Maximum Power Output: | - |
| Open Market Value: | \$20,312.00 |
| Original Registration Date: | 02 Mar 2016 |
| First Registration Date: | 02 Mar 2016 |
| Transfer Count: | 4 |
| Actual ARF Paid: | \$3,047.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 01 Mar 2026 |
| COE Category: | D - Motorcycle |
| COE Period(Years): | 10 |
| QP Paid: | \$6,353.00 |
| COE Rebate Amount: | \$4,184.00 |
| Total Rebate Amount: | \$4,184.00 |

The information contained herein is correct as at 11 Jul 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7405A |
| Vehicle Details | |
| Vehicle No.: | FBP2861K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 12 Jul 2019 |
| Vehicle Make: | YAMAHA |
| Vehicle Model: | YZF-R1 |
| Primary Colour: | Red |
| Manufacturing Year: | 2015 |
| Engine No.: | N526E005183 |
| Chassis No.: | JYARN321000003141 |
| Maximum Power Output: | - |
| Open Market Value: | \$20,312.00 |
| Original Registration Date: | 02 Mar 2016 ✓ |
| First Registration Date: | 02 Mar 2016 |
| Transfer Count: | 4 |
| Actual ARF Paid: | \$3,047.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 01 Mar 2026 |
| COE Category: | D - Motorcycle |
| COE Period(Years): | 10 |
| QP Paid: | \$6,353.00 |
| COE Rebate Amount: | \$4,214.00 |
| Total Rebate Amount: | \$4,214.00 |

The information contained herein is correct as at 12 Jul 2019

OK


**SINGAPORE
POLICE FORCE**


L/20190622/2092

1 of 2

POLICE REPORT (NP299)

Report No. L/20190622/2092

Police Station Of Origin
Woodlands East N.P.C
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

| | | |
|---|---|--------------------------|
| Date/Time Report Made 22/06/2019 22:52 | Vide Report No. | Station Diary No. 167 |
| Name Of Informant HASSAN MOHD HASSAN | Address APT BLK 101 WOODLANDS STREET 13 #06-36 SINGAPORE 739101 | |
| ID Type / ID No NRIC NO / S9533333H | Contact No. Home/Office | Mobile 90107745 |
| Nationality SINGAPORE CITIZEN | Email Address | |
| Occupation TECHNICIAN | Sex Male | Age 23 |
| Institution/School Name | Date of Birth 18/09/1995 | Race Banjarese-Arab |
| Date/Time Of Incident 21/06/2019 15:30 | Location Of Incident EDL EXPRESSWAY BEFORE EXIT E14, TOWARDS KUALA LUMPUR MALAYSIA | |

Brief details.

I am making this report for my friend namely Muhammad Shaqir Danial bin Abdullah Sany (NRIC: S9617747Z) as Shaqir is currently warded at Khoo Teck Phuat Hospital ICU in an unconscious state due to a motorcycle accident. Shaqir was riding a motorcycle bearing FBP2851K.
On 21/06/2019 at about 1530hrs, Shaqir and I was riding our motorcycles along EDL expressway towards Kuala Lumpur. Shaqir was riding along lane 1 while I was riding along lane 3. At that point of


Signature Of Officer Recording The Report

 L / SC2 MOHD HAFIZ FACHRUDIN BIN MOHD
SHAMIEE

 Signature Of Interpreter:
Not applicable

 Officer In-Charge Of Case:
L / Woodlands Police Divisional Investigation Branch,
Insp RAJPAL SINGH KANG
Contact No: 63647559




Authentication Stamp



Signature Of Informant:

 Date/Time:
22/06/2019 22:52

Classification Of Case:

| | | | | |
|---|-----------------------------------|--|-----------------|----------------------------|
|  | SINGAPORE POLICE FORCE |  | L/20190622/2092 | 2 of 2 |
| POLICE REPORT (NP259) | | CONTINUATION OF REPORT | | Report No. L/20190622/2092 |
| <p>time, our distance was about 500 meter apart and was riding about 100km/h. While I was riding, I witnessed a 4-wheeler lorry changing lane abruptly from lane 2 to lane 1. Shaqir tried to swerve his motorcycle to avoid collision however lost control of his vehicle. Due to the impact, Shaqir suffered major head injury, broken wrist and abrasions. I was not able to get the lorry plate number as the lorry did not stop to assist.</p> <p>I am making this report for Shaqir's insurance purposes.</p> | | | | |
| Signature Of Officer Recording The Report: L / SC2 MOHD HAFIZ FACHRUDIN BIN MOHD SHAIIMEE | | Signature Of Informant: | | |
| Signature Of Interpreter: Not applicable | | Date/Time: 22/06/2019 22 52 | | |
| Officer In-Charge Of Case: L / Woodlands Police Divisional Investigation Branch / Insp RAJPAL SINGH KANG Contact No : 63647559 | | Classification Of Case: | | |
| Authentication Stamp  | | | | |

Identification Card - Policyholder

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9447405A



Name

MOHAMMAD RIYAZ S/O SALIM

Race

INDIAN

Date of birth

11-12-1994

Sex

M

S9447405A

Country of birth

SINGAPORE

4409479



NRIC No. S9447405A


Date of issue

26-05-2009


Address

APT BLK 406 BEDOK NORTH AVENUE 3
#06-191
SINGAPORE 460406


Identification Card - driver's IC front




Identification Card - driver's IC back



Driving License - driver's DL front



Driving License - driver's DL back



Certificate of Insurance

1/ 1

18/9/08/M1/SP

**SOMPO**

Sompo Insurance Singapore Pte. Ltd.
 50 Raffles Place, #04-01/02 Singapore 048623
 Tel: 6451 6555 | Fax: 6221 2002 | Web/MR: www.sompo.com.sg
 Co. Reg. No.: 100405420E | GST Reg. No.: 1000005108

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 182)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1950
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTMC01008861
Insured : MOHAMMAD RIYAZ S/O SALIM
Motor Vehicle (Regn No.) : FBP2851K
Cover : Comprehensive
Policy Commencement Date : 12 MARCH 2019 00:00
Policy Expiry Date : 30 OCTOBER 2019 23:59
Maximum Liability (Section 1) : Market value at time of loss
Excess* : \$1500 - Section 1
Named Driver 1 : MOHAMMAD RIYAZ S/O SALIM
Named Driver 2 : MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY
HIRE PURCHASE OWNER : YEW HENG CREDIT ENTERPRISE PTE LTD

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

MOHAMMAD RIYAZ S/O SALIM, MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purposes and

- (a) by the Insured in person in connection with his business or profession or
- (b) in connection with the Insured's business or profession

The Policy does not cover

- (i) Use for hire or reward
- (ii) Use for racing pacemaking, reliability trial or speed-testing
- (iii) Use for the carriage of goods (other than samples) in connection with any trade or business
- (iv) Use for any purpose in connection with the Motor Trade

Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6451 6555.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 182) and Part IV of the Transport Act, 1987 (Malaysia); and (2) the policy terms, conditions and exclusions of the Motorcycle Policy (TRC/MCY-LITAC.02)

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 31 OCTOBER 2018 10:18

IMPORTANT NOTICE


- Keep the Certificate in your Motor Vehicle;
- Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 182), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- On the sale of the Motor Vehicle or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the Insurer's company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 182);
- This Policy will cease to be valid once the Motor Vehicle has been sold to another person. The Policy is not transferable to the new owner of the Motor Vehicle.

Intermediary Code & Name : 11E07001 & ENSURE PTE. LTD. (MOTORCYCLE) CI Code: MY3 30LDMH2P4BMDMKA

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Status |
|------|-------------|---------------|--|--|--|---------------------------|
| Main | 26 Jun 2019 | | 12 Jul 2019 10:10 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | Pending for Survey Report |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | | |
|-------------------|---|------------------------|--|----------------------|
| Insured: | MOHAMMAD RIYAZ S/O SALIM, ID: S9447405A | | | [Created by Insurer] |
| Vehicle Reg. No.: | FBP2861K | Date of Loss: | 21/06/2019 15:00 - :59 [39 Months and 19 Days From LTA Reg Date (Man Yr)] | |
| Claim Type: | OD / CMTD1903077 | Policy/Cover Note No.: | D18MTMC01006861 (Comprehensive) | |
| | | Excess: | S\$1,500.00 | |
| Repairer: | Albert Motor Supply Pte Ltd (Bukit Merah) BLK 1008 BUKIT MERAH LANE 3, #01-10, 159722 Bukit Merah - Tel: 98452975 | | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217] | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/07/2019] | | | |
| Driver/Custodian: | MUHAMMAD SHAQIR DANIAL BIN ABDULLAH SANY (23 / Male) , NRIC: S9617747Z, Tel: +6592481452 Email: NOEMAIL | | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- SOMPO_SG (15/07/2019): Alert - Adj Mandate Revoked - FBP2861K - Claim Handler: GNOH PAU LOONG
- SOMPO_SG (12/07/2019): Cancellation of Assignment: FBP2861K

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*FBP2861K (CMTD1903077)
















































OD

Jun 21 2019 3:00PM

[MOHAMMAD RIYAZ S/O SALIM]

Albert Motor Supply Pte Ltd

| | | | | |
|---|-----------------|---|---|-------------------------------------|
| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 26/06/19 17:38 | Accident Statement | 1 | Load HTM |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 15/07/19 11:02 | Adjuster Immediate Advice | 1 | Load HTM |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 26/06/19 17:32 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG |
| 2 | 26/06/19 17:32 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG |
| 3 | 26/06/19 17:32 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG |
| 4 | 26/06/19 17:32 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG |
| 5 | 26/06/19 17:32 | Accident Photo [Linked Accident Report Documents] | 1 | Load JPG |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 2 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 3 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 4 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 5 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 6 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 7 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 8 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 9 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 10 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 11 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 12 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 13 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 14 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 15 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 16 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 17 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 18 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 19 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 20 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 21 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 22 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 23 | 16/07/19 10:08 | General View | 1 | Load JPG |
| 24 | 16/07/19 10:08 | General View | 1 | Load JPG |

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|--|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print |
| 25 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 16/07/19 10:08 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |


| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|--------------|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print |
| 73 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 74 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 75 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 76 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 77 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 78 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 79 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 80 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 81 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 82 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 83 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 84 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 85 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 86 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 87 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 88 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 89 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 90 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 91 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 92 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 93 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 94 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 95 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 96 | 16/07/19 10:08 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 97 | 16/07/19 10:09 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 98 | 16/07/19 10:09 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 99 | 16/07/19 10:09 | General View | Load JPG | <input checked="" type="checkbox"/> |









| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|----------------|---|--------------|-------------------------------------|
| No | Finalized On | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 08/07/19 14:15 | EMAIL ENSURE TO PROVIDE CURRENT LOCATION & WS OF BIKE | Load PDF | |
| 2 | 11/07/19 09:07 | LKK MV | Load PDF | |
| 3 | 11/07/19 15:26 | LKK revise MV | Load PDF | |
| 4 | 12/07/19 10:08 | PRI - LKK | Load HTM | |

Linked Accident Report Documents

| Assessment Reports | | | View | View In Browser ▼ | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|-----------|-------------------|--------------|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print | | |
| 1 | 26/06/19 17:38 | Accident Statement | Load HTM | | | |
| 2 | 26/06/19 17:53 | Addendum Sheet | Load TIF | | | |
| 3 | 26/06/19 17:55 | Accident Statement Addm. #1 | Load HTM | | | |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|----------------|---------------------------------------|--------------|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 26/06/19 17:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 26/06/19 17:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 26/06/19 17:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 26/06/19 17:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|--|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print |
| 5 | 26/06/19 17:32 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|----------------|---|--|-------------------------------------|
| No | Finalized On | Wah Hong Motors & Credit Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 26/06/19 17:32 | Sketch Plan |  Load TIF | |
| 2 | 26/06/19 17:32 | Sketch Plan #2 |  Load TIF | |
| 3 | 26/06/19 17:35 | Identification Card - Policyholder |  Load TIF | |
| 4 | 26/06/19 17:35 | Identification Card - driver's IC front |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 26/06/19 17:35 | Identification Card - driver's IC back |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 26/06/19 17:35 | Driving License - driver's DL front |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 26/06/19 17:35 | Driving License - driver's DL back |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 26/06/19 17:35 | Certificate of Insurance |  Load TIF | |

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19012328/R1TF3S2

Date: 17/07/2019

REFERENCE

| | | | | |
|-------------------|--------------------------|------------------|-----------------|-----------------------|
| Insured/Claimant: | MOHAMMAD RIYAZ S/O SALIM | Policy No: | D18MTMC01006861 | |
| Date of Loss: | 21/06/2019 | Nature of Claim: | OD | Claim No: CMTD1903077 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | FBP2861K | | |
| Make & Model: | YAMAHA YZF-R1, 998cc (M) | Engine No: | N526E005183 |
| Reg. Date: | 02/03/2016 (Man. Year: 2015) | Chassis No: | JYARN321000003141 |
| Colour: | Multi-colour | Odometer: | 0 km |
| Engine Capacity: | 998 cc | | |
| Market Value/New Car Price: | S\$30,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 120/55R17 | Rear Tyre Size: | 200/55R17 |
| Front Left Side: | Pirelli 4 mm | Rear Left Side: | Pirelli 4 mm |
| Front Right Side: | 0 mm | Rear Right Side: | 0 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|------------------|-------------|-------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 0.00 | 0.00 | 0.00 | |
| - Excess (S\$) | 1,500.00 | 1,500.00 | 0.00 | 0.00 |
| Nett Amount (S\$) | -1,500.00 | -1,500.00 | 0.00 | 0.00 |

INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Albert Motor Supply Pte Ltd (Bukit Merah)
BLK 1008 BUKIT MERAH LANE 3, #01-10
Singapore 159722

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

| | |
|----------------------------|-------------|
| Market Value : | \$30,000.00 |
| OMV : | \$20,312.00 |
| PARF Rebate (1) : | \$0.00 |
| Quota Premium Paid : | \$6,353.00 |
| COE Rebate (2) : | \$4,184.00 |
| Total Rebate (1) + (2) = : | \$4,184.00 |

The total amount incurred will be Market Value \$30,000.00 minus Total Rebate \$4,184.00 = \$25,816.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 17 Jul 2019) | |
| Parts: | N/A | YAMAHA YZF-R1 998cc (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for FBP2861K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >