

22/03/2002

ASS. REC. BY:

REF: CS³/SMO 19012346 / R/C F307

Special Instruction:

Surveyor Rasul ASSIGNMENT (Office)From (Person): Thulma Chod of SMO Date/Time: 12.7.19 13.32p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 38985 Insured: YP 6377Tat Workshop m/s HO Leong Auto Tel: 96654617of 27-A Jurong Port road #01-30Policy No: D18MTPCV6 001573 Claim No: CMTD 1903345

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.4.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12.7.19 1.40p.m Person Contacted: HO Leong H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBC 38985 - X</u>
	<u>YP 6377T - X</u>
<u>22/7/19</u>	<u>@ 1149am HO Leong said no estimate</u>
	<u>Dismantle: 19/7/2019</u>
	<u>After repair: 24/7/2019</u>

ASSIGNMENT

From:

Date:

Veh No:

GBC 38985

Yr Regn:

2012 / APR

Estimated Cost:

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

GBC 38985

Make:

TOYOTA HILUX M

c.c

2982

at Workshop m/s

Ho LEONH AUTO

Colour

GRAY

A/C:

Insured / Std / NI / NA

of

27A, JURNAN PORT R # 01-30

Sp. Reading

380064

T/Radio: Insured / Std / NI / NA

Insured:

SMU

Eng/No:

Policy No.

C/No:

JTPHT02P900V84492

Claims No.

Gen. Cond: Good / ~~Fail~~ / Poor / Burnt

Sum Insured:

Excess:

Steering: ~~Inorder~~ / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ~~Inorder~~ / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

195R15C

R:

Remark: The veh had commenced its

repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / ~~MIC~~ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

06/04/19

D.O.A.

19/07/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Ho LEONH AUTO

CA / REV / RFP. / 24 HRS

Des. of Damages: ~~FR~~ / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range + Days

Repair Range - 2,500-3,000

Repair Days - 4 days

5/9/2019

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

4

1)



: Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100

60

60

11

231

Report Format :

PRR

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jul 2019		12 Jul 2019 13:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM SIANG HUAT PTE LTD, Co. Reg. No.: 199803003N		
Main Claimant:	JAPAN PACK SYSTEM PTE LTD, Co. Reg. No.: 199803003N		
Vehicle Reg. No.:	GBC3898S	Date of Loss:	06/04/2019 11:00 - :59
Claim Type:	TP / CMTD1903345	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)
Vehicle Reg. No. (Insured):	YP6377T	Policy No. (Claimant):	
		Excess:	
Repairer:	Ho Leong Auto Services (HQ) 27-A Jurong Port Road, #01-30 JTC Industrial Service Centre, 619101 Jurong Island - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/07/2019]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	590G
Vehicle Details	
Vehicle No.:	GBC3898S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	1KD2123841
Chassis No.:	JTFHT02P900084492
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	18 Apr 2012
First Registration Date:	18 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,801.00
COE Rebate Amount:	\$13,542.00
Total Rebate Amount:	\$13,542.00

The information contained herein is correct as at 29 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2019 13:50
Date Of Accident	06/04/2019 11:35
Exact Location Of Accident	ALONG ORCHARD LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC3898S
Insured/Policyholder	
Name Of Registered Owner	JAPAN PACK SYSTEM PTE LTD
Co Reg No	199001590G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPCVE003178
Cover Note Number	01/09/2018-17/10/2019

Driver

Name of Driver	KOW SEOH HENG
NRIC No	
Date Of Birth	
Occupation	OUTDOOR
Date Of Driving Pass	
Driving Experience	EARS AND MONTHS
Gender	
Mobile Number	(LOCAL) +
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : KENRESTEE

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

SEMBANWANG NPC

Police Station Address

ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP6377T

Vehicle Make/Model/Colour B

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report no : T/20190406 / 2156

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

	- Reporting Only
	- Claim OD
	- Claim TP
✓	- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time

[Signature]

Driver's Signature
(if driver not the policyholder)
Date & Time

[Signature]

Reporting Centre Personnel's Signature
Name: Kenneth
Nric/Fin No.

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GSA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: Kenneth
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190406/2156

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20190406/2156

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/04/2019 21:54	Vide Report No.:	Station Diary No.: 58
Informant's Particulars		
Name of Informant: KOW SEOH HENG	Address: ADT RI K SINGAPORE	
ID Type / ID No. NRIC NO /	Contact No.:	
	Home/Office:	Mobile:
	Email:	
Age:	Date of Birth:	Type of Informant: Driver
	Language: English	Institution / School Name:
Occupation:	Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 06/04/2019 11:35	Type of Location: Straight Road
Location: Along Road 1 ORCHARD LINK				
Cineleisure Loading and Unloading bay.				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBC3898S	Van	TOYOTA	HIACE	Grey	Slightly Damaged	1
YP6377T	Lorry					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999



T/20190406/2156

2 of 3

Report No. T/20190406/2156

CONTINUATION OF REPORT

Driver			
Name	KOW SEOH HENG		ID No.
Related Vehicle	GBC3898S (Van)		Contact No.
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date
Date Treatment	NIL		Class: 3 Date of Expiry: NIL
No. of Days granted Medical Leave	NIL	Date Discharge	NIL
		Degree of Injury	NIL

Brief Details.

On 06/04/2019 at about 1135 hrs, I had parked my van at the loading and unloading bay of Cineleisure and went for delivery. My son was inside the vehicle.

On the same day at about 1140 hrs, I came back to my van, my son informed me that the damage to my vehicle and a chief working nearby informed me that a lorry, YP6377T (Munchy's brand design)(Lim Siang Huat PTe Ltd) had reversed and hit onto the front of my vehicle causing a dent on the emblem area.

I had contacted my company, Mr Vincent, Assistant Supervisor, Hp: 81005032 and he ask me to lodge a report.



**SINGAPORE
POLICE FORCE**



T/20190406/2156

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3



Report No. T/20190406/2156

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt LIM FEI YANG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 06/04/2019 21:54
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt TAN JEOK LENG Contact No.: 65476144	Classification Of Case: 
Authentication Stamp NP168	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jul 2019		12 Jul 2019 13:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM SIANG HUAT PTE LTD, Co. Reg. No.: 199803003N								
Main Claimant:	JAPAN PACK SYSTEM PTE LTD, Co. Reg. No.: 199803003N								
Vehicle Reg. No.:	GBC3898S	Date of Loss:	06/04/2019 11:00 - :59 [83 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903345	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP6377T	Policy No. (Claimant):							
		Excess:							
Repairer:	Ho Leong Auto Services (HQ) 27-A Jurong Port Road, #01-30 JTC Industrial Service Centre, 619101 Jurong Island - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC3898S (CMTD1903345)
[YP6377T]










































TP


JAPAN PACK SYSTEM PTE LTD

Apr 6 2019 11:00AM

[LIM SIANG HUAT PTE LTD]

Ho Leong Auto Services

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
2	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
3	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
4	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
5	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
6	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
7	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
8	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
9	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
10	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
11	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
12	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
13	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
14	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
15	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
16	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
17	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
18	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
19	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
20	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
21	29/07/19 10:15	General View								Load JPG	<input checked="" type="checkbox"/>	
22	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
23	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
24	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
25	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
26	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
27	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
28	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
29	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
30	29/07/19 10:16	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
31	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
32	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
33	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
34	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
35	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
36	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
37	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
38	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
39	29/07/19 10:18	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)								Thumbnail	Print	
1	12/07/19 10:52	Third Party E-filed GIA report & Lawyer Letter								Load PDF		
2	12/07/19 13:29	TP Letter								Load PDF		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
3	12/07/19 13:31	PRI - LKK (No Consensus)		 Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19012346/R1CF3E2

Date: 16/09/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001573
Claimant Vehicle No :	GBC3898S	Insured Vehicle No :	YP6377T
Date of Loss:	06/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1903345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC3898S		
Make & Model:	TOYOTA HIACE, 2.0 (M)	Engine No:	1KD2123841
Reg. Date:	18/04/2012 (Man. Year: 2011)	Chassis No:	JTFHT02P900084492
Colour:	Grey	Odometer:	380064 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/07/2019	
Date Inspected:	19/07/2019 Inspected At:	Ho Leong Auto Services (HQ) 27-A Jurong Port Road, #01-30 JTC Industrial Service Centre Singapore 619101
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Sep 2019)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC3898S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >