

INS. CASE OWNER:

cc 4, ALG 190 12364, Kea39

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

12/3/19

Date / Time:

Registered in Merimen:

12/3/19

by
ALG

Pre-assign / CCU / FTE

SLK 38810



Insured Vehicle No.:

Claim No.:

Name of Insured:

Ng Tiong Heng

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

5/1/2019

Place of Accident:

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: ☒ YES / NO)OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability: %

Final ? Yes / No

STV 4330L



INSRS:

WSP:

Tel:

Liability:

RMKS:

ngs trading



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STV 4330L, X; SLK 38810 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 23-07-19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

96 S\$2,900

(4 days)

Reduction:

97 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 19-8-19

Confirm with: EVELYN

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost:

S\$2,900.00

NO TRADING FOR 10 DAYS

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 420.00

(\$ 70 x 6 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9320

Total:

S\$3,321.45

Global Sum S\$:

FINAL PAYMENT

Date/Time: 19-08-19

Confirm with: EVELYN

Email ☐Call ☐

Payee 1:

S\$3,321.45

Name 1:

NGS TRADING

Payee 2: (Bank/IFNA)

S\$

Name 2:

Payee 3: (Bank/IFNA)

S\$

Name 3:

μ

F

No. : QT-09329

Your Ref. :
Our Ref : QT-09329/SJV4330
C. C. :
Date : 11-07-2019
Page : 1 of 2

FAX 312/261-1111

Description	Qty	U/ Price	Amount
<p>ACCIDENT ON 05/07/2019@21:00HRS ALONG SEGAR RD</p> <p>INVOLVING SJV4330L & SLK3881D,</p> <p>CLAIMS AGAINST SLK3881D (AIG)</p>			
<p>REPLACEMENT PARTS: HD STREAM</p>			
HEADLAMP RH	1	748.70	748.70
FRT FENDER RH	1	519.30	519.30
FRT FENDER LINING RH	1	105.70	105.70
FRT BUMPER	1	635.60	635.60
FRT HEADLAMP RETAINER RH	1	43.00	43.00
SIDE RETAINER RH	1	28.70	28.70
RAD GRILLE BASE	1	240.60	240.60
RAD GRILLE CHROME	1	280.80	280.80
REINFORCEMENT	1	219.00	219.00
SUPPORT PANEL	1	496.00	496.00
BONNET	1	768.00	768.00
FENDER MARK RH	1	52.50	52.50
BUMPER LOWER COVER RH	1	68.40	68.40
SubTotal			4,206.30
Less 20%	1	-841.26	-841.26
FENDER SHIELD CLIPS 10PCS	10	3.50	35.00
SPORTS RIM	1	480.00	480.00
REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENT, RESHAPED/REALIGN DENTED PANEL. REPLACE DAMAGED PARTS. REFIT INTO POSITION.	1	1,000.00	1,000.00
SPRAY PAINTING	1	600.00	600.00
CHECK WIRING/LIGHT PROPER FUNCTION	1	40.00	40.00

Alignment \$80

60 ✓

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: everlyngstrading@gmail.com
Reg No.: 51106300L

No. : OT-09329

Your Ref. :
Our Ref : QT-09329/SJV4330
C. C. :
Date : 11-07-2019
Page : 1 of 2

FAX :

Not Notarized
6/1 Day 8?
Preserving After Prisms

Alignment rt \$80 60 ✓

- Notification Of Accident For Our Insured Veh SJV4330L

From: Fan, Winnie-LW

To:

Cc:

Sent: 7/12/2019 9:01:44 AM

Attachments:  SLK3881D LTA Search.pdf  SJV4330L SAS Report.pdf

Hi LKK,

Kindly assist to survey, file is already created in Merimen.

Workshop detail:

EVELYN NG (HP 9695 5547)
NGS TRADING
Blk 10 Ang Mo Kio Ind. Pk 2a
#02-01 AMK AutoPoint
Singapore 568047

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

q. 37m @ 12/7/19
vehicle in
person @ Evelyn
Sue O'Connell

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 23 July 2019 10:31 AM
To: EVELYNNNGSTRADING@GMAIL.COM
Subject: Accident Involving SJV 4330L & SLK 3881D on 05/07/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

Accident Involving SJV 4330L & SLK 3881D on 05/07/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAUTO)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Monday, 29 July 2019 11:03 AM
To: Asher Sng (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SLK 3881D (OI) AND SJV 4330L (TP) ON 05/07/2019.

Follow Up Flag: Follow up
Flag Status: Completed

Hi Asher,

You may have mandate up to \$3,327.45 subject to supporting docs.

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Monday, 29 July 2019 10:47 AM
To: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Subject: [EXTERNAL] ACCIDENT INVOLVING SLK 3881D (OI) AND SJV 4330L (TP) ON 05/07/2019.

This message is from an external sender; be cautious with links and attachments.

Your Ref: 4810865621SG

Hi Sir,

We refer to the above matter.

ACCIDENT INVOLVING SLK 3881D (OI) AND SJV 4330L (TP) ON 05/07/2019.

Mandate summary and relevant document submitted in merimen.

For your approval please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 26 July 2019 3:34 PM
To: Evelyn Ng; Asher Sng (LKKAUTO)
Cc: Admin A; CS A Team
Subject: RE: LOD For Our Insured Veh SJV4330L *** LKK REF: CC4/AIG19012364/Kea3
Attachments: SLK3881D LTA Search.pdf; SJV4330L SAS Report.pdf; SJV4330L CI.pdf; SJV4330L DRIVER CONTRACT.pdf

Follow Up Flag: Follow up
Flag Status: Completed

From: Evelyn Ng <ngstrading94@gmail.com>
Sent: Friday, 26 July, 2019 2:56 PM
To: Admin A <admin-a@lkkauto.com>
Subject: LOD For Our Insured Veh SJV4330L

Dear Sir/Madam

**RE: ACCIDENT INVOLVING VEHICLE NO SJV4330L & SLK3881D
ALONG SEGAR RD**

We understand that you are the insurer of SLK3881D vehicle.

I/We wish to inform you that my/our vehicle SJV4330L have been completed repairs to my/our satisfaction by M/s NGS TRADING. I/We therefore propose to claim from you as follow:-

1. Cost of Repair	S\$ 2900.00
2. LTA Search	S\$ 7.45
3. Rental- <u>6days@\$70.00</u>	<u>S\$ 420.00</u> (Include Sunday & Survey)
TOTAL	<u>S\$ 3327.45</u>

A copy each of the following supporting documents is attached:-

- Authorise to Act
- Our bill M/s NGS Trading
- Cert of insurance
- SJV4330L SAS Report
- SLK3881D LTA Search fee
- Driver Contract

Please let us have your reply soonest possible.

Thank you.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 23 July 2019 10:28 AM
To: JNY6500@GMAIL.COM
Subject: ACCIDENT INVOLVING SLK 3881D AND SJV 4330L ON 05/07/2019

Our Ref: CC4/AIG19012364/Kea3

23 JULY 2019

NG TIONG HENG

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 3881D AND SJV 4330L ON 05/07/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

(Direct Third Party Claim)

I/We, Grace On Wheels Automobile Pte Ltd ("the third party claimant"), owner of SJV4330L (vehicle no.) hereby authorize NGS Trading ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SJV4330L that was damaged pursuant to the accident which occurred on 05/07/2019 (date) along Segar Rd (location) involving vehicle no./s SLK3881D ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop "NGS Trading".

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s concerned.

Dated this 8 (day) of 7 (month) 20 19 (year).



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop" (with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **NGS TRADING** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,900.00** (Repair Cost), **S\$420.00** (Loss of Use/~~Rental~~), **S\$7.45** (Disbursement) for vehicle no. **SJV 4330L** that was damaged pursuant to the accident which occurred on **05/07/2019** (date) along **SEGAR RD** (location) involving vehicle no/s **SLK 3881D**.

This is pursuant to the inspection conducted on **12/07/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRACE ON WHEELS AUTOMOBILE PTE LTD** ("the third party claimant") of vehicle no. **SJV 4330L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJV 4330L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of Aug (month) 2019 (year)

 **KSC**
KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

NGS TRADING

Bik 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynnngstrading@gmail.com
Reg No.: 51106300L

INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIMS DEPT
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL : 6419 3000

FAX :

No. : **IV201907-255**
Veh No : SJV4330L HD STREAM
Mileage :
Your Ref : QT-09329/SJV4330L
Our Ref :
Date : 26-07-2019
Page : 1 of 1

Description

Amount
S\$

ACCIDENT ON 05/07/19@21:00HRS ALONG SEGAR RD
INVOLVING SJV4330L & SLK3881D
CLAIMS AGAINST SLK3881D

LUMP SUM REPAIR

2,900.00

SURVEY BY : LKK KENNETH

SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED ONLY

Net Total **2,900.00**

Notes :

1. All cheques should be crossed and made payable to **NGS TRADING**
2. Goods sold are neither returnable nor refundable.



Authorised Signature

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Jul 2019 / 14:50:09

Receipt Date/Time : 11 Jul 2019 / 14:50:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190711-001865

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLK3881D As at 05 Jul 2019/21:00:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLK3881D Enquiry Fee 20190711144850724168	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx1986		Credit Card: Visa /MasterCard	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019 16:27		12 Jul 2019 15:14 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG TIONG HENG, ID: S2578494D, Tel: +6583226338								
Main Claimant:	GRACE ON WHEELS AUTOMOBILE PTE LTD, Co. Reg. No.: 201833077C								
Vehicle Reg. No.:	SJV4330L	Date of Loss:	05/07/2019 09:00 - :59 [113 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4810865621SG	Policy/Cover Note No.:	2100496261 (Comprehensive) Coverage: 30/12/2018 - 29/12/2019						
Vehicle Reg. No. (Insured):	SLK3881D	Policy No. (Claimant):	5105872512						
		Excess:							
Repairer:	NGS TRADING (HQ) Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64815727								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/07/2019]								
Driver/Custodian (Insured):	HO TENG JONG (53 / Female), NRIC: S17660791, Tel: +6590059193 Email: jny6500@gmail.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV4330L (4810865621SG)
[SLK3881D]

TP










GRACE ON WHEELS AUTOMOBILE PTE LTD

Jul 5 2019 9:00AM














[NG TIONG HENG]

NGS TRADING

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	12/07/19 08:55	Video - Accident												1	Load MOV			
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	29/07/19 10:42	Adjuster Immediate Advice												1	Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Chew Goon Motor (AMK)												Thumbnail		Print		
1	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
2	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
3	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
4	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
5	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
6	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
7	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
8	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
9	06/07/19 11:40	Accident Photo [Linked Accident Report Documents]												1	Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	29/07/19 10:35	General View												1	Load JPG	<input checked="" type="checkbox"/>		
2	29/07/19 10:36	General View												2	Load JPG	<input checked="" type="checkbox"/>		
3	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
4	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
5	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
6	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
7	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
8	29/07/19 10:36	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>		
9	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
10	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
11	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
12	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
13	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
14	29/07/19 10:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
15	29/07/19 10:36	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 10:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 10:36	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 10:36	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 10:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 10:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 10:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	06/07/19 11:54	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/19 11:54	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/19 11:54	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/19 11:54	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/19 15:32	OI GIA REPORT	 Load PDF	
2	17/07/19 11:48	TP ESTIMATE - MARKED	 Load PDF	
3	23/07/19 10:28	LETTER TO OI	 Load PDF	
4	29/07/19 10:42	LTA PARF COE Rebate Details	 Load PDF	
5	29/07/19 10:48	LTA SEARCH	 Load PDF	
6	02/08/19 09:14	MANDATE APPROVAL	 Load PDF	
7	02/09/19 08:31	WORKSHOP INVOICE	 Load PDF	
8	02/09/19 08:31	AUTHORISATION TO ACT FORM	 Load PDF	
9	02/09/19 08:31	Release Voucher	 Load PDF	
10	02/09/19 08:31	LOD	 Load PDF	

Linked Accident Report Documents

Photos/Images			View	View in Browser
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	06/07/19 11:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	06/07/19 11:54	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/19 11:54	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/19 11:54	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/19 11:54	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK3881D (Insd veh)	Model:	HONDA STREAM 1.8 L (A)
	SJV4330L (TP veh)		
Date of Accident:	05/07/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,600.04
Final Repair Cost	:	\$	2,900.00
Loss of Use	:	\$	420.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,327.45

6.00 days at \$70.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	NGS TRADING	:	\$ 3,327.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

02 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012364/KEA3Q2

Date: 02/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496261
Claimant Vehicle No :	SJV4330L	Insured Vehicle No :	SLK3881D
Date of Loss:	05/07/2019	Nature of Claim:	TP
		Claim No:	4810865621SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV4330L	Engine No:	R18A13801127
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68609S201133
Reg. Date:	26/01/2010 (Man. Year: 2008)	Odometer:	126115 km
Colour:	Metallic Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,880.04	2,556.20	1,323.84	34.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,180.00	540.00	31.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,600.04	3,736.20	1,863.84	33.28
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	5,600.04	2,900.00	2,700.04	48.21
+ Loss of Use (6.0 x S\$70.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,327.45		

INSPECTION

Date of Assignment:	12/07/2019	
Date Inspected:	12/07/2019 Inspected At:	NGS TRADING (HQ) Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Broken	748.70 FL	*748.70 FL
2	1		*FRT FENDER RH	Bent	519.30 FL	*519.30 FL
3	1		*FRT FENDER LINING RH	Distorted	105.70 FL	*105.70 FL
4	1		*FRT BUMPER	Buckled	635.60 FL	*635.60 FL
5	1		*FRT HEADLAMP RETAINER RH	Cracked	43.00 FL	*43.00 FL
6	1		*SIDE RETAINER RH	Cracked	28.70 FL	*28.70 FL
7	1		*RAD GRILLE BASE	Serviceable	240.60 FL	*- FL
8	1		*RAD GRILLE CHROME	Serviceable	280.80 FL	*- FL
9	1		*REINFORCEMENT	Repair	219.00 FL	*- FL
10	1		*SUPPORT PANEL	Repair	496.00 FL	*- FL
11	1		*BONNET	Bent	768.00 FL	*768.00 FL
12	1		*FENDER MARK RH	Necessary	52.50 FL	*52.50 FL
13	1		*BUMPER LOWER COVER RH	Serviceable	68.40 FL	*- FL
14	1		*SPORTS RIM	Dented	480.00 FS	*200.00 FS
15	10		*FENDER SHIELD CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) 4,721.30 3,136.50

- List Item Discount on L Items 20.00/20.00% (\$\$) 841.26 580.30

Total Parts (\$\$) 3,880.04 2,556.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENT, RESHAPED/REALIGN DENTED PANEL .REPLACE DAMAGED PARTS.REFIT INTO POSITION	New	1,000.00	500.00
2	SPRAY PAINTING	New	600.00	600.00
3	CHECK WIRING /LIGHT PROPER FUNCTION	New	40.00	20.00
4	ALIGNMENT	New	80.00	60.00
Gross Labour Cost (S\$)			1,720.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >