

ASS. REC. BY:

REF:

C88/ANG190/2366/GCD37

Special Instruction:

ole

Survey: QUO Qianey

ASSIGNMENT (Office)

From (Person): Funwinne

of

ANG

Date/Time:

12/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 99192

Insured:

SLC 7396D

at Workshop in/s

Carsmith Private

Tel:

90910000

of

13 Kaki Bukit Road 4 #01-20

Policy No:

1900007137

Claim No:

286010572586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/7/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11.12am @ 12/7/19

Person Contacted:

Alex

Vehicle IN/OUT

Date/Time	Action/Instruction
	Isample (X)
	SLS 99192-X
	SLC 7396D-X
	Dismantle: 15/7/2019.
	After repair: 14/8/2019

Surveys

PKS
Cal

REF:

ALG

ASSIGNMENT

(-2027)

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Carsmith

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GLS 99198

Yr Regn:

11 Jan 2008

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Daimler 4.2 V8

c.c

4196

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

145275

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SAJ CC 82G 78TH 24070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/408R19

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

12/7/19

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s ft

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAR 2 DAYS

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

DAR

Lump Sum / I.B.I. (\$

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2019 Edit Reg		12 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ERIC LIM WEE GUAN (ERIC LIN WEIYUAN),, ID: S7337209G									
Main Claimant: NA									
Vehicle Reg. No.: SLS9919Z		Date of Loss:	11/07/2019 07:00 - :59						
Claim Type: TP / 2860105725SG		Policy/Cover Note No.:	1900007137 (Comprehensive)						
Vehicle Reg. No. (Insured): SLC7396D		Policy No. (Claimant):							
		Excess:							
Repairer: Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah,MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/07/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

RE: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Fan, Winnie-LW
To:
Cc:
Sent: 7/12/2019 10:42:58 AM

Hi LKK,

Kindly assist to survey, car is in.

CARSMITH PRIVATE LIMITED
13 Kaki Bukit Road 4
#01-20 Bartley Biz Centre
Singapore 417807
Person In-Charge: Alex / Wilson
Mobile Number: 9091 0000 / 8838 3318

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	9370F
Vehicle No.:	SLS9919Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jul 2019
Vehicle Make:	DAIMLER
Vehicle Model:	4.2 V8 S/C LWB SUNROOF AUTO
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	0706281246
Chassis No.:	SAJCC82G78TH24070
Maximum Power Output:	218.9 kW (293 bhp)
Open Market Value:	\$127,987.00
Original Registration Date:	11 Jan 2008
First Registration Date:	11 Jan 2008
Transfer Count:	3
Actual ARF Paid:	\$140,786.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Dec 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$51,850.00
COE Rebate Amount:	\$43,877.00
Total Rebate Amount:	\$43,877.00

The information contained herein is correct as at 14 Jul 2019

OK

► jaguar Used Vehicle List (5 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Jaguar XJS 4.0A (COE till 01/2023)	-	-	15-Apr-1993	3,980 cc	128,000 km		Available

Classic Jaguar Convertible Elect Soft Top Tip Top Cond Export Welcome. Best Offer Secures.

Office No. - -

Lim - 96271512

Jaguar XJS 3.6A (COE till 04/2029)	\$75,776	-	26-Jun-1991	3,590 cc	-		Available
---	-----------------	---	-------------	----------	---	--	------------------

Own It For 19 Years, It Always Been An Engaging Drive That Never Bores. You Will Appreciate This Car. Head Turner At Red Lights And Usually The Center Of Topic During Meet Up. View To Believe The Cond...

Office No. - -

Edwin - 98778000

Jaguar XJ8 3.2A LWB (COE till 12/2028)	\$93,800	\$9,950 /yr	15-Dec-1998	3,248 cc	142,300 km	1 & Ones Motoring Pte Ltd	Available
---	-----------------	--------------------	-------------	----------	------------	---------------------------	------------------

Limited Edition Jaguar XJ8, Long Wheel Base, V8 Power, Sports Sedan, Only Produce 771 Units In Worldwide. Fully Serviced/Maintained With Jaguar Auto Specialist Since Day 1, Very Low Mileage, Immaculat...

Office No. - -

Francis - 96665533

Jaguar XJ6 3.2A LWB (COE till 03/2026)	\$110,000	\$16,370 /yr	15-Jul-1996	3,239 cc	-		Available
---	------------------	---------------------	-------------	----------	---	--	------------------

Car Is In Excellent Original Condition With Zero Modifications Car Is Always Garaged In My House And Used For Special Occasions Only As I Have 8 Other Cars, Super Smooth And Quiet To Drive And "Flies"...

Office No. - -

Ajmer Singh - 93693163

Jaguar XJ6 3.2A LWB (COE till 04/2026)	\$95,800	\$14,090 /yr	01-Jun-1996	3,239 cc	-	Roadlink Auto Pte Ltd	Available
---	-----------------	---------------------	-------------	----------	---	-----------------------	------------------

Classic And Popular Model By Jaguar! Mint Exterior And Interior! No Expenses Spared For Preventive Maintenance And Always Kept In Top Condition By Fuzzy Owner, Well Maintained Exterior And Interior. A...

Office No. - 66360538

Tom - 91889988 | Colin Lim - 82255588

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2019 16:13
Date Of Accident	11/07/2019 07:40
Exact Location Of Accident	526 MILTONIA CLOSE CP LOT 84
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS9919Z
Insured/Policyholder	
Name Of Registered Owner	OW SOON POOH
NRIC No	S1439370F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91911452
Alternative Phone No	OTHERS-91911452

Vehicle Particulars

Manufacturer	DAIMLER
Model	DAIMLER / 4.2 V8 S/C LWB SUNROOF AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093635169-01
Cover Note Number	

Driver

Name of Driver	OW TSUI GEK, TRACY(HU CUIYU, TRACY) MRS TRACY LIND
NRIC No	S8338281C
Date Of Birth	02/12/1983
Occupation	OUTDOOR
Date Of Driving Pass	04/08/2003
Driving Experience	15 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91911452
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	526 MILTONIA CLOSE #04-19
Postcode	768107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC7396D
Vehicle Make/Model/Colour	MERCEDES BENZ / GLC250 4MATIC (R18 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4
 Singapore 415933
 Tel: 67416697
 Reporting Centre Personnel's Signature
 Name:
 Fax: 67492305
 NRIC/FIN No:
 Email: vackb@singnet.com.sg

SKETCH PLAN



ASLS99192

BSLC73960

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I Park my car at my house car park Lot 84 my neighbour come to my house and inform me there when he turned out from the parking lot beside me accidentally collided onto my car and cause my front right side damage.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Phone No: 67416697
Name: 
Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg



Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DS		
1005	992341	Frt Bumper Clips	MC		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	CRA		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Reflector RH M/S			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding Inner Garnish	CRA		
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	DM		
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	DR		
1021	991793	Frt Grille	CRA		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel	CRA		
1025	992013	Frt Support Panel	CRA		
1026	992025	Frt Support Panel Top Garnish Cover	RE		
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRA		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	REPAIR		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Finge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No:

4599198

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	CRA		
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	REPAIR		
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp	Inner Garnish	CRA	
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	REPAIR		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2019 Edit Reg		12 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ERIC LIM WEE GUAN (ERIC LIN WEIYUAN),, ID: S7337209G								
Main Claimant:	NA								
Vehicle Reg. No.:	SLS9919Z	Date of Loss:	11/07/2019 07:00 - :59 [138 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2860105725SG	Policy/Cover Note No.:	1900007137 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC7396D	Policy No. (Claimant):							
		Excess:							
Repairer:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS9919Z (2860105725SG)

[SLC7396D]










































TP




















































NA

















Jul 11 2019 7:00AM

[ERIC LIM WEE GUAN (ERIC LIN WEIYUAN),]

Carsmith Private Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
2	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
3	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
4	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
5	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
6	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
7	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
8	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
9	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
10	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
11	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
12	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
13	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
14	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
15	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
16	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
17	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
18	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
19	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
20	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
21	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
22	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
23	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
24	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
25	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
26	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
27	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
28	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
29	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
30	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
31	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
32	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
33	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
34	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
35	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
36	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
37	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
38	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
39	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
40	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
41	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
42	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			
43	29/07/19 15:13	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	29/07/19 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	29/07/19 15:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	29/07/19 15:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	29/07/19 15:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	29/07/19 15:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	29/07/19 15:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	25/10/19 09:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/07/19 10:44	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012366/GCD3E2

Date: 30/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900007137

Claimant Vehicle No : SLS9919Z Insured Vehicle No : SLC7396D

Date of Loss: 11/07/2019 Nature of Claim: TP Claim No: 2860105725SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS9919Z**
 Make & Model: DAIMLER V8, 4.2 S/C LWB SUNROOF AUTO (A) Engine No: 0706281246
 Reg. Date: 11/01/2008 (Man. Year: 2007) Chassis No: SAJCC82G78TH24070
 Colour: White Odometer: 145275 km
 Engine Capacity: 4196 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40Z R19 Rear Tyre Size: 255/40Z R19
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Carsmith Private Limited (HQ)
 13 KAKI BUKIT ROAD 4 #01-20
 BARTLEY BIZ CENTRE
 Singapore 417807

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Distorted	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*FRT BUMPER REFLECTOR RH	Missing	0.00 F	*- F
6	1		*FRT BUMPER INNER GARNISH	Cracked	0.00 F	*- F
7	1		*FRT BUMPER SENSOR	Damaged	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
9	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
10	1		*FRT GRILLE	Cracked	0.00 F	*- F
11	1		*FRT APRON PANEL	Cracked	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
13	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*- F
14	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*BONNET	Repair	0.00 F	*- F
16	1		*ENGINE UNDER COVER	Cracked	0.00 F	*- F
17	1		*FRT RH FENDER	Buckled	0.00 F	*- F
18	1		*FRT RH FENDER INNER GARNISH	Cracked	0.00 F	*- F
19	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >