



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19012457/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 15-09-2020



ATTN: YVONNE ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 2882M	Veh. Inspected	SMG 7228Z
Policy No.	GA173615	Coverage (\$)	0.00
Claim No.	S9M01T7V	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	15/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GK31337167	Colour	METALLIC GREY
Odometer	015012	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	8 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	8 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	8 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2019	Inspection Date	15/07/2019
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**