



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/8/2020

### Survey Details:

Date of loss	7-Jul-19
Date of appointment	15-Jul-19
Date of survey	15-Jul-19
Location of survey	S & H MOTOR PTE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SMG7228Z
Make and Model	HONDA FIT 1.3GF CVT - 1317cc
Date of registration	28-Dec-18
Parf Rebate	
Market Value	\$ 77,000.00
Parf Rebate	\$ 24,377.00
Nett Loss	\$ 52,623.00

### Repair details:

Initial Estimate	\$ 9,096.33
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 6,650.25
Check items (estimate)	NIL
Labour	\$ 1,912.58
<b>Total</b>	<b>\$ 8,562.83</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

<b>Number of days for repair</b>	<b>11.0</b>
----------------------------------	-------------



**Remarks:**

*OID rear-ended third party.*

**Mandate:**

<b>Liability(TP)</b>		<b>100%</b>	
Proposed repair cost (w/GST)	\$	9,162.23	
Loss of use*	\$	360.00	(6days x \$60.00)
Loss of rental *	\$	700.00	(7days x \$100.00)
Loss of income		NIL	no. of days
LTA search fees	\$	2.00	
Others		NIL	
<b>Proposed Total</b>	<b>\$</b>	<b>10,224.23</b>	

\*Kindly refer to the below attached breakdown of number of days(SMG7228Z) for easy reference.

**Breakdown of number of days (SMG 7228Z)**

<b>Date:</b>		<b>Remarks:</b>	<b>Days</b>	
07.07.2019	Sunday	DOA.		
12.07.2019	Friday	TP sent notification to AXA.		
13.07.2019	Saturday	Off	1	LOU
14.07.2019	Sunday	Off	2	
15.07.2019	Monday	LKK conducted survey as per AXA assignment.	3	
16.07.2019	Tuesday	Repair day 1	4	
17.07.2019	Wednesday	Repair day 2	5	
18.07.2019	Thursday	Repair day 3	6	
19.07.2019	Friday	Repair day 4. Start Car Rental.	7	
20.07.2019	Saturday	Repair day 5	8	
21.07.2019	Sunday	Off	9	
22.07.2019	Monday	Repair day 6	10	
23.07.2019	Tuesday	Repair day 7	11	
24.07.2019	Wednesday	Repair day 8	12	
25.07.2019	Thursday	Repair day 9	13	
26.07.2019	Friday	Repair Done. Car collected by third party.	14	