

INS. CASE OWNER:

CC 4, 11 190 12466, R1903 9

LKK:
IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

18/7/2019

Date / Time:

18/7/2019

Registered in Merimen:

18/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3865R

Claim No.:

Name of Insured:

Comfort Transportation P L

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

11-7-19

Place of Accident:

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: ☒ YES / NO)OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SHA 92225



INSRS:

WSP:

Tel:

Liability:

RMKS:

Dmg Auto.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHA 92225 - RTINCL 09/18629/V : 009 - 18/7/10
SHC 3865R - CC/LOR 18/026087/R1903 9 : 3015/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Rasul

Repair Cost:

SS 47001-

(5 days) Reduction: \$3149.28 % 43

Email

Call

FINAL SETTLEMENT

Date/Time:

21/8/19 15:45pm Confirm with Hashim

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 26

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

SS 4547.50

OID open door hit TPV.

Loss of Rental (LOR):

SS 631.80

(6 days) x \$105.30

Loss of Use (LOU):

SS -

(\$ x 6 days)

Loss of Income (LOI):

SS 240.00

(\$ 40 x 6 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 5426.79

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 5426.79

Name 1:

Dmg Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

COPY SENT
18/9/19

Cecilia

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/07/2019 12:58

JOB-NO: 50111834

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9222S TRANS: AUTO
 MAKE / MODEL: HYUNDAI / i40
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHLB41UMGU079781
 ENGINE: D4FDFU553157

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURDISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00			Y 700
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00			Y 200
3 RESPRAY LHS FENDER	1.00	250.00	0.00	250.00			Y 200
4 RESPRAY FRONT LHS DOOR	1.00	350.00	0.00	350.00			Y 200
5 RESPRAY FRONT LHS SIDE MIRROR ASSY	1.00	100.00	0.00	100.00			Y 180
6 R&R FRONT LHS DOOR COMPONENT	1.00	200.00	0.00	200.00			Y 60
7 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	150.00	0.00	150.00			Y 260
8 CALIBRATION OF FRONT LHS POWER WINDOW	1.00	80.00	0.00	80.00			Y X
TOTAL:		3,180.00	0.00	3,180.00			

MATERIALS

1 FRONT BUMPER <i>Part de</i>	1.00	699.68	139.94	559.74	L	Y	
2 FRONT BUMPER RETAINER LH <i>to 3.00</i>	1.00	42.32	8.46	33.86	L	Y	
3 FRONT LHS FENDER <i>bt</i>	1.00	759.60	151.92	607.68	L	Y	
4 FRONT INNER SHIELD LHS <i>X</i>	1.00	186.12	37.22	148.90	L	Y	
5 SIDE MIRROR LH <i>bro</i>	1.00	516.40	103.68	414.72	L	Y	
6 SIDE MIRROR GLASS LHS <i>bro</i>	1.00	62.40	12.48	49.92	L	Y	
7 FRONT LHS DOOR ASSY <i>bt</i>	1.00	2,256.83	451.37	1,805.46	L	Y	
8 FRONT LHS DOOR GLASS CHROME Moulding Outer <i>at</i>	1.00	180.00	36.00	144.00	L	Y	
9 FRONT LHS INNER SHIELD CLIPS <i>re</i>	1.00	35.00	0.00	35.00	S	Y	25
10 FRONT BUMPER ADS STICKER <i>X NV</i>	1.00	150.00	0.00	150.00	S	Y	
11 FRONT LHS ADS STICKER <i>re</i>	1.00	120.00	0.00	120.00	S	Y	
12 FRONT DOOR ADS STICKER LH <i>re</i>	1.00	150.00	0.00	150.00	S	Y	120
TOTAL:		5,160.35	941.07	4,219.28			

TOTAL PARTS & LABOUR :

6,340.35 941.07 7,399.28

EXCESS/LOADING:SS 0.00

No. Of Day:

5 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM:SS

DATE OF SURVEY: 15 107 18 P1550

SURVEYED BY:

Rafael

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURDISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	---------	-----------

CONTACT NO:

900 0068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Lump Sum

Labour = \$ 1500

S/M = \$ 225

Parts = \$ 3615.38

LTSFP = \$ 5340.38 - 20% 1/5

= \$ 4272.30

Final Amount = \$ 4272.30

L/S - 4250

5 days

LXX Auto Centre Ltd. hereby

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/07/2019 12:58

JOB-NO: 50111834

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9222S

TRANS: AUTO

CHASSIS: KMHLB41UMGU079761

MAKE / MODEL: HYUNDAI / I40

ENGINE: D4DFU553157

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00	Y		700
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	Y		200
3 RESPRAY LHS FENDER	1.00	250.00	0.00	250.00	Y		200
4 RESPRAY FRONT LHS DOOR	1.00	350.00	0.00	350.00	Y		200
5 RESPRAY FRONT LHS SIDE MIRROR ASSY	1.00	100.00	0.00	100.00	Y		80
6 R&R FRONT LHS DOOR COMPONENT	1.00	200.00	0.00	200.00	Y		60
7 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	150.00	0.00	150.00	Y		80
8 CALIBRATION OF FRONT LHS POWER WINDOW	1.00	80.00	0.00	80.00	Y		X
TOTAL:		3,180.00	0.00	3,180.00			
<u>MATERIALS</u>							
1 FRONT BUMPER <i>repair de</i>	1.00	899.68	139.94	559.74	L	Y	
2 FRONT BUMPER RETAINER LH <i>2.2.2.2</i>	1.00	42.32	8.46	33.86	L	Y	
3 FRONT LHS FENDER <i>bt</i>	1.00	759.60	151.92	607.68	L	Y	
4 FRONT INNER SHIELD LHS <i>X</i>	1.00	186.12	37.22	148.90	L	Y	
5 SIDE MIRROR LH <i>bro</i>	1.00	518.40	103.68	414.72	L	Y	
6 SIDE MIRROR GLASS LHS <i>bro</i>	1.00	82.40	12.48	49.92	L	Y	
7 FRONT LHS DOOR ASSY <i>bt</i>	1.00	2,256.83	451.37	1,805.46	L	Y	
8 FRONT LHS DOOR GLASS CHROME MOULDING OUTER <i>at</i>	1.00	180.00	36.00	144.00	L	Y	
9 FRONT LHS INNER SHIELD CLIPS <i>re</i>	1.00	35.00	0.00	35.00	S <i>25</i>	Y	
10 FRONT BUMPER ADS STICKER <i>re X</i>	1.00	150.00	0.00	150.00	S	Y	
11 FRONT LHS ADS STICKER <i>re</i>	1.00	120.00	0.00	120.00	S <i>80</i>	Y	
12 FRONT DOOR ADS STICKER LH <i>re</i>	1.00	150.00	0.00	150.00	S <i>120</i>	Y	
TOTAL:		5,160.35	941.07	4,219.28			
TOTAL PARTS & LABOUR:		8,340.35	941.07	7,399.28			

EXCESS/LOADING: S\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM S\$

DATE OF SURVEY: 15 107 18 P1550

SURVEYED BY:

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO: 900 6868 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Lumpsum

Labour = \$ 1500

S/N = \$ 225

Parts = \$ 3615.38

Lftsp = \$ 5340.38 - 20% 4/s

= \$ 4272.30

Final Amount = \$ 4272.30

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/07/2019 12:58

JOB-NO: 50111834

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9222S

TRANS: AUTO

CHASSIS: KMHLE41UMGU079761

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFU553157

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00		Y	700
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
3 RESPRAY LHS FENDER	1.00	250.00	0.00	250.00		Y	200
4 RESPRAY FRONT LHS DOOR	1.00	350.00	0.00	350.00		Y	200
5 RESPRAY FRONT LHS SIDE MIRROR ASSY	1.00	100.00	0.00	100.00		Y	180
6 R&R FRONT LHS DOOR COMPONENT	1.00	200.00	0.00	200.00		Y	60
7 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	150.00	0.00	150.00		Y	260
8 CALIBRATION OF FRONT LHS POWER WINDOW	1.00	80.00	0.00	80.00		Y	X
TOTAL:		3,180.00	0.00	3,180.00			

MATERIALS

1 FRONT BUMPER Repair de	1.00	699.68	139.94	559.74	L	Y	
2 FRONT BUMPER RETAINER LH 2.2.2.2	1.00	42.32	8.46	33.86	L	Y	
3 FRONT LHS FENDER b1	1.00	759.60	151.92	607.68	L	Y	
4 FRONT INNER SHIELD LHS X	1.00	186.12	37.22	148.90	L	Y	
5 SIDE MIRROR LH bro	1.00	518.40	103.68	414.72	L	Y	
6 SIDE MIRROR GLASS LHS bro	1.00	62.40	12.48	49.92	L	Y	
7 FRONT LHS DOOR ASSY b1	1.00	2,256.83	451.37	1,805.46	L	Y	
8 FRONT LHS DOOR GLASS CHROME Moulding Outer	1.00	180.00	36.00	144.00	L	Y	
9 FRONT LHS INNER SHIELD CLIPS ne	1.00	35.00	0.00	35.00	S	Y	25
10 FRONT BUMPER ADS STICKER ne X	1.00	150.00	0.00	150.00	S	Y	
11 FRONT LHS ADS STICKER 2.2.2.2	1.00	120.00	0.00	120.00	S	Y	80
12 FRONT DOOR ADS STICKER LH ne	1.00	150.00	0.00	150.00	S	Y	120
TOTAL:		5,160.35	941.07	4,219.28			

TOTAL PARTS & LABOUR:

8,340.35

941.07

7,399.28

EXCESS/LOADING: S\$ 0.00

No. Of Day:

85 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM S\$

DATE OF SURVEY:

15 07 19 @ 1550

SURVEYED BY:

Rafael

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO:

900 0068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7812778C



Name
ONG ENG HONG
王永鴻
Race
CHINESE
Date of birth
10-05-1978 Sex
M
Country of birth
SINGAPORE




4801780



NRIC No: S7812778C



Date of issue
15-10-2012

APT BLK 460A BUKIT BATOK WEST AVENUE 6 #12-851
SINGAPORE 651460
NRIC No: S7812778C Date: 08/03/2016

REPUBLIC OF SINGAPORE DRIVING LICENCE



ONG HONG
10 May 1978
15 Oct 2012




0021148470

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 4 passengers, exclusive of the driver, and other motor vehicles < 2500kg 27 Jan 1999
Class 4 Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg 28 Jan 2005
Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg

Licence No: S7812778C



NP 428A


Land Transport Authority



VOCATIONAL LICENCE
Year of issue: S7812778C
Name: ONG ENG HONG
Valid from: 31/10/2012
Please visit www.lta.gov.sg to check expiry date of this vocational licence

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI - VL	31/10/2012



Vehicle No: SHA9222S (Hirer Relief)

Reporting Date: 12/7/19 Time: 8:40 hrs

Accident Date: 11/7/19 Time: 23:00 hrs

[OD TP WC / Cash] [PG: 2] [SPD: 15 Km/H]

Mileage: 559911

[HP: 81613557] [Weather Condition: Clear / Raining / other:] [Road surface: Wet / Dry / Other:]

[Location: CHANGI AIRPORT TERMINAL 1 DOOR 4]

TP1: Number Plate SHC3865K Name: WONG PHANG HONG NRIC: S2014927B HP: _____

TP2: Number Plate _____ Name: _____ NRIC: _____ HP: _____

TP3: Number Plate _____ Name: _____ NRIC: _____ HP: _____

[Witness: _____]

[HP: _____]

[Tow: Y/N]

Satisfaction Voucher

17 JUL '19 15:12

Date: 17/07/2019

MS First Capital Insurance Limited

Attention: MOTOR CLAIMS DEPT

Dear Sir/Madam

T30 TIONG HO3

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHA9222S

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number D-18088937MFSH

reference claim number 50111834 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 11/07/2019

at CHANGI AIRPORT TERMINAL 1 DOOF

Dated this day of _____, 201 _____

Signature: [Signature]

NRIC No: S724551111

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0

Company Stamp if applicable

Date Issued : 12/10/2017

CERTIFICATE REF : MZ400A

CERTIFICATE OF INSURANCE (MASTER)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE NO.	D-18088937MFSH
Index Mark and Registration Number of Vehicle	All CityCab taxis operating in the Republic of Singapore.
Name of Insured	CityCab Pte Ltd
Coverage	Third Party Fire and Theft
Effective date of the Commencement of Insurance for the purpose of the Act	01/01/2018
Date of Expiry of Insurance	31/12/2020

Persons or Classes of Persons entitled to drive

- a) Any licensed taxi driver driving on the Insured's order or with their permission.
- b) Any person provided he is in the Insured's employ and is driving on their order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use :

- Use as a taxi.
- Use for social, domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

Excess : All Claims \$2,000.00 each and every accident

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

A/C NO. : B0101

First Capital Insurance Limited
(Approved Insurers)


Authorized Signature

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: 15 July, 2019 8:51 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear Officer,

FYI,

From: Taxis Customer Service
Sent: Friday, July 12, 2019 8:09 PM
To: 'motorclaim@iii.com.sg' <motorclaim@iii.com.sg>
Cc: 'kelly.ding@dingauto.sg' <kelly.ding@dingauto.sg>; 'dd.hashim@dingauto.sg' <dd.hashim@dingauto.sg>; 'Claims@dingautomotive.com.sg' <Claims@dingautomotive.com.sg>
Subject: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear **Officer** ,

Kindly please arrange surveyor as vehicle SHA9222S already at 31 Corporation Road.

Thanks

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

Taxis Customer Service

From: Taxis Customer Service
Sent: Monday, July 15, 2019 9:47 AM
To: Motor Claim - III
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear Officer,

Please arrange LKK Auto Consultants Pte Ltd come on to survey.

Thanks

Best Regards,
Guang
Hp : 93299929 / 62657130

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, July 15, 2019 9:12 AM
To: Taxis Customer Service <taxiscs@stengg.com>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

*****WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.*****

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Taxis Customer Service

From: Taxis Customer Service
Sent: Thursday, July 18, 2019 10:46 PM
To: 'Rasul (LKKAUTO)'
Cc: 'dd.hashim@dingauto.sg'; 'Claims@dingautomotive.com.sg'; 'kelly.ding@dingauto.sg'; 'sur@lkkauto.com'; 'AsherSng@lkkauto.com'; 'cs-a@lkkauto.com'; 'admin-a@lkkauto.com'
Subject: 50111834 / SHA9222S - Finalize Amount & After Repair Photo .
Attachments: ESTIMATE (2).jpg; AFTER PAINT (1).JPG; AFTER PAINT (2).JPG; AFTER PAINT (3).JPG; AFTER PAINT (4).JPG; AFTER PAINT (5).JPG; AFTER PAINT (6).JPG; AFTER PAINT (7).JPG; AFTER PAINT (8).JPG; AFTER PAINT (9).JPG; ESTIMATE (1).jpg

Dear Rasul ,

Please see below for the finalize according to our conversion to finalize for SHA9222S

Please refer attachment Estimate & After Paint for SHA9222S

Lump Sum Repair

Total Repair - 05 Days

Labour = \$1500

S/n = \$225

Parts after discount - 20% = \$3615.38

L+S+P = \$5340.38 -20 % lump sum

Total Finalize amount = \$4272.30

Thank You

Best Regards ,

Guang
Ding Automotive Pte Ltd
Hp : 93299929 / 62657130

Taxis Customer Service

From: Taxis Customer Service
Sent: Friday, July 19, 2019 9:58 AM
To: 'Rasul (LKKAuto)'
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; kelly.ding@dingauto.sg
Subject: RE: 50111834 / SHA9222S - Finalize Amount & After Repair Photo .

Dear Rasul,

We accept this finalize amount.

Thanks

Best Regards,
Guang
Ding Automotive Pte Ltd
HP : 93299929 / 62657130

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Friday, July 19, 2019 9:33 AM
To: Taxis Customer Service <taxiscs@stengg.com>
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; kelly.ding@dingauto.sg
Subject: RE: 50111834 / SHA9222S - Finalize Amount & After Repair Photo .

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Hi Guang,

Finalised amount round up is \$ 4,250 / 5 days lump sum
Kindly confirm

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]
Sent: Thursday, 18 July, 2019 10:47 PM
To: Rasul (LKKAuto)
Cc: dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; kelly.ding@dingauto.sg; SUR; Asher Sng (LKKAuto); CS A Team; Admin A
Subject: 50111834 / SHA9222S - Finalize Amount & After Repair Photo .

Dear Rasul,

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 15 July 2019 11:35 AM
To: Taxis Customer Service; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT
Attachments: SAS2633556.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHA9222S and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Rasmi

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: 15 July, 2019 9:47 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear Officer,

Please arrange LKK Auto Consultants Pte Ltd come on to survey.

Thanks

Best Regards,
Guang
Hp : 93299929 / 62657130

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, July 15, 2019 9:12 AM
To: Taxis Customer Service <taxiscs@stengg.com>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]

Sent: 15 July, 2019 8:51 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: RE: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear Officer,

FYI,

From: Taxis Customer Service

Sent: Friday, July 12, 2019 8:09 PM

To: 'motorclaim@iii.com.sg' <motorclaim@iii.com.sg>

Cc: 'kelly.ding@dingauto.sg' <kelly.ding@dingauto.sg>; 'dd.hashim@dingauto.sg' <dd.hashim@dingauto.sg>;
'Claims@dingautomotive.com.sg' <Claims@dingautomotive.com.sg>

Subject: ACCIDENT INVOLVING SHA9222S AND SHC3865R ON 11/07/2019 SURVEYOR ARRANGEMENT

Dear Officer ,

Kindly please arrange surveyor as vehicle SHA9222S already at 31 Corporation Road.

Thanks

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SHA9222S (MCT19070281)**
[SHC3865R]

TP
CITYCAB PTE LTD
Jul 11 2019 11:00PM

[-]
Ding Auto Pte Ltd (corporation Road)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/08/2019 12:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5426.75) - SHA9222S - Claim Handler: Priya

Approved:5426.75:Request TP WS to issue Tax invoice for Repairs in III's favour


DING AUTOMOTIVE PTE LTD

Blk 10 #01-20 Sin Ming
Industrial Est Sec C
Singapore 575645

Without Prejudice
to our driver's Injury claim

OUR REF: 50111834/TP/SHA9222S/AD/11/07/2019/DD
YOUR REF: SHC3865R/--
30 July 2019

To: MOTOR CLAIMS DEPARTMENT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET #04/#05
IOB BUILDING
SINGAPORE 049711

ACCIDENT INVOLVING : SHA9222S AGAINST SHC3865R ON 11/07/2019
LOCATION ALONG : CHANGI AIRPORT TERMINAL 1 DOOR 4
We refer to the above matter:

	Rate Per Day	Repair/ Claims Day	Amount Before GST	GST 7%	Amount After GST
Cost of Repair	\$ -	6	\$ 4,250.00	\$ 297.50	\$ 4,547.50
Loss Of Rental	\$ 105.30	6	\$ 631.80	\$ -	\$ 631.80
Loss Of Income	\$ 80.00	6	\$ 480.00	\$ -	\$ 480.00
LTA/GIA Search Fee	\$ -	0	\$ 6.96	\$ 0.49	\$ 7.45
Towing Fee	\$ -	0	\$ -	\$ -	\$ -
Surveyor Fee	\$ -	0	\$ -	\$ -	\$ -
Total	\$ 185.30	6	\$ 5,368.76	\$ 297.99	\$ 5,666.75

The accident was caused solely by the negligence of your insured and as a results , We had incurred the following costs of repair and losses of our insurer:

Enclosed are copies of the following documents for your perusal:

⊕	Repair Estimate	⊕	Discharge Voucher
⊕	GIA Report/Accident Police Report	⊕	Certificate Of Insurance
⊕	LTA 3 rd Party Search Fee	⊕	Final Bill/Repair Tax Invoice
⊕	Mileage Record	⊕	Confirmation Finalize/Liability Email Copy
⊕	Rental Invoice	⊕	Letter Of Demand
⊕	Letter Of Authority	⊕	

Our insurer has authorized DING AUTOMOTIVE PTE LTD to deal with the claim in this accident case and also to receive and deal/negotiate with all payment as stated above.
Please look into our client's claim and revert soonest as possible.

Your Sincerely,
DD HASHIM
DING AUTOMOTIVE PTE LTD
HP:81160811
FAX:64520614

LETTER OF AUTHORITY

Accident involving SHA9222S & SHC3865K on 11/7/2019 along CHANGI AIRPORT T1.

I/We, City Cab Pte Ltd NRIC/ Co.Reg Number 199502839G registered owner of vehicle No. SHA9222S which was rented to Hirer/Driver Mr/Ms TEO TIONG HOE NRIC 37245114, hereby authorize Ding Automotive Pte Ltd on this date 12/7/2019 to submit, correspond, negotiate and settle my/our claim for cost of repair and uninsured losses arising from the above accident and without prejudice of our driver's injury claim.

I/We further authorize that agreed settlement sum for cost of repair, loss of income and rental, survey report fee or any legal fee, third party vehicle insurance particulars enquiry fee etc., be made in favour of Ding Automotive Pte Ltd and that the said payment be forwarded to them as full and final discharge of my/our claims.

Owner Signature/Co.Chop



Hirer/Driver Signature

TEO TIONG HOE

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

Without Prejudice
to our driver's liability claim

India Ref: MCT19070281
Claimant Ref: SHA 92225

We/I, DING AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,547.50 (repair cost), S\$ 571.80 (loss of INCOME rental), S\$ 7.45 (search fee), vehicle no. SHA 92225 that was damaged pursuant to the accident which occurred on 11/07/2019 (date) at TERMINAL 1 DEPARTURE HALL (location) involving vehicle no. SHC 3865R (insured vehicle). This is pursuant to the inspection conducted on 15/07/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CITYCAB PTE LTD ("the third party claimant") of vehicle no. SHA 92225 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHA 92225 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,125.75 to DING AUTOMOTIVE PTE LTD

Dated this 03 day of 09 2019

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "the workshop" (with chop)

Kelly Ding

S7907351E

Blk 10, Sin Ming Ind.

Est. Sec C, #01-20
SCS7575

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

CC4/111/9012466/Rlg03

DING AUTOMOTIVE PTE LTD

Business Reg. No : 201619222G
BLK 10, #01-20 SIN MING IND EST, SEC C, SINGAPORE 575645
Tel: 6452 1208 Fax: 6452 0614

Cecilia

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PTE LTD

IOB BUILDING
64 CECIL STREET #04-05
SINGAPORE 049711

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

INVOICE : I-000744
DATE : 28-08-2019
GST REG NO : 201619222G
TERMS : C.O.D.
PO NO : SHC3865R
OUR REF : SHA9222S
PAGE : 1 of 1

ITEM NO.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1.	Cost of repair-SHA9222A	1	4,250.00	4,250.00

REMARKS :

Job card:50111834
Your ref:SHC3865R
Oic:Ms Cecilia LKK
Doe:11/7/2019

SUB TOTAL : 4,250.00
GST : 297.50
TOTAL SGD : 4,547.50
DEPOSIT :
O/S BALANCE :

FOR DING AUTOMOTIVE PTE LTD

Authorised Signature

Customer Signature

I have inspected and hereby confirmed that
the job done and the amount due herein
are entire to my satisfaction

Our Ref: CC19070288



Date: 12 July 2019

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	11/07/2019 @ 23:00 hrs
ALONG	CHANGI AIRPORT TERMINAL 1 DOOR 4
INVOLVING	SHC3865R

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA9222S** (the "Taxi"). The Taxi was hired to **TEO TIONG HOE IC NO S7245511H** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$112.67** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Print Date/Time : 15 Jul 2019 / 08:46:36

Receipt Date/Time : 15 Jul 2019 / 08:46:24

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190715-000248

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC3865R As at 11 Jul 2019/23:00:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHC3865R Enquiry Fee 20190715084527550717	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx3576	Credit Card: Visa /MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019 Edit Reg		15 Jul 2019 00:00 Edit Adj Rpt	\$54,250.00 Edit Estimates	\$54,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHA9222S	Date of Loss:	11/07/2019 23:00 - :59 [44 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19070281	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC3865R	Policy No. (Claimant):	D-18088937MPSH						
		Excess:							
Repairer:	Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road, 649825 Boon Lay - Tel: 81316518								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/07/2019]								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
<ul style="list-style-type: none"> III_SG (26/08/2019): Alert - Adj Mandate Approved (\$5426.75) - SHA9222S - Claim Handler: Priya III_SG (23/07/2019): Alert - Adj Mandate Approved (\$40.00) - SHA9222S - Claim Handler: Priya 									
ALL ASSOCIATED TASKS		View All	Search Tasks						
Create New Task	Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA9222S (MCT19070281)
 [SHC3865R]
 TP
 CITYCAB PTE LTD
 Jul 11 2019 11:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Ding Auto Pte Ltd (corporation Road)

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
2	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
3	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
4	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
5	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
6	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
7	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
8	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
9	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
10	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
11	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
12	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
13	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
14	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
15	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
16	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
17	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
18	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
19	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
20	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
21	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
22	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
23	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
24	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
25	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
26	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
27	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
28	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
29	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
30	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
31	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
32	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
33	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
34	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
35	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
36	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
37	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
38	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
39	23/08/19 17:32	General View								Load JPG	<input checked="" type="checkbox"/>	
40	23/08/19 17:32	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	
41	23/08/19 17:32	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	
42	23/08/19 17:32	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	
43	23/08/19 17:32	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	23/08/19 17:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	23/08/19 17:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	23/08/19 17:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	23/08/19 17:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	23/08/19 17:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/07/19 16:31	EMAIL FROM III DD 15.7.19	1	Load PDF	
2	15/07/19 16:31	TP GIA REPORT	1	Load PDF	
3	18/07/19 09:41	TP ESTIMATE-MARKED	1	Load PDF	
4	22/08/19 14:30	RENTAL RECEIPT	1	Load PDF	
5	22/08/19 14:30	RENTAL MILEAGE	1	Load PDF	
6	22/08/19 14:30	LTA SEARCH	1	Load PDF	
7	22/08/19 14:30	LOD	1	Load PDF	
8	19/09/19 11:50	WORKSHOP INVOICE	1	Load PDF	
9	19/09/19 11:50	AUTHORISATION TO ACT FORM	1	Load PDF	
10	19/09/19 11:50	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	16/07/19 08:27	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19012466/R1GA3Q2

Date: 19/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant	
Vehicle No : SHA9222S	Insured Vehicle No : SHC3865R
Date of Loss: 11/07/2019	Nature of Claim: TP Claim No: MCT19070281

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9222S		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFU553157
Reg. Date:	22/10/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU079761
Colour:	Yellow	Odometer:	559912 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R18	Rear Tyre Size:	205/60 R18
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,219.28	3,840.38	378.90	8.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,500.00	1,680.00	52.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,399.28	5,340.38	2,058.90	27.83
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	7,399.28	4,250.00	3,149.28	42.56
+ GST 7.00/7.00% (S\$)	517.95	297.50	220.45	42.56
Nett Amount (S\$)	7,917.23	4,547.50	3,369.73	42.56
+ Loss of Use (6.0 x S\$40.00/day) (S\$)		240.00		
+ Car Rental (6.0 x S\$105.30/day) (S\$)		631.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,426.75		

INSPECTION

Date of Assignment:	15/07/2019	
Date Inspected:	15/07/2019 Inspected At:	Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road Singapore 649825

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA9222S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	699.68 FL	*699.68 FL
2	1		*FRONT BUMPER RETAINER LH	Necessary	42.32 FL	*42.32 FL
3	1		*FRONT LHS FENDER	Bent	759.60 FL	*759.60 FL
4	1		*FRONT INNER SHIELD LHS	Serviceable	186.12 FL	*- FL
5	1		*SIDE MIRROR LH	Broken	518.40 FL	*518.40 FL
6	1		*SIDE MIRROR GLASS LHS	Broken	62.40 FL	*62.40 FL
7	1		*FRONT LHS DOOR ASSY	Bent	2,256.83 FL	*2,256.83 FL
8	1		*FRONT LHS DOOR GLASS CHROME MOULDING OUTER	Cut	180.00 FL	*180.00 FL
9	1		*FRONT LHS INNER SHIELD CLIPS	Necessary	35.00 FS	*25.00 FS
10	1		*FRONT BUMPER ADS STICKER	Not Necessary	150.00 FS	*- FS
11	1		*FRONT LHS ADS STICKER	Necessary	120.00 FS	*80.00 FS
12	1		*FRONT DOOR ADS STICKER LH	Necessary	150.00 FS	*120.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$)	5,160.35	4,744.23
- List Item Discount on L Items 20.00/20.00% (S\$)	941.07	903.85
Total Parts (S\$)	4,219.28	3,840.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,800.00	700.00
2	RESPRAY FRONT BUMPER	New	250.00	200.00
3	RESPRAY LHS FENDER	New	250.00	200.00
4	RESPRAY FRONT LHS DOOR	New	350.00	200.00
5	RESPRAY FRONT LHS SIDE MIRROR ASSY	New	100.00	80.00
6	R&R FRONT LHS DOOR COMPONENT	New	200.00	60.00
7	CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	New	150.00	60.00
8	CALIBRATION OF FRONT LHS POWER WINDOW	New	80.00	0.00
Gross Labour Cost (\$\$)			3,180.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >