



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

www.cdge.com.sg

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Singapore 609286

24 Senoko Loop Singapore 758156

Singapore 728791

Singapore 768732

Sungei Kadut Sungei Kadut Way

Workshops

Loyang

Pandan

Senoko

CC19070277/ SHC 949C /WT(st) Our Ref :

Your Ref:

Date 23-Jul-19

Attn: Motor Claims Department

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

AXA Insurance Pte Ltd Singapore 508969 8 Shenton Way

#24-01, AXA Tower Singapore 068811

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC 949C YOUR INSURED SFT7000C 10.07.19 AND OTHER

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No: SHC 949C which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SFT7000C we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 4,975.50
2	8 days Loss of Rental @ \$ 161.18 per day	\$ 1,289.44
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
	Sub Total :	\$ 6,272.43

HIRER'S CLAIM

7	8	days Loss of Income @	\$	80.00	per days	\$ 640.00
			72		Total Claims:	\$ 6,912.43

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs

LTA search slip/s of:

b)

SFT7000C

c) GIA / Police report/s of: SHC 949C

Letter of authority from owner / hirer / operator

(X) Photocopie/s of Accident Scene Photo/s

() PIR

() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.





pcs.

6

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

VIANO (Maxi Cab) SHC949C , SFT7000C

ON 10-Jul-19 18:15

ALONG

PIE TOWARDS TUAS AT THOMSON FLYOVER

I / We

TAN GEOK LIN

(Hirer) NRIC No.:

SXXXX682J

and/or

(Relief) NRIC No.: SXXXX682J

Taxi Number

SHC949C

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

11-Jul-2019

Name of Hirer

TAN GEOK LIN

Hirer NRIC

SXXXX682J

Signature:

Address

815B CHOA CHU KANG AVENUE 7 #...

682815

Contact No.

82739609



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SFT 7000C (Insd veh)	
	SHC 949C (TP veh)	Model: MERCEDES BENZ VIANO CDI 2.2L
Date of Accident/ Time:	10/07/2019	

Repair Estimate	:\$	7,759.65
Final Repair Cost w/GST	:\$	1,284.00
LOI	:\$	100.00 2 days at \$ 50.00 per da
Rental (if any)	:\$	322.36 2 days at \$161.18per da
LTA / GIA Search Fee	:\$	7.49
Others:	:\$	
	:\$	
Final Settlement Sum	:\$	1,713.85
Payee Name : ComfortD Is Third Party Workshop GIA		
Is Third Party Workshop GIA I		[X YES [] NO (Kindly indicate below)
Is Third Party Workshop GIA I A) For Non GIA R	Registered?	Shop: Agreed Liability(%)
Is Third Party Workshop GIA I For Non GIA R	Registered? egistered Work ered Workshop	Shop: Agreed Liability
A) For Non GIA R B) For GIA Regist BOLA Liability	Registered? egistered Work ered Workshop	Shop: Agreed Liability(%) BOLA Applicable: Yes/ No BOLA Scenario No: 27

NOTE:

- 1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE

GAPORE 508969

Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative:

Date: 09/09/2021

Signature of Witness / Workshop stamp (if applicable)

59 LOYANG DRIVE SINGAPORE 508969

Sabrina Tan

Please forward your cheque made payable to: COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document"



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01 SINGAPORE 068811

CONTACT NO: 63387288

VEHCLE NO SHC 949C

NO/DATK 91456474 22.07.2019

MERCEDES BENZ

JOB NO. 30531.0607

MODEL. VIANO CDI 2,2L ODOMETER READING

DATE OF REG 11.10.2013

CHASSIS CODE

JOB TYPE

WDF63981323801726

Description: 3P 10.07.2019

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt Add GST @

7.000 %

4,650.00 325.50

Total Invoice amount.

4,975.50

Issued by : KATHERINETAN 22.07.2019 15:19:41
Repair Type : CFSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No.

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CC19070277

Date: 22 July 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

10/07/2019 @ 18:15 hrs

ALONG

PIE TOWARDS TUAS AT THOMSON FLYOVER

INVOLVING

SFT7000C

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC0949C (the "Taxi"). The Taxi was hired to TAN GEOK LIN IC NO S6820682J a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$161.18 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

		1 2 4 5 1				
FRATED (TIME)			()	MILEAGE	HOURS OPERATED (TIME)	SATED (TIME)
TO	DATE	NAME OF DRIVER	MILEAGE READING	(KM)	FROM	TO
	11.07.19	A CC ipent		<i>t</i> -()	(225	ſ
	18.07.19	REPAIR		CM0	1	1730
		7			C = 3	ŧ
			8	*		

Insurance Particulars Enquiry By Agents Detail

https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailBy AA?FUNCTIO...

Enquire Vehicle Insurance Details

Vehicle No.

Incident Date/Time

Search Status

Insurance Company Code

Insurance Company Name

SFT7000C

10 Jul 2019 / 18:15:00

Successful

A12

AXA INSURANCE PTE LTD

Previous

OK



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

21 August, 2019

MANOJ KANTILAL THACKER 2 ARDMORE PARK, #18-03 SINGAPORE 259947

Dear Sir,

OUR REF

: CC4/ASM19012469/K1pb3 // S9M01TSW

YOUR REF : SFT 7000C

ACCIDENT INVOLVING SFT 7000C & SHC 949C ALONG/AT PIE TOWARDS TUAS AT THOMSON FLYOVER ON 10/07/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from COMFORTDELGRO ENGINEERING PTE LTD acting on behalf of the owner of SHC 949C against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. You intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 7 days from the date of this letter if not provided at our <u>reporting centre</u>. The list below is not all inclusive and further document may be required:

- · Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at 6742 3197 or chewht@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Chew Hsiao Tong

Case Handler DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

Cc AXA Insurance Pte Ltd (Motor Claims Dept)









Service Request Details

Claim

S9M01TSW

Reference

CC4/ASM19012469/K1pb3

Loss Date

10 July 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

12 Jul 2019 1:28:45 PM

Request Date

28 February 2020

Due Date

12 July 2020

Services

Pending verification - Direct Settlement

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work







Vehicle Information

Incident Vehicle Registration #

SHC949C

Make

TPVD MERCEDES-BENZ

Model

VIANO (CDI 2.2 EU5) 2013

Service Address

, , ,

Primary Contact/Insured

THACKER MANOJ KANTILAL 2 ARDMORE PARK, #18-03, 259947, Singapore

THACKER.MANOJ@GMAIL.COM

Claim Handler

CHAN Kian Chuan

68805444

kianchuan.chan@axa.com.sg


Additional Instructions

NOT REPORTED



TYPE

9/9/21, 9:22 AM VendorEngage



9/9/21, 9:22 AM VendorEngage







TYPE

29/7/19 11:15 AM

SENT FROM

CHAN Kian Chuan

SUBJECT

REPORTED

BODY

PLS PROCEED DS WITH QUANTUM TO BE AGREED



TYPE

0

0

SENT

13/7/19 10:14 PM

FROM

CHAN Kian Chuan

SUBJECT

NON REPORTING

BODY

FOR YOUR FOLLOW UP ACTION PLS

